Managing change with a living architect OCEAN SWIMMING POOL BY ÁLVARO SIZA

CONSERVATION MANAGEMENT PLAN





Managing change with a living architect

OCEAN SWIMMING POOL BY ÁLVARO SIZA

CONSERVATION MANAGEMENT PLAN

coordinated by

Teresa Cunha Ferreira (FAUP, University of Porto)

prepared by

Teresa Cunha Ferreira (FAUP, University of Porto) Hugo Mendonça (FAUP, University of Porto)



Published with the assistance of the Getty Foundation through its Keeping It Modern initiative

1. INTRODUCTION 1.1 Preamble 1.2 Aims and structur Methodology 1.3 1.3.1 Integrated 1.3.2 Community Safeguarding of n 1.4 in Portugal: prese Authorship and ad 1.5 2. UNDERSTANDIN 2.1 Introduction 2.2 History of the place International and 2.3 Project commission 2.4 2.4.1 Coastal De 2.4.2 Building ac Design and const 2.5 2.5.1 Design chr 2.5.2 Design prir 2.5.3 Building m 2.6 Critical reception 2.7 Programme distri 2.8 Stakeholders 3. ASSESSMENT OF 3.1 Introduction 3.2 Recognition and 3.2.1 National re 3.2.2 Internation Comparative anal 3.3 3.3.1 Álvaro Siza 3.3.2 World Heri 3.3.3 Ocean, nat 3.4 Communities' per

03

Preamble 9		
Aims and structure		
Metho	dology	
1.3.1	Integrated methodology	11
1.3.2	Community-based strategies	12
Safeg	uarding of modern architecture	14
in Por	tugal: preserving the legacy of Álvaro Siza	
Autho	rship and acknowledgements	15
UNDE	RSTANDING THE PLACE	
Introd	uction	21
Histor	y of the place	22
Intern	ational and national context	25
Projec	t commission	
2.4.1	Coastal Development Plan	26
2.4.2	Building actors	28
Desig	n and construction	
2.5.1	Design chronology	30
2.5.2	Design principles	46
2.5.3	Building materials and techniques	48
Critica	al reception	51
Progra	amme distribution	52
Stake	nolders	53
ASSE	SSMENT OF SIGNIFICANCE	
Introd	uction	59
Recog	nition and listing	
3.2.1	National recognition	60
3.2.2	International recognition	62
Comparative analysis		
3.3.1	Álvaro Siza's early works	64
3.3.2	World Heritage List	65
3.3.3	Ocean, natural and tidal pools	67
Comm	nunities' perception	
3.4.1	Site managers and users	70
3.4.2	Virtual community	74
3.4.3	Students	75
3.4.4	Children	77

3.5	Dissemination activities	78	6.	MONITORING
3.6	Discussion of significance		6.1	Introduction
	3.6.1 Comparative discussion	82	6.2	Management syst
	3.6.2 Integrity and authenticity	86		6.2.1 Manageme
3.7	Levels of significance	88		6.2.2 Sources of
3.8	Statement of significance	90	6.3	Monitoring
				6.3.1 Monitoring
4.	CONDITION ASSESSMENT, CONSERVATION AND RISKS			6.3.2 Impact ass
4.1	Introduction	97	6.4	Priority of actions
4.2	Inspection and diagnosis			6.4.1 Priority act
	4.2.1 Condition survey	99		6.4.2 Implement
	4.2.2 Non-destructive and laboratory testing	106		6.4.3 Phasing
	4.2.3 Conclusions	119		
4.3	Conservation interventions			APPENDICES
	4.3.1 Conservation and building extension	120	А	Design reports of
	4.3.2 Concrete conservation interventions	132	В	Interviews with th
4.4	Hazards, vulnerabilities and risks			Council Departme
	4.4.1 Methodology	146	С	Interviews with th
	4.4.2 Hazards	148	D	Inspection and dia
	4.4.3 Vulnerabilities	151	E	Detailed tolerance
	4.4.4 Risk level	154	F	Listing informatio
			G	Admission condit
5.	MANAGEMENT AND CONSERVATION POLICIES			
5.1	Introduction	161		
5.2	Overarching policies			
	5.2.1 General policies	162		
	5.2.2 Stakeholders policies	163		
	5.2.3 Sustainable Development Goals policies	166		
	5.2.4 Interpretation policies	168		
5.3	Site policies	100		
	5.3.1 Planning policies	172		
	5.3.2 Risk assessment and climate	175		
	change adaptation policies	110		
	5.3.3 Landscape policies	178		
5.4	Conservation and management policies			
	5.4.1 Tolerance for change	184		
	5.4.2 Detailed conservation and maintenance policies	188		
	5.4.3 Maintenance schedule	218		
	5.4.4 Operational management and use policies	221		

	233
ystem and sources of finance	
ment system	234
of finance	235
	000
ng and evaluation	236
ssessment	238
ns, implementation and phasing	
actions	239
entation	241
	244
of the original decign (1960, 1995)	051
the life of ginal design (1900-1995)	251
the Heads of Municipal ments	281
the Site Managers and Staff	291
diagnosis report	303
nce for change assessment	353
tion	371
ditions and user regulations	379



1. INTRODUCTION

- 1.1 Preamble
- 1.2 Aims and structure
- 1.3 Methodology
- 1.4 Safeguarding of modern architecture in Portugal: preserving the legacy of Álvaro Siza
- 1.5 Authorship and acknowledgments



1.1 Preamble

1

The Ocean Swimming Pool was designed by the Portuguese non-destructive or minor destructive tests and laboratory architect Álvaro Siza (Pritzker Prize, 1992) between 1960 and tests. They have contributed to the localized repair of ex-1966 (with later additions until 1973) for the coastal town of posed concrete - under Álvaro Siza's coordination - which Leca da Palmeira, to the north of Porto, Portugal. In this earresorted to chromatic and texture integration techniques ly work, Siza adopted expressively modern technology and between the existing surfaces and the new repair mortars. abstract neoplastic language, building a succession of walls The Keeping It Modern grant also funded several activities in reinforced concrete over the seaside rocks. The building directed at understanding the place and assessing its signifiis currently listed as a National Monument (since 2011) and cance, namely a documentary film, an exhibition, four books, is included in the "Ensemble of Álvaro Siza's Architectural several academic papers, a Sharing Memories webinar, in-Works" in the World Heritage Tentative List (2017).

The Ocean Swimming Pool is one of Álvaro Siza's most internationally recognized works, marking a turning point in his career by expressing a tectonic shift from regionalist inspiration towards more abstract design and innovative constructive solutions. Also, the building has been in full use for almost sixty years, becoming a social and cultural landmark for the local communities.

Drafting a Conservation Management Plan for the Ocean Swimming Pool benefits thus from the unique opportunity However, the bathing complex has been at risk for many of engaging the original author in the conservation process. years because of its maritime location and the nearby oil This background allowed for the definition of a set of conrefinery. This combination of factors seriously aggravated servation and management policies - overarching, planning the decay of its concrete structures and contributed to the and landscape, risk mitigation and climate change, visobsolescence of the building's technical installations, deterits and interpretation, communication and dissemination, mining the need for a comprehensive intervention in 2018. maintenance and use (including user manuals and maintenance plan supported by BIM technology). In this way, this Álvaro Siza's recent conservation and extension (2018-2021) enhances the building's significance by preserving the archi-Conservation Management Plan aims at defining adequate tectural integrity of the ensemble and accepting the signs of management of change of this masterpiece still in full use time as a densifying element of architecture. by local communities, mitigating threats and vulnerabilities while preserving its cultural significance and design princi-This Conservation Management Plan began with support ples under the guiding inspiration of Álvaro Siza.

This Conservation Management Plan began with support from the Getty Foundation through its *Keeping It Modern* initiative. The Getty grant enabled inspection and diagnosis to be carried out on the building site through a set of in-situ The Keeping It Modern grant also funded several activities directed at understanding the place and assessing its significance, namely a documentary film, an exhibition, four books, several academic papers, a Sharing Memories webinar, interviews with building actors, surveys of local communities, guided visits, activities with children and the identification of 'Álvaro Siza's Design Principles' for the Ocean Swimming Pool. The lucid mind of Álvaro Siza constitutes an epitome of how living memories can positively contribute to the study and conservation of 20th-century architecture.

1.2 Aims and structure

Conservation Management Plans are a multi-staged process that allows and promotes the active preservation of buildings and places (Kerr, 2013). Anchored in the Burra Charter (ICOMOS Australia, 1999), they provide a cyclical framework in which heritage conservation is carried out by evolving communities' values to foster integrated management. In a holistic approach, the closer the relation of the various rights-holders in assessing significance and developing policies for achieving common agreements on maintaining it, the more efficient conservation is achieved (Mason, 2002).

Thus, this CMP is structured in 6 chapters, following the five stages described below. After a primary description of objectives and methodology in Chapter 1, Chapter 2 summarizes the historical development of the Ocean Swimming Pool. from its first design until the present, framing it on the occupation and evolution of a particular territory and as a result of a specific international and national context. Chapter 3 assesses the cultural significance of the Ocean Swimming Pool, understood as identifying heritage values to inform the development of significance-based policies to guide the conservation, interpretation, and management of the place. Chapter 4 assesses the physical condition of the Ocean Swimming Pool and identifies the vulnerabilities and risks that may affect its future management and conservation. The information gathered aims to inform the CMP's policy development, which must address the identified vulnerabilities. Chapter 5 addresses a broad range of subjects, from planning to maintenan-

ce, establishing a set of policies to implement in this CMP's context. These policies are framed to reinforce the primacy of Álvaro Siza's design principles, ensure adaptations and new uses are compatible with the significant values of the place, and provide guidance for the care and conservation of significant elements and fabric. Chapter 6 presents the monitoring recommendations aimed at providing a comprehensive framework for future management decisions regarding priorities and a timeframe for implementing conservation actions.

Additionally, the Appendices provide supplementary information. Appendix A gathers the design reports documenting the Ocean Swimming Pool's construction and conservation interventions until 1995. Appendices B and C contain the interviews conducted with the heads of Municipal Council Departments, site managers, and staff. The extended versions of the inspection and diagnosis report and the tolerance for change assessment can be read in Appendices D and E, respectively. Information on the listing process of the Ocean Swimming Pool was included in Appendix F, as well as the admission conditions and user regulations set by the site's current management.

1.1 Ocean Swimming Pool conservation management planning process.1.2 Building assessment methodology.

1.3 Methodology

1.3.1 Integrated methodology

The CMP information gathering process includes the integration of both 'documentary evidence' and 'physical evidence' about the site or building (Kerr, 2013).

For the Ocean Swimming Pool, 'documentary evidence' included different kinds of sources from eight archives (written, graphic, photographic, and cartographic materials, among others), published material (more than eighty publications, including books, chapters, articles, and academic works), oral sources (interviews to building actors and to local communities), among others. To collect oral sources and assess the cultural significance of the site, several participation strategies were carried out, namely: i) interviews (building actors - architect, engineer, contractor, owner, site managers, Municipal Council); ii) interviews and surveys to stakeholders (building actors, experts, site managers, users, and visitors); iii) social media; iv) workshops (children, students, experts); and v) other activities (exhibition, visits, documentary film). The cross-analysis of these sources made it possible, even over half a century later, to assess the material history of the building, namely its construction phases and the building materials and technologies applied in its design and construction.

STAGE 1 Understanding the place Gather documentary and physical evidence **STAGE 2** Assessing significance Identify attributes and heritage values Develop a statement of significance **STAGE 3** Building condition assessment and vulnerabilities Assess physical condition Identify vulnerabilities and risks STAGE 4 Management and conservation policies Develop overarching policies covering governance and interpretation Develop site policies on planning constraints, risk assessment, climate change adaptation and landscape preservation Develop detailed conservation and management policies STAGE 5 Monitoring and implementation Establish implementation priorities and phasing Monitor implementation process

1.1



Using the building fabric as the most reliable source (Kerr, 2013, p. 7), the analysis of the 'physical evidence' was also of major importance in the process, supported by a geometric survey (laser scanner and photogrammetry, which allows for 3D BIM modeling for facility management, currently under development), building condition assessment using non-destructive and minor destructive testing. Hence, a laser scanner survey and photogrammetric processing of elevations were carried out. At the same time, inspection and diagnosis included a condition survey, evaluation of the out-of-plane deformations of the walls, and non-destructive and minor-destructive testing. The investigation campaign included: i) concrete carbonation testing; ii) laboratory tests to determine the mechanical properties of the concrete and steel rebars; iii) chloride content testing; iv) water penetration testing; v) concrete testing with Schmidt hammer; vi) sonic testing; vii) color analysis based on spectrophotometry; viii) Ground Penetrating Radar (GPR) testing.

The documentary and physical evidence allowed for the characterization of the building in detail and were the basis for the future definition of conservation and maintenance policies in the framework of the Conservation Plan developed under the *Keeping It Modern* grant awarded by the Getty Foundation to the Ocean Swimming Pool.

Community-based strategies 1.3.2

Community participation and stakeholder integration are among the best practices for heritage management and conservation, shifting from top-down, reactive, and regulatory approaches towards bottom-up, proactive, and participated approaches integrating communities throughout the process. Hence, this project attempted to overcome the traditional practices that only consider citizens' involvement at the final validation stages of conservation management planning. The variety and broadness of the raised aspects regarding the Ocean Swimming Pool demonstrates the potential of citizens' engagement to build more inclusive and democratic planning policies. Moreover, this research adopted a broad 'community' concept going beyond users and visitors, by also encompassing the perspective of academics, staff, concessionaires, and the Municipal Council.

Cultural significance is understood as the set of tangible and intangible qualities that make a place of value to society

(Kerr, 2013, p. 4). The precise identification of the heritage values recognized by specific communities at a particular time and its assessment process is fundamental to inform the development of significance-based policies to guide the conservation, interpretation, and management of the site so that the significance of the place is retained.

Engaging communities in a broad sense, thus, was a fundamental decision within the methodology adopted for the Ocean Swimming Pool CMP. Being a public facility continuously in use, primarily by local communities, made compulsory the integration of these voices, alongside government institutions, experts, and site managers, into the discussion of the future management of change.

1.4 Correspondence between key heritage values and policy response to sustain significance.

DATA COLLECTION METHOD	SUBJECTS/UNIVERSE/SAMPLING	RELEVANCE	TIME PERIOD
Interviews	Building actors (architects, engineers, owner)	Collecting data on original design and recent conservation	July 2020-July 2021
		Assessing Significance	
		Vulnerabilities, Policies	
	Municipal Council Departments (Culture, Heritage, Planning,	Assessing Significance, Vulnerabilities, Expectations	June 2021
	Environment, Civil Protection, Environment, Conservation and	Maintenance and User's Manuals	
	Maintenance)	Use and Vulnerabilities	
		Protection	
		Interpretation Plan	
	Site managers and staff (head of division, technical directors,	Assessing Significance, Vulnerabilities, Expectations	June 2021
	maintenance foreman, receptionist, lifequard, security quard, cleaning	Maintenance and User's Manuals	
	assistant)	Interpretation Plan	
	Bar concessionaire		
Surveys	Users (bathers)	Assessing Significance, Vulnerabilities,	June-July 2021
	Visitors	Expectations	
	Staff	Collecting memories	
Social Media	Instagram (virtual community)	Assessing Significance	April-July 2021
Workshops (activity	Children (drawing)	Assessing Significance	June-July 2021
with children, students, sharing	Students	Collecting Memories	
memories)	Álvaro Siza, Faculty of Architecture, Municipal Council, Casa da Arquitectura, Architects, Historians and critics (Sharing Memories webinar)	Collecting data on the original design and critical reception	September 2021

Other activities (exhibition, visits,	Building actors, Archives, Stakeholders and visitors (exhibition)
documentary film, symposiums)	Visitors (visits)
	Building actors, site managers, viewers (documentary film)

Experts, professionals and academics (Symposiums with ISC20C, Getty, ICOMOS Portugal/ France)

1.3

The policy definition of this CMP is sustained by a variety The ultimate goal of the policies is to retain, conserve and, of sources, such as institutional documents and legislation where possible, enhance the significance of the place. Thus, (national and international), observation, and fieldwork, as the following table establishes a direct relationship between the statement of significance and related values, with the well as the above-mentioned strategies: interviews (with the building actors, the Municipal Council departments related policy response to sustain it. to the Ocean Swimming Pool and the site managers), surveys, workshops, activities, and social media analysis, engaging different kinds of stakeholders and communities.

STATEMENT OF SIGNIFICANCE	CULTURAL VALUE	POLICY RESPONSE TO SUSTAIN SIGNIFICANCE
Outstanding work within the context of the revision of the Modern Movement	Historic	A.2 Álvaro Siza's design principles
Considered a masterpiece by leading international	Historic	A.2 Álvaro Siza's design principles
architecture critics	Aesthetic	
Extensively photographed, filmed, and written about	Historic	A.7 Interpretation Plan / A.10 Archives
	Aesthetic	and Collections
Expressing a tectonic shift from regionalist inspired	Historic	A.2 Álvaro Siza's design principles
designs towards a more abstract language	Aesthetic	
Material integrity has been maintained	Age	B.5 Risk Management Plan/ C.2 Main- tenance Plan
ne of the first constructions in exposed concrete in	Historic	C.3 Maintenance Plan
Portugal, employing innovative construction systems	Scientific	
Reflects a harmonious integration within the topography	Aesthetic	B.8 Landscape Management Plan
and surrounding landscape	Ecological	
Social and cultural landmark for the community	Social	A.7 Interpretation Plan / A.8 Communication strategy / A.9 Community Engagement
One of the most sought after attractions in Matosinhos	Economic	C.5 Capacity and entrance control
An exceptional case of an architect preserving his own	Historic	C.1 Significance and tolerance for
work while enhancing its significance	Aesthetic	change
Is included in the Tentative List for World Heritage Status as a component property of 'Álvaro Siza's Architecture Works in Portugal' and is listed as a National Monument	Political	B.2 Cultural Heritage Safeguarding
1.4		

Assessing Significance	May-July 2022
Collecting Memories	July 2021-2022
Collecting data on the original design and critical reception	1 0001
	June 2021
	July 2022

^{1.3} Community-based strategies.

1. INTRODUCTION

15

1.4 Safeguarding of modern architecture in Portugal: preserving the legacy of Álvaro Siza

Despite its international recognition, 20th-century architecture in Portugal is a 'heritage at risk' since it belongs to a recent past that has not yet been sufficiently recognized, either by the Portuguese management and safeguarding organizations or by the general public. There are few listed buildings (Tostões, 2013), and many are threatened by advanced degradation (due to lack of use and maintenance) or intrusive and transforming interventions.

Nevertheless, some positive programmes have been implemented in the form of inventories and surveys undertaken by DOCOMOMO Iberico, the Inventory of 20th-century architecture in Portugal - (Inquérito à Arquitectura do Século XX em Portugal - IAPXX) developed by the Portuguese Association of Architects (Ordem dos Arquitectos), the National Inventory of Architectural Heritage (Sistema de Informação para o Património Arquitectónico - SIPA) and the recent listing of 20th-century buildings carried out by the Directorate-General for Cultural Heritage (Direcção-Geral do Património Cultural - DGPC), among others. Moreover, seminars, exhibitions, and publications on these subjects have gradually increased, indicating a growing recognition and interest by the academic and professional communities (Ferreira, 2014).

In the international context, the conservation of 20th-century architecture has been a matter of intense debate over the last three decades, with the consensus that existing philosophical approaches are broadly applicable and should follow an architectural reflection based on a casuistic approach; still, there are some specific technical challenges which require careful consideration (Macdonald 2013, p. 8). Regarding this subject, the Madrid Document (2011) settles some principles for the conservation of 20th-century architecture, namely prior in-depth knowledge of material signs, "including physical location, design, construction systems and technical equipment, fabric, aesthetic quality and use", as well as of its intangible values, such as "historic, social, scientific or spiritual associations, or creative genius" (ICO-MOS ISCAH20, 2011, p. 1).

However, some authors maintain that there has been a prevailing trend (particularly regarding the so-called iconic buildings) privileging the formal value of this architecture by restoring an original image and neglecting its material or intangible attributes and values (age, use, social), integrity, authenticity, and aura. Others defend the concept of 'progressive authenticity' (Jerome, 2009), referring to some material signs and alterations that can be preserved as part of the history of the building in time.

On this matter, Álvaro Siza maintains that "in conservation works, there is a mandatory requirement which is, in my opinion, absolute integrity. It is not necessary to change things unless, as I mentioned before, in special or exceptional cases" (Siza, 2011, p. 188), resisting the tendency of leaving the architect's 'signature' in his interventions (Siza, 2005, p. 21).

Sixty years after the construction of the Ocean Swimming Pool, Álvaro Siza carried out the conservation and extension of the bathing complex (2018-2021). According to Siza, one of the greatest challenges was the conservation of the exposed concrete given the numerous anomalies it presented, taking into account that any localized repairs (preferable to a complete replacement, in his opinion) would necessarily be visible. Thus, by assuming the impossibility of disguising 'patches' in the concrete - that is. "neither wanting nor being able to hide what the passage of time determines" (Siza. 2018) - Siza chose to assume some aging signs as 'scars of time' that testify to the material history of the building. In his words, this is also the "most brutalist" (Siza, 2019) attitude and, therefore, correspondingly coherent with the option of truth through the expression of raw materials advocated in the original project.

The recent intervention by Siza represents an interesting case of an architect intervening in his own work. By enhancing its significance while preserving the architectural integrity of the ensemble, Siza definitively finishes the work to the north and sustains its integration into the landscape requalification of the Leça da Palmeira seafront.

1.5 Authorship and acknowledgments

The Ocean Swimming Pool CMP was prepared by Teresa Cunha Ferreira with considerable research and editorial assistance from Hugo Mendonça. As senior consultants of this CMP, Rui Fernandes Póvoas, Paulo B. Lourenço, and Ana Tostões assisted in the process.

The author wishes to thank, first and foremost, Álvaro Siza for his invaluable support, as well as his office's staff, in particular Anabela Monteiro, Chiara Porcu and Rita Amaral, and the engineering team from GOP responsible for the conservation works (2018-2021), in particular Jorge Silva and Raquel Dias.

Raquel Dias. Acknowledgments are due to the Centre for Studies in Architecture and Urbanism (CEAU) of the Faculty of Architecture of the University of Porto, namely the Direction Board, the Administrative Services and the Communication Office. Also, acknowledgments must be made to the Municipal

Also, acknowledgments must be made to the Municipal Council of Matosinhos for the institutional collaboration, namely Fernando Rocha, Manuela Álvares, Maria José Mesquita, Pedro Machado, Manuela Baptista, Clarisse Castro, Isabel Flores, João Quintão, Pedro Rocha, Susana Gonçalves, and to Matosinhos Sport, namely João Regufe, João Galvão, Catarina Teixeira, Eduardo Silva, Nuno Silva, Paula Santos, Tiago Macedo, Manuel Jesus, and Maria da Conceição.

All sections of this CMP have been informed by a relevant amount of published and unpublished material, gently provided by Álvaro Siza, the Canadian Centre for Architecture, and the Municipal Archive of Matosinhos, among others.

Acknowledgements are due for the contributions of Ana Tarrafa Silva on cultural significance assessment; Paulo B. Lourenço, Nuno Mendes, and Javier Ortega on the inspection and diagnosis of the site's fabric; Xavier Romão on the identification of hazards, vulnerabilities and risk assessment; Teresa Portela Marques on landscape management; Patrícia Fernandes Rocha and Joaquim Teixeira on the detailed conservation and maintenance policies; Pedro Murilo de Freitas on policies implementation strategy, monitoring and impact assessment.

Thanks to Ana Resende for the design of this document and of the website in collaboration with Luís de Sousa Teixeira (https://oceanswimmingpool.cargo.site to be migrated to https://sizaoceanswimmingpool.arq.up.pt).

References

Ferreira, T. C. (2014) "Some considerations on the preservation of 20th-century architectural heritage" in Riso, V. (ed.) *Modern building reuse: documentation, maintenance, recovery and renewal.* Guimarães: EAUM, pp. 29-46. Available at: http://repositorium.sdum.uminho.pt/handle/1822/28957 (Accessed: 10 January 2023)

ICOMOS Australia (1999) The Burra Charter. The Australia ICOMOS Charter for Places of Cultural Significance. Burnwood: Australia ICOMOS. Available at: https://australia.icomos.org/wp-content/uploads/BURRA_CHARTER.pdf (Accessed: 10 January 2023)

ICOMOS ISCAH20 (2011) Approaches for the Conservation of Twentieth-Century Architectural Heritage (Madrid Document). Available at: http://orcp.hustoj.com/wp-content/ uploads/2016/04/madriddocumentenglish.pdf (Accessed: 10 January 2021)

Jerome, P. (2009) "Restoring Frank Lloyd Wright's Solomon R. Guggenheim's Museum" Available at: https://www.aicomos. com/wp-content/uploads/2009_UnlovedModern_Jerome_ Pamela_Frank-Lloyd_Paper.pdf (Accessed 9 February 2018)

Kerr, J. S. (2013) Conservation Plan, the 7th edition: A guide to the preparation of conservation plans for places of European cultural significance. Burnwood: Australia ICOMOS. Available at: https://openarchive.icomos.org/id/eprint/2146/1/ICO-MOS-Australia-The-Conservation-Plan-7th-Edition.pdf (Accessed: 10 January 2023)

Macdonald, S. (2013) "Modern Matters: Breaking the Barriers to Conserving Modern Heritage. Conservation Perspectives", *The Getty Conservation Newsletter*, 28, 1, Los Angeles: The Getty Conservation Institute

Mason, Randall. (2002) "Assessing Values in Conservation Planning: Methodological Issues and Choices" in de la Torre, M. (ed.) Assessing the Values of Cultural Heritage. Research Report. Los Angeles: The Getty Conservation Institute. Available at: https://www.getty.edu/conservation/publications_resources/pdf_publications/pdf/assessing.pdf (Accessed: 10 January 2023)

Siza, A. (2005) "Recuperação e Manutenção" in Costa, A. et al. (ed.) A intervenção no património. Práticas de conservação e reabilitação. Porto: FEUP

Siza, A. (2011) "Conferencia para el CAH20" in Intervention Approaches in the 20th Century Architectural Heritage. International Conference CAH20th, Madrid:ETSAM/ISC20C

Siza, A. (2018) "Entrevista por Teresa Cunha Ferreira", Construção Magazine, 83, January

Siza, A. (2019) "Entrevista por Magda Seifert e Pedro Baía" in Seifert, M. and Baía, P. (eds.) *Porto Brutalista*. Porto: Circo de Ideias

Tostões, A. (2013) "Património moderno: conservação e reutilização como um recurso", *Revista Património*, 1, pp. 44-53 1



2. UNDERSTANDING THE PLACE

2.1 Introduction

- 2.2 History of the place
- 2.3 International and national context
- 2.4 Project commission
- 2.5 Design and construction
- 2.6 Critical reception
- 2.7 Programme distribution
- 2.8 Stakeholders

18—55

2.1 Introduction

Chapter 2 summarizes the historical development of the Gathering and examining documentary and physical eviden-Ocean Swimming Pool, from its original design until the presce is the first stage of any Conservation Plan (Kerr, 2013, p. 4). ent day, framing it on the evolution of a particular territory Therefore, when preparing the Ocean Swimming Pool's CMP, and as a result of a specific international and national context. the most significant information regarding first-hand involve-This historical knowledge is essential for a full understanding ment with the place was collected from the archival holdings of the form and fabric of the place, its components, and the of the Canadian Centre for Architecture (CCA), where the bulk relationship it establishes with the setting. Its purpose is to of Álvaro Siza's archive is held, the personal archive of the arinform the CMP's assessment of cultural significance and the chitect and the Municipal Archive of Matosinhos. If the former development of conservation policies. allowed for a detailed understanding of the evolution of the design and its changes over time through plans and sketches. The chapter starts with a brief record of Leça da Palmeira's the latter provided information regarding program requirehistorical development until 1960 (2.2). It is followed by an ments, construction specifications, technical opinions, and analysis of the post-war architectural context, both on an insubmission dates.

ternational and national level (2.3). The fourth section (2.4) is centered on the project commission, detailing the urban redevelopment strategy of which the Ocean Swimming Pool was part, the programme definition, and the choice of location, besides providing brief biographical remarks on the most significant building actors.

The fifth section (2.5) presents a thorough chronology of the construction, both nationally and internationally, over eighty design process, describing the evolution of the proposals as publications on the subject, including books, chapters, artia result of changing requirements and new extensions. It also cles, and academic dissertations, were also considered for identifies Álvaro Siza's design principles which should inform this research. Oral evidence also played a crucial part in this the definition of conservation policies and any proposals for context, namely the invaluable testimony of Álvaro Siza and a future changes, together with the identification of the building series of interviews and surveys conducted with the commumaterials and techniques employed. Furthermore, section 2.6 nities and site managers. analyses the critical reception of the Ocean Swimming Pool The above-mentioned documentary and oral evidence colsince its construction, comprising national and international publications and exhibitions. The last two sections include a lected were combined with a detailed examination of the exisdescription of the program distribution (2.7) and the identifiting fabric to achieve a thorough understanding of the place. cation of the different stakeholders involved in the site's management (2.8).

Relevant graphic and written documentation was also collected from the FAUP Documentation Centre (CDUA-FAUP). Espólio Fotográfico Português, Serralves Foundation, and Casa da Arquitectura, amongst other private archives of architects, photographers, engineers, and conservators. Moreover, given the interest the Ocean Swimming Pool has sparked since its

2.2 History of the place

Leça da Palmeira is a parish of approximately 6 km² located at the Leça river's right bank, next to its mouth. Together with the parish of Matosinhos, they form the urban nucleus of the Matosinhos municipality, a city of 170 000 inhabitants in the vicinity of Porto (INE, 2021).

The earliest evidence of human settlement in this territory is the remains of a hillfort nearby the Leça estuary that dates back to the Iron Age. With the beginning of the Roman occupation, the populations gradually moved from the hilltops to the valley's fertile lands, taking advantage of the optimal conditions for the practice of agriculture. The natural configuration of the estuary, sheltered by numerous rocky outcrops (the Leixões), allowed for the establishment of maritime trade with the south of the peninsula and the Mediterranean as early as the 2nd century BC (Santos, 2017, p. 29).

Despite the construction of a fortification to protect the estuary mouth during the 17th century, Leça da Pameira remained a small maritime village devoted to agriculture and fisheries, with clusters of rural houses set along the river bank. It was only during the second half of the 19th century that some English families associated with the trade of port wine, and Porto's bourgeoisie started to visit the area with regularity, initially staying in rented houses and later building their own residences (Oliveira, 1999, p. 98). The main reason for this sudden interest had to do with the sea and river baths, a habit that saw an increase in popularity throughout European countries in the eighteen hundreds since it was thought to have therapeutic properties. This attractiveness led to the significant expansion of the village that would see its rural constructions give way to bourgeois weekend chalets and small hotels, along with the paving of roads and the creation of a public park (Santos, 2017, pp. 47-49).

Leça's very intimate relationship with the riverside, however, would see a drastic change in the late 19th century when alternatives to the Douro harbor began to be sought due to the difficulties in entering the river mouth that originated, along the years, numerous shipwrecks and significant losses to the city's commercial actors. Due to its proximity and favorable

natural setting, the Leça river estuary was chosen as an alternative harbor for vessels to wait in calmer waters when adverse conditions prevented the entrance into the Douro river mouth (Cleto, 1998, pp. 14-17). The design, by the engineer Afonso Joaquim Nogueira Soares, consisted of two jetties perpendicular to the coast, one to the north of the river mouth, in Leça da Palmeira, and one to the south, in Matosinhos. These were laid out in an arch configuration, taking advantage of the preexisting set of rocks as their foundations, the aforementioned Leixões, the name for which the port would eventually be known.

The construction of the two jetties and the increasing movement of ships inside the harbor originated a progressive decrease in the water quality of what was formerly the bathing beach by the river mouth, which led to its displacement to the north, to be outside the port (Oliveira, 1999, pp. 102-103). This change would be of paramount importance for Leça's future development and expansion along the seafront. Since the nearby Douro River was getting silted up and the increase in the steamboats' size prevented them from traveling in it, Leixões would progressively start assuming the leading role as the main commercial port from then on. The future extensions to the port would take place inward, towards the land, through the excavation of docks along the Leça riverbank (Cleto, 1998, p. 25). The opening of the first dock in 1940 put an end to the close relationship between both parishes (of Leça and Matosinhos) and the river's natural course, being, from that point onwards, separated by the new industrial infrastructure.

This significant change to the south was accompanied by a renewed interest in the unexplored beach extension to the north after the construction of the Boa Nova lighthouse in 1927 (Oliveira, 1999, p. 109). Thus, while the excavation of the artificial port was taking place, the earth removed from the river bank was being used for the construction of the coastal avenue facing the Atlantic. This would represent the first step in the touristic and leisure-oriented redevelopment of Leça da Palmeira, in which the Ocean Swimming Pool designed by Álvaro Siza (1933-) would play a key part.







2.3



24

- 2.1 Leça da Palmeira beach, n/d.
- 2.2 Leixões port, 1962.
- 2.3 Leça da Palmeira coastline before the con-
- struction of the avenue, n/d.
- 2.4 Leça da Palmeira coastal avenue, 1960.









2.3 International and national context

In the aftermath of World War II, the positivist faith of the Modern Movement was being called into question, and a revision process was on its way. At the forefront of this process was the Italian architect and historian Bruno Zevi (1918-2000), who published in 1945 Verso una architettura organica (Towards an Organic Architecture), in which he re-evaluated Frank Lloyd Wright's work that he considered to have been neglected by Siegfried Giedion (1888-1968) in Space, Time and Architecture (1941) and sought for an organic overcoming of the rationalist standstill. The social emerges as the founding dimension of the 'organic project', replacing a pre-formulated objectual dimension attributed to rationalism. Alvar Aalto (1898-1976) was seen, at the time, as a vivid example of this path (Figueira, 2014, pp. 22-23).

During the mid-1950s, new contributions to overcome the crisis emerge. Ernesto Nathan Rogers (1909-1969), at the head of Casabella-Continuità magazine (1954-1965), wishes to reaffirm the continuity of history without denying the original actions of the Modern Movement, framing it in the course of history and suggesting that the future of the practice should be built upon its lessons in order to surpass it (Rogers, 1957). Ultimately his goal was that the avant-garde logic gave way to a process of evolution through continuity, in which the focus was not on stylistic affiliation but on method.

This perspective was met with the fiercest opposition by the English architecture critic Reyner Banham (1922-1988), who thought that the Modern Movement had failed for not pursuing the functionalist ideals to the utmost extent (Banham, 1955). Appropriating Le Corbusier's expression "L'architecture, c'est avec des matières bruts, établir des rapports émouvants" (Le Corbusier, 1923, p. 121), he launched, in 1955, the 'new brutalism' that was based on the clear exhibition of structure, the valuation of materials 'as found' and memorability as image. The subsequent development of the Brutalist style found much of its vocabulary in the late work of Le Corbusier. His revitalization of the Mediterranean vernacular proved seminal to the formation of the Brutalist sensibility, deeply rooted in popular culture and the anthropological aestheticism of Jean Dubuffet's art brut (Figueira, 2014, p. 36).

2.5 Sindicato Nacional dos Arquitectos (1961) Arquitectura Popular em Portugal. Lisboa: Sindicato Nacional dos Arquitectos.

2.6 Municipal Market of Vila da Feira (1954-1959) designed by Fernando Távora.

2.7 Calouste Gulbenkian Foundation Headquarters (1959-1969) designed by Alberto Pessoa, Pedro Cid and Ruy Jervis d'Athouguia

2.7

Portugal was not immune or unaware of the debates that were taking place, even though between 1933 and 1974, the country was under the dictatorial rule of António de Oliveira Salazar (1889-1970), which sought to impose a romantic vision of vernacular values on Portuguese architecture, combined with an imperial monumentality influenced by Nazi Germany and Fascist Italy (Fernandes and Pereira, 2019). The architect Fernando Távora (1923-2005), considered to be the master of the School of Porto, and who had Álvaro Siza as his direct disciple and collaborator, actively participated in the last four CIAM (Congrès Internationaux d'Architecture Moderne) that took place in the 1950s.

Already in 1945, Távora had published a text entitled 'The Problem of the Portuguese House', in which he criticized Salazar's official architectural doctrine and defended the idea that architecture built in Portugal should simultaneously be Portuguese and Modern (Távora, 1945). Many of his colleagues defended an uncompromising internationalism three years later at the 1948 Congress of Portuguese Architects (Sindicato Nacional dos Arquitectos, 1948). Nevertheless, it seemed too late to implement modern internationalist architecture by pre-World War II standards.

As a compromise between modern rationalism and the proximity to local contexts, the architect Francisco Keil do Amaral (1910-1975) claimed that the study of traditional constructions and of the context that shaped them would help in making contemporary design decisions (Ferreira, Barbosa and Fernandes, 2021). His appeal was answered, in 1955, with the beginning of the fieldwork for the *Survey on Regional Architecture in Portugal*, a State-funded program promoted by the Union of Portuguese Architects, which would be "of the grea*test cultural and political significance, working as a lever for the rescue of the modern tradition made either with the incorporation of local preexistences as well as the interpretation of the avant-gardes*" (Tostões, 2022, p. 29).

The discussions that were taking place within the context of the modern revision, both on an international and national level, with the reflection dictated by the *Survey*, were at the origin of the synthesis between an organicist functionalism and the vernacular (Tostões, 2016, p. 45) that Fernando Távora achieved in works such as the Municipal Market of Vila da Feira (1954-59), the Ofir House (1957-58), the Tennis Pavilion of Quinta da Conceição (1956-59) and the Cedro Elementary School (1957-61).

Between 1955 and 1961, a period that saw the launch of the architectural competition for the design of the Calouste Gulbenkian Foundation Headquarters (1959) and the publication of the Survey's results under the title Arquitectura Popular em Portugal (1961), a new Portuguese Architecture emerged, "made with programmatic, formal and spatial invention, where the local vernacular is synthesized with disparate international references (...) in which the Portuguese circumstance of technological backwardness constitutes a potential to be explored with the use of a competent artisanal workforce" (Tostões, 2022, p. 29).

2.4 Project commission

2.4.1 Coastal Development Plan

The idea to foster the economic development of Leça da Palmeira through tourism had in Fernando Pinto de Oliveira (1911-1975) one of its main promoters. First, as a municipal councilor in charge of tourism (1955-1958) and afterward as mayor (1958-1970), he was a relentless worker in pursuing his goal of modernizing Leça and transforming it into a relevant leisure destination.

In very close articulation with Henrique Schreck from the port administration and the architect Fernando Távora, he prevented the installation of industrial warehouses in the proximity of the docks, preserving the surrounding green areas and bourgeois estates. One of those estates, the Quinta da Conceição, was acquired by the Municipal Council and transformed into a public park by Távora, whose design included a tennis court and a swimming pool (under the responsibility of Álvaro Siza, who worked, at the time, in Távora's office), a museum, a library, an exterior amphitheater, while preserving numerous architectural artifacts from the convent that occupied the plot until the 19th century (Pinto, 2011, p. 145).

The seafront of Leça was at the core of Pinto de Oliveira's transforming strategy, for which he envisioned not only the extension of the coastal avenue further north, as numerous leisure infrastructures. These included the renowned Boa Nova Tea House and Restaurant (1958-1963), designed by Álvaro Siza, as well as a campsite, a hippodrome, and some restaurants, besides the Ocean Swimming Pool (Santos, 2017, p. 112). In an attempt to protect this vision, the Municipal Council commissioned, in 1966, additional urban plans for this area to the architect Arménio Losa (1908-1988). One of the main goals of these plans was to prevent the construction of any significant industrial building along the seafront. These attempts, however, did not succeed since the Petrogal's oil refinery was constructed in 1970 by the Boa Nova lighthouse, in an area where Pinto de Oliveira envisioned the construction of a golf course.

In 1954, the Municipal Tourism Commission's president, Edmundo Ferreira, identified the need, for the first time, to build a swimming pool in Leça da Palmeira. This intention would be formulated again in 1957, as the action was deemed necessary to overcome the difficulties presented by the sea condition during the bathing season (Pinto, 2011, pp. 152-154). The engineer Henrique Schreck and the port's commander Basílio de Sousa Pinto are entrusted with studying the coast in detail to identify the most suitable and economical location for the pool. Even if everything already seemed to point to the solution that would eventually be chosen, some ambiguity regarding the location of the pool remained, as testifies to the acquisition by the Municipal Council of a plot by the coastal avenue for this purpose.

In 1958, the Tourism Commission presented a proposal to build a saltwater swimming pool with a seafood restaurant to the north of Leça's beach. This area, known as *meia laranja*, consisted of a coastal avenue platform extending over the beach where a rocky outcrop already presented a natural cove. The Commission's view on this matter was that the construction should not rise above the avenue level to safeguard the surrounding landscape, admitting the possibility of building directly over the rocks (Pinto, 2011, p. 154). It must be said that this favorable location was already being explored for lobster farming and that to the south there was a previous bathing pool limited by a low semicircular wall where people could bathe when the sea conditions were rougher.

Even if there is a decision of the Municipal Council to promote a public competition for the pool's preliminary design, the fact is that it never took place. Instead, in November 1959, the Municipal Council promoted a direct consult to the firm Ribeiro da Silva, Lda., which was a public works company specialized in maritime works, to assess the feasibility of the project and a first cost estimate (Ferrão, 1960, p. 1). At this stage, the project consisted solely of an artificial tank that would fill and empty according to the movement of the tides. For economic reasons, the tank should take advantage of the preexisting rocky outcrops as its limits and adapt to the existing bedrock with minimum regularization. Within this program, the aforementioned company sent a description of the required works and the respective estimate to the Municipal Council, that, in its turn, requested the presentation of the definitive design and the conditions under which the contractor could undertake the execution of the work with the intent of having it finished before the 1960 bathing season. Nonetheless, the sensitive nature of the context in which the intervention would take place made it clear that a study of its urban arrangement was necessary, leading to the indication of the architect Álvaro Siza to integrate the design team (Ferrão, 1960, pp. 1-3).



2.10

2.11







2.8

2.8 Boa Nova Tea House and Restaurant (1958-1963) designed by Álvaro Siza.

2.9 Quinta da Conceição Swimming Pool (1958-1965) designed by Álvaro Siza.

2.10 Bathing pool at Leça beach, 1947.

2.11 Leça da Palmeira coastal avenue, 1960.

2.12 Leça da Palmeira coastal development plan

(1966) conceived by Álvaro Siza.

2.13 Leça da Palmeira coastline during the oil refinery's construction, n/d.





2.4.2 Building actors

Fernando Pinto de Oliveira (1911-1975)

Fernando Pinto de Oliveira attended the Superior Institute of Agronomy of the Technical University of Lisbon, where in 1938 he graduated as an agricultural engineer. In 1955, he joined the Matosinhos Municipal Council as a councilor in charge of tourism. He presided, by inherence, the Municipal Tourism Commission, where he carried out a relevant action, creating the Tourism Office, where art exhibitions and other shows were hosted. He also held the position of vice-president, which meant that after the death of Fernando da Hora Aroso (the former mayor), he was appointed for the position of President of the Municipal Council (1958-1970). During his mandate, he pursued the implementation of his vision for the economic development of the municipality through tourism, promoting the acquisition of former bourgeois estates that were transformed into public parks, the extension of the coastal avenue further north, and the construction of multiple infrastructures along the coast as the Boa Nova Tea House and Restaurant, the Angeiras campsite or the Ocean Swimming Pool (Pinto, 2011).

Bernardo Ferrão (1913-1982)

Bernardo Ferrão graduated as a civil engineer from the Faculty of Engineering of Porto in 1938, starting his career as an employee of the Directorate-General for Hydraulic Services. In 1948 he started his own practice, specializing in major public works, among which the riverside road along the Douro, its retaining walls, and the Ribeira tunnel (the first road tunnel built in Portugal) are worthy of mention. He pioneered the use of bituminous pavements and introduced numerous technologically innovative solutions in his bridge designs, such as the use of heavy prefabrication and pre-cast concrete. On the other hand, as a prolific writer and editor, he collected information relating to the technical state of the art (retaining walls and masonry coatings (Ferrão, 1945), construction legislation and regulations (Ferrão 1947; 1962a), public works contractors (Ferrão, 1962b) and the accounting of public works (Ferrão, 1963), among other subjects.

Thus, due to his great expertise, Bernardo Ferrão played an important role, working both as an engineer and a contractor in the construction of the Ocean Swimming Pool, which was one of the first in the country to make use of exposed concrete (Ferreira, Barbosa and Fernandes, 2021).

Álvaro Siza (1933-)

Born in Matosinhos in 1933, Álvaro Siza studied architecture After the 1974 Portuguese Revolution, Siza started working at the Fine Arts School of Porto (Escola Superior de Belas Aron a series of social housing projects for the cities of Porto, tes do Porto) from 1949 through 1955. His early career was Évora, Berlin, The Hague, and Venice, among others. These closely linked to that of his teacher and colleague Fernancommissions brought him significant international recognido Távora, with whom he worked between 1955 and 1958. tion, and from the late 1970s onwards, he increasingly wor-Through this association, he had the opportunity to design ked outside Portugal. The ensemble of his work, comprising the Boa Nova Tea House and Restaurant (1958-1963) and the more than 500 projects and built works in 16 countries and 4 Quinta da Conceição Swimming Pool (1958-1965), both in Macontinents, earned him many awards, including the Mies van tosinhos. In 1966 he started teaching at the Fine Arts School der Rohe Award for European Architecture (1988), the Pritof Porto and ever since has been a visiting professor at numezker Architecture Prize (1992), the Japan Art Association's rous universities, namely at Harvard University, University of Praemium Imperiale prize for architecture (1998), the Royal Pennsylvania, Los Andes University of Bogota, and the École Gold Medal for Architecture of the Royal Institute of British Polytechnique de Lausanne, besides being a guest lecturer in Architects (2008) and the Golden Lion for lifetime achievemany others (Castanheira, 2009, p. 298). ment at the Venice Architecture Biennale (2012).



2.15

2.14 Fernando Pinto de Oliveira at the opening of the Municipal Park of Quinta da Conceição, 1960.

2.15 Álvaro Siza presenting the design of Boa Nova Tea House and Restaurant, 1960.



2.5 Design and construction

2.5.1 Design chronology

1960

Even though the first design presented in 1960 by the engineer Bernardo Ferrão envisaged the construction of a swimming pool in front of the meia laranja structure (measuring 20 x 33.33 m), the sanitary need for water treatment was soon identified, preventing the use of the tides to supply the pool. The progressive increase in the programme's complexity and the understanding that it would be desirable to study the urban arrangement of the place led to the indication of the architect Álvaro Siza to collaborate on the commission. As a result, new design options emerged: the use of exposed concrete instead of stone masonry, the tops of the swimming pool support walls measuring just 1 m, ladders, and removable railing, the need for a children's pool in a place to be defined, among others (Ferrão, 1960, pp. 2-3). If the first drawings (plans and sections) only show the adults' pool and a water treatment facility, sketches from 1961 already depict the children's pool and an architectural solution that is very close to the definitive one.







2.16 Beginning of the pool's construction, 1961.

2.17 Sketches of the changing room's building, 1961.2.18 Plan of the swimming pool as envisaged by Bernardo Ferrão, 1960.



1962

As part of a plan to enhance the landscape of the Leça da Palmeira seafront, Álvaro Siza presents, in 1962, a first preliminary design with two pools (for children and adults, taking advantage of the terrain's topography), and a support building (equipped with changing rooms, bathrooms and a water treatment facility), running parallel to the retaining wall of the avenue. The meia larania structure would then be demolished to make way for the new building and a solarium area (Siza, 1962, p. 1). Articulated perpendicularly with the volume of the changing rooms, to the north, it was foreseen the existence of a restaurant with a fan distribution and sloping roofs, which would not be built. Several drawings attest to the formal research of the changing rooms and restaurant volumes. Hygienist concerns are already apparent at this stage, namely the separation of shoed and barefoot circuits, the foot washing basins, and the suspension of wooden structures to allow for the washing of the floors. Judging by the dates of detail drawings, the construction is thought to have been carried out between 1963 and 1964, despite the project's entry record in the Municipal Council dating of April 1965.

2.19 Sketches of the overall composition with the (unbuilt) restaurant volume, n/d.2.20 Preliminary plan, 1962.



2.20





The set of drawings from 1965, signed by Siza and Ferrão, systematizes what was initially built and which existed at the time of the swimming pool's opening in May of that year. From the 1962 draft, the configuration of the children's pool and the changing rooms, bathrooms, and water treatment building, accessed by a ramp from the avenue, is maintained. The solarium is extended and equipped with a set of concrete platforms and stairs that ensure the connection between the different levels of these permanence areas. The bar's design was still being studied, with only its intended location indicated on the plan. The design report, dated February 1965, details the project's evolution, the dimensioning of spaces, the construction and materials, and the operation of equipment and technical installations (Siza and Ferrão, 1965). The adopted construction system is characterized by lightly reinforced concrete walls supporting a Baltic pine roof structure clad with copper. This is the richest phase in terms of designed and photographic documentation, setting out the materialized solutions, together with photographs illustrating the first moments of the pool's operation.

2.21 Ocean Swimming Pool's surrounding context, 1965 (previous spread).
2.22 Changing rooms' building and walkway over the children's swimming pool, n/d.
2.23 Men's changing room, n/d.
2.24 Plan, 1965.



2.22

It was also in 1965 that Álvaro Siza presented the preliminary design of a restaurant located to the north of the complex, the need for which is based on the first months of operation experience of the swimming pool. This building is set on a rocky massif, forming a 45° angle with the retaining wall of the avenue to accentuate the boundary of the enclosure and shelter it from the prevailing winds (Siza, 1965, p. 1).



2.26 Sketches of the restaurant building, n/d.

2.27 Restaurant's first and second floor plans,

1965.



2.26



2.24





The 1966 design envisages the enlargement of the enclosure at its northern and southern ends to solve the embedding of the buildings in the retaining wall of the avenue (namely the encounter between the exposed concrete and the granite masonry), as well as a programmatic and circulation clarification (Siza and Ferrão, 1966, p. 1). The previous lack of definition regarding the design of the bar and the bathrooms for shoed users led to its functioning in provisional structures. Having demonstrated the correctness of the bar setting, its definitive construction is planned on the same location, now equipped with a terrace protected from the prevailing winds by a wall oriented at a 45° angle in relation to the changing rooms building. This phase would also entail the construction of bathrooms for shoed users (to the north) and storage rooms (to the south) under the retaining wall of the avenue. As a result of several setbacks, namely the need to overcome the successive objections raised by the Water Sanitary Board (Junta Sanitária de Águas), the start of the construction work would only take place at the beginning of the following decade (1970).



1973

The fact that the previously planned interventions had not yet been completed was at the origin of the project presented in 1973, which results from a review of the 1966 proposal in accordance with the opinions formulated by the competent authorities, as well as specific improvements resulting from the operating experience of the swimming pool (Siza, 1973, p. 1). Among them are the definitive installation of the shoed users' toilets (to the north) and storage and personnel areas (to the south) under the retaining wall of the avenue, as well as the definition of a wider service area and pantry associated with the bar. The southern end of the complex is also formalized through an amphitheater-shaped staircase that makes the transition between levels. The design also envisaged completing the complex to the north by extending the platform to the 2.30 place where the restaurant would be located, a work that was never carried out.

2.30 South platform's amphitheatre, n/d. 2.31 Plan, 1973.



2.28 Sketches of the bar's terrace, n/d.



2.28

2.29

37



In 1993, the Municipal Council of Matosinhos awarded the restaurant's design and the technical supervision of the Ocean Swimming Pool's conservation works to Álvaro Siza. These works, carried out in partnership with the engineer João Sobreira, included, among other interventions, the complete replacement of the copper cladding, the repair of the swimming pool's concrete walls, and the cleaning and stripping of the wooden surfaces.

There is detailed documentation regarding the restaurant's architectural design (plans, sections, elevations, and details) as well as the engineering projects. The building was to be accessed by a ramp from the avenue and constructed with materials identical to those of the remaining buildings: expo- 2.32 sed concrete (floors, walls, and ceilings) and wood, besides an exposed concrete roof slab with a reflecting pool, for aesthetic and cooling purposes (Siza, 1995). The sketches of the building's interior illustrate the spatial fluidity and the frank relationship with the landscape through a wide glazing on the south elevation and an almost entirely blind elevation to the north, to protect the set from the prevailing winds. For unknown reasons, the restaurant was never built, even though the executive drawings were delivered, approved, and awarded by the Matosinhos Municipal Council in 1995.







2.33





2.32 North volume concrete repair, 1995.

2.33 Roof after copper removal, 1995.

2.34 Copper sheet replacement, 1995.

2.35 Restaurant longitudinal and cross sections, 1995.

2.36 Ocean Swimming Pool's surrounding context, 2021 (following spread).





2.37 Ocean Swimming Pool construction phases.











TO A DIST OF MIL



















2.5.2 **Design principles**

The design principles of the Ocean Swimming Pool aim to clarify Álvaro Siza's original design intent, being a permanent reference for the conservation of the building and an instrument to manage proposals for change. It should also be considered when establishing planning controls for the surrounding landscape, ensuring the preservation of visual relationships and future long-term improvements to the setting. As the Ocean Swimming Pool evolves to meet future needs, it is essential to strike a delicate balance between the building's functional effectiveness and the preservation of its architectural integrity for the benefit of future generations.

To remain faithful and respectful of Siza's thoughts and design approach, these design principles are based on his own words, namely on a selection of 'aphorisms' collected from his texts, design reports, and interviews dedicated to the Ocean Swimming Pool (fig. 2.38). The definition of 8 design principles is inspired by one of his very few texts on his work method called "Eight Points" (Siza, 1983). This work was the object of a dedicated book entitled Design Principles. Álvaro Siza: Ocean Swimming Pool (1960-2021) and published in 2023.

DOCUMENT TYPE	DATE	DOCUMENT
	1962	Siza, A. (1962) Leça da Palmeira Ocean Swimming Pool: Design Report
	1965	Siza, A and Ferrão, B. (1965) Leça da Palmeira Ocean Swimming Pool - 2nd Phase - Project: Design Report
	1966	Siza, A. and Ferrão, B. (1966) Leça da Palmeira Ocean Swimming Pool - 3rd Phase - Project: Enlar- gement of the enclosure, including storage rooms, toilets, bar, terrace, platform and retaining walls to the north and south: Design Report
Design reports1967Siza, A. and Ferrão, B. (1967) Leça project process, including built pha	Siza, A. and Ferrão, B. (1967) Leça da Palmeira Ocean Swimming Pool: Design Report: Complete project process, including built phases and phases to be built	
	1970	Siza, A. (1970) Construction Specifications Report
	1973	Siza, A. (1973) Design Report: Leça da Palmeira Ocean Swimming Pool: Intercalary draft of the 3rd and 4th phases
	1995	Siza, A. (1995) "Ocean Swimming Pool Restaurant: Leça da Palmeira: 1993: Design Report" in Casta- nheira, C. and Porcu, C. (eds.) <i>As cidades de Álvaro Siza</i> . Lisboa: Figueirinhas, 2001
	2018	Siza, A. (2018) Construction Specifications Report for the conservation and expansion works
	1980	Siza, A. (1980) "Piscina de Leça da Palmeira" in Morais, C. C. (ed.) 01 textos. Porto: Civilização, 2009
Texts and	1998	Siza, A. (1998) Imaginar a evidência. Lisboa: Edições 70
essays	2022	Siza, A. (2022) "The difficulty of restoration" in Ferreira, T. C. and Urbano, L. (eds.) No place is deser- ted. Álvaro Siza: Ocean Swimming Pool (1960-2021). Porto: FAUP/Afrontamento
	2016	Siza, A. (2016) FRAMPTON, K. Álvaro Siza Vieira in conversation with Kenneth Frampton: a pool in the sea. Chicago: IITAC
	2018	Siza, A. (2018) Interview by Luís Urbano in Urbano, L. (ed.) Circa 1963. Porto: AMDJAC
	2018	Siza, A. (2018) Interview by Teresa Cunha Ferreira in Construção Magazine, 83, January 13, 2018
Interviews and	2019	 Siza, A. (2022) "The difficulty of restoration" in Ferreira, T. C. and Urbano, L. (eds.) No place is deserted. Álvaro Siza: Ocean Swimming Pool (1960-2021). Porto: FAUP/Afrontamento Siza, A. (2016) FRAMPTON, K. Álvaro Siza Vieira in conversation with Kenneth Frampton: a pool in the sea. Chicago: IITAC Siza, A. (2018) Interview by Luís Urbano in Urbano, L. (ed.) Circa 1963. Porto: AMDJAC Siza, A. (2018) Interview by Teresa Cunha Ferreira in Construção Magazine, 83, January 13, 2018 Siza, A. (2019) Interview by Magda Seifert and Pedro Baía, in Seifert, M. and Baía, P. (eds.) Porto Brutalista. Porto: Circo de Ideias
conversations	2020	Siza, A. (2020) Interview by Teresa Cunha Ferreira, in Álvaro Siza's office, July 24, 2020
	2021	Siza, A. (2021) Interview by Teresa Cunha Ferreira, in the construction site, July 9, 2021
	2021	Siza, A. (2021) Intervention at the "Sharing Memories: Ocean Swimming Pool" webinar, September 9, 2021
	2022	Siza, A. (2022) Conference at the Symposium "Conserving Concrete", FAUP, July 1, 2022

2.39 Documents informing the identification of

Álvaro Siza's design principles, 2022.

2.40 Sketch of the overall composition, 1973.



2.40

1. Integration into the landscape

"In these complementary works, the principles initially adop-"In opting for the cabin system for changing clothes, with a ted regarding the integration of the building into the landscentral storage space and a separation between shoed and cape are maintained; integral conservation of the conditions barefoot people, 24 cabins were found to be necessary, asof the site, where possible; and the superimposition of built suming that the number of hangers in the deposit should be areas, where necessary." (Siza, 1966, p. 1) close to 3/5 of the number of square meters of the pool, that the daily use of each cabin is 40 people, and that each cabin is used twice a day (Prof. Ernest Neufert, 'Architects' data')." 2. Optimize the conditions created by nature (Siza, 1962, p. 1)

"Conversely, the idea of my project was to optimize the conditions created by nature, which itself had already begun to design its own pool. I thought it necessary to take advantage of the same rocks and restrict the use of walls to the absolute minimum to complete the containment of water. Thus, a far closer connection was established between the natural and built environment." (Siza, 1998, p. 25)

3. Outline a geometry on that organic image

"The aim was to outline a geometry on that organic image: to discover what was available and ready to receive geometricity. Architecture is geometrizing." (Siza, 1998, p. 25)

4. When executing the design, there was no intention of originality

"We would like to emphasize that, when executing the design, there was no intention of originality. The circumstance of originality mentioned in the report of the Water Sanitary Board naturally reflects the circumstance of a certain location and the integration in certain previously defined principles for the development of the area. It was about making up for inconveniences, in an area of beaches that was in many ways magnificent." (Siza, 1967, p. 9)

2.39

5. Separation between shoed and barefoot people

6. Zigzag walkways, producing a contradictory sense of depth

"At the same time, resolving the problem of access was essential. There was little depth as the road was very close to the coast. Moreover, there was a plastered wall over a kilometre and a half in length, which clearly separated the coast road level from that of the beach. (...) The solution was to design zigzag walkways, producing a contradictory sense of depth which was crucial in defining the access point to the enclosure." (Siza, 1998, p. 27)

7. Raw use of materials

"One of the characteristics of brutalism is the raw use of materials. Seeing the material for what it is." (Siza, 2019, p. 21)

8. One never completely restores

"One never completely restores (...) the worst that can happen is establishing a contrast with an ambition of impossible perfection. And then, always taking into account the factor of time, especially in a place like this, because time will take care of the fusion between what is old and what is new, in this case." (Siza, 2021)

2.5.3 **Building materials and techniques**

The Ocean Swimming Pool was built with very few materials and techniques: copper cladding, reinforced concrete, stone and wooden structures, and joinery. The wooden elements were assembled with brass screws and coated with boiled linseed oil to create a washable and waterproof surface. Regarding concrete and stone, Ferrão had performed previous research and practical works specifically focused on retaining walls (Ferrão, 1945). The buildings are anchored at the lower level of the seaside avenue. In this way, all the east side walls are retaining walls composed of two layers: an interior in cyclopean concrete, waterproofed with water-repellent plaster, and an exterior in exposed concrete with wooden plank formwork. A drainage curtain was made of dry stone on the back of these walls, and a perforated concrete drain was installed at the bottom (Mota, 1972, p. 28).

The exposed concrete walls required a careful execution of the formwork to define the horizontal lines. The formwork was made of pinewood, which could later be reused due to its thickness (4 cm) and the application of oil. These walls were lightly reinforced, with a 5 mm-thick mesh consisting of a 15 × 15 cm grid. 'MEYCO' rubbers were applied to the expansion joints instead of copper because the former material offered better resistance to the vibrator during concreting. The slabs were also separated from the walls to improve structural behavior (Mota, 1972, pp. 29-30).

The roof slabs were built without any interruption (to avoid joints), and the concrete was mechanically vibrated using a Wacker machine. The slabs were waterproofed with prefabricated plastic-asphalt membranes consisting of a polyethylene film covered on both sides with layers of special catalytic asphalt (Mota, 197, pp. 31-36).

The pavements of the north, south, and west platforms and the bar terrace were executed in troweled plaster on a foundation of cyclopean concrete. The floor of the access ramp, changing rooms, south bathrooms, and bar were made of 4 cm thick white concrete slabs, reinforced with steel mesh, and laid on a water-repellent screed foundation (Mota, 1972, pp. 37-38).

When exposed, the water supply network was made of copper and galvanized iron when embedded. All the faucets were in copper-plated brass, while the showers were in copper tubes.

For the construction works that took place until 1965, the contractor was a small local company, Ribeiro da Silva, Lda., owned by the engineer Bernardo Ferrão, who designed all the building's structures and infrastructures, while the works from that date onwards (1965-73) were conducted by the company Enobra. The construction staff consisted of one civil engineer (the contract director), one builder (serving as the liaison between the contract director and the site foreman), one foreman, eight stonemasons, five carpenters, two builders, and ten laborers. The building site included several areas for manufacturing and assembling materials (steel rebar, formwork, and masonry, among others). The steel assembly and cutting area was equipped with a folding table and manual cutting scissors. The amount of steel used between 1971 and 1973 (7000 kg) did not require the use of more efficient electrical equipment. Similarly, the formwork area was simple, with only one circular saw. Moreover, the site had two concrete mixers used to produce a total volume of 800 m³ of concrete (Ferreira, Barbosa and Fernandes, 2021).







2.43



2.44



- 2.41 Detailing of the retaining walls, 1966.
- 2.42 Construction site, 1971.
- 2.43 Retaining walls (under construction), 1971.
- 2.44 Water treatment room's roof slab, 1965.
- 2.45 Roof slab (under construction), 1971.







2.46



2.50







2.54

2.51

2.46 Almeida, P. V. (1967a) "Un análisis de la obra de Siza Vieira", Hogar y Arquitectura, 68. 2.47 Almeida, P. V. (1967b) "Uma análise da obra de Siza Vieira" and "Três obras de Álvaro Siza Vieira: Cooperativa de Lordelo. Casa unifamiliar em Maia. Piscina de Leça", Arquitectura: Revista de Arte e Construção, 96. 2.48 Bohigas, O. (1976) "Álvaro Siza Vieira". Bis. 12.

2.49 Gregotti, V. and Bohigas, O. (1976) "La passion d'Alvaro Siza", L'Architecture d'Aujourd'hui: Portugal, 185.

2.50 Gregotti, V. (ed.) (1979) Padiglione d'Arte Contemporanea di Milano: ALVARO SIZA Architetto 1954-1979. Milano: Idea Books.

2.51 Salgado, J. (1985) Álvaro Siza em Matosinbos. Matosinhos: CMM.

2.52 Siza, A. (1986) Álvaro Siza: Poetic Profes-

sion. Milano/New York: Electa/Rizzoli.



ARQVITECTVR12S EN LAS MARGENES

JOSEP MARIA JUJOL

ALVARO SIZA VIEIRA

IDEOLOGIA

Y LENGUAJE EN LAS ARQVITECTVR12S

DEL PODER

LA UNIVERSIDAD LABORAL DE GIJON

O EL PODER DE LAS

ARQVITECTVR12S

ARQVITECTVR12S

2.48



PORTUGAL

2.56

2.53 Moura, E. S. (1986) "La Piscina de Leça, 25 años después", Arquitectura: Revista del COAM, 261. 2.54 Ganshirt, C. (2004) 1959-73 Swimming Pool on the Beach at Leça da Palmeira: Álvaro Siza. Lisboa: Blau. 2.55 Toussaint, M. and Melo, M. (coord.) (2016) Piscina na praia de Leça: a pool on the heach, Lisboa: A+A Books. 2.56 Frampton, K. (2016) Álvaro Siza Vieira in conversation with Kenneth Frampton: a pool in the sea. Chicago: IITAC.



The Ocean Swimming Pool has been the subject of numerous essays and academic works, photographic reports, and even documentary films, becoming a place of pilgrimage for architects and scholars from all over the world, conveying the influence of Álvaro Siza as a key figure of 20th-century modernism. Indeed, the bathing complex was the object of over eighty publications in multiple languages (Portuguese, English, French, Spanish, German, Japanese, among others),

An important stage in the international recognition of the including books, chapters, journal articles, and academic Ocean Swimming Pool also derives from the numerous Exhidissertations. bitions in which this work was systematically highlighted, na-This interest started even before construction ended, with mely in Álvaro Siza at the Centre Georges Pompidou (Costa the comprehensive article published by the Portuguese arand Siza, 1990), Álvaro Siza: Obras y Proyectos at the Galician chitect and critic Pedro Vieira de Almeida in 1967, firstly in Centre of Contemporary Art and other itinerancies (Llano the Spanish journal Hogar v Arguitectura (Almeida, 1967a) and Castanheira, 1995), Arquitectura do Século XX: Portugal and, only two months afterward, in the Portuguese Arguitecat the Deutsches Architektur-Museum (Becker, Tostões and tura. Revista de Arte e Construção (Almeida, 1967b). From a Wang, 1997), Alvaro Siza Architetto at the Basilica Palladiaformal point of view, the author perceived the project as the na (Frampton, 1999), Les universalistes. 50 ans d'architectubeginning of a new stage in Álvaro Siza's work, in which an re portugaise at the Cité de l'Architecture & du Patrimoine economy of expression definitely overcomes the references (Grande, 2016) and, more recently, Álvaro Siza; (In) Discipline to the Survey on Regional Architecture in Portugal and the in the Serralves Museum (Grande and Muro, 2018), among others. The inclusion of the Ocean Swimming Pool in a vast trivialization of the vernacular. In addition, Vieira de Almeida considers this to be the first time in Portugal that an archiset of monographs on Álvaro Siza should also be mentioned, tect is able to critically face and control the spaces along a being these intensified after he was awarded the Pritzker Priroute, revisiting the rationalist theme of the 'promenade arze in 1992, with the broad proliferation of publications on his chitecturale'. work in the following decades and until this day (Testa, 1984; Gregotti, 1989; Fleck, 1992; Rodrigues, 1992; Santos, 1993; Ce-Less than a decade later, the Portuguese Revolution of 1974 cilia and Levene, 1994; Trigueiros, 1997; Jodidio, 1999; Castaand its consequences in the domain of architecture led to nheira and Porcu. 2001).

the publication of a dedicated issue by the influential journal L'Architecture d'Auiourd'hui (Gregotti and Bohigas, 1976) Numerous essays by renowned authors would also require with essays by Vittorio Gregotti and Oriol Bohigas, including referencing, such as William Curtis, Rafael Moneo, and Mathe Ocean Swimming Pool (being this edition adapted from nuel Aires Mateus (Curtis, 1994; Moneo, 2004; Mateus, 2009), an earlier publication in the Spanish magazine Bis). Despite deepening knowledge and highlighting the design lessons of Portugal's relative isolation, the interest sparked by Álvaro Siza on this masterpiece of 20th-century architecture. Siza's work derived from its contribution to the ongoing in-The first monograph exclusively dedicated to the Ocean ternational debate on the critical revision of modern archi-Swimming Pool was published in 2004 - 1959-1973 Piscina tecture, simultaneously integrating Bruno Zevi's contribuna praia de Leça da Palmeira (Ganshirt, 2004) - by Christian tions, Nathan Rogers' strategy of 'continuità' and the ethical Gänshirt, a former collaborator in Siza's office, who is also the and aesthetic premises of Brutalism as theorized by Reyner author of a dedicated chapter in Volume IV of Twentieth-Cen-Banham. tury Architecture (Ganshirt, 2017), where the Leca bathing Even if the Ocean Swimming Pool was not included in the secomplex features alongside with celebrated buildings such as lection of works presented in the journal Controspazio (1972), the Villa Savoye, the Fallingwater, the Villa Mairea and Louis preceded with essays by Vittorio Gregotti and Nuno Portas on Kahn's Salk Institute.

Siza's architecture, the bathing complex would be featured in the exhibition on Álvaro Siza, curated by Gregotti, at the Padiglione di Arte Contemporanea (PAC) in Milan (Gregotti, 1979). The Ocean Swimming Pool's international recognition will be fully consolidated (along with Siza's architecture) in the following decade, especially through the publication of a dedicated number of Quaderns d'arquitectura i urbanisme in 1983 (Mateo, 1983) and of Álvaro Siza Poetic Profession in 1986 (Siza, 1986), that counted on critical contributions by Kenneth Frampton, Nuno Portas, Alexandre Alves Costa, Pierluigi Nicolin, Oriol Bohigas, Bernard Huet, and Giovanni Chiaramonte's photographs of the swimming pool.

51

2.53

2.49

In the national context, in 1985, the Leça Swimming Pool was included by José Salgado in a monograph focused on Siza's designs for his hometown of Matosinhos (Salgado, 1985). The following year, an essay by Eduardo Souto Moura in the Spanish journal Arquitectura provided a critical comparison with Frank Lloyd Wright's Taliesen West and Mies Van der Rohe brick house (Moura, 1986).

In 2016, two books drew our attention to the bathing complex: A Pool in the Sea: In conversation with Kenneth Frampton (Frampton, 2016), which contains dialogues between Frampton and Siza, and Michel Toussaint's monography Piscina na praia de Leça (Toussaint and Melo, 2016) with texts of recognized authors in the Portuguese context. More recently, the Catalogue of the exhibition NO PLACE IS DESERTED. Álvaro Siza: Ocean Swimming Pool (1960-2021) (Ferreira and Urbano, 2022) presents the bathing ensemble as a palimpsest (since it was never conceived as a single gesture but is the result of several commissions and additions), while it provides critical essays, design reports and an illustrated chronology of the building's design and construction phases (Ferreira, 2022).

2.7 **Programme distribution**

The building has been in operation for almost sixty years, since its public opening in 1965. Simultaneously a leisure area and a meeting place for both local people and visitors, this has become a social and cultural landmark for the community, playing an essential role in its identity and collective memory.

The main users of the Ocean Swimming Pool are the bathers and visitors. If the former come mainly for the leisure experience of the swimming pool and the beach, the latter wish to get to know the building and wander around the site. For this reason, Siza's original design already had designated areas for shoed users, mainly for the visitors, which included the area to the north of the site, including the entrance, the bar's terrace, and technical areas. The rest of the spaces were meant for barefoot users. This separation was driven by hygienistic concerns to prevent shoed users from bringing dirt and other residues from the street to the areas where the bathers walked barefoot.

The site is currently in use without any significant change to its original program. The Ocean Swimming Pool is only open to the public during the bathing season, which lasts for three months every year from mid-June to mid-September.

The facilities that support the bathers' needs, such as the changing rooms, cloakroom, bathrooms, bar, and water treatment rooms, are located next to the entrance ramp. Access paths to the swimming pools along the beach fitted with foot wash basins ensure the separation between shoed and barefoot users.

The south area of the site houses technical functions that support the good functioning of the complex, such as the security room, the water collection room, and storage rooms. To the north, the bar has support facilities, such as storage rooms, waste management room, employee changing rooms, and bathrooms for visitors, bar users, and people with mobility impairments.



2.57 Ocean Swimming Pool during bathing season. 2014. 2.58 Ocean Swimming Pool organization scheme 2.59 Ocean Swimming Pool stakeholders identification

2.57



(1) adults' swimming pool; (2) children's swimming pool; (3) entrance ramp; (4) men's changing rooms; (5); women's changing rooms; (6) cloakroom; (7) changing rooms hallway; (8) collective changing room; (9) chlorine cabinet; (10) water treatment room; (11) south bathrooms; (12) access path and solarium; (13) south platform; (14) bar; (15) kitchen; (16) bar's terrace; (17) security room; (18) south storage room; (19) water collection room; (20) west platform; (21) north platform; (22) north bathrooms; (23) employee's changing rooms and bathrooms; (24) north storage room; (25) waste management room. 2.58

2.8 Stakeholders

To better plan the management and safeguarding of the heritage safeguarding, both on an international and national Ocean Swimming Pool, it is crucial to understand the present level; local management entities; the architect Álvaro Siza, dynamics behind the functioning and managing of the site by responsible for the design management; the site's users, studying the different stakeholders involved and their relacomprising visitors, bathers, and the virtual community. The tionship with the property. The stakeholders were identified following infographic presents the stakeholders and their inand organized under four categories: entities responsible for teractions (black arrows).



2.59

Heritage safeguarding

Cultural Heritage, I. P.

The Cultural Heritage, I. P. ensures the management, safe-Matosinhos Sport is a municipally owned corporation charguarding, enhancement, and conservation of assets integraged with managing and maintaining all municipal sports faciting Portugal's cultural heritage. It is responsible for implelities. As the Ocean Swimming Pool is not open the entire year, menting heritage protection legislation on a national level and Matosinhos Sport is only responsible for its management and the listing of national interest assets, such as the component maintenance during the bathing season. parts. The licensing of any work, intervention or change of use Casa da Arquitectura concerning a listed property and in the Buffer Zone requires Casa da Arquitectura (Portuguese Centre for Architecture) is a prior consent from the competent Regional Coordination and Development Commission and, subsequently, a binding decinon-profit cultural association that promotes architectural desion will be made from Cultural Heritage, I. P. bate and collects architect's documental estates. It is responsible for the Ocean Swimming Pool's guided tours.

ICOMOS (International Council on Monuments and Sites)

ICOMOS is a global non-governmental organization dedicated to promoting heritage conservation and protection. Every year, Matosinhos Sport promotes a public procurement It is an advisory board of UNESCO's World Heritage Comprocedure to select a supplier that will be in charge of the mittee, ensuring the conservation status of properties and bar's management during the bathing season. enforcing compliance with the World Heritage Convention **Design Management** of state parties.

Local Management

Municipal Council of Matosinhos

As the owner of the Ocean Swimming Pool, the Municipal Council is responsible for its management and maintenance during the period in which the equipment is closed to the public. Also, as the responsible entity for landscape and urban policies, it must abide to and enforce the Cultural Heritage, I. P. decisions on listed buildings and reflect them on the Municipal Master Plan.

Matosinhos Sport

Bar concession

Architect Álvaro Siza

All design decisions or modifications determined by management procedures should be discussed with Álvaro Siza and submitted to his approval.

Users

Visitors, bathers, and virtual community

Being a fully functioning facility, users and the values they assign to the site play an important role in defining management policies. Three main kinds of interactions from the general public with the site were identified: visitors, bathers, and the virtual community (online interaction).

References

Almeida, P. V. (1967a) "Un análisis de la obra de Siza Vieira", *Hogar y Arquitectura*, 68, January/February, pp. 73-76

Almeida, P. V. (1967b) "Uma análise da obra de Siza Vieira" and "Três obras de Álvaro Siza Vieira: Cooperativa de Lordelo. Casa unifamiliar em Maia. Piscina de Leça", *Arquitectura: Revista de Arte e Construção*, 96, March/April, pp. 64-74

Becker, A., Tostões, A. and Wang, W. (org.) (1997) *Portugal: Arquitectura do Século XX*. Munich/New York: Prestel

Banham, R. (1955) "The New Brutalism", *The Architectural Review*, 118, December, pp. 354-361

Bohigas, O. (1976) "Alvaro Siza Vieira", Bis, 12, March, pp. 11-18

Castanheira, C. and Porcu, C. (eds.) (2001) As cidades de Álvaro Siza. Lisboa: Figueirinhas

Castanheira, C. (2009) Álvaro Siza: The Function of Beauty. London: Phaidon

Cecilia, F. M. and Levene, R. C. (eds.) (1994) Alvaro Siza: 1958-2000. Madrid: El Croquis

Cleto, J. (1998) Pequena História de um Grande Porto. Porto de Leixões. Fotografias de Domingos Alvão e Emílio Biel. Matosinhos: APDL

Costa, A. A. and Siza, A. (1990) Álvaro Siza. Lisboa: Centre Georges Pompidou/Imprensa Nacional Casa da Moeda

Costa, A. A. (1996) *Álvaro Siza em Matosinhos*. Matosinhos: Câmara Municipal de Matosinhos

Curtis, W. (1994) "Álvaro Siza: An Architecture of Edges" in Cecilia, F. M. and Levene, R. C. (eds.) *Alvaro Siza: 1958-2000*. Madrid: El Croquis

Fernandes, E. and Pereira, R. (2019) "A metáfora do Grifo na obra de Januário Godinho: entre ecletismo, contextualismo e a retórica do Estado Novo" in Ferreira, F. and Fernandes, E. (eds.) *Representações de Poder de Estado*. Porto: LAB2PT/ Circo de Ideias

Ferrão, B. (1945) Perfis-Tipo e dimensionamento de suportes e revestimentos de alvenaria. Porto: Lopes da Silva

Ferrão, B. (1947) Urbanização: legislação geral de uso corrente. Porto: Lopes da Silva

Ferrão, B. (1960) Piscina da Praia de Leça - 1ª Fase: Memória descritiva e justificativa

Ferrão, B. (1962a) *Regulamento Geral das Edificações Urba*nas. Porto: Lopes da Silva

Ferrão, B. (1962b) Empreiteiros de obras públicas. Porto: Lopes da Silva

Ferrão, B. (1963) Contabilidade de obras públicas. Porto: Lopes da Silva

Ferreira, T. C., Barbosa, F. and Fernandes, E. (2021). "Construction Culture between Tradition and Modernity: Three Works by Álvaro Siza" in Mateus, J. M. and Pires, P. (eds.) *History*

of Construction Cultures, Proceedings of the Seventh International Congress on Construction History (7ICCH). Leiden: CRC Press/Balkema

Ferreira, T. C. (ed.) (2022) Sharing Memories. Álvaro Siza: Ocean Swimming Pool (1960-2021). Porto: FAUP/Afrontamento

Ferreira, T. C. and Urbano, L. (2022) No place is deserted. Álvaro Siza: Ocean Swimming Pool (1960-2021). Porto: FAUP/ Afrontamento

Figueira, J. (2014) A periferia perfeita: Pós-Modernidade na Arquitectura Portuguesa: Anos 1960-1980. Casal de Cambra: Caleidoscópio

Fleck, B. (1992) Alvaro Siza. Basel/Berlin/Boston: Birkhauser

Frampton, K. (ed.) (1999) Álvaro Siza: tutte le opere. Milano: Electa

Frampton, K. (2016) Álvaro Siza Vieira in conversation with Kenneth Frampton: a pool in the sea. Chicago: IITAC

Ganshirt, C. (2004) 1959-73 Swimming Pool on the Beach at Leça da Palmeira: Álvaro Siza. Lisboa: Blau

Ganshirt, C. (2017) "The Presence of the Atlantic Ocean -Swimming Pool on the Beach at Leça da Palmeira" in Mallgrave, H. (ed.) The Modern Project: Companion to the Twentieth Century. Volume IV: Twentieth Century Architecture. Hoboken: Wiley-Blackwell, pp. 525-538

Grande, N. (ed.) (2016) Les Universalistes. 50 ans d'architecture portugaise. Paris: Éditions Parenthèses/Fundação Calouste Gulbenkian/Cité de l'Architecture et du Patrimoine

Grande, N. and Muro, C. (eds.) (2018) Álvaro Siza: in/disciplina. Porto: Fundação de Serralves

Gregotti, V. and Bohigas, O. (1976) "La passion d'Alvaro Siza", L'Architecture d'Aujourd'hui: Portugal, 185, May/June

Gregotti, V. (ed.) (1979) Padiglione d'Arte Contemporanea di Milano: ALVARO SIZA Architetto 1954-1979. Milano: Idea Books

Gregotti, V. (ed.) (1989) Álvaro Siza: 1954-1988. Tokyo: A+U

INE (2021) Censos 2021

Jodidio, P. (ed.) (1999) Álvaro Siza. Koln: Taschen

Le Corbusier (1923) Vers une architecture. Paris: Les Éditions G. Crès et C

Llano, P. and Castanheira, C. (eds.) (1995) *Álvaro Siza: Obras* e *Projectos*. Madrid: Centro Galego de Arte Contemporánea/ Electa

Mateo, J. L. (ed.) (1983) Quaderns d'arquitectura i urbanisme. Monográfico dedicado a Alvaro Siza Vieira, 159, October/November/December

Mateus, M. (2009) "Álvaro Siza Leça Swimming Pools" in Steele, F. and Canales, F. G. (eds.) *First works: architectural*

experimentation of the 1960s & 1970s. London: Architectural Association, pp. 76-79 Siza, A. (1973) Memória Descritiva e Justificativa: Piscina da Praia de Leça da Palmeira: Ante-projecto intercalar das 3ª e 4ª fases

Moneo, R. (2004) Inquietud teórica y estrategia proyectual en la obra de ocho arquitectos contemporaneos. Barcelona: Actar Siza, A. (1983) "Oito pontos" in Quaderns d'Arquitectura i Urbanisme: Monográfico dedicado a Álvaro Siza, 159, pp. 58-59

Mota, R. (1972) Relatório de Estágio realizado sob a direcção de A. Siza Vieira. Porto: ESBAP Moura, E. S. (1986) "La Piscina de Leça, 25 años después", Arruitatura: Devite del Calagia Oficial de Arguitates de Ma

Moura, E. S. (1986) "La Piscina de Leça, 25 años después", Arquitectura: Revista del Colegio Oficial de Arquitectos de Madrid, 261, July/August

Oliveira, J. M. (1999) "Leça da Palmeira: lazer e evolução urbana litoral entre finais do século XIX e meados do século XX" in *Revista da Faculdade de Letras - Geografia I*, XV/XVI, pp. 97-115 Siza, A. (1995) "Restaurante da Piscina das Marés: Leça da Palmeira: 1993: Memória Descritiva" in Castanheira, C. and Porcu, C. (eds.) As cidades de Álvaro Siza. Lisboa: Figueirinhas, 2001

Pinto, M. (2011) Fernando Pinto de Oliveira: Um Homem além Siza, A. (2018) Interview by Teresa Cunha Ferreira in Construção Magazine, 83, January 13, 2018

Rogers, E. N. (1957) "Continuità o Crisi", *Casabella-Continuità*, Siza, A. (2019) Interview by Magda Seifert and Pedro Baía, in Seifert, M. and Baía, P. (eds.) *Porto Brutalista*. Porto: Circo de Ideias

Rodrigues, A. J. (1992) Álvaro Siza: obra e método. Porto: Civilização

Salgado, J. (1985) Álvaro Siza em Matosinhos. Matosinhos: Câmara Municipal de Matosinhos

Santos, F. R. (2017) Leça da Palmeira, evolução urbana entre os séculos XVIII e XXI. Matosinhos: Câmara Municipal de Matosinhos

Santos, J. P. (ed.) (1993) Álvaro Siza: obras y proyectos 1954-1992. Barcelona: Gustavo Gili

Sindicato Nacional dos Arquitectos (1948) 1º Congresso Nacional de Arquitectura, Maio/Junho de 1948. Relatório da comissão executiva. Teses. Conclusões e Votos do Congresso. Lisboa: Sindicato Nacional dos Arquitectos

Siza, A. (1962) Piscina da Praia de Leça da Palmeira: Memória Descritiva

Siza, A. and Ferrão, B. (1965) Piscina da praia de Leça da Palmeira - 2ª Fase - Projecto: Memória descritiva e justificativa Trigueiros, L. (ed.) (1997) Álvaro Siza: 1954-1976. Lisboa: Blau

Siza, A. (1965) Piscina da Praia de Leça da Palmeira - 4ª Fase -Anteprojecto: Alargamento do recinto, incluindo restaurante, arrecadações, sanitários, bar e esplanada: Memória Descritiva

Siza, A. and Ferrão, B. (1966) Piscina da Praia de Leça da Palmeira - 3ª Fase - Projecto: Alargamento do recinto, incluíndo arrecadações, sanitários, bar, esplanada, plataforma e muros de suporte a norte e a sul: Memória Descritiva

Siza, A. and Ferrão, B. (1967) Piscina da Praia de Leça da Palmeira: Memória Descritiva: Processo completo do projecto, incluindo fases construídas e a construir Siza, A. (1998) Imaginar a evidência. Lisboa: Edições 70

Távora, F. (1945) "O Problema da Casa Portuguesa" in *Sema*nário Aléo, November 10, 1945

Testa, P. (1984) The architecture of Alvaro Siza. Massachussets: MIT Press

Tostões, A. (2022) "Ocean Swimming Pool: Álvaro Siza between Japanese Poetry and an Atlantic Topos" in Ferreira, T. C. (ed.) Sharing Memories. Álvaro Siza: Ocean Swimming Pool (1960-2021). Porto: FAUP/Afrontamento, pp. 27-31

Toussaint, M. and Melo, M. (coord.) (2016) *Piscina na praia de Leça: a pool on the beach*. Lisboa: A+A Books



3. ASSESSMENT OF SIGNIFICANCE

3.1 Introduction

- 3.2 Recognition and listing
- 3.3 Comparative analysis
- 3.4 Communities' perception
- 3.5 Dissemination activities
- 3.6 Discussion of significance
- 3.7 Levels of significance
- 3.8 Statement of significance

56-93

3.1 Introduction

Chapter 3 assesses the cultural significance of the Ocean be complementary, as long as they are equally addressed in Swimming Pool, understood as the set of tangible and intanconsequent planning policies. The information gathered from gible qualities that make it a place of value to society (Kerr, non-experts' engagement and vision, complemented with the 2013, p. 4). The precise identification of the heritage values work of a multidisciplinary expert group, might be the key to and its assessment process is essential to inform the devea management and action plan that connects with the place. lopment of significance-based policies to guide the conserits people, and its identity (Court and Wijesuriya, 2015). Although and despite international recommendations such as vation, interpretation, and management of the site so that the significance of the place is retained. the Faro Convention (CoE, 2005) or, most recently, the HUL Recommendation (UNESCO, 2011), the effective integration The chapter opens with a section on recognition and listing of community engagement initiatives among urban planning (3.2), focusing on the listing process of the Ocean Swimming practices is still shallow and seldom in international and na-Pool as National Monument (2011) and its integration in the tional contexts (Bandarin and Oers, 2014).

The chapter opens with a section on recognition and listing (3.2), focusing on the listing process of the Ocean Swimming Pool as National Monument (2011) and its integration in the World Heritage Tentative List (2017) as a component property of 'Álvaro Siza's Architecture Works in Portugal'. The third section (3.3) entails the comparative analysis between similar heritage sites (among other Álvaro Siza's works, the World Heritage List, or similar typologies) by examining the criteria that sustained its heritage value and underlying how the exceptional attributes of the Ocean Swimming Pool fill an important gap in terms of cultural significance.

The fourth section (3.4) discusses the process and most relevant outcomes of the participatory activities, such as interviews, surveys, workshops, and social media analysis, undertaken to identify the perspectives of a broad spectrum of communities and stakeholders on the bathing complex. The fifth section (3.5) details all the research dissemination initiatives that indirectly contributed to identifying qualities. Furthermore, section 3.6 presents the comparative discussion between the values recognized by all the actors involved in the cultural significance assessment. As the contribution of each building area to the general significance is different, they were assessed according to their level of significance (3.7). Ending the chapter, the statement of significance (3.8) summarizes the key heritage values of the Ocean Swimming Pool as identified and assessed in the previous sections.

Cultural significance encompasses the values recognized by The analysis of the values and attributes recognized in social specific communities at a particular time, leading to the register or statutory listing as heritage. Identifying cultural signifimedia platforms enabled the sampling expansion, although cance through the physical investigation of the place, archive limited as the research has no pretension of extrapolation to research, and actors' consultation is a critical component of a a broader reality. However, it stands as an unprecedented picplace's management process and the first step for decisionture of the Ocean Swimming Pool users and visitors' commu--making, namely, over what should be preserved and what nity, revealing the potential outcomes of these approaches. can be changed (ICOMOS Australia, 2013). Hence, it beco-Other techniques, such as seminars with experts, workshops mes crucial to implement cultural significance assessments with students, and activities with children, complement those by identifying what aspects (attributes) should be conserved mentioned above, being cross-cutting methodologies an adand why (values) (Tarrafa Silva and Pereira Roders, 2012). ded value for assessing cultural significance.

However, most cultural significance assessments and heritage listings have traditionally been performed by heritage-related experts, such as historians, archaeologists, architects, and art curators, reflecting their knowledge, disciplinary bias, and values system (Smith and Waterton, 2012). On the other hand, non-expert communities introduce different levels of empathy to assets and create their own "heritage lists", although the values identified by those, namely social, are often neglected in heritage assessment processes (Wagenaar et *al.*, 2023). Both lists are likely to differ but without ceasing to

Engaging communities in a broad sense, thus, was a fundamental decision within the methodology adopted for the Ocean Swimming Pool CMP. Being a public facility continuously in use, primarily by local communities, made compulsory the integration of these voices, alongside government institutions, experts, and site managers, into the discussion of the future management of change. Besides, the involvement of communities also benefits the establishment of a greater sense of identity and connection with the place through their engagement in different activities (Court and Wijesuriya, 2015).

This multimethod approach, through implementing of different participation strategies (fig. 3.12), contributed to minimizing potential gaps and expanding the research representativeness. Document analysis of the statements of significance accompanying the inclusion of the property into national and international heritage registers and inventories provided the expert and official perspective. The semi-structured interviews with site managers were critical sources for understanding the perspective of the daily management actors. The interview protocol and the survey design applied to users and visitors were methodologically influenced by the experiences of referenced case studies (City of Ballarat, 2013), particularly the seminal "IMAGINE Ballarat" project.

Regarding data analysis, namely the identification of recognized cultural values, the research followed the taxonomy developed by Tarrafa Silva and Pereira Roders (2012) exclusively for all different collection methods. The systematic nature of this content analysis methodology enabled further comparison between different sources and perspectives and the draft of a statement of significance representing the aspiring inclusiveness of the approach.

3.2 Recognition and listing

3.2.1 National recognition

National Inventories

The Ocean Swimming Pool is registered in the National Inventory of Architectural Heritage (Sistema de Informação para o Património Arquitectónico - SIPA), organized by the Directorate-General for Cultural Heritage (DGPC), under the number IPA.00020880. In the registration form, it is stated that the Ocean Swimming Pool:

"stands out for its harmonious integration into the maritime landscape, without failing to assert the work's artificial character which the rigor of the geometric forms and the exposed concrete emphasize." (SIPA, 2011)

It also integrates the Inventory of 20th-century architecture in Portugal (Inquérito à Arquitectura do Século XX em Portugal - IAPXX), an online database developed between 2003 and 2006 by the Portuguese Association of Architects (Ordem dos Arquitectos) merging all information on built architectural heritage of this period in Portugal, under the number N200595. Specifically regarding the Ocean Swimming Pool, it is considered that:

"The different built volumes and long walls are arranged longitudinally with punctual (angular) geometry deviations, often misaligned with respect to each other, configuring an organic whole. More than the definition of shapes, the building as a whole seems to be subordinated to the definition of pathways embedded between walls. Oriented towards a landscape dominated by the sea, the site holds a labyrinth that conceals more than what it reveals, unlike Le Corbusier's promenade architecturale. (...) The Ocean Swimming Pool's design is a formal (or topographical) extrapolation that seeks an intensified sensory experience of a location in its specificity." (IAPXX, 2006).

Even if the National Inventory of Architectural Heritage is more detailed than the Inventory of 20th-century architecture in Portugal, which simply identifies the author, the function, and the location, both lack information on the assessment of cultural significance (values and attributes).

National Listing

The Cultural Heritage, I. P. is responsible for proposing to the Portuguese Government a list of buildings of relevant cultural interest to be listed as National Monuments (the highest level in the Portuguese listing system), following the procedure of paragraph 3, article 2 of the Law for Cultural Heritage, with the general guidelines laid out in article 17 thereof:

"the analysis of the building's scientific, heritage, and cultural value is made in accordance with the criteria of authenticity, originality, rarity, singularity, and exemplarity, which should be expressed in the way that they have been appropriated by the citizens, and in their symbolic relevance as places for the arts within the collective historical and political memory" (Law No. 107/2001, 2001).

On May 25, 2011, under the terms of Decree No. 16/2011, after a long process that started in 2004, the Portuguese Govern- 3.1

ment listed the Ocean Swimming Pool as National Monument, with the following description:

"(...) the Leça da Palmeira Ocean Swimming Pool represents a remarkable accomplishment for its integration into the place without resorting to mimesis, instead frontally assuming the artificial character which the rigor of the geometric shapes and the exposed concrete emphasize.

The buildings are set in a linear way along the beach wall, without interruptions in its volumes, but through the design of the paths and the geometry of the wall, it invites visitors to contemplate the maritime landscape. The ability to engage in a harmonious dialogue with the context, without denying its own artificiality, is one of the main characteristics of Siza Vieira's early work, which has in Leça Ocean Swimming Pool one of the best examples in Portugal.

Its listing as National Monument is justified by its architectural, urbanistic and landscape value, but also by the historical value of a work that is already an essential reference of modernist architecture and still remains in full use" (Decree No. 16/2011, 2011).

The definition of a Buffer Zone as a consequence of the listing process took place in two phases: a) firstly, in 2011, the definition of a General Buffer Zone (Zona Geral de Protecção) with



the ZEP also aims at safeguarding the listed properties and a 50 m radial perimeter as determined by the Portuguese legislation (fig. 3.1); secondly, on October 24, 2012, under the their fundamental landscape, identified as the surrounding Ordinance No. 608/2012 a Special Buffer Zone (Zona Especoastal area and coastal avenue, ensuring the continuity of the dialogue between the Boa Nova Tea House and the Ocean cial de Protecção) was defined including both listed National Monuments along the seaside of Leca da Palmeira: The Boa Swimming Pool in Leça and the coastal avenue, the beach and the sea" (Ordinance No. 608/2012, 2012). Nova Tea House and Restaurant and the Ocean Swimming Pool, integrating the seaside avenue and beaches between In summary, the Portuguese Government listed the Ocean them as a means of protection of the coastal landscape (fig. Swimming Pool complex as National Monument, identifying 3.2). According to the Ordinance:

" (...) both buildings, authored by Álvaro Siza Vieira and holding emblematic character in the framework of Portuguese architecture of the 20th century, have a remarkable setting in the coastal landscape (...) The joint definition of the Special Buffer Zone (ZEP), with each of the monuments enjoying the limits defined in the ZEP, attentive to the specificities of the place and its relationship with the building, results from the understanding of the unity of location, topography and visual relationships. The ZEP takes into account the setting of the buildings and their relationship with the land and sea surroundings, considering it as a determining part of the architectural design, and also recognizes the morphology of the land, the landscape, and the views, as well as the conditions defined by the current management and planning tools. The definition of

Monumento Nacional
 Zona Especial de Protecçã



In summary, the Portuguese Government listed the Ocean Swimming Pool complex as National Monument, identifying the concrete shapes as the main attribute and recognizing its aesthetical, ecological, historic, and economic values. Other attributes were further mentioned, which, despite not directly related to any specific value, might be interpreted as contributing to the cultural values recognized for the whole bathing complex, namely the beach wall, as well as the intangible attributes related to the character and design options, such as the linear (form) along the beach wall without interruptions, the design of the paths and the geometry of the wall. The character inviting contemplation of the surroundings also indicates intangible attributes related to the place, namely the maritime landscape, reinforcing the ecological value of the complex.

International recognition 3.2.2

International Inventories

The Iberian DOCOMOMO Foundation, responsible for pursuing the DOCOMOMO (Documentation and Conservation of buildings, sites, and neighborhoods of the Modern Movement) objectives in Spain and Portugal, maintains an online database of significant 20th-century architectural heritage which includes the Ocean Swimming Pool. The inventory entry includes the identification of the author, the location, the construction time frame, and an extensive set of photographs and drawings.

Together with ICOMOS ISC20 (International Scientific Committee on Twentieth Century Heritage) and the Iberian DOCO-MOMO Foundation, the EU-funded research and innovation project Innova Concrete focused on the development of innovative techniques to preserve concrete-based monuments, included the Ocean Swimming Pool amongst the 100 most significant concrete-based 20th-Century Heritage Sites in Europe. The relevance of the selected entries for the history of architecture and engineering is further detailed in the description below:

"All the selected sites are outstanding examples of architecture and engineering from the 20th century on technical, social, and aesthetic levels. They reflect innovation in building materials and structure, as well as in building methods, construction techniques, and detailing. They often exemplify new uses and typologies, characteristic of the social, cultural, and economic development of their time, and they are significant in the history of architecture and engineering." (Innova Concrete, 2019).

World Heritage Tentative List

The Ocean Swimming Pool is part of 'Ensemble of Álvaro Siza's Architecture Works in Portugal', submitted in 2017 by the Portuguese Government to the World Heritage Tentative List. It comprises a series of buildings that represent Álvaro Siza's oeuvre's exceptional, and incomparable attributes.

The ensemble components have been selected from his built works in Portugal, among an ongoing architectural production of over six decades that, consecutively and uninterruptedly, gained wide international recognition and the most prestigious awards (Pritzker Prize, Mies Van der Rohe, Alvar Aalto Medal, Golden Lion, etc.) for his more than 500 projects and

The 'Ensemble of Álvaro Siza's Architecture Works in Portugal' is aligned with the UNESCO World Heritage Committee's request to State Parties to submit nominations for 20th-century heritage (ICOMOS, 2005). The nomination was submitted by the Permanent Delegation of UNESCO in Portugal under the Cultural Heritage criteria (ii) and (iv), with the

"The architectural work of Álvaro Siza Vieira is exceptional and of universal value for an ever-growing number of reasons, which overlap in an unusual manner. They make him one of the protagonists of contemporary architecture. His architecture is unmistakable, specific, and incomparable. The integrity and the physical, aesthetic, and historical characteristics of his work make it an example of unmatched authenticity and genuineness. The universal and exceptional value of his work is the result of that ensemble of characteristics and qualities." (Ensemble of Álvaro Siza's Architecture Works in Portugal, 2017).

This serial nomination for inscription on the World Heritage List was submitted in January 2024 under the title 'Álvaro Siza's Architecture: A Modern Contextualism Legacy'.

built works in 16 countries and 4 continents. following description:



3.3 **Comparative analysis**

3.3.1 Álvaro Siza's early works

Some of Álvaro Siza's first work commissions were part of a broader urban plan for promoting tourism in the village of Leça da Palmeira, envisaged by Fernando Pinto de Oliveira (1911–1975). Among them, besides the Ocean Swimming Pool (1960-1973), are the Boa Nova Tea House and Restaurant (1956-1963) and the Quinta da Conceição Swimming Pool (1958-1965), all built between 1958 and 1973 and, in the case of the last two while Siza was still working at Fernando Távora's office.

The Boa Nova Tea House and Restaurant composition is based on three main principles, conceptually related to Portuguese vernacular architecture: an almost mimetic reinterpretation of the site topography, a respectful attitude in terms of the relationship with the preexisting chapel, and a constant correlation with the landscape, achieved through the intentional design of a 'promenade' built in Portuguese limestone (fig. 3.4). Hence, Siza proposes the use of a mixture of traditional tectonics (timber and ceramic tiles) and modern tectonics (reinforced concrete), seeking to combine vernacular constructive elements with the use of modern technologies. In contrast to the formal vernacular influence visible in the Tea House, the Ocean Swimming Pool displays an abstract language, being composed of a succession of walls in reinforced concrete, running parallel to the shoreline and covered with a low-slope copper roof (Ferreira and Fernandes, 2021, p. 1-3).

The Quinta da Conceição Swimming Pool, a public park designed by Távora (1956-60) on the grounds of an old convent, is implanted on an uphill path. One must, therefore, approach it from below and go around a white-walled hilltop, entirely closed when seen from the outside except for a narrow stepped opening. The pool enclosure is defined by a series of walled platforms open to the sky, revealing remarkable conceptual similarities with Boa Nova and the Ocean Swimming Pool in understanding and reinterpreting the topography. In this work, Siza once again used a combination of traditional construction culture (masonry walls, timber, and ceramic roof tiles) (fig. 3.5) and modern tectonics (reinforced concrete slabs and external walls) (Ferreira et al., 2021, p. 2-3). Besides the tectonic differences, the building's perfect physical integration into its setting is taken to an extreme in the Ocean Swimming Pool: building and setting merge, incorporating and reinterpreting the preexisting seaside wall.

However, we cannot say that this tectonic shift, even if it has its best example in the Ocean Swimming Pool, started or en-

3.4 Boa Nova Tea House and Restaurant (1958-1963) designed by Álvaro Siza. 3.5 Quinta da Conceição Swimming Pool (1958-1965) designed by Álvaro Siza. 3.6 20th century post-war architecture in UNESCO World Heritage List. 3.7 Lordelo do Ouro Cooperative (1960-1963) designed by Álvaro Siza.

ded with this project. Siza had already been experimenting with exposed concrete structures in a previous design for the Parish Centre in Matosinhos (1955-1960), which was, nevertheless, still very indebted to vernacular influences. It would only be in the Lordelo do Ouro Cooperative building (1960-1963) that a more brutalist language was clearly assumed. Almost entirely closed to the outside, this building comprises a series of clearly defined and sharp juxtaposed volumes. It is wholly built in exposed concrete with a very distinctive horizontal wood formwork, and the window frames were initially made out of very large wooden planks that gave it a particular material weight (fig. 3.7). The tectonic proximity with the Ocean Swimming Pool is undeniable, showing that this was something Siza was interested in pursuing at the time. Even so, in what has to do with the relationship with the surroundings, the two projects could not be more different, as the Lordelo do Ouro Cooperative does not seek to integrate or merge with the urban fabric, searching for some formal autonomy in a clear rejection of what exists around it. The fact that we can find this sameness and difference within contemporary works, ideas that seem divergent and contradictory, is, as Peter Testa puts it, revealing of "Siza's non-ideological, non- -dialectical thinking (...) setting in motion a deeper trajectory and methodology - a non-binary praxiography for architecture." (Testa, 2022, p. 72),





3.5

World Heritage List 3.3.2

In recent years, the World Heritage List has seen an increase in 20th-century post-war architecture with the inclusion of 10 properties due to their contributions to the development of 20th-century architecture and urbanism. As a component property of 'Álvaro Siza's Architecture Works in Portugal, which integrates the World Heritage Tentative List since 2017, the

LISTED PROPERTY	CRITERIA	LISTING YEAR	LOCATION
Brasilia	(i, iv)	1986	Brazil
Ciudad Universitaria de Caracas	(i, iv)	2000	Venezuela
Luis Barragán House and Studio	(i, ii)	2004	Mexico
Le Havre, the City Rebuilt by Auguste Perret	(ii, iv)	2005	France
Sydney Opera House	(i)	2007	Australia
Central University City Campus of the Universidad Nacional Autónoma de México (UNAM)	(l, ii, iv)	2007	Mexico
The Architectural Work of Le Corbusier, an Outstanding Contribution to the Modern Movement	(i, ii, iv)	2016	Argentina, Belgium, France, Germany, India, Japan, Switzerland
Pampulha Modern Ensemble	(I, ii, iv)	2016	Brazil
Ivrea, industrial city of the 20 th century	(iv)	2018	Italy
The 20 th Century Architecture of Frank Lloyd Wright	(ii)	2019	United States of America



65

Ocean Swimming Pool represents an exceptional example for its modern typology (touristic, sports, and healthcare facility) as well as its landscape integration, constructive innovation, its representativeness in the collective memory and its contextual design framed within the critical revision of the Modern Movement as coined by Kenneth Frampton.





3.8



3.9

3.3.3 Ocean, natural and tidal pools

Even though natural pools filled with ocean water seem to have existed for thousands if not millions of years, sea bathing as a human activity is much more recent, in a first instance sparked by enthusiasm for physical fitness as it was believed to have medicinal properties. The existence of man-made ocean pools is particularly significant along the coast of New South Wales, in Australia, the first ones being built as early as the beginning of the 19th century (McDermott, 2012, p. 90). The hazards posed by surf, rip currents, and the abundance of sharks, combined with the bans that were in place at the time, forbidding public bathing in daylight, fostered the development of these pools. As the coast began to be understood as a recreational space, from the 1890s onwards, these structures became increasingly popular, hosting swimming competitions, with racing courses and places for spectators (fig. 3.9).

This enthusiasm for communal exercise went hand in hand signing the pool in Leça during the 1960s. with the first steps of the tourism industry all around Europe, as a new middle class emerged with the reduction of la-As we see it, the uniqueness of the Ocean Swimming Pool, bor hours and the improvement of wages during the interwar amongst other examples of the same typology, resides preperiod (Marsden and Spearritt, 2021, p. 138-139). In the 1920s cisely in the fact it is an architectural object that goes beyond and 1930s, numerous leisure infrastructures comprising saltthe swimming tank, with support facilities that were designed water swimming pools were built along the coast of the Uniand articulated as a whole, together with an almost seamless ted Kingdom under the name of Lidos (after the Venetian laintegration into the landscape that is not limited to the placegoon's island) (McLachlan, 2019). These were, in many cases, ment of the pool and extends to the surrounding area as a key enormous and flamboyant structures that went far beyond piece of a broader plan. Furthermore, it was fundamental in simple swimming pools, hosting live shows and all sorts of the context of Álvaro Siza's early works as it expressed a tecattractions to turn small coastal towns into mass tourist destonic shift from previous vernacular-inspired designs towards tinations (fig. 3.10). As it has become clear, the appearance of a more abstract language and expressively modern materiaocean pools is usually associated with locations where the lity. The exceptional attributes of the Ocean Swimming Pool, sea's natural conditions are not fit for year-round bathing. thus, fill an important gap in terms of cultural significance, es-Along the coast of Brittany, also a popular tourist destination, pecially if we consider how underrepresented are works from the second half of the 20th century in the World Heritage List, we can find swimming pools built during the 1930s that take advantage of rock outcrops along the beaches (fig. 3.8). specifically from this transition period in the aftermath of the Modern Movement.



3.10

67

Even if we can trace the typological origin of the Ocean Swimming Pool in all of the above, none present the set of attributes of Álvaro Siza's masterpiece. Although the ocean pools in New South Wales are also built in a very close relationship with nature, taking advantage of the geological formations of the coast and minimizing man-made construction, they are usually located in remote areas and with minimal support facilities, in many cases precarious and not conceived as part of a whole together with the swimming tanks. In the case of British Lidos, one may say precisely the opposite, as support facilities take the predominant role and the swimming pools assume a much more artificial configuration. Its theme park appearance could not be further apart from Siza's strategy, very attentive to landscape integration, seeking to be invisible amongst the horizontality of the landscape. It is most likely that none of the above were known by Siza when he was de-

3.8 Bon-Secours swimming pool (1936),
Saint-Malo.
3.9 Bronte Baths (1887), Sydney.
3.10 Tinside Lido (1935), Plymouth.

3.4 Communities' perception

Community participation and stakeholder integration are among the best practices for heritage management and conservation, shifting from top-down, reactive, and regulatory approaches towards bottom-up, proactive, and participated approaches integrating communities throughout the process. This project attempted to overcome the traditional approaches that only consider citizens' involvement at the final validation stages of conservation planning. The variety and broadness of raised aspects related to the Ocean Swimming Pool demonstrated the potential of citizens' engagement to build more inclusive and democratic planning policies. Moreover, the broadness of the implemented methodology was one of the concerns of this research, combining the perspective of experts and governmental institutions with the building actors, site managers, and non-expert communities (e.g. users and visitors, including children). This multi-

WHO	HOW
Site managers and	Interviews
users	Surveys (Love, Change, Imagine)
Virtual community	Social media analysis
Students	Word cloud activity
Children	Drawing activity

-method approach, which included i) interviews, ii) surveys, iii) social media analysis, iv) workshops, and v) other activities, contributed to minimizing potential gaps and expanding the research representativeness (fig. 3.11).

The three key questions (fig. 3.12) of the 'Imagine Ballarat' methodology (City of Ballarat, 2013) formed the basis for the protocol design of the structured interviews with site managers and the surveys of visitors and users. Besides other practical questions, they were all inquired about i) What do they LOVE in the site (values and attributes), ii) What would they CHANGE (vulnerabilities and problems) and iii) How do they IMAGINE the site in the future (expectations and recommendations). One of the positive aspects of this method is that it entangles, very simply and efficiently, the cultural significance with policy planning. However, in some groups, the adapted 'Imagine Ballarat' LCI questions were partially applied, for the sake of clarity, time constraints, language, or other surveying restrictions. In these cases, it was given preference to the 'love' question, as cultural significance assessment precedes importance in developing a statement of significance.

The results of the participatory strategies were further analyzed through a coding technique supported by the taxonomy of cultural values of Tarrafa Silva and Pereira Roders (2012). This framework of eight cultural values - social, economic, political, historic, aesthetic, scientific, age, and ecological (fig. 3.13) – allowed the identification and further comparison with the results gathered with the above-mentioned community groups.



Especially in interviews with site managers and staff, quoge, it allows the survey to be conducted by non-specialists tations of key nucleons of their responses were selected, and to speed up data analysis. Moreover, in addition to foltranscripted, and grouped for comparative analysis. Addilowing the precoding categories, new ones could be created tionally, in surveys with the communities of users, in the first (post-coding), allowing broader information to be included. phase, a precoding technique was developed through inter-The systematic nature of this content analysis methodology preting nucleon sentences and words summarizing answers enabled further comparison between different sources and collectively, an issue especially critical for 'change' and 'imaperspectives and the draft of a statement of significance regine' questions. Since these questions were not supported presenting the approach. by a thesaurus, this technique proved to be useful to build one preventively. During the second phase application sta-

VALUE		
Social	It represents beliefs, myths, religions (c rations. It can evidence memory and pe identity, motivation, and pride, sense of places representative of some social hi	
Economic	It shows the function of the asset, origin which has its value in the past, that can on whether to make some use of it or ne fied by the role for the contemporary m to a financial promotion of the property	
Political	Exhibits the education role that heritag myths, glorification of political leaders, present), to disseminate cultural aware prosperity perceptions stem from the h	
Historic	It is a heritage asset with the potential t testimonies of stylistic or artistic move an object that retains conceptual signs history, or a fact that the object has bee might be connected with Ancient civiliz	
Aesthetic	It represents the original product of cre re. It is the integral materialization of co representing the authentic exemplar of	
Scientific	Defines original result of human labor, correpresenting an outstanding quality through the second se	
Age	Exhibits craftsmanship value oriented t reflecting the passage/lives of past ger on the forms, components, and materia	
Ecological	It represents harmony between the bui the identification of ecological ideologi tured resources which can either be rea	
3.13		

3.11 Identification of participants and participation strategies.
3.12 The three key questions of the 'Imagine Ballarat' methodology.
3.13 Taxonomy of cultural values (Tarrafa Silva and Pereira Roders, 2012).

3.12

3.11

DESCRIPTION

organized or not), legends, stories, testimonials of past geneersonal life experiences, showing notions related to cultural f "place attachment" and communal value. Integrates objects/ ierarchy/status.

nal or attributed. It can indicate the asset's expired function, be determined by its physical evidence (of materials), option ot, and bequest value (for future generations). It can be identinarket, namely for the tourism industry, such as being oriented y.

ge assets may play, using it for political targets (nations' birth , etc.). It might represent part of strategies and policies (past or eness, and explored for political targets. Power, authority, and heritage asset.

to provide knowledge about the past as part of a few or unique ments, which are now part of history, as well as the quality of a (architectural, urban planning, etc.), which are now part of en related with such as an important event in the past which zations.

eativity and imagination, which might hold a creator's signatuonceptual intentions, implying a conceptual background and f a decade, part of the History of Art or Architecture.

raftsmanship, which shows technical and material skillfulness, ough the integral materialization of conceptual intentions.

towards the production period, evidencing a piece of memory, nerations, showing marks of the time passage (patina) present als.

ilding and its environment (natural and artificial). Can evidence ies on its design and construction, such as the use of manufacused, reprocessed, or recycled.
3.4.1 Site managers and users

Site managers

When assessing cultural significance, it is important to have a broad perspective on the building's daily management and use by including different stakeholders (see section 2.8), such as the site managers. The management of the Ocean Swimming Pool is a shared responsibility between the Municipal Buildings Division and the municipally owned corporation Matosinhos Sport. The Municipal Council owns and is the main responsible for the maintenance of the Ocean Swimming Pool, a responsibility shared with other municipal departments that were also considered for the interviews. During the bathing season (June - September), Matosinhos Sport ensures its daily maintenance routines and determines the use regulations.

As regards the assessment of cultural significance, there was a common approach to all the actors related to the site's management which consisted of interviews based on the 'Imagine Ballarat' methodology. Hence, questions addressed the i) values and attributes recognized on the site (love), ii) identifying site vulnerabilities (change), and iii) expectations concerning maintenance and conservation (imagine). If the policymakers' (Municipal Council Departments) interview protocol included other questions related to the policies and site-related documents, the protocol adapted to the staff was more focused on their daily routines (see Appendices B and C).

The interviews conducted with the six heads of the Municipal Council Departments related to the site's general management (Culture, Heritage, Planning, Environment, Civil Protection, and Municipal Buildings), and the Matosinhos Sport ten staff members (head of division, technical coordinator, technical director, bar concessionaire, maintenance foreman, receptionist, lifeguard, security guard and cleaning assistant) took place on June 2021.

i) The collected answers indicated that the most valued aspects (what they love) by respondents correspond to the site's 'integration into the landscape' (50%), 'everything' of the site (13%), and with equal percentage the 'views of the sea', 'modern architecture' features and the 'significance of the building in the collective memory' (9%). The inquired also identified issues related to the 'fabric of the building' and the 'diversity of users' (5%).

Following the aforementioned taxonomy of cultural values, the results reveal that the site managers were able to identify predominantly aesthetic, ecological, and historic values, even if scientific and social values were also recognized.

ii) Among the aspects they would prefer to change, a large part of the respondents stated that they would change 'nothing' (40%), specifying in second place the need for 'more space for towels' (12%), 'accessibility improvements' (12%) and 'more safety measures for children' (12%). With a lower percentage but still mentioned by site managers is the need for 'more lighting in the changing rooms', the bar being 'in use during the entire year', the 'completion of the original design (restaurant)', and 'improved signage to facilitate access' to the building.

iii) Finally, respondents tend to imagine the building in the future as 'exactly the same' (72%), as a 'referential building of Matosinhos' (21%), and 'with a greater number of visitors' (7%).

ATTRIBUTE	VALUE	PARAMETER
integration into the landscape	Ecological	It represents harmony between the building and its environment (natural and artificial).
modern architecture	Historic	It is part of a few or unique testimonies of stylistic or artistic movements, which are now part of history.
views of the sea	Ecological	It represents harmony between the building and its environment (natural and artificial).
significance in the collective memory	Social	It can evidence memory and personal life experiences, showing notions rela- ted to cultural identity, a sense of "place attachment" and communal value.
fabric of the building	Aesthetic	It represents the original product of creativity and imagination, which might hold a creator's signature.
	Scientine	Defines original result technical and material skillfulness, representing an outstanding quality of work through the integral materialization of conceptual intentions.
diversity of users	Social	It can evidence memory and personal life experiences, showing notions rela- ted to cultural identity, a sense of "place attachment" and communal value.

Users and visitors

As mentioned before, the involvement of communities includes the Ocean Swimming Pool users. Their vision, experience, and expectations are essential for the definition of this CMP's policies. As such, surveys to community users were conducted between June 2021 and July 2022, during the bathing season, and with the participants of the 'Open House' annual initiative in both years (figs. 3.15 and 3.16). Surveys containing all adapted 'Imagine Ballarat' LCI questions were distributed on-site, both through a printed version and an online one that could be accessed through a QR code. These were implemented in two different phases: a trial test with open-ended questions was first applied to a set of 20 respondents (June 2021), followed by a second set of inquiries (July 2021) which, based on the results of the first set, entailed multiple-choice questions (to help the inquirer) with the possibility of adding an open answer.

The precoding strategy enabled by surveys proved to be useful during the application stage, allowing it to be conducted by non-specialists and speeding up data analysis. Therefore, data analysis, in addition to following the precoding categories, creates new ones (post-coding) resulting from the additional information provided by the respondents.

iii) Finally, respondents tend to imagine the building in the future as 'exactly the same' (59%), in 'good conservation condition' (14%), and 'operational during the entire year' (8%). Other aspects that the users imagine for the future are the site as a 'referential building of Matosinhos', with the 'completion of the original design (restaurant)', 'more support infrastructure for visitors', twith a greater number of visitors', the 'implementation of new technologies' and 'as National Monument'.

i) Survey results indicated that the most valued attributes (what they love) by respondents correspond to the site's 'integration into the landscape' (43%), the 'harmonious relationship with the rocks' (14%), and 'modern architecture'



3.15

3.14 Justification of the values identification based on the cultural values taxonomy (Tarrafa Silva and Pereira Roders, 2012).

3.15 Open survey, 2021.

features (10%). The inquired also identified several attributes related to the 'views of the sea', the 'fabric of the building', the 'significance of the building in the collective memory', 'diversity of users', the 'privacy of the building' and the 'conservation of the original design'.

Following the aforementioned taxonomy of cultural values, the results reveal that users and visitors were able to identify predominantly ecological, aesthetic, and historic values, even if social, scientific, and age values were also recognized.

ii) Among the aspects they would prefer to change, a large part of the respondents stated they would change 'nothing' (42%), specifying in second place the need for 'more space for towels' (12%), the 'reduction of the entrance fees' (10%) and 'more lighting in the changing rooms' (10%). With lower percentage but still mentioned by users was the need for the bar to be 'in use during the entire year', the 'completion of the original design (restaurant)', 'accessibility improvements', 'signage improvements to facilitate access' to the building and 'more safety measures for children'.



^{3.16} Open survey, 2021.

ATTRIBUTE	VALUE	PARAMETER
integration into the landscape	Ecological	It represents harmony between the building and its environment (natural and artificial).
harmonious relationship with the rocks	Ecological	It represents harmony between the building and its environment (natural and artificial).
modern architecture	Historic	It is part of a few or unique testimonies of stylistic or artistic movements, which are now part of history.
views of the sea	Ecological	It represents harmony between the building and its environment (natural and artificial).
significance in the collective memory	Social	It can evidence memory and personal life experiences, showing notions related to cultural identity, a sense of "place attachment" and communal value.
fabric of the building	Aesthetic Scientific	It represents the original product of creativity and imagination, which might hold a creator's signature.
		Defines original result technical and material skillfulness, representing an outstanding quality of work through the integral materialization of conceptual intentions.
diversity of users	Social	It can evidence memory and personal life experiences, showing notions related to cultural identity, a sense of "place attachment" and communal value.
privacy of the building	Aesthetic	It is the integral materialization of conceptual intentions, implying a conceptual background.
conservation of the original design	Aesthetic Age	It represents the original product of creativity and imagination, which might hold a creator's signature.
		Exhibits a piece of memory, reflecting the passage/lives of past genera- tions, showing marks of the time passage (patina) present on the forms, components, and materials.

When comparing the results of the surveys to site managers and users it is clear that there is significant convergence between both groups regarding the identification of attributes, vulnerabilities, and expectations, even if there are some aspects in which they diverge, likely due to the different nature of the relationship each has with the asset (the institutional/ operational perspective of the site managers and the user perspective of the visitors).

i) Regarding the most valued attributes (what they love), both respondent groups converge in the recognition of the 'integration into the landscape', 'modern architecture', 'views of the sea', the 'fabric of the building', and the 'diversity of users'. Site managers highlighted the 'significance of the building in the collective memory' while the 'harmonious relationship with the rocks', the 'privacy of the building', and the 'conservation of the original design' were attributes solely recognized by users and visitors.

ii) Among the aspects they would prefer to change, both respondent groups converge on the need for 'more space for towels' and the bar being 'in use during the entire year'. Site ma-

nagers highlighted the need for 'accessibility improvements', 'more safety measures for children', the 'completion of the original design (restaurant)', and 'signage improvements to facilitate access', while users and visitors focused on the 'reduction of the entrance fees' and the need for 'more lighting in the changing rooms'.

iii) Finally, both respondent groups tend to imagine the building in the future 'exactly the same'. Site managers see it as a 'referential building of Matosinhos' with a 'greater number of visitors', while users and visitors seem to imagine it in 'good conservation condition', 'operational during the entire year', the 'completion of the original design (restaurant)', with 'more support infrastructure for visitors', with the 'implementation of new technologies' and continuing 'as National Monument'.

3.17 Justification of the values identification based on the cultural values taxonomy (Tarrafa Silva and Pereira Roders, 2012). 3.18 Imagine methodology cultural significance recognition results.





IMAGINE



73



3.4.2 Virtual community

Nowadays, virtual communities play a relevant role in the assessment of cultural heritage, as well as in the definition of policies and the broader discussion about heritage sites. Hence, social media is a powerful tool that generates dialogues between the most diverse actors, delivering data that communicates valuable aspects of different heritage sites through experiences and memories exposed in these community interaction networks (Ginzarly *et al.*, 2019, p. 1). The study of these platforms allows the identification of the landscape qualities spontaneously manifested by the community without directly relating the publication to heritage significance, which enables the emergence of values and attributes that might be hidden (Ginzarly *et al.*, 2019, p. 3-4).

The approach to social media was considered only to expand the sample of the first question (love) of adapted 'Imagine Ballarat' LCI questions, enabling the integration of general public perception by using the social network Instagram. Using the search tool to identify and group photos with specific tags (#) related to the Ocean Swimming Pool, each element of open-access publications, namely photographs, tags (#), and related comments, was coded to assess values and attributes ascribed to the Ocean Swimming Pool (Dunkel, 2015; Ginzarly et al., 2019; Pettinati et al., 2021). In this case, four relevant tags were identified: #piscinadasmares (2,614 publications), #piscinadasmarés (824 publications), #piscinasdasmares (795 publications) and #piscinasdasmarés (205 publications). From these, one hundred images published over nine years (February 13, 2012 - March 26, 2021) were selected for analysis. Retrieved data was systematized according to: date of publication, URL of the publication, type of profile, photograph, tags (#), and description of the photograph's content.

Following the aforementioned taxonomy of cultural values, the attributes (tags) were translated to values, revealing that the virtual community was able to identify predominantly aesthetic, ecological, social, historic, and economic values.



3.4.3 Students

A word cloud activity was developed with Architecture Master students from the Faculty of Architecture of the University of Porto resorting to the Poll Everywhere platform during a conference concerning the Ocean Swimming Pool's conservation works. The Poll Everywhere app is an online polling platform that enables the creation of a dynamic space to respond to open or multiple-choice questions enhancing class participation and understanding through discussion, and presenting the results in real time. The 'Imagine Ballarat' questions were adapted as follows: students were asked to identify the three elements they love the most about the Ocean Swimming Pool (attributes) and then give three reasons why they should be protected (values). The final result, displayed through word clouds, reveals the most recognized attributes and values (figs, 3.21 and 3.22) that were later coded to integrate with other participatory results.

What do you LOVE the most about the Ocean Swimming Pool and what do you think should be protected? Identify 3 elements (attributes).

balneários vista tanque entrada balneários balneários tanque tan tanque tan tan tan tanque tanque ta

3.19 Social media analysis cultural significance

3.20 Justification of the values identification based on the cultural values taxonomy (Tarrafa

3.21 Word cloud activity results (attributes).3.22 Word cloud activity results (values).3.23 Word cloud activity cultural significance

recognition results.

recognition results.

Silva and Pereira Roders, 2012).

3.21

PICTURE	ATTRIBUTE (TAGS)	VALUE	PARAMETER
	architecture pool building siza	Aesthetic	It represents the original product of creativity and imagination, which might hold a creator's signature.
	landscape sea views	Ecological	It represents harmony between the building and its environment (natural and artificial).
	memories community experience	Social	It can evidence memory and personal life experiences, showing notions related to cultural identity, a sense of "place attachment" and communal value.
	modern architecture	Historic	It is part of a few or unique testimonies of stylistic or artistic move- ments, which are now part of history.
Piscina De marks	pool use function entertainment tourism	Economic	It shows the function of the asset, identified by the role for the tourism industry, such as being oriented to a financial promotion of the property.

3.20

The word cloud activity revealed that the swimming pool (*piscina*), the fabric (*materialidade*), concrete (*betão*), paths (*percursos*), and nature (*natureza*) were among the most identified attributes. Unlike the other participatory activities, besides being asked what they love about the Ocean Swimming Pool, students had to identify the reasons for the protection of the identified attributes. Therefore, the transposition for the Tarrafa Silva and Pereira Roders (2012) taxonomy of cultural values was, for this case specifically, based on the recognized values instead of the attributes. Following the aforementioned taxonomy of cultural values, the results reveal that the students were able to identify predominantly aesthetic and social values, even if historic, political, ecological, and age values were also recognized.



WHY do you love these elements and consider they should be protected? Identify 3 reasons (values).

EXPRESSION	VALUE	PARAMETER
Heritage (Património)	Political	It represents part of strategies and policies, as well as strategies for the dissemination of cultural awareness.
Cultural	Social Historic	It can evidence memory and personal life experiences, showing no- tions related to cultural identity, a sense of "place attachment" and communal value.
		It is a heritage asset that retains conceptual signs (architectural, urban planning, etc.), which are now part of history.
History (História)	Historic	It is a heritage asset that retains conceptual signs (architectural, urban planning, etc.), which are now part of history.
Aesthetical (Estético)	Aesthetic	It represents the original product of creativity and imagination, whi- ch might hold a creator's signature.
Collective memory (Memória colectiva)	Social	It can evidence memory and personal life experiences, showing no- tions related to cultural identity, a sense of "place attachment" and communal value.
Signs of time passage (Sinais do tempo)	Age	Exhibits marks of the time passage (patina) present on the forms, components, and materials.
Artistic (Artístico)	Aesthetic	It represents the original product of creativity and imagination, whi- ch might hold a creator's signature.
Contrasts (Constrastes)	Aesthetic	It is the integral materialization of conceptual intentions, implying a conceptual background.
Light/dark (Claro/escuro)	Aesthetic	It is the integral materialization of conceptual intentions, implying a conceptual background.
Identity (Identidade)	Social	It can evidence memory and personal life experiences, showing no- tions related to cultural identity, a sense of "place attachment" and communal value.
Interior/exterior	Aesthetic	It is the integral materialization of conceptual intentions, implying a conceptual background.
Spatial perception (Percepção espacial)	Aesthetic	It is the integral materialization of conceptual intentions, implying a conceptual background.
Artistic/cultural (Artístico-cultural)	Aesthetic	It represents the original product of creativity and imagination, whi- ch might hold a creator's signature.
Simbolic (Simbólico)	Political	Exhibits the education role that heritage assets may play, using it for political targets.
Urban (Urbano)	Ecological	It represents harmony between the building and its environment (natural and artificial).
Landscape (Paisagístico)	Ecological	It represents harmony between the building and its environment (natural and artificial).

3.24 Justification of the values identification based on the cultural values taxonomy (Tarrafa

3.25 Drawing activity with children, 2021.

3.26 Drawing activity with children, 2021.

3.27 Justification of the values identification based on the cultural values taxonomy (Tarrafa

Silva and Pereira Roders, 2012).

Silva and Pereira Roders, 2012).

3.24

3.4.4 Children

The Ocean Swimming Pool is visited by many children du-Results revealed a pattern related to the pool and its surrounring the bathing season, in the context of leisure, sports, dings, highlighting their relationship. An extensive analysis of school, and other activities among family and friends. For the activity results demonstrated that children enjoy natural this reason, they are a public that cannot be ignored when elements such as water and rocks pointing its 'integration into assessing cultural significance. Children's engagement with the landscape' (50%), the 'views of the sea' (24%), evidencing the identification of attributes and values took place through also the 'architecture' (10%) of the site by showing the lines on-site drawing activities during the bathing season of 2021 and geometry of the pool in the drawings. In addition, they of-(figs. 3.25 and 3.26). Hence, it was possible to approach chilten represented themselves enjoying the swimming pool in dren aged between 5 to 13 years old, which visited the site the company of friends and family engaging the 'significance in summer activity groups, with schools, or accompanied of the building in the collective memory' (16%). The drawings by their families. In this case, only the 'love' question from express the desire to maintain the site as it is now, imagining the 'Imagine Ballarat' methodology was possible to retrieve. it exactly as it is in the future. Therefore, it can be deduced Despite that, this allowed us to include in the assessment of that in this activity, kids highlighted the ecological, social, and significance a group normally disregarded, but with an imaesthetic values as the main heritage values of the property. portant and very direct unbiased perspective.



3.25

VALUE	
Aesthetic Ecological	It is the integra tual backgroun It represents and artificial).
Aesthetic	It is the integra tual backgrou
Aesthetic Ecological	It is the integra tual backgroun It represents I and artificial).
Social	It can evidenc lated to cultura
	VALUE Aesthetic Ecological Aesthetic Ecological Social

3.27

3.26

PARAMETER

al materialization of conceptual intentions, implying a concepnd.

harmony between the building and its environment (natural

al materialization of conceptual intentions, implying a concepnd.

al materialization of conceptual intentions, implying a concepnd.

harmony between the building and its environment (natural

e memory and personal life experiences, showing notions real identity, a sense of "place attachment" and communal value.

3.5 Dissemination activities

Even if not specifically targeted at assessing significance as the aforementioned participatory activities, there have been numerous dissemination initiatives, such as a dedicated exhibition, guided visits, international symposiums, and publications, that have proven to be very important, not only for raising public awareness and discussion on the Ocean Swimming Pool, but also for collecting information to inform the significance assessment.

Sharing Memories webinar

The Sharing Memories webinar took place on September 9, 2021, organized by the Faculty of Architecture of the University of Porto together with the Municipal Council of Matosinhos and Casa da Arquitectura.

The webinar aimed at sharing different records and memories related to the Ocean Swimming Pool almost sixty years after its inauguration. Over thirty speakers were invited from various fields of study such as architecture, photography, history, and journalism: João Pedro Xavier, Fernando Rocha, Nuno Sampaio, Susan Macdonald, Álvaro Siza, Pierluigi Nicolin, Giovanni Chiaramonte, Dominique Machabert, Brigite Fleck, Nuno Grande, Peter Testa, Wilfred Wang, Christian Gänshirt, Jonathan Sergison, Luis Martínez Santamaría, Juan Domingo Santo, Michel Touissant, Luís Urbano, Alexandre Alves Costa, Joaquim Moreno, Eduardo Fernandes, Roberto Cremascoli, Filipa Guerreiro, José Cabral Dias, Ana Alves Costa, Teresa Novais, Carlos Machado, Pedro Leão Neto, Nuno Brandão Costa, Ana Tostões, Teresa Cunha Ferreira, and Rui Póvoas.

The webinar allowed to collect the participants' different testimonies, from period photographs and drawings to personal remarks and childhood memories of the building. This activity revealed multiple perspectives, impressions, and values of the Ocean Swimming Pool through the personal memories of each participant.

Following the webinar, the book *Sharing Memories*. *Álvaro Siza: Ocean Swimming Pool (1960-2021)* gathers the contributions of renowned national and international authors who, with different approaches, bring us their memories, experiences, and reflections. The volume is structured into five chapters - with unavoidable overlapping and contaminations - "Context and references", "From history to memories", "Critical perspectives", "Lessons from the Pool" and "Representations of the Pool", providing renewed perspectives and readings on this referential work of 20th-century architecture.

Exhibition

The Exhibition NO PLACE IS DESERTED. Álvaro Siza: Ocean Swimming Pool (1960-2021) draws upon Álvaro Siza's famous aphorism on the multiplicity of references (natural, topographical, built, immaterial) an architect finds on site that provides a creative catalyst for the design. It sought to illustrate the multiple lives of one of the most emblematic works of 20th-century architecture through a set of drawings, photographs, audiovisual materials, models, and objects – many previously unpublished – to put together a critical narrative of the design, construction, and conservation processes that have been taking place over the last six decades.

Documentary film

The documentary film *Life between Tides*, directed by Teresa Cunha Ferreira, collects a series of interviews with different building actors (Álvaro Siza), site managers (Manuela Batista, Pedro Machado), and academics (Paulo Lourenço, Nuno Mendes) as well as a detailed report on the recent conservation and extension works. It is structured in three parts embracing the complete life cycle of the building: i) original design, ii) recent conservation, iii) management and maintenance.

Guided visits

In the Open House Porto during a weekend, the public is invited, completely free of charge, to discover an itinerary proposed by the curator of the event. Each participant is able to create a tailor-made itinerary, exploring architecture and the city through a new perspective. In 2021 and 2022, under this initiative, the project leader Teresa Cunha Ferreira was invited to guide visits to the Ocean Swimming Pool focused on the design process and recent conservation interventions, as well as the work developed under the Keeping It Modern grant. At the end of the visits, participants were invited to fill in the aforementioned surveys (attributes, vulnerabilities, expectations).

- 3.28 NO PLACE IS DESERTED. Álvaro Siza: Ocean Swimming Pool (1960-2021) exhibition.
- 3.29 Exhibition detail, 2022.
- 3.30 Exhibition announcement, 2022.
- 3.31 Exhibition opening, 2022.
- 3.32 Life between Tides documentary film, 2021.
- 3.33 Ocean Swimming Pool guided visit during
- Porto Open House, 2022.



3.28

3







3.29















3.38





3.37



3.39



3.40

Symposium Recognising and Managing 20th Century Heri tage

The symposium Recognising and Managing 20th Century Heritage took place on June 30, 2022, at the Serralves Foundation library, organized by FAUP and the ICOMOS Twentieth Century Heritage International Scientific Committee (ISC20C), in partnership with ICOMOS Portugal and the Getty Foundation. The meeting was part of the Keeping It Modern: Ocean Swimming Pool project, funded by the Getty Foundation, the Siza ATLAS: Filling the gaps for World Heritage project, funded by the Foundation for Science and Technology (FCT), and the UNESCO Chair Heritage, Cities and Landscapes. Sustainable Management, Conservation, Planning and Design.

3.34 Recognising and Managing 20th Century Heritage Symposium announcement, 2022.
3.35 Recognising and Managing 20th Century Heritage Symposium, 2022.

3.36 Restaurer les bétons/ Conserving Concrete Symposium announcement, 2022.

3.37 Restaurer les bétons/ Conserving Concrete Symposium, 2022.

3.38 Sharing Memories. Álvaro Siza: Ocean Swimming Pool (1960-2021) book launch announcement, 2022.

3.39 Sharing Memories. Álvaro Siza: Ocean Swimming Pool (1960-2021) book launch, 2022.
3.40 Collection of publications on the Ocean Swimming Pool, 2022.

Principios de Projeto Piscina de Marés		Conversas Piscina de Marés	
	Álvaro Siza		Álvaro Siza
Design Principles Ocean Swimming Pool		Conversations Ocean Swimming Pool	
	1960-2021		1960-2021
Approximate State		Monto Licos	

Symposium Recognising and Managing 20th Century Heri- Symposium Restaurer les bétons/ Conserving concrete

The symposium Restaurer les bétons/ Conserving concrete took place on July 1st, 2022 at the Fernando Távora Auditorium, organized by FAUP and ICOMOS France, in partnership with the ICOMOS Twentieth Century Heritage International Scientific Committee (ISC20C) and ICOMOS Portugal. The meeting was part of the project funded by the Getty Foundation Keeping It Modern: Ocean Swimming Pool, the FCT project Siza ATLAS: Filling the gaps for World Heritage, and the UNESCO Chair Heritage, Cities and Landscapes. Sustainable Management, Conservation, Planning and Design. The symposium included a lecture by Álvaro Siza on the Ocean Swimming Pool.

Books and articles

Under the Keeping it Modern grant, the project leader Teresa Cunha Ferreira organized a collection of publications on the Ocean Swimming Pool, aiming at broadening knowledge and making the collected information available to the general public. Among them there is the catalogue of the exhibition that took place in the Faculty of Architecture of the University of Porto between May and July 2022, named NO PLACE IS DE-SERTED. Álvaro Siza: Ocean Swimming Pool (1960-2021) and co-edited by Luís Urbano; the collection of essays presented on the Sharing Memories webinar in September 2021, Sharing Memories. Álvaro Siza: Ocean Swimming Pool (1960-2021); Design Principles. Álvaro Siza: Ocean Swimming Pool (1960-2021); and Conversations. Álvaro Siza: Ocean Swimming Pool (1960-2021), a critical exercise aiming at clarifying Siza's fundamental principles behind his designs to serve as a permanent reference for future readings or interventions on his works.

Besides these books, other articles have been published or submitted to public presentations in congresses, conferences, journals, or books. For further information on publications see the website (https://oceanswimmingpool.cargo.site to be migrated to https://sizaoceanswimmingpool.arq.up.pt).

3

3.6 Discussion of significance

3.6.1 Comparative discussion

The definition of cultural significance corresponds to the sum of the values attributed by the deemed actors of the heritage site. Hence, the declaration of cultural significance results from identifying the heritage attributes and values of the place, supported by content analysis techniques applied to evaluating related documentation, on-site information, and the analysis of the outcomes from the various participatory strategies presented previously. The identification of attributes of a place allows us to recognize its significance and facilitates the planning and establishment of policies and action measures in favor of maintaining the values defined by the different users. As a result, different measures are established to adapt and develop an action plan emphasizing the care of the site values.

Figure 3.41 summarizes the cultural significance recognized by all the actors involved in the current assessment, understanding attributes as the characteristics or qualities of the property, i.e., what should be conserved and the values supporting the conservation decision (why). This assessment resulted from a thematic analysis of all the data collected using various methods according to each actor, coding results according to the adapted cultural values taxonomy from Tarrafa Silva and Pereira Roders (2012).

The social, aesthetical, and ecological values emerged as the most referenced values identified by all the assessed groups in this paper. If, on the one hand, the identification of social values by both experts (site managers) and non-expert communities contradicts the theory formulated by Wagenaar *et al.* (2023), as exclusive for non-expert communities, on the other hand, the identification of aesthetical and historic values by the majority (the last except by children group) sustain the idea that the values traditionally associated with the Authorized Heritage Discourse (Smith & Waterton, 2012) can also be found in non-experts perceptions. The consensus over ecological value, from site managers to virtual community, along with the social and aesthetical values, may be related to the

experience of landscape and the connection with the natural attributes. However, declarations of the virtual community tend to be more abstract – because they lack daily experience (or are based on single visits) – and, because of that, are more relatable with "common sense", which is prone to reinforce already listed justifications. This is somehow shared by students, which, in a similar way, are more attentive to design qualities and materials.

The scientific value was only identified in site managers and users and visitors revealing. The first emerged probably due to the nature of their professional link to the place, being more concerned with the need to ensure the correct functioning of the building. Along with the social, these values are embodied through their daily work by the recognition of the quality of the facility to embrace users' diversity and the outstanding technical innovation from the time the building was built. The identification of those technological values by users and visitors, mainly visitors, is probably related to the fact that some of the surveys were implemented during an experts-organized visit (Open House). This strong influence by expert perspective also may justify the exclusive identification of age values by the groups of users/visitors and the architecture students. On the other hand, users develop affectionate memories of family gatherings, events, and activities that enable the "sense of place" and sustain the "sense of time".

The economic and political values were only mentioned by one group each, virtual community and students, respectively. The economic value as related to property's use is highly valuable to the broader community, in the way that valorises the possibility of still visiting and using the place in its original function, which is also very relatable for tourists. Lastly, the exclusive identification of the political value by the students is also related to the bias and the pre-knowledge related to the works of the architect and the awareness of this importance in the conference that the poll was applied.

		VALUES							
ACTOR GROUPS	ATTRIBUTES	Social	Economic	Political	Historic	Aesthetic	Scientific	Age	Ecological
Institutional (listing justification)	Concrete shapes; Beach wall (linear and uninterrupted form, paths and geometry, landscape frame); Building (entire asset); relationship with the land and coastal context.								
Experts (architects and critics)	Role in the communities identity and collective memory; In continuous use for almost 60 years; Part of a political tourism driven transformation strategy; Significant contribution in the context of the revision of the Modern Movement; Design responsive to the specificities of place merged with a synthesis of international references; Pioneering use of exposed concrete in the Portuguese context; Patinas and concrete anomalies were maintained as signs of the passage of time; Landscape integration.								
Site managers (Municipal Council, Matosinhos Sport and building staff)	Integration into the landscape; modern architecture; views of the sea; significance in the collective memory; fabric of the buil- ding, diversity of users.								
Users and visitors	Integration into the landscape; harmonious relationship with the rocks; modern architecture; views of the sea; significance in the collective memory; fabric of the building; diversity of users; privacy of the building; conservation of the original design.								
Virtual community	Memories; community; experience; pool use; function; enter- tainment; tourism; modern architecture; architecture; pool; buil- ding; siza; landscape; sea views.								
Students	Pool; material; architecture; users; view; concrete; landscape.								
Children	Pool; landscape; sea; users; memories.								

3.41 Ocean Swimming Pool cultural significance according to each of the inquired actor groups.

Social significance

Being an extremely popular leisure area and meeting place for both locals and visitors, the Ocean Swimming Pool has become a social and cultural landmark for the community. Its social significance is rooted in the strong relationship local communities have established with the place since its construction, being an indissociable element of their identities and occupying an unmistakable place in their collective memory and experience. As it became clear in the inquiries to all the actors groups, the site is seen as part of the city's identity and is present in the memories of multiple generations of locals, highlighting the importance of the social value.

Economic significance

The Ocean Swimming Pool has been in operation for more than fifty years under its original function, thus retaining its economic significance. Even though it is only fully open to the public during the bathing season, it is visited by more than sixty thousand people every year, representing an income source to the Municipal Council that is not negligible as bathers and visitors are charged entrance fees. During the rest of the year the site is only open for booked guided tours hosted by Casa da Arquitectura to answer the interest the building sparks both on a national and international level, being one of the most sought-after attractions in Matosinhos. Even though the actor groups' answers do not clearly identify the economic value, it is implicit as many of the values identified depend on the fact that the Ocean Swimming Pool remains in continuous use by the communities.

Political significance

The construction of the Ocean Swimming Pool, promoted by Fernando Pinto de Oliveira who was the President of the Municipal Council of Matosinhos from 1958 until 1970, was part of a broader redevelopment strategy of the seafront that aimed at transforming Leça da Palmeira into a relevant tourist destination. The understanding of the Municipal Council regarding the importance of the Ocean Swimming Pool to the city remained unchanged until today as the recent investment in the building conservation and extension works testify. Its political significance was enhanced by its listing as National Monument in 2011 by the Directorate-General for Cultural Heritage (DGPC), the national government agency responsible for the implementation of heritage protection legislation and the listing of national interest assets.

Historic significance

The Ocean Swimming Pool has a remarkable historic significance as it was a work in which Álvaro Siza introduced ideas not yet tried and closely related to the place. It reflects quite clearly the debates that were taking place at the time, revisiting Frank Lloyd Wright's fluidity and flexibility in the succession of spaces, or Le Corbusier's 'promenade architecturale' in the sequence of spaces thought of as a route, while employing, at the same time, a raw materiality in line with the brutalist movement, then emerging. Soon after its construction, it was considered a masterpiece by leading international architecture critics because of its modernity and organic integration into the surrounding landscape. There are more than eighty publications dedicated to it in different languages, transmitting the significance of the site and the international influence of the architect. Thus, the Ocean Swimming Pool stands out as a referential work in the context of the revision of the Modern Movement. Most of the inquired actors groups consider the historic significance one of the most relevant values of the place.

Aesthetic significance

The concept of aesthetical value is closely related to creati-Built almost sixty years ago, the Ocean Swimming Pool vity, imagination, and the product of a creator (Tarrafa Silva emerged with a new vision of society and well-being maniand Pereira Roders. 2012). The Ocean Swimming Pool has a fested through modern programs such as tourism, leisure, remarkable aesthetic significance given its direct association and health infrastructures. The age significance is visible with the nationally and internationally acclaimed architect Álthroughout the complex in the patinas that several materials varo Siza. He has approximately 500 designs and built works, exhibit as its material integrity has been maintained until to-19 honorary doctorates, hundreds of dedicated publications. day. Furthermore, during the recent conservation intervenand more than 100 distinctions and awards (including the Mies tion, Álvaro Siza decided to keep all the concrete cracks that Van der Rohe Award in 1988, the Alvar Aalto Medal in 1988. did not present any structural risks open as signs of the pasthe Pritzker Prize in 1992, the Golden Lion for the Best Project sage of time. Despite its importance, the specificity of the age in 2002 and the lifetime achievement award (Venice Biennale. value makes difficult its immediate identification by most of 2012), the Royal Gold Medal for Architecture in 2008, the Luthe inquired actors groups. so-Spanish prize for Art and Culture in 2010, among others). This Ocean Swimming Pool, built between 1960 and 1973, was one of his first projects, being faithful to the architect's style **Ecological significance** and signature, where the combination of nature and moder-The Ocean Swimming Pool's ecological significance rests nist elements stand out. All inquired actors groups indicate upon its harmonious integration within the topography and the representation of Modernist aesthetic features as one of surrounding landscape. The intervention takes into account the most relevant values of the place.

Scientific significance

The Ocean Swimming Pool's scientific significance is related to the expertise of engineer Bernardo Ferrão who employed a series of innovative building solutions. It is one of the first exposed concrete constructions in Portugal, expressing engineering advances such as its hydraulic infrastructure and seawater collection system or the building tectonics of brutalist expression, using raw materials such as exposed concrete, Baltic pine, and copper. Despite its importance, the specificity of the scientific value makes difficult its immediate identification by most of the inquired actors groups.

Age significance

the horizontality of the site and incorporates it in the design, with the building mediating the transition between the coastal road and the natural extension of beaches. The architect takes advantage of the site's natural configuration to insert the swimming pools amongst the rock outcrops with minimum intervention. This value was mentioned by all inquired actors, from experts to visitors, as one of the key features that should be preserved for further generations.

3.6.2 Integrity and authenticity

Integrity

The integrity of a heritage place encompasses a multiplicity of factors such as buildings, interiors and collections, immediate landscapes, and wider settings. The Ocean Swimming Pool retains a very high degree of integrity as it is maintained in good condition, including all elements necessary to express its values and significance. The building itself retains a high degree of original fabric, including interior fittings and fixtures. Even though the wider landscape has changed significantly, the immediate coastal setting too is largely intact.

The property limits defined by the Buffer Zone include all the necessary elements that express the significance of the Ocean Swimming Pool, namely the access ramp, the changing rooms' building, the beach pathways and platforms, the two swimming pools, and the immediate surroundings, essential to the property's distinctive setting. The building did not suffer any significant change during its lifetime aside from the reconstruction and extension of the north area (2018-2021) carried out by Álvaro Siza, respecting the original design and fabric.

The repair of concrete elements implied the removal of previous inadequate interventions that were affecting the integrity of the original texture and color. In some cases, the cracks were repaired with a carefully studied mortar to blend in with the original material. In other cases, when there were no structural implications, the cracks were left exposed as signs of the natural aging of the building. Only when strictly unavoidable were concrete elements replaced, with close attention to the preexisting concrete color and texture, as was the case of the south storage room's roof slab that presented a severe state of decay. These interventions, monitored by Álvaro Siza, had no impact on the building's integrity, given that the new concrete elements will blend in with the existing ones over time.

The Buffer Zone's limits include the extended landscape from the north jetty of the Leixões Port to the Boa Nova Tea House and Restaurant. In this way, the views from the site toward the surrounding landscape are protected. On the other hand, the urban development on the other side of the seaside has negatively affected these views, interrupting the horizontal relationship between land and sea. Currently, the Ocean Swimming Pool does not have development threats since the dismissal of the oil refinery that was located in the vicinity.



3.42

86

Authenticity

An authentic place is the honest product of its history, where there has been no adverse impact upon its fabric or the reasons for which it is considered significant. From the extensive archival sources documenting the design, construction, and subsequent developments until the present day, it can be concluded that the Ocean Swimming Pool has a very high degree of authenticity which must be respected when managing change. The Ocean Swimming Pool's authenticity was assessed according to the categories defined by the Nara Document on Authenticity (UNESCO, 1994):

Form and design: The Ocean Swimming Pool mantains the overall authenticity of form and design over time. The conservation works carried out recently by Álvaro Siza have followed the design principles of the original construction, while reversing some incorrect interventions that took place in the past, even if they never significantly affected the building's form and design.

Materials and substance: The Ocean Swimming Pool main-
tains most of the original materials. Although some materials
had to be replaced due to degradation, all the works were mo-
nitored by Álvaro Siza in close collaboration with specialists,
achieving a conservation work that maintains the substance
of the materials and their shape. The materials that were ad-
ded in the new project have been selected by the architect to
be in keeping with the originals.aspect in determining that the sensation and spint that is in-
ved in the building remains intact.Traditions, techniques and management systems: The Ocean
Swimming Pool maintains the original traditions, techniques
and management systems. The building's technical installa-
tions have been updated, including the replacement of the
water filters in the water treatment area, pipes, the electrical
wires and artificial lighting.

Use and function: The Ocean Swimming Pool maintains its original use and function with compatible contemporary

3.42 View towards west over the bar terrace, 2021.

adaptations. The pools fully maintain their original use and operation as they have such a specific program. Although today the pools carry out other types of events such as guided tours and some social events, the main function of the swimming pool remains unaltered.

Location and setting: The Ocean Swimming Pool urban context has undergone some changes due to real estate development. However, the Buffer Zone has protected the urban context from invasive interventions. Furthermore, its location bordering the sea assures visibility towards the coast and is maintained without the impact from external factors. The new interventions in the building have been carefully developed by the architect and are respectful of the specificities of the site.

Spirit and feeling: The Ocean Swimming Pool maintains an original and intimate relationship with nature, being in the rocky coastal area of Leça da Palmeira. The path that guides the visitors through different light intensities ensuring the transition between the urban and the natural is an important aspect in determining that the sensation and spirit that is lived in the building remains intact.

3

3.7 Levels of significance

The assessment of levels of significance is essential to plan and justify the decisions and actions to be taken. This evaluation establishes policies for conservation and treatment to maintain its tangible and intangible values.

However, the different spaces and components that contribute to its general significance have different levels of importance according to their attributes. For this purpose, the *Sydney Opera House Conservation Management Plan* (Croker, A. 2017) assessment of significance methodology was followed, adopting its five-level scale: i) Exceptional significance, which are the areas and elements fundamental to the cultural significance of the building, ii) high significance, areas and elements with a high cultural significance but not fundamental, iii) moderate significance, areas and elements that support other zones of greater significance, iv) some significance, which are invasive elements that change and alter the significant components of the place.

The definition of the levels of significance was informed by the interviews conducted with the Municipal Council Departments, document consultation, on-site observation, and the information collected in community surveys. This study methodology provides a global knowledge to determine an accurate definition of the building's cultural significance.

The spaces of exceptional and high level of significance are defined as the ones that respect original design and function at a high level showing a strong aesthetic and social value. In this case, the spaces correspond to the entrance ramp, chan-

ging rooms, changing rooms' hallway, adults and children swimming pools, foot washes, beach and access paths, cloakroom, south bathrooms, south platform, bar, terrace, west platform, and north platform.

The spaces of moderate and some significance in the building are defined as the spaces that have no relevance on their own but as a support area. These spaces correspond to the collective changing room, water treatment room and chlorine cabinet, security room, south storage rooms, kitchen, north bathrooms, water collection room, employee's changing rooms and bathrooms, north storage room, and waste management room.

Concerning the intrusive level, the Ocean Swimming Pool does not have any area that affects or diminishes its level of cultural significance. Furthermore, although invasive interventions were carried out on elements and components of the building, these actions were corrected in the last intervention carried out by Álvaro Siza. Therefore, today, there are no elements that negatively affect the building.

Having identified the levels of cultural significance according to spaces, it is now possible to develop the tolerance for change assessment that each one has. This evaluation will enable the definition of opportunities and future action plans for the adequate conservation of the property, creating an objective framework in the decision-making orientation on a scale of priorities seeking to maintain the integrity and authenticity of the place as much as possible.

<u> </u>	
	Exceptional significance
	High significance
	Moderate significance
	Some significance
3.4	3
	LEVEL OF SIGNIFICANCE
E	ceptional significance
н	igh significance
M	oderate significance

3.43 Ocean Swimming Pool levels of significance.3.44 Building areas according to the level of significance.

3.44



BUILDING AREAS

- Entrance ramp (3)
- Changing rooms (4/5)
- Changing rooms' hallway (7)
- Adults swimming pool (1)
- Children swimming pool (2)
- Foot washes
- Beach and access paths (12)
- Cloakroom (6)
- South bathrooms (11)
- South platform (13)
- Bar (14)
- Terrace (16)
- West platform (20)
- North platform (21)
- Collective changing room (8)
- Water treatment room and chlorine cabinet (10)
- Security room (17)
- South storage rooms (18)
- Kitchen (15)
- North bathrooms (22)
- Water collection room (19)
- Employee's changing rooms and bathrooms (23)
- North storage room and waste management room (24)

3.8 Statement of significance

This statement of significance summarizes the key heritage values of the Ocean Swimming Pool as identified and assessed in the preceding sections.

context of the revision of the Modern Movement, both on a debates that were taking place at the time, revisiting modernist ideas while employing, at the same time, a raw materiality in line with the brutalist movement, then emerging.

The Ocean Swimming Pool was considered a masterpie-ce by leading international architecture critics because of The Ocean Swimming Pool has a unique setting and reflects its modernity and organic integration into the surrounding a harmonious integration within the topography and surroulandscape. There are more than eighty publications dedicanding landscape. The architect took advantage of the site's ted to it in different languages, transmitting the significance natural configuration to insert the buildings and swimming of the site and the influence of the architect on an internatiopools amongst the rock outcrops with minimum intervention. nal level.

The Ocean Swimming Pool has become a place of international pilgrimage for architects and designers. Hence, since its construction, it has been extensively photographed, filmed, and written about, demonstrating the influence of Álvaro Siza in the context of 20th-century architecture.

The Ocean Swimming Pool is visited every year by an excess The Ocean Swimming Pool's recent conservation and exof sixty thousand people, being one of the most sought-after tension works (2018-2021) led by Álvaro Siza represent an exceptional case of an architect preserving his own work attractions in Matosinhos. while enhancing its significance by remaining faithful to the building's attributes and the design principles behind the original design. The Ocean Swimming Pool marked a turning point in Álvaro

Siza's career by expressing a tectonic shift from regionalist inspired designs towards a more abstract language and innovative constructive solutions.

The Ocean Swimming Pool is one of the first constructions in exposed concrete in Portugal, employing innovative construction systems such as its plumbing and seawater collec-tion system or the tectonics of brutalist expression, using raw materials. Hence, the constructive elements, together with the infrastructures, furniture, and details, were all conceived as a 'total work of art'.

The Ocean Swimming Pool is an outstanding work within the The Ocean Swimming Pool showcases the emergence of modern programs such as tourism, leisure, and health innational and international level. It reflects quite clearly the frastructures during the 1960s as a result of a new vision of society focused on well-being. It formed part of a broader redevelopment strategy of the seafront conducted by the Municipal Council that aimed at transforming Leça da Palmeira into a relevant tourist destination.

> The Ocean Swimming Pool has been in full use for almost sixty years, becoming a social and cultural landmark for the community. Its popularity is deeply rooted in the strong relationship local communities have established with the building since its construction, occupying an unmistakable place in their collective memory.

> The Ocean Swimming Pool's material integrity has been maintained, despite its significant exposure to extreme weather phenomena. During the recent conservation intervention, Álvaro Siza decided to keep the signs of the passage of time such as patinas and cracks as evidence of the material history of the building.

> The Ocean Swimming Pool is included in the Tentative List for World Heritage Status as a component property of 'Álvaro Siza's Architecture Works in Portugal' and is listed as National Monument for its architectural, urbanistic, and landscape values.

References

Bandarin, F. and Oers, R.V. (2014) Reconnecting the city: the historic urban landscape approach and the future of urban heritage. Oxford: Wiley Blackwell

Blok, J. M. (2019) A sustainable policy response to urban shrinkage in a world heritage city: the case study of Porto (Master Thesis). Eindhoven: Eindhoven University of Technology

Burke, S. et al. (2018) Eames House Conservation Management Plan. Los Angeles: Getty Conservation Institute. Available at: https://hdl.handle.net/10020/gci_pubs/eames_cmp (Accessed: 10 January 2021)

City of Ballarat (2013) Ballarat Imagine. What You Said. Ballarat. Available at: https://www.ballarat.vic.gov.au/media/1726952/ballarat_imagine_summary_report_v5_final.pdf. (Accessed: 10 January 2021)

Society (Faro Convention). Faro: Council of Europe

Court, S. and Wijesuriva, G. (2015) People-centred approaches to the conservation of cultural heritage: Living heritage. Rome: ICCROM

Croker, A. et al. (2017) Sydney Opera House Conservation Management Plan. Sydney: Heritage Council of New South Wales. Available at: https://www.svdnevoperahouse.com/ content/dam/pdfs/conservation-management-plan/soh-cmp-printable-1.pdf (Accessed: 10 November 2022)

Decree No. 16/2011 (2011) Procede à classificação como monumentos nacionais da Casa do Passal, dos Concheiros de Muge, da Igreia do Carmo, do Terreiro da Batalha do Ameixial, do antigo Convento dos Eremitas de São Paulo da Serra de Ossa ou de Jesus Cristo, incluindo a cerca, do sistema de abastecimento de águas à cidade de Braga no século XVIII, designado por «Sete Fontes», da Casa de Chá da Boa Nova e das Piscinas de Marés de Leca da Palmeira. Available at: https://dre.pt/pesquisa/-/search/673416/details/maximized (Accessed: 10 January 2021)

Dunkel, A. (2015) "Visualizing the perceived Environment using crowdsourced photo geodata", Landscape and Urban Planning, 142

Fayad, S. and Buckley, K. (2019) "The transformational power of the HUL approach: Lessons from Ballarat, Australia, 2012-2017", in Roders, A. P. and Bandarin, F. (eds.) Reshaping Urban Conservation. Creativity, Heritage and the City, vol. 2. Singapore: Springer

Ferreira, T. C., Barbosa, F. and Fernandes, E. (2021)."Construction Culture between Tradition and Modernity: Three Works by Álvaro Siza" in Mateus, J. M. and Pires, P. (eds.) History of Construction Cultures. Proceedings of the Seventh International Congress on Construction History (7ICCH). Leiden: CRC Press/Balkema

Ferreira, T. C. and Fernandes, E. (2021). "Álvaro Siza's Tectonic Shift in Leça da Palmeira: From Design to Conservation", in Tostões, A. and Yamana Y. (eds.) 16th International Docomomo Conference. Inheritable Resilience: Sharing Values of Global Modernities, Tokvo: Docomomo

Ferreira, T. C. (2014) "Some considerations on the preservation of 20th-century architectural heritage" in Riso, V. (ed.) Modern building reuse: documentation, maintenance, recovery and renewal. Guimarães: EAUM, pp. 29-46. Available in http://repositorium.sdum.uminho.pt/handle/1822/28957 (Accessed: 10 January 2021)

Ginzarly, M. et al. (2019) "Mapping historic urban landscape values through social media", Journal of Cultural Heritage, 36

IAPXX (2006) Inguérito à Arguitectura do Século XX em Portugal. Available at: http://iap20.pt/Site/FrontOffice/default. aspx (Accessed: 10 November 2022)

ICOMOS Australia (2013) The Burra Charter: The Australia CoE (2005) Convention on the Value of Cultural Heritage for ICOMOS charter for places of cultural significance. Burwood: **ICOMOS** Australia

> ICOMOS ISCAH20 (2011) Approaches for the Conservation of Twentieth-Century Architectural Heritage (Madrid Document). Available at: http://orcp.hustoj.com/wp-content/ uploads/2016/04/madriddocumentenglish.pdf (Accessed: 10 January 2021)

> Innova Concrete (2019) 100 from the 20th - Innova Concrete selection of significant 20th century heritage sites in Europe. Available at: https://100of20.innovaconcrete.eu/ (Accessed: 10 November 2022)

> Jerome, P. (2009) "Restoring Frank Lloyd Wright's Solomon R. Guggenheim's Museum". Available at: https://www.aicomos. com/wp-content/uploads/2009_Unloved Modern_Jerome_ Pamela_Frank-Lloyd_Paper.pdf (Accessed: 9 February 2018)

> Law No. 107/2001 (2001) Lei de Bases do Património Cultural. Available at: http://www.pgdlisboa.pt/leis/lei mostra articulado.php?nid=844&tabela=leis (Accessed: 10 January 2021)

> Macdonald, S. (2013) "Modern Matters: Breaking the Barriers to Conserving Modern Heritage. Conservation Perspectives ", The Getty Conservation Institute Newsletter, 28

> Pettinati, L., Ferreira, T. C. and Marques, T. P. (2021). "Significado Cultural na Paisagem Histórica Urbana no Vale de Massarelos: a perceção das comunidades", in Costa, A. et al. (eds.) CONREA 2021 - O Congresso da Reabilitação. Aveiro: UA Editora

> Marsden, S. and Spearritt. P. (2021) The Twentieth-Century Historic Thematic Framework: A Tool for Assessing Heritage Places. With contributions from Leo Schmidt, Sheridan Burke, Gail Ostergren, Jeff Cody, and Chandler McCoy. Los Angeles: **Getty Conservation Institute**

> McDermott, M. (2012) Wet, wild and convivial : past, present and future contributions of Australia's ocean pools to surf, beach, pool and body cultures and recreational coasts (Doctorate Thesis). Perth: Faculty of Education and Arts/Edith Cowan University

McLachlan, J. (2019) "The Rise and Fall and Rise Again of Britain's Lidos". Available at: https://theculturetrip.com/europe/ united-kingdom/england/london/articles/the-rise-and-fall--and-rise-again-of-britains-lidos/ (Accessed: 28 July 2022)

Ordinance No. 608/2012 (2012) Zona Especial de Protecção da Casa de Chá da Boa Nova e Piscina de Marés de Leça da Palmeira. Available at: https://dre.pt/dre/detalhe/portaria/608-2012-3236601 (Accessed: 10 January 2021)

Permanent Delegation of Portugal to UNESCO (2017) Ensemble of Álvaro Siza's Architecture Works in Portugal. Available at: https://whc.unesco.org/en/tentativelists/6224/ (Accessed: 10 January 2021)

Siza, A. (2005) "Recuperação e Manutenção" in Costa, A. et al. (eds.) A intervenção no património. Práticas de conservação e reabilitação, Porto: FEUP

Siza, A. (2011) "Conferencia para el CAH20th", in Intervention Approaches in the 20th-Century Architectural Heritage, International Conference CAH20th, Madrid

Siza, A. (2017) "Entrevista a Álvaro Siza por T. C. Ferreira" in Veldpaus, L. (2015) Historic urban landscapes: framing the in-Ferreira, T. C. and Rocha, P. F. (coord.) Saber manter os edifítegration of urban heritage planning in multilevel governance. cios: pensar, desenhar, construir : manutenção dos edifícios Technische Universiteit Eindhoven da Faculdade de Arquitectura e da Faculdade de Engenharia Wagenaar, P., Rodenberg, J. and Rutgers, M. 2023. "The croda Universidade do Porto, Porto; Afrontamento/ CEAU-FAUP/ wding out of social values: on the reasons why social values CEES-FEUP

so consistently lose out to other values in heritage manage-Siza, A. (2018a) "Entrevista a Álvaro Siza por T. C. Ferreira", ment". International Journal of Heritage Studies, 29 (8), doi: Construção Magazine, 83 10.1080/13527258.2023.2220322

Siza, A. (2018b) Interview by T. C. Ferreira. Unpublished

SIPA (2011) Piscina de Marés de Leça da Palmeira. Available at: http://www.monumentos.gov.pt/Site/APP_PagesUser/ SIPA.aspx?id=20880 (Accessed: 10 November 2022)

Smith, L. and Waterton, E. (2012) Constrained by commonsense: the authorized heritage discourse in contemporary debate in R. Skeates, C. McDavid and J. Carman (eds.), The Oxford Handbook of Public Archaeology. Oxford: Oxford University Press, pp. 153-171

Tarrafa Silva, A. and Pereira Roders, A. (2012) "Cultural Heritage Management and Heritage (Impact) Assessments" in Michell, K., Bowen, P. and Cattell, K. (eds.) Proceedings of the Joint CIB W070, W092 & TG72 International Conference on Facilities Management, Procurement Systems and Public Private Partnership, Cape Town: Department of Construction Economics and Management. University of Cape Town. Available at: https://www.irbnet.de/daten/iconda/CIB_DC24053. pdf. ISBN: 978-0-620-50759-2. pp. 375-382. (Accessed: 10 January 2021)

Tarrafa Silva, A., Ferreira, T. C. and Pinto, L. (2018) "Towards a Historic Urban Landscape approach: community engagement through local population's perception on heritage values and attributes" in Amoeda, R. et al. (eds.) HERITAGE 2018. Proceedings of the 6th International Conference on Heritage and Sustainable Development (Universidad de Granada, 12-15 de Junho). Granada/Barcelos: Universidad de Granada/Green Lines Institute, pp. 295-306.

Tarrafa Silva, A, and Pereira Roders, A, (2021) Taxonomias do significado cultural do património: valores e atributos in Marado, C. A., Valente, T. and Bernardes, J. P. (eds.) Gestão do Património Cultural: experiências e desafios. Faro: University of Algarve. Available at: https://doi.org/10.34623/vt4s-7r64. (Accessed: 10 January 2022)

Tavares, A. (2012) "Prize-winning ruins". Available at: https:// www.domusweb.it/ en/ architecture/2012/03/14/ prizewinning-ruins.html (Accessed: 9 February 2018)

Testa, P. (2022). "Ocean Swimming Pool: An Eidetic Memory" in Ferreira, T. C. (ed.) Sharing Memories. Álvaro Siza: Ocean Swimming Pool (1960-2021), Porto: Afrontamento/ CEAU--FAUP

UNESCO (2011) Recommendation for the Historic Urban Landscape. Paris: UNESCO. Available at: https://whc.unesco. org/en/hul (Accessed: 10 January 2022)



4. CONDITION ASSESSMENT, CONSERVATION AND RISKS

- 4.1 Introduction
- 4.2 Inspection and diagnosis
- 4.3 Conservation interventions
- 4.4 Hazards, vulnerabilities and risks



4.1 Introduction

Chapter 4 assesses the physical condition of the Ocean Swimming Pool and identifies the vulnerabilities and hazards that may affect its future management and conservation. It is intended to provide an overall summary of the fabric's current conditions and a clear understanding of external factors, such as environmental or use-related pressures, which may affect the heritage significance of the place. The information gathered aims at informing the CMP's policy development which must address the identified vulnerabilities.

The chapter opens with a section on inspection and diagnosis (4.2), aimed at surveying damage, estimating material and geometric properties, and identifying degradation mechanisms. The third section (4.3) details the conservation interventions that took place between 2018 and 2021, including different pilot demonstrations for concrete repair. Finally, the last section focuses on the identification of hazards, vulnerability scenarios, and risk levels.

Inspection and diagnosis of the site's fabric was led by the engineers Paulo B. Lourenço, Nuno Mendes, and Javier Ortega from the University of Minho between 2020 and 2021. Besides a preliminary damage survey developed by the Faculty of Architecture of the University of Porto, evaluation of the out--of-plane deformations of the walls, and non-destructive and laboratory testing were conducted. The experimental campaign included: i) concrete carbonation testing; ii) laboratory tests to determine the mechanical properties of the concrete and steel rebars; iii) chloride content testing; iv) water penetration testing; v) concrete testing with Schmidt hammer; vi) sonic testing; vii) color analysis based on spectrophotometry and viii) Ground Penetrating Radar (GPR) testing.

Álvaro Siza selected specific locations for concrete repair, which were submitted to two different methodologies. The first were intervened using the Gray Concrete Restoration Method (GCR-Method) (Miranda, et al., 2021) to characterize the concrete surface, including the color and texture of the surface, to design the restoration mortar, to define the application and finishing procedures and to assess the intervention. This intervention was performed by a team from the Civil Engineering Research and Innovation for Sustainability (CERIS), composed of Judite Miranda, Jonatas Valença, Hugo Costa, and Eduardo Júlio. The second localized concrete repairs were conducted by the specialized conservator-restorer Pedro Antunes (Cinábrio Restauro).

The adopted risk, vulnerability, and hazard identification approach falls into the category of qualitative methods and combines the likelihood and severity of the selected hazard scenarios with the vulnerability levels that were identified to establish the risk levels. Although in a qualitative form, the vulnerability levels that are identified consider physical impacts and impacts on the cultural significance and values of the site.



4.2 Inspection and diagnosis

4.2.1 **Condition survey**

The inspection and diagnosis were aimed at surveying dama-The most evident signs of deterioration in the concrete walls ge, estimating material and geometric properties (concreare in the form of cracks, creating visible discontinuities in its te, cement paste, steel rebars, and timber), and identifying surface. Most of these cracks are not related to steel corromaterial degradation mechanisms. This task involved visual sion. The vertical cracks in the longitudinal walls seem to be inspection, scanning of the structure with a laser scanner and caused by shrinkage and/or thermal movements, as a result drone, as well as in-situ non-destructive and minor destrucof the absence of movement joints in the original design. Thetive tests and laboratory tests of samples extracted from the se were worsened by interventions performed by the Municistructure (concrete, cement paste, steel rebars, and timber). pal Council, namely the filling of the cracks with incompatible The in-situ tests and the samples were conducted and collecmortar (Portland cement mortar with limited compatibility. ted in parts of the structure built in different phases. reversibility, or aesthetic integration concerns) (fig. 4.11). Moreover, some concrete surfaces have small red/brown stains The visual inspection allowed us to verify that the building is from metal oxidation inside the concrete, which has deposiin a reasonable state of conservation, without interventions ted on the surface. In some beams, there are signs of spalling that have substantially altered its original form (figs. 4.2 and caused by the corrosion of steel rebars (fig. 4.4). The bottom 4.3). However, the building is at risk because of its maritisurface of the south storage room's roof slab was severely afme location which has aggravated concrete decay. Salt wafected by rebar corrosion (fig. 4.8). There is also damage aster and salt fog chlorides penetrate the concrete and cause sociated with pattern cracking (taking the form of a polygonal rebar corrosion, which consequently causes the cracking net, similar to a spider's web) caused by the addition, in the and spalling of concrete. Furthermore, repair campaigns 1980s, of a 4 cm concrete layer (with light mesh) over some conducted by the Municipal Council of Matosinhos since the walls, because of incompatibility with the preexisting concre-1980s have led to problems such as delamination, pattern te or shrinkage (fig. 4.5).

cracking, and staining.

The building and the swimming tanks are mainly built in good quality lightly reinforced concrete. In contrast, the beams and slabs are more heavily reinforced, which is where the main corrosion problems and subsequent spalling have been observed. Spalling also occasionally occurs at the top of the walls or in the swimming pool tanks, namely at the points where the tanks connect with the rocks. Regarding the concrete used in the building site there were different compositions; i) the cyclopean concrete walls were composed of granite stones, filled with 300kg cement per m³; ii) the foundation, the platforms pavements, and the bar's triangular terrace is made out of concrete with 250kg/m³ cement; iii) the concrete walls are reinforced with 10kg/m³ of steel in the retaining walls and 15kg/m³ in the remaining walls; iv) the concrete roof slabs in the north and south storage rooms have 52kg/m³ and 130kg/ m³ of steel, respectively; v) in the north area, there is a concrete beam (which extends to the retaining wall) that is reinforced with 190kg/m3 of steel (Mota, 1972).

4.1 Formwork texture of the east façade. 4.2 Ocean Swimming Pool west elevations damage mapping (following spreads). 4.3 Ocean Swimming Pool east, south and terrace elevations damage mapping (following spreads).

Some of the walls show signs of efflorescence in the form of a textured white stain, which is caused by the infiltration of water in the concrete. The building also suffers from localized spots displaying a chromatic change, caused by the rainwater running off the surface and leaving a deposit. There are also the effects of biological colonization growing on the concrete surface, which changes its texture and color.

The roof's copper cladding presents a green color due to oxidation and leakages have been identified, resulting from weather exposure and lack of maintenance. The roof's timber structure and the changing rooms' partition walls present localized detachment of the coating and an oily texture, which results from the excessive amounts of linseed oil used in its maintenance. The screws used for the timber structure show signs of oxidation, with brown textured spots on their surface.

Finally, the most notable deficiency in the building's use is related to the plumbing system, as many of the pipes of the water system have either been destroyed by corrosion or are clogged with sand, which means that they were compromising the Ocean Swimming Pool's functionality (closed to the public in 2018 and reopened in 2021).





1960-1961

Construction of the adults swimming pool in cyclopean concrete.

1962-1965

ging rooms building in lightly reinforced concrete, Baltic pine and copper roof.

1965-1972

Construction of the bar, north and south storage rooms, redefinition of the retaining walls and platforms in concrete and screed.

1972-1973 / 1995

Construction of the bar counter and south platform amphitheatre / conservation works on the copper roof and concrete walls.





Mineral deposit (dust)

Atmospheric dust deposit, formation of dark grey areas.

Causes: atmospheric particulate.







Causes: carbonation of concrete, atmospheric agents, corrosion of rebars.

Spalling



Detachment of concrete fragments. Causes: carbonation of concrete, presence of chlorides, rebar corrosion.

Causes: humidity by condensation.



Trickling

Superficial vertical tracks of diversified color. Causes: building morphology, atmospheric agents, air pollution.



Presence of light and dark green areas. Causes: porosity, elevated humidity indices,

Presence of vegetation on the surface. Causes: porosity, elevated humidity indices,

Irregularly shaped area and diverse color

Superficial vertical tracks of diversified color. Causes: building morphology, atmospheric agents, air pollution.









4.6



4.9

4.8

- 4.4 Concrete spalling (1).
- 4.5 Distributed crack pattern (2).
- 4.6 Vertical crack (3).
- 4.7 Efflorescence (4).
- 4.8 Exposed corroded rebars (5).
- 4.9 Rainwater run-off stains (6).



4.12



4.14

- 4.10 Biological colonization (7).
- 4.11 Incorrect repair interventions (8).
- 4.12 Corroded screws and oily texture of wooden elements (9).
- 4.13 Corroded water pipes (10).
- 4.14 Condition survey photographs location.



4.11



4.2.2 Non-destructive and laboratory testing

Evaluation of out-of-plane deformations

The diagnosis of the building included a laser scanner survey, which was used to evaluate the out-of-plane deformation of the concrete walls. In this first analysis, the out-of-plane deformations of the retaining wall and the main façade's North were evaluated. It is noted that the deformations were evaluated with respect to a theoretical vertical plane passing through the base of the wall, using colormaps and 2D cross-sections.

The results of this first analysis allow us to verify that the maximum out-of-plane deformation of the retaining wall is equal

to 28 mm and occurs at the cross-section W1_4 in the east direction (inwards) (fig. 4.15 and 4.17). The maximum out-of--plane deformation in the west direction (outwards) is equal to 12 mm (cross-section W1_18). In the main façade's North, the maximum out-of-plane deformation is equal to 34 mm and occurs at the cross-section W3_18 in the west direction (fig. 4.16 and 4.18). In the opposite direction, the maximum deformation of this wall is equal to 27 mm (cross-section W3_6). Although these deformations are low, the out-of-plane deformation of the other walls may be also evaluated in the future for further documentation.



4.15 Colormap of the retaining wall out-of-

plane deformation (section AA). 4.16 Colormap of the main façade north out-of-

plane deformation (section BB).

4.17 Cross sections of the retaining wall with the highest out-of-plane deformation.

4.18 Cross sections of the main façade north

with the highest out-of-plane deformation.

Concrete carbonation testing

termining the carbonation depth in the concrete. The carbonation depth is determined based on the reaction of the phe-Carbonation is a chemical process that causes a reduction in nolphthalein solution with the concrete (color of the surface), the alkalinity of the concrete and, consequently, corrosion in i.e. pink means non-carbonated concrete and grey means the steel rebars and damage to the concrete. This chemical carbonated concrete. The concrete cores were extracted process occurs when atmospheric carbon dioxide reacts with using a drilling machine with 110 mm of diameter (fig. 4.19 to the calcium hydroxide of the cement paste, producing cal-4.21). The phenolphthalein solution was prepared according cium carbonate and reducing the pH. Typically, the cement to EN 12390-12:2020 (CEN, 2020). paste no longer provides a passive environment, which protects the steel rebars, when the pH of the concrete reduces Figure 4.22 presents the concrete cores sprayed with the to about 9. In general, for very dry or saturated concrete, the phenolphthalein solution, and it is possible to observe that carbonation process is slow. It is noted that young concrete is the entire surface of all the concrete cores is pink, meaning a highly alkaline material with pH values around 12-13, protecthe concrete in these zones of the building is not carbonated. ting the steel rebars against corrosion. However, the concrete elements are located in an environ-

In the diagnosis, three zones of the building were selected to carry out in-situ concrete carbonation tests: (1) adults' tank (Phase 1 - exterior); (2) children's tank (Phase 2.1 - exterior); (c) water collection area (Phase 2.1 - interior). The tests involved the extraction of three concrete cores and the application of a phenolphthalein solution on the core's surface, aiming at de-









4.22

ment with high relative humidity and the carbonation testing with the phenolphthalein solution (simplified method) includes uncertainties. Thus, cement paste samples were collected and tested at the laboratory to conclude the carbonation of the concrete.



4.21



4.19 Concrete cores extraction in the adults tank.

4.20 Concrete cores extraction in the children tank

4.21 Concrete cores extraction in the water collection room

4.22 Extracted concrete cores after the application of the phenolphtalein solution.

Concrete and steel mechanical properties testing

The concrete cores extracted for the carbonation tests were used in the laboratory tests to determine the mechanical properties of the concrete. Ten cylindrical concrete specimens were prepared based on the EN 12390-1:2012 (CEN, 2012) (fig. 4.23), namely three specimens of the adults ' tank (T1.1; T1.2; T1.3), four specimens of the children's tank (T2.1; T2.2; T2.3; T2.4) and three specimens of the water collection area (I1: I2. I3). The area and density of the concrete specimens are presented in the table below (fig. 4.26). Two types of tests were carried out: (1) tests to determine Young's modulus based on the LNEC E397:1993 (LNEC, 1993) (fig. 4.25); (2) tests to determine the compressive strength based on the EN 12390-3:2019 (CEN, 2019). In the test planning, one concrete specimen of each zone was first tested in compression (destructive test) to estimate the compressive strength needed to perform the tests to determine Young's modulus. Then, these tests were performed for the remaining specimens, with the exception of the specimen T2.3 1. due to its low length. Finally, the specimens were tested in compression. The table below (fig. 4.26) presents the results of the laboratory tests carried out on the concrete specimens. The mean compressive strength is equal to 36 MPa, 24 MPa, and 23 MPa for the concrete of the adults' tank, children's tank, and water collection area. respectively. The compressive strength of the specimens with an I/d ratio (length/diameter) lower than 2 was corrected based on the correction factors presented in the ASMT C 42/C 42M (ASMT, 2013). The mean Young's modulus is equal to 39 GPa, 27 GPa, and 38 MPa for the concrete of the adults' tank, children's tank, and water collection area, respectively. It is noted that high values for the mechanical properties of the concrete specimens are expected since the concrete of these parts of the building corresponds to cyclopean concrete, with large stone aggregates. The external concrete walls present another type of concrete. However, no concrete cores could be extracted from the external walls, not to affect the original materials in visible areas.

Samples of steel rebars were also collected, namely at the top of the retaining wall, the adults' tank, and in the slab of the South's storage room. In the laboratory, one steel specimen of the rebar of the retaining wall (P1.1), three steel specimens of the rebars of the adults' tank (T1.1; T1.2; T1.3), and two steel specimens of the slab of the south storage room (A1; A2) were prepared and tested, aiming at determining the tensile strength of the steel (fig. 4.25). The tensile tests were carried out based on EN 10002-1:2001 (CEN, 2001). The P1.1 specimen presents corrosion (minimum diameter equal to 5.72 mm) and a tensile strength significantly lower (ultimate strength equal to 253 MPa) than the other specimens (fig. 4.27). The steel specimens of the adults' tank have a mean diameter equal to 6.30 mm (smooth rebars without significant corrosion) and ultimate strength equal to 397 MPa. The mean yield strength (fy,0.6fu) of these steel specimens is equal to 238 MPa (fig. 4.27), which allows us to conclude that this steel corresponds to the class A235 (Portuguese steel class for smooth rebars of normal ductility and yield strength equal or higher than 200 MPa). Finally, two rebars of the slab of the South's storage room present corrosion and have a mean diameter of 9.44 mm. The mean yield strength (fy,0.6fu) of these two steel specimens is equal to 294 MPa.

4.24	Tests to determine the concrete Young's
modu	lus and compressive strength.
4.25	Tests to determine the steel rebars tensile
streng	zth

4.23 Concrete specimens.

- 4.26 Properties of the concrete specimens.
- 4.27 Properties of the steel rebars specimens.



4.23

		Area	Density	Average density	F _{max}	fc	fm	Е	Em
Location	Specimen	[cm ²]	[kg/m³]	[kg/m³]	[kN]	[MPa]	[MPa]	[GPa]	[GPa]
Adults tank	T1.1	86.39	2345		325.90	37.72		-	
	T1.2	86.61	2361	2365	326.30	37.67	36.09	39.80	39.36
	T1.3	86.41	2390		284.10	32.88		38.92	
Children tank	T2.1	104.88	2298	2209	268.70	25.62	23.83	27.18	26.69
	T2.2	104.92	2127		331.10	27.25		-	
	T2.3_1	104.93	2131		273.30	22.22		-	
	T2.3_2	104.99	2281		212.50	20.24		26.19	
Water collection room	11	104.81	2271		250.30	23.20		34.18	
	12	105.03	2292	2298	250.20	23.29	23.03	42.33	38.28
	13	104.86	2331		257.20	22.60		-	

(Fmax: maximum force; fc: compressive strength; fm: mean compressive strength; E: Young's modulus; Em: mean Young's modulus) 4.26

Specimen	Diameter	Area	Fmax	fu	^f y,0.6fu	fy,0.2%
	[mm]	[cm ²]	[kN]	[MPa]	[MPa]	[MPa]
P1.1	5.72	0.26	6.49	252.56	151.54	143.52
T1.1	6.40	0.32	13.59	422.77	253.66	301.69
T1.2	6.16	0.30	11.16	375.00	225.00	294.75
T1.3	6.34	0.32	12.47	394.65	236.79	276.90
Average	6.30	0.31	12.41	397.48	238.49	291.11
A1	9.16	0.66	32.60	493.94	296.36	465.31
A2	9.71	0.74	36.09	487.70	292.62	487.47
Average	9.44	0.70	34.35	490.82	294.49	476.39

(Fmax: maximum force; fu: ultimate tensile strength; fy,0.6fu: yield tensile strength assuming the proof stress equal to 0.6 of the ultimate strength; fv.0.2%: yield tensile strength assuming the proof stress associated to the strain equal to 0.2%) 4.27





4.24

Chloride content testing

Under normal conditions, concrete provides protection that prevents the corrosion of the steel, mainly associated with the high pH of concrete and low electrical conductivity. However, during the lifetime of the reinforced concrete structure, external actions, such as the penetration of chlorides, can promote the electromechanical corrosion of the rebars, causing a reduction of the effective cross-section of the steel rebars and damage in the concrete. The penetration of chlorides is associated with environmental factors, such as the exposure of the building.

Since the building is located very close to the sea (sea water, salt fog, winds, and high relative humidity), samples of the concrete paste were collected and the chloride content was estimated based on chemical tests performed at the laboratory. The samples were collected at the adults' tank (T1.10; T1.20; T1.30), the children's tank (T2.10; T2.20; T2.10.B; T2.20.B), the water collection area (C10; C20; C30) and the bar (B10; B20; B30). The cement paste samples were collected using a drilling machine at different depths (from 10 cm to 30 cm, from the external surface), without contamination of the samples (fig. 4.27). In general, three samples of each zone were collected, with the exception of the children's tank where four samples were extracted (two at the external mortar layer, namely T2.10 and T2.20, and two at the original concrete, namely T2.10.B and T2.20.B). The collection of samples cement paste at the 30 cm depth (0.18%).

causes minor damage and, consequently, no concrete paste samples were collected at other parts of the building, such as at the external walls. It is noted that, during the collection of samples, the wall of the bar (external wall) was cut, due to the intervention that was being carried out, and the cement paste samples were collected orthogonally to the cross-section of the wall without causing damage in the external surface, but not according to the typical procedure (from the external surface to the interior of the wall).

The following table (fig. 4.29) presents the results of the chemical tests with the estimation of chloride content in the cement paste. In general, the results present a significant chloride content (higher than 1% - upper limit defined by EN 206-1 (CEN, 2000), which decreases in depth. In contrast, the samples of the adults' tank present an increase in the chloride content in depth. It is noted that it corresponds to a cyclopean concrete with large stone aggregates and, consequently, the samples can also include stone, influencing the percentage of chlorides in the sample. The samples of the bar also present an unexpected evolution of the chloride content in depth. However, as it was previously referred to, the collection of these samples did not follow the typical procedure. It is also noted that the concrete of the water collection area (interior wall) presents a significant reduction of the chloride content in the



4 27

Location	Sample	Depth	Chloride content in the cement paste
		[mm]	[%]
	T1.10	10	1.32
Adults tank	T1.20	20	1.68
	T1.30	30	1.86
Children tank	T2.10	10	2.96
(external mortar layer)	T2.20	20	2.00
Children tank	T2.10_B	10	1.84
(concrete)	T2.20_B	20	1.36
	C10	10	0.78
Water collection room	C20	20	0.40
	C30	30	0.18
	B10	10*	2.16
Bar ¹	B20	20*	2.11
	B30	30*	3.35

¹ Samples collected using an indirect procedure. * depth is parallel to the wall face. 4.29

4.27 Cement paste sample collection. 4.28 Cement paste samples. 4.29 Results of the chemical tests to estimate the chloride content in the cement paste.



Water penetration testing

The in-situ water penetration tests with Karsten's tube aim to estimate the amount of water that penetrates the concrete over time, which is also an indirect measure of the superficial porosity or permeability. In this test, Karsten's tube (glass tube with a graduated scale) is glued to the concrete surface, without causing damage, and filled with water. The water exerts pressure on the surface, simulating wind-driven rain speeds up to 98 mph (pressure equal to 1140 Pa).

In the diagnosis of the building, four water penetration tests were carried out, namely at the interior surface of the wall of the water treatment area (Q1), the external surface of the wall of the water treatment area (Q2), the external surface of the wall the South's corridor (CA) and the external surface of the wall of the changing rooms (PV) (fig. 4.32). The penetration of the water into the concrete was measured every 5 min for 20 min.

The following table (fig. 4.31) presents the results of the water penetration tests, in which it is observed that the surfaces of the tested walls present significantly different performances. The highest water absorption (permeability of the concrete) occurs at the wall of the water treatment area (1.6 ml and 1.1 ml at the interior and external surface, respectively, after 20 min), which corresponds to a water absorption coefficient of 1.00 kg/m².min0.5 after 20 min (for example, the expected range for traditional cement-based renders is 0.2-1.5 kg/m².min0.5). The tested surface of the wall of the South corridor showed low permeability and no water absorption was observed at the tested wall of the changing rooms, during 20 min of the test. The results are according to the expected since the external surfaces of the concrete walls present a significantly different appearance.



4.30

Time	Decrease of the water level in the Karsten's tube				
[min]	[ml]				
2	Q1	Q2	CA	PV	
5	0.3	0.3	0.1	0	
10	0.7	0.6	0.2	0	
15	1.1	0.8	0.3	0	
20	1.6	1.1	0.3	0	

4.31

4.30 V	Vater penetration testing.
--------	----------------------------

4.31 Results of the water penetration tests.

4.32 Concrete testing with the Schmidt ham-

- mer..
- 4.33 Results of the tests with the Schmidt ham-

mer.

Concrete testing with Schmidt hammer

Non-destructive tests were also carried out at the external concrete walls (where it was not possible to extract concrete cores) and the tanks, such as tests with a Schmidt hammer. This type of non-destructive test is based on the surface hardness, in which the rebound number provided by the Schmidt hammer is correlated with the compressive strength. Thus, this type of test is only representative of a layer of about 5 cm depth and the results can be affected by steel rebars, large aggregates, carbonation, and moisture.

The concrete tests with the Schmidt hammer were performed according to the EN 12504-2 (CEN, 2013), in several areas of the building, with ten test repetitions in each location, aiming at evaluating the dispersion of the results (fig. 4.32).

The following table (fig. 4.33) presents the resume of results, namely the mean compressive strength (fcm) and the coefficient of variation (CoV). The original concrete of the adults' tank presents an average compressive strength equal to 42 MPa (15% higher than the value obtained from the laboratory tests). On the other hand, the original external mortar of the children's tank presents an average compressive strength equal to 54 MPa. The average compressive strength of the new concrete applied in the tanks during the intervention is equal to 25 MPa. The compressive strength estimated by the tests with the Schmidt hammer of the original concrete of the external walls ranges from 38 MPa to 77 MPa, in which the

Location	Point	fcm	CoV
		[MPa]	[%]
Adults tank	T1_P1	48	18
	T1_P2	37	25
	T1_P3 ¹	30	18
Children tank	T2.P1 ²	54	11
	T2.P2 ¹	25	12
Changing rooms	PV.P1	79	7
	PV.P2	70	8
Main façade south	PS.P1	68	15
	PS.P2	68	17
Main façade north	PN.P1	68	11
	PN.P2	38	26
South corridor	CA.P1	77	10
Bar	B.P1	57	31
Retaining wall	P.P1	54	13
	P.P2 ¹	30	14

(f_{cm}: mean compressive strength; CoV: coefficient of variation) ¹ New concrete. ² External mortar. 4.33

high values can be related to the hardening of the concrete over time, and the presence of aggregates and rebars at the testing points. Finally, the tests showed that the compressive strength of the concrete of the retaining wall ranges from 30 MPa (new concrete) to 54 MPa (Phase 3). Again, the high values can be affected by the presence of steel rebars close to the testing points.



Sonic testing

Sonic testing is a non-destructive technique that allows to determine the velocity of the wave propagation (V) from a transmitting transducer to a receiving transducer:

$$V = \frac{s}{\Delta t}$$

where s is the distance between the transmitting and the receiving transducers, and Δt is the time that the wave takes from the transmitting transducer to the receiving transducer. The velocity of the wave is associated with the elastic material properties and can be used to evaluate the material homogeneity of the structure.

In this experimental campaign, direct tests were carried out based on the ASTM C597-02 (ASTM, 2002), using a piezoelectric accelerometer with a sensitivity of 10 V/g (receiving transducer), an instrumented hammer (transmitting transducer), an acquisition board with 24 bits resolution, coaxial cables, and software developed by the University of Minho. The sonic tests were performed on five concrete walls: (1) three points of the wall of the South corridor (CA); (2) three points of the wall of the South bathrooms (CS); (3) four points of the main's façade South (PS, two points above and below the horizontal crack, fig. 4.34); (4) three points of the wall of the changing rooms (PV); (5) three points of the wall of the water treatment area (Q). The distance between the transducers is equal to the thickness of the walls (0.298-0.300 m) and the Δt was determined from the P waves of the direct sonic tests. At each point, six repetitions of the direct test were performed.

The results of the direct sonic tests (fig. 4.35) show that the average velocity of the waves ranges from 2326 m/s (main's façade South) to 2898 m/s (changing rooms), in which the coefficient of variation is equal to 8%. The tested walls of the South corridor. South bathrooms, and Water treatment area present similar results (velocity about 2580 ms/s; coefficient of variation of 1%), leading to the conclusion that the concrete of these walls does not present significant differences in the elastic properties.



4.34

Location	Point	Mean velocity	Average velocity
	. •	[m/s]	[m/s]
	P1	2195	
South corridor (CA)	P2	2737	2598
	P3	2862	-
	P1	2231	
South bathrooms (CS)	P2	2728	2560
	P3	2720	_
	P1	2524	
Main facade south (PS)	P2	2317	2326
	P3	2078	
	P4	2387	_
	P1	2760	
Changing rooms (PV)	P2	3052	2898
	P3	2881	_
	P1	2474	
Water treatment room (Q)	P2	2797	2582
	P3	2474	_

4.35

Color analysis based on spectrophotometry The tests with a spectrophotometer were carried out at ten locations of the building, including original concrete and new The color analysis of the concrete was performed using a concrete applied in the intervention (fig. 4.37). Moreover, ten spectrophotometer Konica Minolta CM-2600d (fig. 4.36). The test repetitions were considered in each location. The results spectrophotometer provides the parameters L (lightness), a were evaluated in terms of ΔE and represented using the (redness-greyness of the color) and b (yellow-blueness of the Adobe RGB 1998 and sRGB color spaces (fig. 4.38). As excolor) (CIELAB color space) for a testing point, which allows pected, the results present a high dispersion, with the color evaluating the color difference between testing points, based ranging from beige to dark gray. The lighter colors were deon the ΔE distance (Eq. 2). In general, it is considered that the tected in the children's tank (T2_e1, original concrete) and the color difference is perceivable by the human eye when ΔE is main façade South's (PN_e1). The new concrete (T1_e3; T2_e2; higher than 2.0. ΔE higher than 5.0 and 6.0 mean significant P_e2) presents also different color with respect to the original color difference and different colors, respectively. concrete (T1_e1, T1_e2; T2_e1; P_e1).



4.36



4.34 Results of the direct sonic tests.

4.35 Sonic testing of the west wall.

4.36 Colour analysis of the changing rooms wall.

4.37 Colour analysis of the bar wall.

4.38 Results of the colour analysis.

4.38



4.37

Main facade north (area 2) Changing rooms (area 2) South corridor Bar Retaining wall (area 1) Retaining wall (area 2, new concrete)

Ground penetrating radar testing

Ground Penetrating Radar (GPR) tests were carried out in several locations of the building. The main objective of the GPR tests was to determine the type of connection existing between the cantilever beams located over the changing rooms. GPR tests were also carried out on other reinforced concrete walls, aiming to verify the spacing of the vertical and horizontal reinforcement.

The tests were carried out using the RAMAC/GPR system from MALA (Guideline Geo). Given the objective of the works and the estimated thickness of the structural elements under analysis (around 30 cm), the tests were carried out using a 1600 MHz antenna. The GPR method is based on the emission of high-frequency electromagnetic waves (radar waves) into a building element using a dipole antenna. The waves are generated by a transmission antenna placed on the surface of the analyzed object. The wave propagates through the material and part of it is reflected back to the testing surface (where the reception antenna is also located) when discontinuities are observed. Discontinuities correspond to a change in the dielectric properties of the medium, which happen when they reach an interface between different materials, namely the end of an element (backside of a wall), a metallic element (reinforcement bars), voids, etc.

The time between the emission and reception of the reflection can be measured, which allows the determination of the location and depth of the anomaly observed. The transmission and reception antennas are within the same device, which is also a cart. Thus, the antennas can be moved along the surface of the element under investigation, producing radargrams. Radargrams are charts that show the position of the antenna against the travel time of the wave. If the velocity of propagation of the radar waves within the media is known, the location and depth of the different obstacles (interfaces, rebars, the backside of elements, etc.) can be estimated. For reference, it is noted that the average radar-wave velocity in concrete is 10 cm/ns, according to the literature that two dowels were used to connect the beams. These do-(Daniels, 2014).

A series of GPR profiles were carried out in the three beams that compose the entrance of the changing rooms. The main objective was to understand the connection between the beam with no evident supports (B) and the two perpendicular cantilever beams (A and C) (fig. 4.45). Assuming the likely presence of dowels connecting the beams, vertical GPR profiles were carried out each 10 cm (close to the connection) and each 20 cm (around the center of beam B). The test aimed to determine two specific construction details: (1) the number of dowels connecting the beams; (2) the length of the dowels. Figure 4.45 shows schematically the number and location of the profiles carried out.

The thickness of the beam is known (30 cm). Thus, the velocity of the waves in the concrete could be defined for this specific case. A velocity of 11 cm/ns was found, which is within the common range recommended in the literature (ASTM, 2002). Once the velocity was calibrated, the depth of the steel reinforcement bars and ties can be determined from the radargrams.

The first radargram (fig. 4.39) was obtained at the head of beam A. The radargram shows parabolas that indicate the presence of steel reinforcement elements, separated approximately 20 cm. These reinforcement elements can be more clearly detected in the second radargram (fig. 4.40), carried out on beam B, 30 cm from the joint between beams A and B. Therefore, there seem to be five longitudinal reinforcement elements in beam B. Among these five rebars, some of them should go through the joint and penetrate the perpendicular cantilever beam (beam A) to make the connection between the two beams. These five bars are spaced 20 cm in height and are located at a depth of approximately 4-5 cm within the beams.

Radargram 3 (fig. 4.41) was carried out 50 cm away from the joint between beams A and B, confirming the presence of the five reinforcement bars) and indicating that their length within beam B is greater than 50 cm. The tests performed at a location further than 50 cm from the joint no longer show the presence of the five bars. In radargram 4 (fig. 4.42), carried out 110 cm away from the joint between beams A and B, only three steel reinforcement elements can be detected. In conclusion, the dowels that connect beams A and B seem to have a length of 50 cm within beam B and there are two of them. The three reinforcement elements located seem to be the longitudinal reinforcement of beam B, located at the top, bottom, and middle of the height given the beam's large size.

Radargram 5 (fig. 4.43) was carried out 180 cm away from the joint between beams A and B and 30 cm away from the joint between beams B and C. The radargram shows again five reinforcements, indicating the presence of dowels in the interior of beam B at this end of the beam to connect with beam C. The reinforcement details thus seem to be similar at both ends of the beam. The tests carried out led to determining wels are separated by 40 cm, located approximately 40 cm from the top and 40 cm from the bottom of the beam. They have a length of approximately 50-60 cm within beam B (beam with no vertical supports).

Several radargrams were carried out on the interior face of the beam, leading to similar conclusions. The results indicate that the same reinforcement detail was used at both faces of the beams.

In conclusion, the hypothesis shown in fig. 4.46 indicates the probable presence of two dowels connecting the perpendicular beams in each face (in dark red), making it four in total. It also shows an approximate distribution of the stirrups (in light blue) and the longitudinal reinforcement bars (in orange) of beam B, again in each face. The probable location of the three longitudinal reinforcement bars in beams A and C (in dark blue), and in each face, is also shown. The arrangement is assumed to be symmetric from the vertical axis of the beams.













4.42





4.44



4.45





4.39 Radargram 1 of beam B.

4.40 Radargram 2 of beam B.

4.41 Radargram 3 of beam B.

4.42 Radargram 4 of beam B.

4.53 Radargram 5 of beam B.

4.44 GPR testing of the cantilever beams over the changing rooms entrance ..

4.45 Location of the GPR profiles of the cantilever beams over the changing rooms entrance. 4.46 Likely reinforcement details of the connection between the cantilever beams over the changing rooms entrance.

Laboratory tests on a timber specimen

A timber specimen (2×12×3 cm³) was taken from the structure to be inspected and tested in laboratory conditions. From an initial visual inspection (fig. 4.47), the plank did not present any superficial defects, e.g. knots or splits and cracks. There was no slope of grain and the growth rings are regular. From the color and the dimension of the rings, it is believed that the species of the specimen is Baltic pine (pinus sylvestris). The density of the specimen was obtained according to standard ISO 13061-2 (2014), in which 10 specimens were cut with dimensions of 20×20×25 mm³. The specimens were measured and weighed. A wood density of 635.41 kg/m³ (CoV of 9.8%) was obtained.

Resistograph tests were performed on the timber specimen to determine the quality of the timber, and the presence of possible cavities or decayed parts in the timber specimen not detected by a simple visual inspection. The resistograph is an equipment that drills with a 1.5 mm drill into the wood at a speed of 8000 rpm (fig. 4.48). The plan was to perform 4 holes in the timber specimen. However, due to the high quality of the specimen and its high density, as well as its low moisture content, only one hole was made, breaking the needle while performing the second hole, due to the high values of resistance. The resistographic measurement (RM), valid for sound and defect-free timber, is given by the ratio between the area underneath the curve and the drilling depth (in this case, 12 cm). A resistographic measurement of 93.27% was found. From the graph (fig. 4.49), it is clear that throughout the section, the timber has a good quality, maintaining a uniform resistance. The second hole, which broke the needle, showed even higher values of momentary drill resistance.

There is a direct relationship between RM and the compressive strength of sound timber, i.e. timber without defects (Henrique et al., 2011), showing that the higher the RM the higher the compressive strength of wood.



Laboratory tests on cement paste samples

Paste cement samples were collected from the structure, including the concrete cores, namely at; (1) adult's tank (T1.1); (2) children's tank (T2.1); (3) water collection area (11); (4) water treatment area (Q); (5) changing rooms (PV); (6) bar (B1); (7) South's storage room (A). The samples were used to perform the following tests and analyses in the laboratory: (1) thermal gravimetric analysis (TGA); (2) nanoindentation; (3) energy dispersive X-ray analysis (EDS); (4) X-ray diffraction (DRX); (5) scanning electron microscopy (SEM); (6) mercury intrusion porosimetry tests.

For further detail on thermal gravimetric analysis, nanoindentation, energy dispersive X-ray analysis, X-ray diffraction, scanning electron microscopy, and mercury intrusion porosimetry tests see Appendix D.



4.2.3 Conclusions

The inspection and diagnosis allowed us to conclude that the rebars of the slab of the South's storage room (Phase 3) prebuilding presents moderate damage, namely several discresent corrosion and mean yield strength (fy,0.6fu) of 294 MPa. te cracks at the concrete walls, distributed cracking in some The tests carried out in the timber specimen at the laboratory walls, and corrosion of the steel rebars with detachment of allowed us to conclude that the species of the timber seems the concrete. The most severe steel corrosion was located to be Baltic pine (pinus sylvestris) and presents high quality, at the bottom surface of the slab of the south storage room. resistance and density, and low moisture content. The tanks (Phases 1 and 2.1) are made of cyclopean concre-The results obtained from the laboratory tests on cement paste with large stone aggregates (fig. 4.23). The walls (Phases te samples allowed us to obtain detailed data on the cement 2.2-2.4) present differences in terms of deterioration of the pastes, such as their chemical characterization, phases, and surfaces, color, and permeability. The external surface of the pore size. The highest critical pore, estimated from the mertested wall of the changing rooms presented the lower water cury intrusion porosimetry tests, was obtained in the sample absorption (fig. 4.33), the highest compressive strength (esticollected at the slab (bottom surface) of the south storage mated by the Schmidt hammer, see fig. 4.35), and the velocity room, which presents steel corrosion. These tests allowed of the P waves (obtained from direct sonic tests, see fig. 4.36). us to conclude, as opposed to the results obtained from the The highest water absorption coefficient (1.00 kg/m².min0.5) concrete carbonation tests with phenolphthalein on-site, that occurs at the wall of the water treatment area (fig. 4.33). Hothe concrete of all samples is carbonated. The sample collecwever, and for example, it is within the expected range for ted from a surface previously covered with a switchboard of traditional cement-based renders (0.2-1.5 kg/m².min0.5). A the water treatment area (closed area) presents low carbonasignificant chloride content was detected in the concrete of tion. Moreover, they allowed us to validate the results obtaithe tanks and the walls of the water collection area and bar ned from the first tests, namely the presence of high chloride (fig. 4.31), higher than the upper limit defined by EN 206-1 content in the cement paste of the children's tank and bar, (1%). The two evaluated walls (the retaining wall and the main which is also expected for all external surfaces of walls. It is façade North) do not present significant out-of-plane deforalso concluded that the physical, chemical, and mechanical mations. The GPR tests allowed us to estimate the connecproperties of the concrete of the building present high dispertion between the upper beam and two orthogonal cantilever sion, which is expected since corresponds to concretes made beams of the changing rooms (probable presence of four doon-site and made in different phases, with different exposuwels, namely two dowels at each face, connecting the upper res (tanks, exterior walls, closed areas) and different damage beam to the two orthogonal cantilever beams), and conclude severity. However, it should be noted that the low percentage that the walls present a low percentage of steel rebars. The of steel rebars is a crucial aspect so that the damage associatest for determining the tensile strength of the steel allowed ted with the corrosion (carbonated concrete and presence of us to conclude that the mean yield strength (fy,0.6fu) of steel chlorides) is not most severe. Finally, the presence of dilation specimens of the adults' tank (Phase 1) is equal to 238 MPa joints at the connection between walls and slabs prevented (fig. 4.28), which corresponds to the steel of class A235 (Porthe occurrence of damage, at these connections, associated tuguese steel class for smooth rebars of normal ductility and with deformations caused by thermal actions. yield strength equal or higher than 200 MPa). The two tested

4.47 Cross-section of the timber specimen.

4.48 Timber specimen testing with the resistograph.

4.49 Resistograph result of the timber specimen testing.

4.3 **Conservation interventions**

4.3.1 Conservation and building extension

Recent conservation interventions designed by Álvaro Siza (2018-2021) represent an exceptional case of an architect preserving his own work, respecting the building's values and character through conservation and the addition of a new extension to enhance the site's viability and functionality. Its main focus has been infrastructural, namely the hydraulic network, as most of its pipes had been destroyed by salt or were clogged with sand. Moreover, this same intervention envisaged the reconstruction of the north buildings to improve the bar's facilities. Hence, the current legal requirements governing the operation of catering areas called for changes to be made regarding the bar's conditions, as well as its services and support spaces.

Siza's conservation works respected the integrity and authenticity of the preexisting building, restoring the original interior layout while also maximizing the preservation of existing materials - including their texture and patina - replacing them only when strictly necessary.

One of the greatest challenges in terms of conservation was the update of the installations to meet the current requirements (water, electricity, internet, etc.). Existing electrical cables were replaced and inserted in exposed copper tubes carefully fixed to the building's structure to respect the original layout. For the water network, technical galleries were created to enable access to the water pipes of the swimming pools, which had previously been embedded in the concrete slab. Furthermore, access to the already existing galleries was improved. In the adults' swimming pool, new water inlets were created. To perform these changes, the pool tanks had to be partially reconstructed. Additionally, the equipment of the water treatment room and the water supply network were replaced.

All preexisting elements in Baltic pine were inspected, cleaned of their former linseed oil coating, and varnished to restore their original appearance. Some doors, metal fittings, furniture, and sanitary installations had to be replaced, respecting the original design and materials as much as possible.

To improve functionality (as well as to assure compliance with current legal requirements regarding such facilities), recent interventions involved the demolition of the bar's bathrooms and the extension of the building to the north (including public bathrooms for people with mobility impairments, employees' changing rooms, storage, and waste management rooms).

The new building is located under the coastal avenue, revealing a concrete retaining wall with small horizontal openings, interior partitions, joinery, and details that follow the design principles of the preexisting building. In this intervention, the platform at the northern end was finally extended to the place where the restaurant would be located, culminating in a 45º inflection, in line with the compositional principles of the set. This way, while preserving his own work, the architect finally and definitively completes the design of the building complex enhancing its significance for future generations.

4.50 Conservation and extension works plan with red (new/rebuilt) and yellows (demolished) of the intervention.

4.51 Plan of the new north volume.

4.52 Elevations and sections of the new north volume

4.53 Joinery details of the bar window.













4.56



4.58

4.54 Bar terrace wall and north platform before the intervention.

- 4.55 North limit before the intervention.
- 4.56 North volume before the intervention.
- 4.57 Changing rooms' hallway before the inter-

vention.

4.58 Water treatment room before the intervention.



4.59

- 4.59 South storage room before the interven-
- tion.
- 4.60 Walkway before the intervention.
- 4.61 Foot wash before the intervention.
- 4.62 Children swimming pool before the inter-
- vention.
- 4.63 Adults swimming pool before the inter-
- vention.



4.60



4.62



4.64

4.64 Location of the image captions.

4.61









4.67



4.69

4.65 Excavation of the north platform extension.

4.66 Setting of the north platform's pavement.4.67 Rebar of the new concrete walls of the north volume.

4.68 Changing rooms' hallway during the wood cleaning process.

4.69 Water treatment room after the removal of the original equipment.



4.70

4.70 South storage room after the demolition of the roof slab.
4.71 Formwork of the walkway rebuild.
4.72 Concrete pouring over the new technical galleries.
4.73 Concrete pouring in the curved wall of the children swimming pool.
4.74 Demolition of the inner side of the adults swimming pool concrete walls.



4.71



4.73



4.75

4.75 Location of the image captions.

4.72







4.78



4.80

- 4.76 Rebuilt north volume and retaining wall.
- 4.77 North platform extension.
- 4.78 Rebuilt north volume.
- 4.79 Changing rooms' hallway after the intervention.
- 4.80 Water treatment room after the interven-
- tion.
- 4.81 South storage room after the intervention.
- 4.82 Rebuilt walkway.



4.81

- 4.83 View towards north after the intervention.
- 4.84 Children swimming pool after the inter-
- vention.
- 4.85 Adults swimming pool after the intervention.
- 4.86 Location of the image captions.
- 4.87 Details before and after the intervention (following spread).



4.82



4.84



4.86

4.83

CONDITION ASSESSMENT, CONSERVATION AND RISKS 4.

















4.87

61











4.3.2 Concrete repair

General approach

Although the quality of the original concrete was very good, the damage survey has identified several problems and their causes. Hence, some of the concrete structures, such as the walls on the north side and the walkway that leads to the swimming pools, were already in an advanced state of decay, presenting severe rebar corrosion. In addition to spalling related to steel corrosion, the main signs of decay were 'pattern cracking, erosion of the concrete surfaces, and patches caused by incorrect interventions.

There were four types of approaches to concrete repair: i) demolition and replacement of concrete structures with same texture and formwork integration (this was the case of the suspended walkway and the roof slab of the south storage room, where the condition of the concrete was beyond repair); ii) localized repair of concrete spalling with chromatic, texture and formwork integration (in the cantilever beam over the changing room's entrance); iii) localized repair of material loss or detachment (in specific locations with impact on the geometry or the continuity of wall planes); iv) maintenance of cracks that did not present signs of steel corrosion and therefore did not pose a risk to the building's structure, some of which were left open as signs of the material history of the building.

The first three types of works on the concrete were performed with pine formwork in keeping with the original texture. In the latter case (iv), given the patches of the incorrect remedial interventions conducted over time, as well as the inevitable visibility of new repairs over existing cracks, Siza chose to preserve several cracks open in the exposed concrete as 'scars of time' that testify to the material history of the building (the cracks were related to the absence of expansion joints in the original design and are not related with rebar corrosion). In his own words, Siza performs a "*minimum intervention, nei-ther wanting nor being able to hide what the passage of time* determines" (Siza, 2018). This is also, according to him, the "*most brutalist*" attitude and therefore coherent with the option of truth advocated by the use of raw materials in the original design (Siza, 2019, p. 19).

In this way, Siza recognizes the "age value" (Riegl, 1903) in modern buildings, intended as the passage of time and an explicit sense of the life cycle. However, despite recognizing time as an added value in architecture, Siza calls for the importance of regular maintenance: "The passage of time in buildings is part of their quality; it increases the density of the buildings", except when there is "a lowering, for economic reasons, of either the quality of the materials or the execution, or a lack of maintenance" (Siza, 2017, p. 151). Siza thus maintains that "the work of rehabilitation should be converted into maintenance. Otherwise you repair, and afterward it decays again. Carrying out regular maintenance is a matter of economics" (Siza, 2017, p. 141).

The conservation intervention in the Ocean Swimming Pool entailed the challenging subject of an architect preserving his own work. Understanding the work 'of the other' (the young Siza), Siza's recent intervention in the Ocean Swimming Pool (2018-2021) preserved the architectural integrity of the ensemble and accepted the marks of time as a densifying aspect of architecture (Ferreira, 2022).

4.88 Rebuilt north volume (previous spread).4.89 Rebuilt walkway and south storage room roof slab.

4.90 Vertical crack on the wall by the entrance ramp before the intervention (filled with an inadequate mortar).

4.91 Vertical crack on the wall by the entrance ramp after the intervention (cleaned and left exposed).



4.89





Pilot demonstration 1

The west façade presented a concrete detachment of about 0.5 m² in the angle between a higher and a lower wall (R1). caused either by the lack of movement joints or by foundation movement (fig. 4.95). The same façade also presented, at the lower corner of the wall over the concrete bench, a material discontinuity that led to the separation of a wall fragment, possibly due to the dilatation of a corroded vertical rebar (fig. 4.105).

The repair interventions were conducted by the specialized conservator-restorer Pedro Antunes (Cinábrio Restauro) and began with the elaboration of restoration mortar samples with different combinations of washed concrete sand, 2/4 mm pebbles, 0/1.2 mm yellow stone dust and 0/0,7 mm black ground limestone. A quick-setting binder was used to allow the application of olive shadow and black iron oxide pigments to fine-tune the coloration. Ten samples of the repair mortar were produced for analysis and selection by Álvaro Siza, with the objective of an optimized blending and integration of the new mortar with the preexisting concrete in terms of color and texture (fig. 4.93 and 4.94). The interventions were minimal, employing a restricted number of products and techniques, selected according to their stability, reversibility, and temporal inalterability, as well as their compatibility with the original materials.

The first repair (R1) required the reconstruction of the detached portion. For this purpose, 316 stainless steel threaded rods were inserted in the preexisting concrete and coated with epoxy resin before the application of the restoration mortar. A siliconized sheet was then applied on top of it to keep the joint open and allow structural movements. Wooden planks were used as formwork to achieve the intended texture in keeping with the original. The repair mortar was gently introduced inside the formwork and after ten to fifteen minutes of curing, a water-soaked sponge was used to mimic the wear of the existing surfaces, followed by a supplementary localized chromatic reintegration to mimic the concrete wall's pigmentation (fig. 4.103).

The second repair (R2) started with the removal of the loose fragments and their numbering for later repositioning. The 2 cm corroded vertical rebar was subjected to mechanical and chemical cleaning, followed by the application of a rust converter and an epoxy resin coating to prevent future corrosion. The fragments' inner surfaces were punctured to allow their realignment with the wall and then glued with an epoxy resin. Lastly, the remaining gap created by the fragmentation was filled with the same mortar and methodology used in the previous intervention (Cinábrio, 2021).



4.92

4.92 Location of the concrete repair interventions

Pilot demonstration 2

A finishing texture reproduced with untrimmed formwork boards and brush was first tested in sample panels. These The remaining two spots selected by Álvaro Siza for concrete were then brought to the site for color evaluation, compared repair presented concrete spalling. The first one is located at to the original concrete to check if final refinements were nethe cantilever beam over the changing rooms' entrance (R3). cessary, based on image processing and the opinion of Álvaro The beam exhibited concrete delamination caused by rebar Siza. Both surfaces to be repaired and the samples presencorrosion, the latter originated mostly by chloride ingress ted an identical value for V (in HSV color space), with 0.56% (from the seafront environment), combined with concrete differences. The color difference in these surfaces was also carbonation. The second is located at the top of the terrace measured in the CIELAB color spaces, considering that a JND 45° angled wall (R4). Here, the anomaly was caused by the (Just Noticeable Difference) value of 2.3 represents the lower unauthorized removal of material to embed electrical wires limit of color variations that are noticeable to the human eye. for exterior lighting. Both locations were intervened using the The measured color variation between the surfaces was 1.24, Patch Restoration Method (Valença et al., 2015) specifically making it imperceptible. These results in both color spaces the Gray Concrete Restoration Method (GCR-Method) (Miranallowed the validation of the restoration mortars and set the da et al., 2021) to characterize the concrete surface, including final formulation (Miranda et al., 2022). the color and texture of the surface, to design the restoration mortar, to define the application and finishing procedures and The application of the restoration mortar started with prelito assess the intervention.

The chromatic characterization of the surfaces was performed through image processing techniques using the HSV (Hue, Saturation, Brightness) and CIELAB color spaces. The Brightness (V) color parameter was used to correlate the percentage of pigment to be added to a reference mortar in the case of gray concrete. The chromatic characterization indicated 4% of black pigment to be added to the restoration mortars in the R3 affected area. In the first case, since proportions between 2.5% and 4% result in lower variation of the V parameter, it was decided to incorporate 3% of black pigment in the mortar mixture, to ensure a slightly lighter color than the surface to be repaired, in case the chromatic compatibility was not perfect. This facilitated the application of located color corrections and glazes that replicate the stains of the surrounding surface through the application of yellow pigment. In the 45° angled wall (R4), a reduced area of binder was measured because of the aggregates' (sand and pebbles) high exposure to erosion. Thus, it was concluded that the aggregates have a major contribution to the color and texture of the surface, and no black pigment was incorporated in the mortar. On the other hand, the results obtained in the CIELAB color space were used to estimate the proportion of pigments to be used, which indicated a slight trend toward red and yellow. The incorporation of 1.5% of yellow pigment and 0.5% of red pigment, in relation to the cement weight, was tested and validated.

The restoration mortar was developed to ensure all mechanical, physical, and durability requirements taking into account the location of the building, mainly its high exposure to chlorides. In that sense, the mortar's mixture was designed with a water to cement ratio of 0.5, and cement was partially replaced by micro limestone filler and natural ground pozzolan, assuring a high-quality and compact matrix with reduced permeability, leading to a durable and sustainable solution.

minary work for substrate preparation, namely the removal of deteriorated concrete. In the first case (R3), it was extended to the rebars' concrete overlay, removing any material that could be affected by corrosion. This was followed by intense brushing and the application of a corrosion protection product. Additionally, longitudinal and transversal rebars (galvanized steel rods) were added and glued with epoxy resin. In the other case (R4), the depth of the opening was increased to allow the restoration mortar to have a minimum thickness.

The application of the restoration mortar in the entrance area (R3) was done with untrimmed pine formwork boards to recreate the stereotomy and texture of the preexisting concrete surface's texture. After 5 hours of curing, the formwork was removed. It was followed by a chromatic reintegration through the application of glazes (pointillism) on the transition areas while the restoration mortar was still fresh to allow the partial absorption of the pigments into the superficial matrix. Additionally, any texture and level difference in the transition areas were smoothed through the use of a small spatula and brushes, and completed with a final sanding process after the curing process with a grouting sandpaper. In the case of the 45° angled wall (R4), the mortar was directly applied in the gap. The addition of the pebbles in the superficial mortar was done by hand, allowing the regularized restoration mortar to be approximately 3 millimeters thicker than the wall's surface. A superficial hardening retarder was posteriorly applied to delay the curing process of the first 2 to 3 millimeters depth of the restoration mortar. After 5 hours of curing, the excess unhardened mortar layer was removed with a wet sponge, recreating the eroded texture of the wall and exposing all the aggregates. Both repairs underwent a final color evaluation after six months, and color differences between the repaired and the original concrete surfaces were lower than JND (not perceptible to the human eye).









4.95



4.97

4.93 Restoration mortar discussion with Álvaro Siza.

- 4.94 Restoration mortar validation.
- 4.95 Joint between a higher and a lower section
- of the west wall before the intervention (R1).
- 4.96 Brushing of the intervention area (R1).
- 4.97 Drilling for the insertion of rebar (R1).
- 4.98 Application of glue in the rebar holes (R1).
- 4.99 Initial restoration mortar filling (R1).



4.98

4.100 Application of formwork to the lower section (R1).
4.101 The lower section after the removal of the formwork (R1).
4.102 Application of restoration mortar on the upper section (R1).
4.103 Color and texture corrections (R1).
4.104 Final result after the intervention (R1).



4.99



4.101



4.103

4.100

4.102







4.107



4.109

- 4.105 Joint between the west wall and the con-
- crete bench before the intervention (R2).
- 4.106 Bioccide application (R2).
- 4.107 Removal of loose fragments (R2).
- 4.108 Cleaning of loose fragments (R2).
- 4.109 Application of epoxi resin on the exposed
- steel rod (R2).4.110 Application of glue on the loose fragments
- (R2).



4.110

- 4.111 Placement of the loose fragments (R2).
- 4.112 Placement of the loose fragments (R2).
- 4.113 Application of the restoration mortar (R2).
- 4.114 Color and texture corrections (R2).
- 4.115 Horizontal joint that was maintaned
- (R2).
- 4.116 Final result after the intervention (R2).



4.111



4.113



4.115

4.117 Changing rooms hallway after the intervention (following spread).

4.112








4.119





4.120



4.122

4.118 Restoration mortar validation (R3).

4.119 Restoration mortar discussion with Álvaro Siza (R3).

4.120 Cantilever beam over the changing rooms entrance before the intervention (R3).4.121 Material removal and rebar reinforcement (R3).



4.123

4.122 Application of restoration mortar with formwork (R3).

4.123 Color and texture corrections (R3).

4.124 Sanding of the transition areas (R3).

4.125 Final result after the intervention (R3).

4.126 Top of the 45^o terrace wall before the in-

tervention (R4).



4.124



4.126



4.128

4.127 Application of restoration mortar with pebbles (R4).

4.128 Application of the superficial retarder (R4).

4.129 Final result after the intervention (R3).

4.130 Changing rooms entrance after the intervention (following spread).

4.125



4.127



4.4 Hazards, vulnerabilities and risks

4.4.1 Methodology

Reinforced concrete constructions located in coastal environments, namely in intertidal and splash areas, are known to be vulnerable to a wide range of degradation phenomena (Mehta, 1980; Santhanam and Otieno, 2016; Qu, et al., 2021). Exposure to the ingress of chloride ions from seawater alone can cause steel corrosion in reinforced concrete, which can then lead to spalling of its surface (James, et al., 2019). Moreover, these constructions can be further exposed to damage resulting from coastal erosion or hydrometeorological events (Pranzini, Wetzel and Williams, 2015; Gomes, et al., 2018). In addition, the increasing rate of phenomena related with climate change is introducing new challenges that can affect the vulnerability of these constructions. For example, aside from creating new threats such as sea-level rise, climate change is also intensifying the occurrence of coastal erosion and extreme hydrometeorological phenomena (Masselink and Russell, 2013; Stott, 2016; Konisky, Hughes and Kaylor, 2016). Furthermore, for the particular case of reinforced concrete constructions, the rise of atmospheric CO₂ concentration and temperature are known to lead to an increase in concrete carbonation (Yoon, Copuroğlu, and Park, 2007; Stewart, Wang and Nguyen, 2011; Talukdar, Banthia and Grace, 2012) which in turn leads to a non-negligible increase in carbonation-induced corrosion of steel reinforcement (Stewart, Wang and Nguven, 2012; William and Attar, 2015; Köliö et al., 2015). Overall, these several phenomena can lead to a number of issues that may affect the functionality, aesthetics and durability of reinforced concrete constructions.

Anthropogenic hazards are another source of threat to constructions in general. These hazards are related to human-induced actions or inactions that endanger constructions and can lead to devastating consequences if left unaddressed. Anthropogenic hazards can be grossly divided into intentional human activity that is malicious and has negative impacts, intentional human activity that is non-malicious, but that may have negative impacts, and non-intentional human activity that may have negative impacts. While the identification of some of these hazards is sometimes difficult, one of the key challenges for their inclusion in risk management processes is often related with the definition of their likelihood since their occurrence cannot be predicted using probabilistic models based on the recurrence of these events.

When the construction exposed to the hazard is also considered culturally significant, additional features are also at risk due to the likely loss of integrity caused by the negative hazard impacts. In this context, Modern architecture is particularly vulnerable to certain types of hazards given that, at the time of construction, the material and technological features that were involved were often experimental. For example, it has been shown that concrete ages faster than other materials (Di Biase, 2009), which makes the preservation of historic constructions in concrete a time-constraint activity requiring proactive solutions. Furthermore, given the referred climate change effects that are likely to accelerate concrete degradation, addressing its preservation becomes urgent. Given the importance of this topic, several documents have been highlighting the cultural significance of reinforced concrete heritage constructions, namely the Madrid-Delhi Document (ICOMOS ISC20C, 2017) and the Cádiz Document (ICOMOS ISC20C. 2021), discussing the need for their preservation. However, there are no comprehensive methodologies for assessing how the impacts of different types of hazards may affect the cultural significance of such heritage constructions, namelv in cases where some of the hazards may be intensified by climate change.

The proposed approach can be seen as a simplified first-level assessment framework for identifying relevant hazards, vulnerabilities and risks in reinforced concrete heritage constructions. The methodology was supported by the analysis of different information sources, with a special focus on the consultation of regional and local level legal and administrative documents (policies, regulations, reports, maps, etc.). This information was complemented with data collected from interviews conducted to officers of the Municipal Council heading the Culture, Urban Planning, Environment, Civil Protection, and Heritage Commission departments. The identification of hazard impacts took into account the site's values that contribute to its cultural significance, given their essential nature for the decision-making process over what should be preserved and what can be changed.



4.131

The risk, vulnerability and hazard identification approach The methodology that was followed for risk, vulnerability and hazard identification considers that risk can be defined as the that was considered herein falls into the category of qualitapotential negative impacts in the asset under assessment tive methods and combines the likelihood and severity of the due to the occurrence of a threatening event, which need to selected hazard scenarios with the vulnerability levels that account for the diversity of values and functions associated were identified to establish risk levels. Regarding the selecto the asset (Reisinger, et al., 2020). The threatening events ted hazard scenarios, natural and anthropogenic hazards are are termed hazards and represent a potentially damaging considered, including both sudden- and slow-onset hazards, physical event, natural or anthropogenic, that can have negaand also accounting for the likely effects of climate change. tive impacts on the asset under assessment. These negati-Although in a qualitative form, the vulnerability levels that are ve impacts represent the risk measure but are often globally identified consider physical impacts on the asset (i.e. physical termed as losses (GFDRR, 2014), Globally, these impacts can damage) and impacts to the cultural significance and values be seen as the result of the dynamic interaction between the of the asset. Finally, given the preliminary nature of the propohazard and existing vulnerabilities (e.g. physical, social, ecosed analysis, these risk levels must be understood as a tool to nomic or environmental vulnerabilities) which represent the establish risk mitigation priorities and identify issues requisusceptibility of the asset under assessment to the damaging ring more detailed and resource-demanding analyses. effects of the hazard, combined with a lack of ability to cope Regarding the selected hazards, it is noted that the potenwith those impacts, i.e. a lack of resilience (Romão, Paupério tial impacts of the Galp Energia oil refinery that was located and Pereira, 2016). Within this definition, it is noted that the nearby are not considered in the current analysis. The refinery word "potential" refers to the presence of uncertainty when was decommissioned in mid-2021 and is no longer a threat. analyzing these issues. The uncertainty can have different According to available information, the site is going to be sources and occurs across the different elements of the risk transformed into a green and innovative district with housing, assessment, namely when establishing the likelihood of oca university campus, a large park, and various facilities over currence of the hazard that can cause the negative impacts the next 4 years. or when estimating the actual negative impacts.

4.131 Graphic representation (in red) of a +1.00 m sea level rise (adapted from Gilabert Campos, Castellano Pullido and García Píriz, 2019).

Hazards 4.4.2

Natural hazards

Given the location of the Ocean Swimming Pool, the more relevant natural hazards were found to be storm surges and chloride action. In addition, given their relation with climate change, events such as sea level rise and the increase of atmospheric carbon dioxide were also considered in the current assessment.

In terms of chloride action, the most important source of chlorides for the Ocean Swimming Pool is the contact with marine air and splash-water (Schueremans, 2007). Chloride concentration will vary according to the nature of the shoreline and the resulting surf, wetting and drying cycles, as well as wind direction and speed, all of which can vary seasonally and on a daily basis. Additionally, chloride deposition also depends on ambient temperature as well as rainfall regimes that may wash off some of the chlorides. All these variables influence the chloride deposition rate, resulting in a higher or lower deposition of these ions according to the cumulative effect of these conditions (Liu, 2018).

A storm surge is an abnormal rise of seawater over the predicted astronomical tide level that storms generate. These storms originate in low pressure systems, or depressions, which temporarily increase the sea level by decreasing atmospheric pressure. Due to their morphology, low and sandy coasts are particularly sensitive to this extreme hydrodynamic phenomenon. In some European regions along the Atlantic coast, storm surges can reach over 2 m above normal tide levels. Nevertheless, the highest recorded values on the Portuguese coast were closer to 1 m (Santos and Miranda, 2006). However, one of the effects of climate change might be an increase in storminess along the Portuguese continental coast, which was hit by a significant number of storms between 2010 and 2018: Xynthia (February 2010), Hercules (January 2014) and Emma (March 2018). These eight years concentrate 53% of the total number of coastal flooding occurrences since 1980 (Tavares, 2021). The presented coastal flood scenarios (figs

4.132-4.133) were based on the Mod.FC_2 projection (0.44 m for 2050 and 1.15 m for 2100 in relation to the vertical datum of Cascais 1938), considering maximum high-tide and additional storm surge with a return period of 100 years, according to the Directive 2007/60/EC (Antunes, Rocha and Catita, 2019, p. 239). These scenarios show a 20% to 40% flood probability (with a water depth between 2.80 m and 2.90 m) in 2050 and of 60% to 80% (with a water depth between 3.00 m to 3.35 m) in 2100 for the site.

In the context of climate change and its effects, it is currently known that, from 1880 to 2012, the average global temperature increased by 0.85ºC (IPCC, 2014, p. 40). Given current concentrations and ongoing emissions of greenhouse gases, it is likely that global mean temperature will continue to rise above the pre-industrial level until the end of this century. The world's oceans will warm and ice melting will continue, leading to an increase in the average height of the ocean surface, designated by Global Mean Sea Level (GMSL). Up to 2050, GSML projections exhibit little scenario dependence and estimate a likely sea level rise of 0.19 m and 0.23 m between the baseline period (1995-2014) and 2050. Beyond 2050, the scenarios increasingly diverge. Between the baseline period (1995-2014) and 2100, processes in whose projection there is medium confidence estimate a likely GSML rise between 0.44 m and 0.77 m (IPCC, 2021, p. 1302). The specific sea level rise projections for the west coast of Portugal, based on the intermediate hazard scenario Mod.FC 2b, point to permanent tide submersion levels of 0.44 m in 2050 and of 1.15 m in 2100, relative to the Cascais Vertical Datum 1938 (Antunes, 2019). The specific tide submersion scenarios for 2050 and 2100 in the area of the swimming pools (figs. 4.134-4.235) indicate that, for the latter, both swimming pools are likely to be submerged for 9 hours a year.

Given its relation with climate change, the impact of the rise in atmospheric CO₂ is also considered herein. As referred before, the rise of atmospheric CO2 concentration can lead to an increase in concrete carbonation, which in turn leads to a



4.133

non-negligible increase in carbonation-induced corrosion of sed wear and tear, potentially compromising the structural steel reinforcement. Carbon dioxide levels are higher today stability and authenticity of the site. Inadequate visitor mathan at any point in human history, mostly as a result of annagement can further exacerbate the damage caused by thropogenic emissions (e.g., burning of fossil fuels for enerincorrect use. gy). In 2021, according to the Global Monitoring Lab of the Long-term neglect or insufficient maintenance poses a per-National Oceanic and Atmospheric Administration (NOAA), vasive threat to heritage constructions worldwide. The passaglobal average atmospheric carbon dioxide was 414.72 ppm ge of time, exposure to natural elements, and lack of regular (Lindsey, 2022).

upkeep can lead to significant deterioration of historic struc-It is expected that, with higher atmospheric CO₂ concentures. Although maintenance is essential for ensuring the pretration, the proportion of emissions taken up by both ocean servation of cultural heritage constructions, stakeholders ofand land will decline. Thus, even if there is considerable unten neglect systematic and routine maintenance works. This certainty in projections of future CO₂ concentration, the IPCC neglect can arise due to a lack of understanding about the projections lead to a CO₂ concentration for 2010 that ranges unique needs of these structures, as well as the unavailability from 651 to 682 ppm (IPCC, 2001, p. 222). or inconsistent allocation of resources.

Anthropogenic hazards

Given the location and past history of the Ocean Swimming Pool, vandalism, incorrect or improper use, and neglect or lack of maintenance were the three types of anthropogenic hazards considered in the current analysis.

Vandalism, characterized by acts that cause deliberate damage or even destruction, has been a persistent issue throughout history. Regardless of the underlying motivations, the consequences of vandalism inflict willful damage upon the material landscape of cultural heritage constructions. These malicious acts can take various forms, such as graffiti, defacement, theft of valuable artifacts, or intentional physical damage to structures. Vandalism not only causes irreversible harm to a heritage site but also disrupts its historical context and erodes the collective memory embedded within these sites.

Heritage constructions that retain their original purpose and remain accessible to the general public often face issues related to incorrect or improper use. The continuous flow of visitors and the lack of proper monitoring can lead to increa-



4.132 Leça da Palmeira coastline extreme flooding scenarios for 2050.

4.133 Leça da Palmeira coastline extreme flooding scenarios for 2100. (adapted from Antunes, *et* al. 2017) A scale of blue hues, from dark to light, represents the five levels of confidence of the Flood Hazard Index: 1-Very low; 2-Low; 3-Medium; 4-High; 5-Extreme; separated by 20% flood probability intervals.

4.134 Leça da Palmeira coastline tide submersion scenarios for 2050 after GMSL rise.

4.135 Leça da Palmeira coastline tide submersion scenarios for 2100 after GMSL rise. (adapted from Antunes, et al. 2017) A scale of blue hues, from dark to light, represents the percentage of submersion hours and its absolute values during a year: 10% or 876 hours; 5% or 438 hours; 2.5% or 219 hours; 1% or 88 hours; 0.1% or 9 hours.

Classification of the hazard scenarios

Figure 4.136 presents a summary of the previously described hazard scenarios along with a likelihood classification using three levels: LOW, MEDIUM and HIGH. For the slow-onset natural hazards related with climate change, this classification reflects the confidence in the climate model that predicts the

event. In contrast, for the case related to chloride action, whose classification is HIGH, it reflects the fact that the asset is continuously exposed to that hazard. For anthropogenic hazards, the classification reflects the likelihood of the hazard occurring at least once a year.

Category	Hazard	Scenario	Description	Source
Slow-onset natural hazard	Sea level rise	Sea level rise of 0.44 m until 2050	Likely sea level rise at west coast Portugal according to scientists	Antunes (2019)
		Likelihood: HIGH		
Slow-onset natural hazard	Increase of atmospheric carbon dioxide	Atmospheric CO ₂ increase between 236- 267 ppm until 2100	Likely atmospheric CO ₂ increase according to the Intergovernmental Panel on Climate Change (IPCC)	IPCC (2001)
		Likelihood: HIGH		
Slow-onset natural hazard	Chloride action	Permanent marine environment exposure	The asset is permanently exposed to the effect of airborne chlorides	
		Likelihood: HIGH	carried by the sea winds	
Sudden-onset natural hazard	Storm surge	Occurrence of a storm surge	The asset's location makes it particularly vulnerable to storm	Antunes, Rocha and
		Likelihood: HIGH	surges and coastal flooding	Catita (2019)
Sudden-onset anthropogenic	Vandalism	Theft of copper elements and graffiti	The absence of clear fences and the low height of the building's roof	
hazard		Likelihood: LOW	make the site particularly vulnerable to trespassing and vandalism	
Slow-onset anthropogenic	Misuse	Throwing waste into toilet vases	Throwing waste into toilet vases might lead to clogging and to	
hazard		Likelihood: MEDIUM	repair costs	
Slow-onset anthropogenic	Lack of maintenance	Absence of regular surveys	The absence of regular surveys prevents the early identification of	
hazard		Likelihood: MEDIUM	anomalies and leads to costly and more difficult repairs in the future	

4.136

4.136 Summary of the selected hazard scenarios.

4.4.3 Vulnerabilities

Vulnerability to natural hazards

Sea level rise is particularly threatening to coastal structures such as the Ocean Swimming Pool. The entrance level These extreme events are more clearly illustrated by figures of the property from the street is at +7.50 m above the sea 4.138-4.142 which pin-points the exact extension each one level, while the changing rooms and the swimming tanks had and its immediate impacts on the Ocean Swimming Pool were built at +5.00 m and +2.90 m above the current sea between 2017 and 2019. It is noted that the 2011 Matosinhos level, respectively. As such, there is an increased likelihood Municipal Plan for Civil Protection Emergency (CMM, 2011) rafor the swimming tanks to be impacted by wave overtopping tes storm surges with overwashing of the coastline with a mein future storms, but also in normal conditions if sea level dium-low level risk, meaning a low frequency (e.g. one time rise reaches significant values (wave height above 2.00 m every 5 years). However, given the apparent increase in the are rather common under normal weather conditions). This rate of occurrence of these events, there is a need to review particular vulnerability of the Ocean Swimming Pool is made this rating based on empirical data combined with the outcovisible through the simulation presented in figure 4.131 whimes of numerical simulations. ch shows the impact of a 1.00 m sea level rise in terms of the area reached by water in these conditions and its closeness to the larger swimming tank.

The durability of concrete in coastal areas is mainly deter-Due to the site's natural setting along a continuous stretch mined by its deterioration over time which is affected by the of beaches, it has no clear limits or fencing, making it vulexposure conditions of the surrounding environment. In such nerable to trespassing, vandalism and theft. Therefore, the an environment, the penetration of chlorides in concrete building is particularly exposed to damaging anthropogenic structures increases the likelihood of rebar corrosion, resulactivities such as wall inscriptions like graffiti, material desting in cracking and delamination of the concrete cover and truction or theft of valuable materials like copper. As most a subsequent reduction of the reinforcement cross section, of the walls of the asset are made of exposed concrete, they which seriously affects the load bearing capacity of structucannot be painted over, which increases the difficulty of removing graffiti. Also, its low-lying copper roof is tempting ral elements (Costa and Appleton, 2001, p. 242). In addition to this issue, climate change is likely to cause an acceleration given the rise in the price of this material. Copper theft of of deterioration processes that will also affect the safety and the roof's sheeting or of water fixtures affects the normal serviceability of concrete infrastructures. In this context, the operating conditions of the asset, resulting in the occurrenmain driver for increased concrete deterioration is the atce of anomalies that might have serious consequences if not mospheric CO₂ concentration. The increase in CO₂ levels is promptly addressed. The permanent presence of a security expected to increase the likelihood of concrete carbonation guard can mitigate these vulnerabilities. (Yoon, Copuroğlu, and Park, 2007; Stewart, Wang and Ngu-The Ocean Swimming Pool has been permanently operational yen, 2011; Talukdar, Banthia and Grace, 2012) which in turn since it opened in 1965. Since then, it has been visited by an leads to a non-negligible increase in carbonation-induced reaverage of sixty thousand people each year (based on avaibar corrosion (Stewart, Wang and Nguyen, 2012; William and lable data from 2018 shared by the Municipal Council of Ma-Attar, 2015; Köliö et al., 2015) as referred before. This impact of tosinhos). As a result, the asset is vulnerable to unintentional climate change on existing infrastructures is expected to be damage from intensive use or willful damage from improper considerable, as corrosion damage is disruptive and costly to use. As it is a fully functional public facility, some of the issues repair (Stewart, Wang and Nguyen, 2011, pp. 13-26). that can occur are difficult to prevent, such as clogged toilet The vulnerability of coastal constructions also needs to be vases due to improper waste disposal, or damaged showers and water faucets.

considered regarding the occurrence of storm surges given their immediate and prolonged impacts, namely damage to The lack of a structured and clearly defined maintenance pothe swimming pool tanks and the retaining walls. During a surlicy facilitates the occurrence of uncontrolled degradation of ge, the combined moving force of waves and wind may lead to the asset, compromising its preservation for future generadamage to the constructions, as well as to the infrastructures, tions. The development and implementation of maintenance including access roads and electrical or hydraulic networks. plans not only ensure the execution of regular visual inspec-Wave overtopping, overwashing and flooding of coastal areas tions and scheduled material replacement but also define are likely to occur during these surges, exposing the concrete intervention guidelines that should prevent unauthorized or surfaces to direct contact with seawater, increasing the level incorrect interventions that may hinder the significance of the of chloride deposition that will significantly decrease the lisite. Adequate maintenance plans therefore allow the prompt fespan of the building. After the surge, ground subsidence identification of anomalies and provide guidance for the most and increasing coastal erosion can occur which, in turn, may adequate response to these anomalies. create more damage to constructions and hydraulic networks. Furthermore, suspended sediments and materials in the seawater may mechanically degrade the concrete surfaces

and clog the water supply and filtering systems, compromising their normal working conditions.

Vulnerability to anthropogenic hazards

Classification of the vulnerability scenarios

Figure 4.137 presents a summary of the previously described vulnerability scenarios along with a severity classification using three levels: LOW, MEDIUM and HIGH. This classification considers both the severity of the physical damage that can occur as well as the severity of the impact on the cultural values that can be affected. A severity level classified as LOW means that the physical damage is either negligible or small enough to be easily repa-rable, while the impacts to cultural

values are also expected to be negligible. A severity level classified as MEDIUM means that the physical damage is not negligible and re-pairing it will also involve non-negligible costs. This damage will also have relevant impacts to cultural values, but these are also expected to be recoverable after the damage repair. A severity level classified as HIGH means that the physical damage is expected to be significant and may not be fully repairable. As such, the impacts to cultural values in this case may not be recoverable.

Affected cultural values	Hazard	Vulnerability	Description		
All	Sea level rise	Permanent submersion	Sea level rise, as a result of climate change,		
		Severity: HIGH	preventing its fruition in the future		
Aesthetic	Increase of atmospheric carbon dioxide	Acceleration of concrete carbonation and rebar corrosion	The increase of atmospheric carbon dioxide, as a result of climate change, will accelerate concrete carbonation, leading to the corrosion of steel		
		Severity: MEDIUM	rebars which can cause cracking, spalling and the weakening of reinforced concrete elements.		
Aesthetic	Chloride action	Acceleration of rebar corrosion	The permanent exposure to the maritime environment, which is richer in chlorides,		
		Severity: MEDIUM-HIGH	accelerates the corrosion of steel rebars which can cause cracking, spalling and the weakening of reinforced concrete elements.		
Economic	Storm surge	Building damage	The moving force of storm surge may result in		
Aesthetic		Infrastructural damage	Dunding damage.		
		Severity: HIGH	Direct exposure to seawater will seriously compromise the normal operating conditions of infrastructural networks due to direct contact with water, chlorides or due to water-suspended sediments that can clog the hydraulic and filtering systems.		
Economic	Vandalism	Graffiti	Graffiti have a negative impact on the asset's		
Aesthetic		Copper theft Severity: MEDIUM-LOW	since the asset was built mainly with unprotected materials (exposed concrete).		
			Copper theft (the roof cladding or the water pipes) affect the normal operating conditions of the asset and might lead to serious consequences if not promptly addressed.		
Economic	Misuse	Equipment damage	The misuse of the facilities might lead to		
		Severity: MEDIUM-LOW	equipment damage and determine the need for unexpected repairs and additional costs.		
Economic	Lack of	Acceleration of the	The lack of regular and appropriate maintenance		
Aesthetic	maintenance	asset's degradation Severity: MEDIUM-HIGH	interventions will accelerate the degradation of the asset.		

4.137

4.137 Summary of the selected vulnerability scenarios.



4.138

4.

2017

2018



4.140



4.141

2019











4.4.4 Risk level

Figure 4.143 presents the risk levels that were identified for iii) Tolerable risk - this represents a non-negligible risk level the selected hazard and vulnerability scenarios. The risk levels were classified into four categories:

i) Acceptable risk without the need to implement any action - iv) Unacceptable risk - this represents a non-negligible risk this is a negligible risk level.

ii) Acceptable risk with the implementation of monitoring actions - this is a negligible risk level but actions for monitoring the evolution of the conditions of the asset are recommended to understand if the risk level is increasing, due to a change in the hazard or the vulnerability.

for which mitigation actions are only expected to be implemented if the results of a cost-benefit analysis are favorable.

level for which mitigation actions must be implemented urgently.

Hazard	Scenario	Vulnerability	Risk level
Sea level rise	Likelihood: HIGH	Severity: HIGH	Unacceptable risk, mitigation actions are inevitable and urgent
Increase of atmospheric carbon dioxide	Likelihood: HIGH	Severity: MEDIUM	Tolerable risk
Chloride action	Likelihood: HIGH	Severity: MEDIUM-HIGH	Unacceptable risk
Storm surge	Likelihood: HIGH	Severity: HIGH	Unacceptable risk
Vandalism	Likelihood: LOW	Severity: MEDIUM-LOW	Acceptable risk without the need to implement any action
Misuse	Likelihood: MEDIUM	Severity: MEDIUM-LOW	Acceptable risk with the implementation of monitoring actions
Lack of maintenance	Likelihood: LOW	Severity: MEDIUM-HIGH	Acceptable risk with the implementation of monitoring actions

4.143

4.138 Damage to the west platform ramp as a consequence of coastal erosion. 4.139 Concrete detachment as a consequence of wave impact. 4.140 Effects of coastal erosion. 4.141 Effects of coastal erosion. 4.142 Flooding and coastal erosion occurrence plan.

4.143 Risk levels for the identified hazard and

vulnerability scenarios.

 $4.144 \quad {\rm Wave \ overtopping \ during \ a \ storm \ surge} \, .$



References

Antunes, C. (2019) "Assessment of Sea Level Rise at West Coast of Portugal Mainland and Its Projection for the 21st Century", J. Mar. Sci. Eng. Int., 7(3), 61. Available at: https://doi. org/10.3390/jmse7030061.

Antunes, C., Rocha, C., and Catita, C. (2019) "Coastal flood assessment due to sea level rise and extreme storm events: A case study of the atlantic coast of Portugal's mainland", Geosciences, 9(5), 239. Available at: https://doi.org/10.3390/geosciences9050239.

CMM (2011) Municipal Plan for Civil Protection Emergency. Câmara Municipal de Matosinhos. Available at: https://www. cm-matosinhos.pt/cmmatosinhos2020/uploads/writer_file/ document/30312/pme_net.pdf.

Costa, A. and Appleton, J. (2001) "Concrete carbonation and chloride penetration in a marine environment" in Concrete Science and Engineering, 3

Di Biase, C. (ed.) (2009) Il degrado del calcestruzzo nell'architettura del Novecento. Santarcangelo di Romagna: Maggioli.

Ferreira, T. C. (2022). "Siza preserves Siza: Concrete conservation on the Ocean Swimming Pool (2018-2021)" in Ferreira, T. C. and Gandini, B. (org.) Conserving Concrete/Restaurer les Betons Book of Extended Abstracts. Porto: FAUP/ ICOMOS France

GFDRR (2014) Understanding Risk in an Evolving World: Emerging Best Practices in Natural Disaster Risk Assessment. Global Facility for Disaster Reduction and Recovery. Available at: https://www.preventionweb.net/guick/43547

Gilabert Campos, M. A., Castellano Pulido, F. J. and García Píriz, T. (2019) "Arguitecturas del baño frente a la subida de la cota cero". in XIII CTV 2019 Proceedings: XIII International Conference on Virtual City and Territory: "Challenges and paradigms of the contemporary city": UPC. Barcelona. October 2-4, 2019. Barcelona: CPSV. p. 8482. Available at: http://dx.doi. org/10.5821/ctv.8482.

Gomes, M. et al. (2018) "Hazard assessment of storm events for the Portuguese northern coast". Geosciences, 8(5), p. 178.

ICOMOS ISC20C (2017) Approaches to the Conservation of Twentieth-Century Cultural Heritage Madrid - New Delhi Document. ICOMOS ISC20C. Available at: https://openarchive. icomos.org/id/eprint/2692.

ICOMOS ISC20C (2021) The Cádiz Document, InnovaConcrete Guidelines for Conservation of Concrete Heritage, ICO-MOS ISC20C. Available at: https://openarchive.icomos.org/id/ eprint/2578.

IPCC (2021) Climate Change 2021: The Physical Science Basis. Contribution of Working Group I to the Sixth Assessment Report of the Intergovernmental Panel on Climate Change. Cambridge and New York: Cambridge University Press.

IPCC (2014) Climate Change 2014: Synthesis Report, Contribution of Working Groups I, II and III to the Fifth Assessment Report of the Intergovernmental Panel on Climate Change (Core Writing Team, R.K. Pachauri and L.A. Meyer (eds.)). Geneva: IPCC.

IPCC (2001) "The Carbon Cycle and Atmospheric Carbon Dioxide". In Climate Change 2001: The Physical Science Basis. Contribution of Working Group I to the Third Assessment Report of the Intergovernmental Panel on Climate Change. Cambridge and New York: Cambridge University Press

James, A. et al. (2019) "Rebar corrosion detection, protection, and rehabilitation of reinforced concrete structures in coastal environments: A re-view". Construction and Building Materials, 224, 1026-1039.

Köliö, A. et al. (2015) "Corrosion products of carbonation induced corro-sion in existing reinforced concrete facades." Cement and Concrete Research, 78, 200-207.

Konisky, D. M., Hughes, L., and Kaylor, C. H. (2016) "Extreme weather events and climate change concern". Climatic change, 134, 533-547.

Lindsey, R. (2022) "Climate Change: Atmospheric Carbon Dioxide". Available at: https://www.climate.gov/news-features/ understanding-climate/climate-change-atmospheric-carbon-dioxide (Accessed: 4 August 2022)

Liu, J., Ou, G., Qiu, Q., Xing, F., Tang, K., Zeng, J. (2018) "Atmospheric chloride deposition in field concrete at coastal region". Construction and Building Materials, 190, 1015-1022.

Masselink, G., and Russell, P. (2013) "Impacts of climate change on coastal erosion". MCCIP Science Review, 2013, pp. 71-86.

Mehta, P.K. (1980) Performance of Concrete in Marine Environment. American Concrete Institute, Michigan.

Miranda, J., Valença, J., Costa, H., Júlio, E. (2022) "Methodo-Siza, A. (2011) "Conferencia para el CAH20" in Intervention Approaches in the 20th Century Architectural Heritage. Interlogy for the restoration of heritage built in exposed concrete. The case study of 'Piscina das Marés', Portugal", Construction national Conference CAH20th, Madrid: ETSAM/ISC20C. and Building Materials, Elsevier 328: 127040.

Miranda, J., Valença, J., Costa, H., Júlio, E. (2021) "Chromatic design and application of restoration mortars on smooth textos: Álvaro Siza. Lisboa: Parceria A. M. Pereira, 2018. surfaces of white and gray concrete", Structural Concrete, fib Siza, A. (2018) Interview by Teresa Cunha Ferreira. 14 January. Journal, Wiley 22(s1); E535-E348.

Ou, F. et al. (2021) "Durability deterioration of concrete under marine environment from ma-terial to structure: A critical review". Journal of Building Engineering, 35, 102074.

Pranzini, E., Wetzel, L. and Williams, A. T. (2015) "Aspects of coastal erosion and protection in Europe". Journal of coastal conservation, 19, pp. 445-459.

Reisinger, A. et al. (2020) The Concept of Risk in the IPCC Sitructure". Structural Safety, 35, pp. 29-39. xth Assessment Report: A Summary of Cross-Working Group Discussions. Intergovernmental Panel on Climate Change, Stott, P. (2016) "How climate change affects extreme weather Geneva, Switzerland, events", Science, 352(6293), 1517-1518,

Riegl, A. (1903) "The Modern Cult of Monuments: Its Charac-Talukdar, S., Banthia, N. and Grace, J. R. (2012) "Carbonation in ter and Its Origin", Oppositions, 25, 1982, pp. 21-51. concrete infrastructure in the context of global climate change-Part 1: Experimental results and model development". Ce-Romão, X., Paupério, E., Pereira, N. (2016). "A framework for ment and Concrete Composites, 34(8), 924-930.

the simplified risk analysis of cultural heritage assets", Journal of Cultural Heritage, 20, 696-708, Available at: https://doi. org/10.1016/j.culher.2016.05.007.

Santhanam, M., Otieno, M. (2016) "Deterioration of concrete in the marine environment." in Marine concrete structures: Design, Durability and Performance, Alexander, M (ed.), Woodhead Publishing, pp. 137-149.

Santos, F.D. and Miranda, P. (Eds) (2006). Alterações climáticas em Portugal. Cenários, impactos e medidas de adaptacão. Projecto SIAM II. Lisboa: Gradiva

Schueremans, L. et al. (2007) "Chloride penetration in RC--structures in marine environment - Long term assessment Yoon, I. S., Çopuroğlu, O. and Park, K. B. (2007) "Effect of gloof a preventive hydrophobic treatment" in Construction and bal climatic change on carbonation progress of concrete". At-Building Materials, 21, 1238-1249. Available at: https://doi.ormos-pheric environment, 41(34), 7274-7285. g/10.1016/i.conbuildmat.2006.05.006.

Siza, A. (2005) "Recuperação e Manutenção" in Costa, A. et al. (ed.) A intervenção no património. Práticas de conservação e reabilitação. Porto: FEUP.

SIZA, A, (2013) "Discurso de Aceitação do grau de Doutor Honoris Causa pelo Politécnico de Milão" in Morais, C. C. (ed.) 02

Siza, A. (2019) "Interview by M. Seifert and P. Baía", in Seifert, M. and Baía, P. (eds.) Porto Brutalista. Porto: Circo de Ideias.

Stewart, M. G., Wang, X., and Nguyen, M. N. (2011) "Climate change impact and risks of concrete infrastructure deterioration". Engineering Structures, 33(4).

Stewart, M. G., Wang, X., and Nguyen, M. N. (2012) "Climate change adaptation for corrosion control of concrete infras-

Tavares, A. O. et al. (2021). "A coastal flooding database from 1980 to 2018 for the continental Portuguese coastal zone". in Applied Geography, 135.

Valença, J., Almeida, C., Miranda, J., Júlio, E. (2015) "Patch Restoration Method: a New Concept for Concrete Heritage". Construction and Building Materials, Elsevier 101, Part 1: 643-651. December 2015.

William, K., and Attar, A. (2015) "Carbonation-induced and chloride-induced corrosion in reinforced concrete structures". Journal of Materials in Civil Engineering, 27(9), 04014245.



5. MANAGEMENT AND CONSERVATION POLICIES

- 5.1 Introduction
- 5.2 Overarching policies
- 5.3 Site policies
- 5.4 Conservation and management policies



5.1 Introduction

Chapter 5 addresses a broad range of strategies, from planning to maintenance, establishing a set of policies to be implemented in the context of this CMP. These policies are framed to: i) respect and reinforce the primacy of Álvaro Siza's design principles in understanding significance and guiding all management and change; ii) retain and respect the Ocean Swimming Pool's setting; iii) ensure adaptations and new uses are compatible with the significant values of the place while preventing uses that could result in its progressive degradation; iv) retain the authenticity, integrity, character, and quality of the building and its various elements, providing guidance for care and conservation of significant elements and fabric; v) retain the integrity of the original structural systems, materials, and finishes, while allowing for necessary upgrading; vi) and draw attention to the need for coordination of planning, continuity of conservation and other expert advice, including implementation of cvclical maintenance.

The policy definition is sustained by a variety of sources, such continuity of conservation and other expert advice, including as institutional documents and legislation (national and interimplementation of cyclical maintenance. national), interviews with the Municipal Council departments The chapter is organized under three sections which corresrelated to the Ocean Swimming Pool and the site managers, pond to the main sets of policies (numbered and highlighted observation, and fieldwork. The ultimate goal of the policies in separate boxes); A) Overarching Policies, B) Site Policies, is to retain, conserve and, where possible enhance, the signiand C) Conservation and Management Policies. Therefore, ficance of the place. Thus, the following table establishes a disection 5.2, Overarching Policies, focuses on the importance rect relationship between the statement of significance and the of any future intervention being informed by Álvaro Siza's depolicy response to sustain it. sign principles; the clarification of the stakeholders' role in the

STATEMENT OF SIGNIFICANCE

Outstanding work within the context of the revision of the Mode vement

Considered a masterpiece by leading international architecture

Extensively photographed, filmed, and written about

Expressing a tectonic shift from regionalist inspired designs to more abstract language

Material integrity has been maintained

One of the first constructions in exposed concrete in Portuga ploying innovative construction systems

Reflects a harmonious integration within the topography and nding landscape

Social and cultural landmark for the community

One of the most sought-after attractions in Matosinhos

An exceptional case of an architect preserving his own wor enhancing its significance

Is included in the Tentative List for World Heritage Status as a c nent property of 'Álvaro Siza's Architecture Works in Portugal' listed as National Monument

5.1

5.1 Correspondence between the key heritage values of the statement of significance and policy response to sustain significance.

framework of this CMP for better integration; commitments and contributions for sustainable development as expressed by UN 2030 Agenda; and interpretation, to organize and disseminate knowledge about the Ocean Swimming Pool whilst promoting ways to maintain public engagement with the listed property. Section 5.3, Site Policies, frames the management and conservation of the Ocean Swimming Pool within its territorial, landscape, and spatial planning context, as to define policies and guidelines for the management and safeguarding of the site while considering risk assessment and climate change adaptation. Finally, section 5.4, Conservation and Management Policies, provides guidance for the management of change, conservation, detailed actions of periodic maintenance, and informing operational management and use.

	POLICY RESPONSE TO SUSTAIN SIGNIFICANCE
ern Mo-	A.2 Álvaro Siza's design principles
e critics	A.2 Álvaro Siza's design principles
	A.7 Interpretation Plan / A.10 Archives and Collections
wards a	A.2 Álvaro Siza's design principles
	B.5 Risk Management Plan/ C.2 Maintenance Plan
al, em-	C.2 Maintenance Plan
surrou-	B.8 Landscape Management Plan
	A.7 Interpretation Plan / A.8 Communication strategy / A.9 Community Engagement
	C.5 Capacity and entrance control
k while	C.1 Significance and tolerance for change
compo- ' and is	B.2 Cultural Heritage Safeguarding

5.2 Overarching policies

5.2.1 General policies

The definition of general policies is essential to prevent the implementation of ad-hoc or circumstantial decisions that do not take into account the conservation of the place's values and significance. Therefore, not only any future changes or interventions should be preceded by a detailed investigation, as they should be analyzed by an advisory body gathering stakeholders and experts and ensuring respect for Álvaro Siza's design principles identified in section 2.5.2 of this CMP. They are meant to be the primary source of guidance and inspiration for any proposed changes to the place as well as its ongoing management, conservation, and use.



5.2.2 Stakeholders policies

The stakeholders of the Ocean Swimming Pool, identified in section 2.8, range from heritage safeguarding organizations to local management, Álvaro Siza, and the different users.

The objective of this section is to provide a correlation network and an overall agreement of actions and roles for the conservation of the property. The graphic on the right details the interaction between the different stakeholders of the Ocean Swimming Pool, relating them with the power and interest each one has. The black arrows represent the direct links between stakeholders.

The most important stakeholders for the safeguarding of the Ocean Swimming Pool are the ones with the most power and interest. However, it is important to find ways to engage with the stakeholders with less power/interest to enhance involvement and thus achieve more success in preserving and managing the site.

The main lines of direct influence presented in the previous chart, identifying the interaction between the different stakeholders of the Ocean Swimming Pool and relating them with the power and interest each one has, are explained below:

STAKEHOLDER CATEGORY	STAKEHOLDER	INTEREST IN THE PROJECT	IMPACT (POWER/ INTEREST)	POTENTIAL STRATEGIES FOR GAINING SUPPORT OR REDUCING OBSTACLES
Heritage	Cultural Heritage, I. P.	Ensure the management, safe- guarding, enhancing and conser- vation of assets integrating the national cultural heritage, such as the Ocean Swimming Pool; Responsible for the implemen- tation of legislation and listing of cultural heritage; Authorize any intervention on listed properties.	Medium power/ High interest	Encourage to be more present in the decision making and protection regarding the Ocean Swimming Pool; Advocate for more frequent communication with local entities.
safeguarding	ICOMOS	Enforce the compliance with the World Heritage Convention, in case the Ocean Swimming Pool is included in the World Heritage List; Ensure the conservation status of the site and that interven- tions follow the most adequate technological, methodological and theoretical conservation approach.	Medium power/ High interest	Encourage to be more present in the decision making and protection of the Ocean Swim- ming Pool.

5.2 Design Principles Álvaro Siza: Ocean Swimming Pool (1960-2021).

 $5.3 \quad {\rm Stakeholder's\ interest/influence\ grid}.$

A.1	Advisory body	Promote the creation of an advisory body, which manages to articulate the different stakeholders to generate mechanisms for reaching consensus and enhancing participation with the interested parties in the implementation and monitoring of the CMP. Álvaro Siza, as a stakeholder, should be part of this advisory body and must be consulted regarding any future interventions on the Ocean Swimming Pool.
A.2	Álvaro Siza's design principles	A.2.1 <i>Program</i> - Ensure the site maintains its current use as established by Álvaro Siza in the original design.
		A.2.2 Interventions - Ensure any intervention in the Ocean Swimming Pool, determined by future needs, follows Álvaro Siza's design principles, defined in section 2.5.2.
		A.2.3 Urban policies - Consider Álvaro Siza's design principles in the definition of landscape and urban policies regarding the site's surroundings.
A.3	Investigation and knowledge	Ensure any intervention in the Ocean Swimming Pool is preceded by a detai- led investigation, condition survey, expert analysis, and the consultation of Álvaro Siza. The techniques, methodologies, and materials applied must follow the best international and technical standards.



Local management	Municipal Council of Matosinhos	Preserve and protect the city's cultural heritage including the Ocean Swimming Pool, by defining the urban and lanscape policies of its surroundings and also assuring its maintenance routines; Benefit from the economic impact of tourism as a result of the national and international recognition of the Ocean Swimming Pool. Make profit out of the Ocean Swimming Pool's use; Maintain, repair and replace building elements with minimum disruption and cost; Maintain the daily functioning of the Ocean Swimming Pool and ensure an effective interaction between the staff and suppliers.	High power/ High interest	Advocate for more communi- cation between departments and ensure that no change to the Ocean Swimming Pool can be done without consulting		Design management	Álvaro Siza	Ensure that the design prin of the Ocean Swimming Po respected.	siples High power/ ol are High interest	Involve the architect in the planning process/decision making from the outset and provide regular updates according to use or security needs.
				the Cultural Heritage, I. P.; Integrate the Cultural Herita- ge, I. P. decisions regarding listed properties in the Munici- pal Master Plan; Develop and implement poli- cies to protect and preserve the Ocean Swimming Pool; Improve the communica- tion strategy of the Ocean Swimming Pool, facilitating	Users	Bathers	Have a good sports and experience	eisure Low power/ Low interest	 Engage in workshops and other educational activities so that less informed users recognize the significance of the site, underlining the importance of following the user regulation inside the premises; Encourage to become part of the onsite virtual community or take action in disseminating the Ocean Swimming Pool significance. 	
				as opening schedules, visits, user regulations, etc.		Visitors	Increase knowledge about site and obtain a firsthand rience.	t the Low power/ ^{expe-} Low interest	Encourage to become part of the virtual community or take action in disseminating the Ocean Swimming Pool's signi- ficance.	
				Advocate and encourage more communication bet- ween Matosinhos Sport and the Municipal Council of Ma- tosinhos in order to prevent conflicts and improve results regarding maintenance and conservation interventions.			Virtual community	Disseminate knowledge o Ocean Swimming Pool.	n the Low power/ Low interest	Keep informed and provide appropriate platforms to con- sult/share information about the Ocean Swimming Pool.
					5.4 On a second level, there are the indirect influence stakeholders that hold some decision power over the site. This is the case of other national regulatory entities linked with environmental management such as the Portuguese Environment Agency (APA) which also holds an important role in the regulation and conservation of buildings, sites, and					
	Casa da Arquitectura	Disseminate knowledge and educate specialised and general public on Portuguese architec- ture and notably on the Ocean Swimming Pool; Make profit out of the guided visits conducted on the Ocean Swimming Pool.	High power/ High interest	Increase its role in the dis- semination strategy of the Ocean Swimming Pool; Create a cyclical visit program.		adaptation to climate change impacts such as sea level rise. neighborhoods of the Modern Movement, may play an im tant role in the safeguarding and dissemination of knowle about the Ocean Swimming Pool. It is also important to nowledge the Faculty of Architecture of the University of to and other education and research institutions for the di mination, promotion, and safeguarding of Álvaro Siza's wo				
	Bar concessionaire	Make profit out of the bar in the Ocean Swimming Pool;	Low power/	Extend the opening period beyond the normal functio- ning schedule of the Ocean		5.4 Potential strategies for gaining stakehold- er's support or reducing obstacles.				
		Provide the best possible service to the users.	Low interest	Swimming Pool so that visitors can enjoy the place for purposes other than bathing.		A.4 E	ngagement of stakehold	ers Engage with ICOMO tions, universities, a about the Ocean Swin	5, DOCOMOMO, and nd schools in dissem nming Pool.	other heritage related organiza- ninating and sharing knowledge
						A.5 A	dministrative control	Ensure the building's	management roles an	d responsibilities are clearly defi-

Ensure the building's management roles and responsibilities are clearly defined, assigned, and understood by all stakeholders. This CMP recommendations should be formally adopted by the Municipal Council of Matosinhos.

5.2.3 Sustainable Development Goals policies

The Sustainable Development Goals (SDGs) are a set of goals created by the United Nations to assess some of the most demanding issues that humanity is facing in the 21st century. There are currently 17 Goals, defined in 2015, based on the UN 2030 Agenda for Sustainable Development (UN, 2015). These are important strategic goals for the countries to take action upon granting world peace and achieving prosperity while tackling important issues like sustainability, equality, education, economic growth, and several others.

The Ocean Swimming Pool CMP seeks to comply with these goals, contributing to a set of measures that will maintain the good practices the property has been applying so far. It is also the utmost intent to adopt new SDGs that will further complement its role in the world's inclusiveness, education, shared knowledge, and sustainability as a recognized cultural heritage.

Promote the reduction of pollution, elimination of dumping

and minimization of hazardous chemicals and materials re-

Develop a plan to achieve these goals, save water and assu-

lease through a more sustainable management of water.

The CMP is committed to fulfilling the following SDGs:

CLEAR WATER AND SANITATION

QUALITY EDUCATION

TARGETS

4.7

COMMITMENTS

Promote quality education and learning opportunities.

CONTRIBUTION

Contribute to the education and training of site magers, staff and users regarding sustainability trough awareness and leadership.

8 DECENT WORK AND ECONOMIC GROWTH

TARGETS

8.3, 8.7, 8.9

COMMITMENTS

Promote sustainable tourism and fair and inclusive job opportunities.

CONTRIBUTION

Promote equality in the access to employment.

Promote local investment by using local sustainable products and services.

Foster practices of sustainable tourism by creating norms to protect the environment and the cultural heritage.

RESPONSIBLE CONSUMPTION AND PRODUCTION

CO

TARGETS

5

12.2, 12.5, 12.6, 12.4

COMMITMENTS

Efficiently use natural resources and reduce waste.

CONTRIBUTION

Increase resources efficiency by establishing productive measures and keeping record of the performance.

Develop maintenance and practice guides so that the different stakeholders can adopt sustainable measures and follow the same protocol.

4 LIFE BELOW WATER

TARGETS

14.1, 14.2, 14.3

COMMITMENTS

Manage natural water resources in a responsible manner.

CONTRIBUTION

Promote and safeguard local biodiversity by setting rules and restrictions for the users of the Ocean Swimming Pool and educate about its relevance to the environment.

Prevent any kind of ocean pollution resulting from the pool facilities by monitoring its waste and enforcing due procedures.

5.5

6

6.3

TARGETS

COMMITMENTS

CONTRIBUTION

Improve water quality.

re appropriate monitoring.

13 CLIMATE ACTION

TARGETS

13.1, 13.3

COMMITMENTS

Help reduce its environmental impact on climate change and its capacity to mitigate and adapt to it, safeguarding its heritage.

CONTRIBUTION

Achieve carbon neutrality and reduce energy consumption according to the Portuguese Government *Roadmap for Carbon Neutrality 2050*.

Increase the site's resilience to climate change by following the Coastal Zone Program, the Municipal Strategy for Climate Change Adaptation and Matosinhos Municipal Emergency and Civil Protection Plan.

Develop and antecipate lines of action for emergency response and disaster recovery.

17 PARTNERSHIPS FOR THE GOALS

8

TARGETS

17.6, 17.16, 17.17

COMMITMENTS

Create future and enhance present partnerships.

CONTRIBUTION

Create partnerships with other heritage sites at a national or international level in order to share experiences and knowledge.

Promote a good relationship and transparency between the different public and private entities and stakeholders that manage the site.

Promote meetings, protocols and other forms of contact between the Ocean Swimming Pool and other entities that can better help it accomplish the Sustainable Development Goals.

Comply with the good practices of the Sustainable Development Goals (SDG – UN 2030 Agenda) contributing to the inclusion, education, knowledge sharing, and sustainability of the world.



Interpretation policies 5.2.4

In order to convey the cultural significance and the heritage values of the Ocean Swimming Pool to the public, policies that foster interaction with visitors and several types of users are a fundamental part of this CMP so that they can establish responsible use and natural care about the place.

As expressed by the ICOMOS Charter for the Interpretation and Presentation of Cultural Heritage Sites, 'interpretation' refers to "the full range of potential activities intended to heighten public awareness and enhance understanding of cultural heritage sites" (ICOMOS-ICIP, 2008, p. 4). On the Ocean Swimming Pool, it can represent a series of active strategies that provide users with information about the site and keep them actively involved in acquiring more knowledge about its heritage values. It is also expected that interpretation allows people to create new narratives and engage with the place through experience and facilitate cultural significance recognition whilst maintaining public awareness about the conservation strategies proposed in this CMP.

The interpretation of the Ocean Swimming Pool should be made through effective communication by the Municipal Council of Matosinhos, Matosinhos Sport, and Casa da Arquitectura (see section 5.2.2). It would also be important to provide context about the significance of the Ocean Swimming Pool in the framework of buildings designed by Álvaro Siza, including those in the World Heritage Tentative List. This knowledge must be communicated through easy, direct, and concise activities with the public.

Hence, an Interpretation Plan should be based on comprehensive research to identify significant themes and interpretative opportunities that should be adapted according to the different audiences for the interpretative activities, providing a framework for managing visitors. The Plan should be regularly reviewed to incorporate lessons taken from the results of previous activities.

The Interpretation Plan shall include i) Communication, ii) Visits and events, iii) Community engagement, and iv) Archives and collections policies, to be further detailed in this section.

Communication

The complex dynamics behind the site's management, for whitre. The objective would be to create a shared knowledge ch the Municipal Council is ultimately responsible. Matosinhos network and make available the different procedures and Sport is charged with its operation during the bathing season methodologies adopted for the Ocean Swimming Pool and and Casa da Arquitectura organizes the guided tours, results the conservation and maintenance of other architectural in the lack of a coordinated communication strategy. Informaworks of Álvaro Siza. tion is, therefore, dispersed by each stakeholder's online pages preventing those interested in visiting from obtaining a com-Today, general information on the Ocean Swimming Pool is prehensive perspective on opening times, entrance fees, and presented in a vertical totem in front of the access ramp (fig. booking of visits. The site is closed to the public for most of 5.6). This hinders the interpretation of the site, as it prevents the year, a period in which visits have to be booked at least five an unobstructed perspective over the spaces and the fluidity days in advance and depend on the inscription of at least five of the oriented spatial experience. Hence, interpretation sigparticipants to take place, a procedure that excludes the possinage with significant size and impact should be avoided. Any sign or textual information should be easy to understand and bility of individual visits. Furthermore, the absence of year-round staff on the premises prevents many visitors who head to comply with Álvaro Siza's design principles, without disturthe site, unaware of the requirement to book visits in advance, bing the views of the site or obstructing circulation spaces. from experiencing its remarkable sequence of spaces or get-Also, it would be necessary to reflect on the criticalities of disting to know the history of its design and construction. playing information physically because of its impact on the property's perception, while reflecting on how this could be integrated in digital means through specific web apps.

The single online platform proposed above should also include this CMP and relevant information and documentation on the Ocean Swimming Pool belonging to other institutions

	ORGANIZA	TION	WEE	BSITE	LANGUAGE	CONTENTS
	Municipal Council Matosinhos		https://www.cm-matosi piscina-das-mares	nhos.pt/conhecer/lazer/	PT/EN	Description, opening schedule, fees, location and user regulation.
	Matosinhos S	port	https://www.matosinho	sport.com/gca/?id=440	PT	Opening schedule, fees, location and user regulation.
	Leça da Palm Parish Board	eira	https://www.leca-palmeira.com/piscinas-de-le- ca-da-palmeira-horarios-e-precos/		PT	Opening schedule, fees and loca- tion.
	Casa da Arquitectura		https://casadaarquitectura.pt/pt/visitas-guia- das/itinerarios/piscina-das-mares/		PT/EN	Guided visits schedule, prices and booking contacts .
 (FAUP (Keeping It Modern grant - Getty Foundation)		https://oceanswimmingpool.cargo.site to be migrated to https://sizaoceanswimmingpool. arq.up.pt		EN	Information regarding the history of the Ocean Swimming Pool and all the activities that took place under the Keeping It Modern grant.
	ISCTE-IUL/ FAUP http		https://istar.iscte-iul.pt,	ps://istar.iscte-iul.pt/sizaatlas/		Inventory of Álvaro Siza's built works and documentation of the works in the World Heritage Tentative List.
	5.8					
	A.8 Communication strategy		A.8.1 Online platform - Co general public that gather ming Pool, such as openi mation on the site's histo	reate a single o ers all relevant ir ng schedules, e ry and significa	nline platform easily accessible by the nformation regarding the Ocean Swim- ntrance fees, user regulations, or infor- nce.	
				A.8.2 Shared knowledge those responsible for the integrated dissemination	network - Estal management of	blish a shared knowledge network with of other Álvaro Siza's works, creating an



Interpretation Plan

56

A.7



5.7

Develop and implement a comprehensive Interpretation Plan based on a clear understanding of the significance of the place and that establishes how the cultural significance will be communicated through specific programs, visits and activities, engaging the community and its users.

5.6 Vertical information totem placed in front

5.8 Online platforms with institutional infor-

mation on the Ocean Swimming Pool.

of the access ramp, 2021. 5.7 Matosinhos Sport webpage. such as the Canadian Centre for Architecture, the Municipal Archive of Matosinhos, and the FAUP Documentation Cen-

Visits and events

An Interpretation Plan should be developed involving all the interested parties, namely the stakeholders responsible for the Ocean Swimming Pool operation. The significant values of the asset should be made accessible and communicated to all who use and visit the place, as well as those who access it by other means. The most important active interpretation of the site is through its ongoing use as a public swimming pool. As long as this activity continues, then arguably the most significant aspects of the place are being interpreted. Guided visits are other interpretation initiatives that should be promoted as they are very effective in engaging the physical, emotional, and intellectual capacities of the visitor, revealing gualities and stories about a place which would not otherwise be evident. Thus, the training of guides and the definition of the visits' contents are of uttermost importance. They should engage the visitor with Álvaro Siza's design principles and the site's cultural significance. The creation of a web app with an audio guide or tour proposal could be considered as an alternative for individual visits.

The possibility of occasionally hosting events such as concerts or exhibitions should be explored as a means for broadening general public contact with the Ocean Swimming Pool. However, the site's high exposure to the marine environment creates some weather-related unpredictability so this calendar of recreational activities must be flexible and with low impact. Also, surveys to users and visitors have demonstrated an interest in having the bar open beyond the bathing season and the possibility of buying tickets directly on the premises.

Community engagement

'Community engagement' is understood as a process of creating opportunities for knowledge sharing and collaboration of stakeholders with low power to propose guidelines for the preservation of the Ocean Swimming Pool. As previously presented (see section 5.2.2), they are the visitors, the users, and the bathers. Policies in this category should address ways to combine official and scientific interpretation and communication strategies to the emergence of affective memories and new narratives of cultural significance.

Casa da Arquitectura performs visits for visually impaired people, as well as several workshops with children. Children are important as the future guardians of the Ocean Swimming Pool. Since they are amongst the bathers and visitors, especially in the holiday season, a proposal for learning programs should be carried out, making children aware of heritage values through games and playful activities. This will bring them closer to the work of Álvaro Siza and engagement can be achieved through stimulation, curiosity, and motivation by provoking the creation of affectionate memories with the support of architecture and art.

Archives and collections

In 2014, Álvaro Siza donated his archives to three internationally renowned institutions: the Canadian Centre for Architecture (CCA) in Montreal, Canada, the Gulbenkian Foundation in Lisbon, and the Serralves Foundation in Porto, Portugal. Even though the bulk of the documentation regarding the Ocean Swimming Pool is held in Montreal by the Canadian Centre for Architecture, further documentation is held by the Municipal Archive of Matosinhos, the Faculty of Architecture of the University of Porto and in the personal archives of both Álvaro Siza and some photographers that registered the site before and during the time of its construction. Therefore, all the documen-

5.9 Guided visit during Porto Open House,
2021.
5.10 Guided visit during Porto Open House,
2021.
5.11 Terrace chair detail, 1973.





5.9



A.9.1 *Learning programs* - Develop learning programs for schools and families, composed of didactic activities for children, related to the Ocean Swimming Pool.

A.9.2 Broadening access - Promote specific visits and knowledge dissemination activities aimed at visitors with additional access needs, such as deaf and visually impaired audiences, promoting inclusiveness and broadening access to the site.



5.11

A.10	Archives and collections	A.10.1 Archives Ocean Swimmi ting a compreh
		A.10.2 Collection cifically design location and concumentation.

tal evidence related to the Ocean Swimming Pool which is dispersed throughout different institutions should be cataloged and digitized, creating a comprehensive database available for consultation of interested parties from all over the world.

This inventory should be extended to significant furniture pieces and fittings specifically designed by Álvaro Siza for the property to retain and protect their significance into the future, even if they are still in use. Also, the existing operations manual should be reviewed against international best practice to identify gaps and improvements in housekeeping, namely weekly monitoring as part of regular maintenance actions.

- Gather, catalog, and digitize all documentation related to the ng Pool that is dispersed throughout different institutions, creatensive digital database available for consultation of interested over the world.

ons - Create an inventory of all the furniture and objects spened by Álvaro Siza for the property with information on their pondition to assure their future preservation and exhaustive do-

5.3 Site policies

5.3.1 Planning policies

The site policies' definition of this CMP was supported by international and national guidelines and legislation that define the site's management with regard to its spatial planning, as well as risk assessment and climate change adaptation (fig. 5.12).

The Portuguese Spatial Planning System is organized into three hierarchical levels: national, regional, and local. National and regional programs are the responsibility of the Government (in collaboration with regional and local authorities), being mainly strategic and framework providers for other plans. At the local level, the municipal planning tools are organized hierarchically: Municipal Master Plans, Urban Plans, and Detailed Plans. Un-

der the responsibility of Municipal Councils, those instruments are primarily regulatory and land-use based.

The Municipal Master Plan, mandatory for the 308 Portuguese municipalities, defines the strategy and rules to manage rights and duties over land and resources. This plan also incorporates other 'tools', fundamental to support the management of susceptible resources, such as heritage (Heritage Map), and environmental ones (Legal Regime of the National Ecological Reserve). Those guidelines and rules are the boundaries for other municipal planning tools, such as the operative and physical related design, such as the Urban Plans and Detailed Plans.

SCOPE	SPHERE OF ACTION	PLANNING INSTRUMENTS	DATE
International level	Climate change	Draft updated Policy Document on the impacts of climate change on World Heritage properties (WHC, 2021)	2021
		The Future of Our Pasts: Engaging Cultural Heritage in Climate Action (ICOMOS, 2019)	2019
		Paris Agreement (UNFCC, 2015)	2015
	Sustainable Development	Transforming our world: the 2030 Agenda for Sustainable Development (UN, 2015)	2015
	Risk assessment	Sendai Framework for Disaster Risk Reduction 2015-2030 (UNDRR, 2015)	2015
		Managing Disaster Risks for World Heritage (WHC, 2010)	2010
		Directive on the assessment and management of flood risks (Directive 2007/60/EC, 2007)	2007
	Climate change	Policy Document on the Impacts of Climate Change on World Heritage Pro- perties (WHC, 2006a)	2006
		Climate Change and World Heritage. Report on predicting and managing the impacts of climate change on World Heritage (WHC, 2006b)	2006
National and regional level	Sea level rise/ Climate change	Caminha-Espinho Coastal Zone Program (Resolution of the Council of Ministers No. 111/2021, 2021)	2021
	Climate change	Roadmap for Carbon Neutrality 2050 (Resolution of the Council of Minis- ters No. 107/2019, 2019)	2019
	Environment	Legal Regime of the National Ecological Reserve (Decree-Law No. 166/2008, 2008)	2008
	Heritage	Law for Cultural Heritage (Law No. 107/2001, 2001)	2001
	Planning	Legal Framework of the Ports of Douro and Leixões Administration (Decree- -Law No. 308/87, 1987)	1987
Municipal level	Planning	Municipal Master Plan (Notice No. 13198/2019, 2019)	2019
	Climate change	Municipal Strategy for Climate Change Adaptation (CMM, 2019)	2019
	Disaster response	Matosinhos Municipal Emergency and Civil Protection Plan (CMM, 2011)	2011

Heritage Safeguarding

The Heritage Safeguarding Map aims to protect heritage by inventorying and mapping its architectural and archaeological sites (including their Buffer Zones), defining specific rules for those protected areas in the context of the Municipal Master Plan. This mapping process targets every work of architectural, artistic, ethnographic, technical, or social interest that was



B.1	Spatial Planning	The Ocean Sw with the legal in Master Plan and
B.2	Cultural Heritage Safeguarding	Comply with the any intervention to affect it, with detailed safegu pation and prior vention criteria parts of the set ban and landsc
B.3	Buffer Zone preservation	Respect the res 608/2012, to er perty into the la integration of a vant to the cont topography, alig the exterior finis the cultural heri

172

selected to be protected. The Ocean Swimming Pool is listed as National Monument, being thus identified as a Listed Property, protected by a Special Buffer Zone which includes the Boa Nova Tea House and Restaurant, designed by Álvaro Siza and also listed as National Monument.

5.12 International, national, regional and municipal level planning instruments.5.13 Municipal Master Plan heritage safeguarding plan.

rimming Pool's management and conservation must comply istruments that regulate spatial planning, such as the Municipal d others at the national, regional, and local levels.

the Law for Cultural Heritage (Law No. 107/ 2001), which forbids ns, inside or outside listed properties or any change of use likely nout prior consent from the cultural heritage administration. A uarding plan for the area must be established, defining: occurity uses; the conservation works to be implemented; the interin the built and natural elements; the inventory of all the integral t; the strategic lines of intervention, in the economic, social, urtage renewal contexts.

strictions posed by the Buffer Zone, defined by Ordinance No. Insure the preservation of views and the integration of the proandscape. The Buffer Zone ensures the landscape and visual a given property including the surrounding areas that are reletext. Licenses for construction works or any work that alters the gnments, heights, and the distribution of volumes and roofs or ishes of buildings cannot be granted without prior assent from itage administration.

Coastal protection

The Ocean Swimming Pool is conditioned by the restructured Caminha-Espinho Coastal Zone Program (POC-CE), as it is positioned between the Maritime Protection Zone (more specifically the Coastal Protection Strip that aims to safeguard natural resources) and the Land Protection Zone (more specifically the

Seashore that aims to safeguard and manage the water domain). Subsequently, the Ocean Swimming Pool is also set in the Coastal Erosion Safeguard Strip (Level 1) and the Coastal Flood and Overflow Safeguard Strip (Level 1) which aim to safeguard the coastal risks, for the time scenario of 2050 (which corresponds to level 1).



- Coastal Erosion Safeguarding Strip (Level 1) 5.14
- Coastal Flood and Overflow Safeguarding Strip (Level 1)

5.3.2 Risk assessment and climate change adaptation

The set of policies outlined for risk assessment and climate The identified extreme risks from natural origin are Coastal change adaptation are supported by a broad number of inter-Erosion (Level 1) and Oceanic Overflow and Coastal Flooding national, national, and municipal plans and legislation outli-(Level 1). Identified as high risks are accidents in the oil refinery, ned in section 5.3.1. According to information from the Muniin loading and unloading of hazardous substances from ships cipal Master Plan and the Civil Protection Department, risks in the port of Leixões or the transport of dangerous substanare classified into two main levels, according to the severity ces through pipelines, among those of technological origin, degree, and likelihood of occurrence: extreme risk and high and the occurrence of extreme weather phenomena along the risk. They are further classified according to their origin, be it coast, such as storm surges, as the most significant risk of natechnological (resulting from human activity) or natural. tural origin.



Coastal protection regulation	Comply with the Caminha-Espinho Coastal Zone Program, which determines	
, ,	that new constructions, soil sealing actions, changes to the coastline, and acti-	
	vities that result in the direct destruction of relevant marine ecosystems or rock	
	outcrops are forbidden along the Coastal Protection Strip in which the property	
	is set.	
	Coastal protection regulation	Coastal protection regulationComply with the Caminha-Espinho Coastal Zone Program, which determines that new constructions, soil sealing actions, changes to the coastline, and acti- vities that result in the direct destruction of relevant marine ecosystems or rock outcrops are forbidden along the Coastal Protection Strip in which the property is set.

5.14 Coastal Zone Program plan. 5.15 Risk map (adapted from the Municipal Master Plan and information provided by the Civil Protection Department).

Climate change is a global challenge for the present and fu-scenarios and vulnerabilities ranked according to their liketure generations that has become one of the biggest threats to humankind and built heritage. It is crucial to acknowledge and understand the impacts that natural and anthropic hazards have on the Ocean Swimming Pool, in particular those cur through a flexible plan that considers multiple scenarios whose effects are intensified by climate change, to ensure and an emergency/post-disaster plan that would rapidly and that they are prevented, mitigated, or, when that is not possi-efficiently restore the situation back to normal. ble, that adaptation measures are implemented. In chapter 4 (section 4.4) these hazards were already identified, alongside

lihood and severity to assess their risk level. It is essential to adapt to the present and future impacts they will have on the property and to assure preparedness when such events oc-

B.5	Risk Management Plan	B.5.1 <i>Risk management</i> - Develop and implement a Risk Management Plan which includes regular risk assessments, the development of mitigation measures, and emergency preparedness measures.
		B.5.2 <i>Disaster recovery</i> - Develop and anticipate lines of action for emergency response and disaster recovery.
B.6	Green procurement	B.6.1 Environmental analysis - Conduct an environmental analysis of the Ocean Swimming Pool's regular functioning to identify energy-saving opportunities.
		B.6.2 Green procurement - Adopt green procurement (energy, waste, and water) and carbon offsetting strategies, emphasizing green products, services, and business models.
B.7	Climate change adaptation	B.7.1 Adaptation measures - Compile a set of measures, or actions (as a study case), for implementation in other cases with similar constraints, to help other listed sites to adapt to climate change. Similarly, the knowledge obtained from this case study should also suggest additional measures or guidelines for local and regional policies.
		B.7.2 Permanent flooding - Study future lines of action for building conserva- tion in case of permanent damage or flooding that makes the normal use of the built structures and infrastructures impossible (be it relocation, the construc- tion of more permanent protection measures like walls or spurs, etc.).
		B.7.3 Staff training - Train staff/stakeholders and inform users on more efficient management strategies, and promote the use of sustainable practices while working, using, or managing the place. It would be beneficial to the implementation of these strategies if there were participatory activities, presentations, or workshops to raise public awareness of appropriate mitigation measures.
		B.7.4 Archival information - Organise an archive containing exhaustive information on the Ocean Swimming Pool (3D and 2D mapping, visual information, etc.) to assure its proper reconstruction and future preservation in case of damage or material loss.

5.16	Ocean	Swimming	Pool	during	a	storm
surge	e (folowi	ng page).				



5.3.3 Landscape policies

The Ocean Swimming Pool landscape integration is a crucial element to its cultural significance, as it was one of the main concerns of the original design and must, therefore, be preserved. Being listed as National Monument, its Buffer Zone contributes to the protection of the visual integrity between the property and its surrounding context.

However, this landscape integration is exposed to several vulnerabilities. Real estate pressure led to a significant increase in constructions along the seafront, which created a negative impact, since they are visible from the site, compromising the radical horizontality of the setting that was fundamental for Siza's original design principles.

The beaches play a crucial part in the composition of the views, so they can have a negative visual impact if not well maintained. This includes the removal of accumulated waste as a result of human activities or transported by the tides.

Finally, the absence of a Landscape Management Plan makes it more difficult to enforce a coherent approach toward the protection of the site's visual relationships, namely the visual alignment that the terrace wall establishes with the port's mole.





5.18

5.17

- 5.17 Location of the image captions.
- 5.18 Location of the image captions.

5.19 Visual continuity towards the south and the Port of Leixões (View 1), 2021.5.20 Visual continuity towards the north and the Boa Tea House (View 2), 2021.



5.19





5.21



5.22

5.21 Uninterrupted views towards the sea from the avenue (View 3), 2021.5.22 Integration of the adults swimming pool

(View 4), 2021.

5.23 Warning sign by the adults swimming pool disturbing visual relationships, 2021.

5.23

5.24 Visual continuity towards the north and the Boa Tea House (View 5), 2021.
5.25 Visual alignment (dashed line) that the 45° terrace wall establishes with the port's mole (View 6), 2021.



5.24





5.26



5.27



5.28

5.26 Relation between the site and the street, where it is evident the real estate pressure created by the taller buildings (View 7), 2021.
5.27 View from the south beach, where the marginal avenue's taller buildings break the idea of a horizontal wall that separates de viewer from the stree (View 8), 2021.

5.28 Terrace furniture, 2021.5.29 Intrusive placement of furniture along the north platform, 2021.

3.8	Landscape Management Plan	B.8.1 Landscap ment Plan that racteristics, ess site or inside its ensure the clos cape is retained
		B.8.2 Urban platby the seaside diate context.
		B.8.3 Visual re ture that obstr and its surrour
		B.8.4 Landscap ding's roof, with avoid obstructi
		B.8.5 Beach cle crops to avoid t
		B.8.6 <i>Placemer</i> tables to the ba the bar concess sionaire should on the exterior.
		B.8.7 Placement curity warnings to prevent the c

5.29

e integration - Develop and implement a Landscape Manageensures the preservation of the site's surrounding context chasential for the building's significance. Any intervention in the s Buffer Zone must be submitted to the Cultural Heritage, I. P. to e relationship between the property and the surrounding landsd.

anning - Enforce urban planning restrictions on building height avenue, preventing further visual impacts over the site's imme-

lations - Ensure the prohibition of any intervention or strucructs the visual relations between the Ocean Swimming Pool adings.

bing - Implement a landscaping plan for the gardens on the builn regular maintenance cutting and pruning of the vegetation to ng the view from the avenue.

aning - Implement a cleaning routine of the beach and rock outthe accumulation of waste on the site.

at of furniture - Limit the presence of furniture such as chairs and ar terrace. Parasols for the use of bathers must be requested to sionaire and abide by uniform design features. The bar conces-I restrain from placing equipment (such as ice cream freezers)

nt of signage - Control the placement of signage (such as ses) and other elements in the building, swimming pools, or rocks disturbance of the visual relation with the landscape and the sea.

5

5.4 **Conservation and maintenance policies**

5.4.1 Tolerance for change

This section aims at identifying the tolerance for change levels of the most significant spaces and components of the Ocean Swimming Pool. It should serve as a tool for managing change while retaining and eventually enhancing the site's cultural significance. Future changes or conservation inter-

ventions must not interfere with the components and functions of higher significance, hence the importance of clearly establishing each space's tolerance for change to inform management decisions and the conservation methodologies adopted in future interventions.

SPACE	TOLERANCE FOR CHANGE		ANGE	CONSIDERATIONS			
Changing rooms	1 = Low tolerance				Any intervention in this space must be of conser-		
significance ranking: A		oderate	tolerar	nce	vation as its configuration and material are most		
Built between 1962 and 1965, the changing rooms, with their dark and involving atmos- phere, are an essential part of the oriented spatial experience, mediating the transition between the street level and the interior of the bathing complex.		gh tole	rance		stain and its copper cladding, the exposed con-		
		FABRIC	FUNCTION	LOCATION	crete walls with horizontal formwork finish, the Baltic pine partition walls, doors and joinery with dark stain, original brass fittings and the white concrete slabs must be retained unaltered.		
Copper cladding	1	1	1	1	Configuration and material are most important. Retain unaltered.		
Baltic pine roof structure with dark stain	1	1	1	1	Configuration and material are most important. Retain unaltered.		
Exposed concrete walls with horizontal formwork finish	1	1	1	1	Configuration and material are most important. Retain unaltered.		
Baltic pine partition walls with dark stain	1	1	1	1	Configuration and material are most important. Retain unaltered.		
White concrete slabs	1	1	1	1	Configuration and material are most important. Retain unaltered.		
Baltic pine doors, frames and joinery with dark stain	1	1	1	1	Configuration and material are most important. Retain unaltered.		
Copper and brass fittings	2	1	1	2	Configuration and material are most important. There is, nevertheless, some tolerance for change in form or location to respond to future needs.		
Ceramic wash basins and foot washes	2	2	1	2	The original foot washes should be kept. Even if there is some tolerance for change in form or loca- tion to respond to future needs, the replacement of any component should take into account the overall coherence and opt for similar models.		
Exposed water network in copper tubes	2	1	1	2	Configuration and material are most important. There is, nevertheless, some tolerance for change in form or location to respond to future needs.		
Exposed electrical network in copper tubes	2	1	1	2	Despite being a result of the recent conservation works (2018-2021), the exposed copper tubes were carefully integrated in the architectural de- sign and follow Álvaro Siza's design principles for the set. Even if there is some tolerance for change in form or location to respond to future needs, the visibility of new elements should be minimized.		

The methodology of this section is aligned with the tolerance for change framework at heritage places (Burke, 2017) and supported by the analysis and evaluation of different sources, with a special focus on interviews with site managers and visual inspection, as well as archival and documental research. This process allowed a better understanding of the characteristics of the original construction and the interventions the property suffered over time. Having the most significant spa-

The identification of the tolerance for change of each space was implemented through tables in which every component was discriminated and evaluated individually (fig. 5.30). For a more clear presentation, the results of this work were converted into synthesis tables (presented in Appendix E) in which according to the overall evaluation of its components, a single level of tolerance for change is attributed to each space, followed by a brief description of the characteristics of the space, the conservation works it underwent and considerations regarding future interventions and opportunities for change (fig. 5.31). Lastly, a summary of the results is presented in figure 5.32.

ces of the building identified, the four steps for managing tolerance for change listed below were applied to each of them: i) Establish the level of significance of each space. This process is supported by the assessment of significance carried out in chapter 3, in which four levels were identified: exceptional, high, moderate, and some significance; ii) Identify the components of each space that contribute to the cultural significance of the place;



Space	Changing rooms (2)
Level of significance	Exceptional significance
Tolerance for change	Low tolerance
Description	Built between 1962 and 1965, the an essential part of the oriented level and the interior of the bathi During the last conservation wor tionally, the electrical wiring was architectural design and in accord
Considerations and opportunities for change	Any intervention in this space r most important. The i) Baltic pin exposed concrete walls with ho doors and joinery with dark stain be retained unaltered.
	There is some tolerance for char washes to respond to future need nt the overall coherence and opt
	There is some tolerance for chan networks to respond to future ne sibility of new elements should b
5.31	

5.30

iii) Evaluate the tolerance for change of each component, according to its form, fabric, function, and location, on a scale of three levels: low, moderate, and high;

iv) Define operating guidelines to manage future conservation interventions to minimize negative impacts and keep the site's values intact, considering opportunities for change that support or enhance its cultural significance.

changing rooms, with their dark and involving atmosphere, are spatial experience, mediating the transition between the street ing complex.

rks all the wooden elements were cleaned and varnished. Addiplaced inside exposed copper tubes, carefully integrated in the ordance to Álvaro Siza's design principles.

must be of conservation as its configuration and material are ne roof structure with dark stain and its copper cladding, ii) the prizontal formwork finish, iii) the Baltic pine partition walls, iv) n, v) original brass fittings and vi) the white concrete slabs must

nge in form or location of the vii) ceramic wash basins and foot eds. The replacement of any component should take into accoufor similar models.

nge in form or location of viii) the exposed water and ix) electrical eeds. Nevertheless, only copper tubes are to be used and the vipe minimized, in compliance with Álvaro Siza's design principles.

SPACES	LEVEL OF	TOLERANCE FOR CHANGE ²				
011020	SIGNIFICANCE	FORM	FABRIC	FUNCTION	LOCATION	
Entrance ramp and changing rooms hallway (1) (3)	А	1	1	1	1	
Changing rooms (2)	А	1	1	1	1	
Collective changing room (21)	С	1	2	2	1	
Cloakroom (15)	В	1	1	2	1	
Water treatment room and chlorine cabinet (18) (20)	С	1	1	1	1	
South bathrooms (13)	В	1	2	1	1	
Security room (22)	С	2	2	3	1	
Water collection room (19)	D	3	3	1	1	
South storage rooms (24) (25)	С	2	2	3	1	
South platform (10)	В	1	1	1	1	
Beach and access paths (8) (4)	А	1	1	1	1	
Swimming pools and foot washes (6) (7) (5)	А	1	1	1	1	
West platform (11)	В	1	1	1	1	
Bar and terrace (16) (9)	В	1	1	1	1	
Kitchen (17)	С	1	2	2	1	
North platform (12)	В	1	1	1	1	
North bathrooms (14)	С	2	2	2	1	
Employee's changing rooms and bathrooms (23)	D	3	2	3	1	
North storage room and waste management room (26) (27)	D	3	2	3	1	

¹Level of Significance: A) Exceptional B) High C) Moderate D) Some ²Level of Tolerance for Change: 1) Low 2) Moderate 3) High 5.32

5.30 Tolerance for change definition for the components of each space (example).

5.31 Tolerance for change definition for each space, including brief description and oportuni-

ties for change (example, see Appendix E).

5.32 Summary of the tolerance for change definition.

5.33 Building elements and components (water treatment room and changing rooms).

C.1	Significance and tolerance for change	All elements of th naged in accorda 3 and the identifi lowing general po the place and are guidance for char cance refer to sec
		A) Exceptional sig
		unless otherwise conservation and to re of the element is
		B) High significan
		Alteration of election of election of exceptional sign Change tables. It retained and resp
		C) Moderate sign
		Alteration of elem order to retain o mentioned in the supporting eleme
		D) Some significa
		Elements consider mentioned in the supporting eleme



the Ocean Swimming Pool are to be maintained, used and madance with their relative level of significance, defined in Chapter tified tolerance for change for their component parts. The folpolicy statements have been formulated to guide changes at re supplemented by more detailed conservation guidelines and hange on each component in Appendix E. The levels of signifisection 3.7 and are to be considered as part of this policy.

significance:

ements considered of exceptional significance is not permitted se mentioned in the Tolerance for Change tables. Maintenance, nd repair interventions are permitted to ensure their ongoing retain significance. It is essential that the original design intent is retained and respected.

ance:

elements considered of high significance is permissible only cessary in order to retain or strengthen an element considered significance or unless otherwise mentioned in the Tolerance for It is essential that the original design intent of the element is spected.

gnificance:

ements considered of moderate significance is permissible in or strengthen those of higher significance, unless otherwise he Tolerance for Change tables. It is essential that their role in ments and functions of higher significance is retained.

cance:

idered of some significance may be altered, unless otherwise he Tolerance for Change tables. It is essential that their role in ments and functions of higher significance is retained.

5

5.4.2 Detailed conservation and maintenance policies

This section aims at providing non-exhaustive guidance for the conservation and maintenance of the Ocean Swimming Pool. In order to approach all the constructive elements of the building in detail, this section is subdivided into sub-sections dedicated to the different elements and their components: Roofs (copper cladding/ wooden structure/ concrete slabs); Walls (cyclopean concrete retaining walls/ lightly reinforced concrete walls/ wooden partition walls); Pavements (white concrete slabs/ cement plaster pavements); Frames and hardware (wooden frames/ metal frames); Furniture and Fittings; Tanks; and Installations (plumbing/ electrical wiring).

The identification of 'Maintenance Source Elements' (Abrantes, 1994; Calejo, 2006) and their respective components is an essential parameter to enable an adequate recognition and framework of the functional and constructive characteristics of the building and the definition of the Maintenance Plan. Each 'Maintenance Source Element' corresponds to a building system, with its own conditions and mechanisms, which allows to optimize the assigned service performance levels and thus outlining maintenance policies and strategies.

Maintenance actions allow to obtain information based on management assumptions and resource optimization necessary for the implementation and execution of the various procedures of maintenance strategies. The set of actions to which a preventive maintenance strategy corresponds (inspection, cleaning, proaction) is characterized by acting before pre-pathology phenomena, and, therefore, seeking to obtain more satisfactory results.

The Maintenance Plan (IPQ, 2007) is a part of great importance in the CMP, as it describes the set of specifications that aim to foresee and plan the various maintenance actions, defining the various tasks to be performed for: i) inspection, ii) cleaning, iii) proaction and iv) repair. The latter includes replacement and correction actions aiming at restoring the initial conditions foreseen in the design.

i) Inspection actions render it possible to obtain behavior indicators of the various elements of the building, which enhance the recognition of pre-pathology phenomena.

ii) Cleaning actions allow for an improvement in performance equal to that initially foreseen and can range from housekeeping procedures that ensure the element/component remains clean, to a technical cleaning seeking to implement a set of actions to improve the element's performance carried out by a specialized technician.

iii) Proaction makes it possible to obtain functioning indicators of the various elements and guarantee their correct performance. This process can be particularly important, before pre-pathology phenomena, because it can help to anticipate the appearance of anomalies, which would end up implying an early replacement of the element or component.

iv) Repair actions are meant to restore the initial performance of the elements/components (after prior inspection). The implementation of these actions depends on some aspects, such

as the correction of anomalies and the diagnosis, thus seeking to avoid a functional breakdown or an anticipated end of life. In a limit situation, when the end of its useful life occurs, the total replacement of the element/component will be necessary, corresponding to its end of cycle.

This section focuses on compiling detailed information on building elements and components as support for future conservation and maintenance actions (both preventive and reactive) responding to threats and vulnerabilities, daily wear and tear, or interventions related to functional upgrades or adaptations responding to new requirements. Its structure is based on sheets for each 'Maintenance Source Element' and its components, including: i) characterization of the original design solution (1960-1973), ii) description of the most recent conservation intervention (2018-2021), and iii) guidance for future interventions.

Based on the effects the previously identified hazards can have on the element's condition, it is possible to generate management and maintenance actions to guarantee its good condition and physical integrity. Therefore, it is possible to ensure preventive conservation that minimizes physical changes through specialized advice in conservation decisions and actions. Thus, specific lines of action were developed for each constructive element in order to maintain its integrity and at the same time preserve the site's significance.

5.34 Coding of building components.5.35 Identification of building components

(changing rooms section).

ELEMENT	COMPONENT	CODE	
Roofs	Copper cladding	Rc	
	Wooden structures	Rw	
	Concrete slabs	Rs	
Walls	Cyclopean concrete retaining walls	Wr	
	Lightly reinforced concrete walls	Wc	
	Wooden partition walls	Ww	
Pavements	White concrete slabs	Ps	
	Cement plaster pavements	Рр	
Frames and	Wooden frames	Fw	
hardware	Metal frames	Fm	
Furniture and fittings			
Tanks			
Installations	Plumbing	lp	
	Electrical wiring	le	

5.34





Roofs

Copper cladding (Rc)

"The construction system adopted is that of unplastered ne, composed of asphaltic felt and copper alloy finish, applied poorly reinforced concrete walls, supporting a Baltic pine roof, covered with copper cladding over asphalt fabric." (Siza, 1965)

Original design (1960-1973)

The roofs of the changing rooms, south bathrooms, water treatment room, and bar are clad with 'Alcufol' type membra-



over 10 mm thick cork agglomerate. This solution included 1

mm thick copper sheet tops and rain gutters. In 1995, the ori-

ginal cladding solution was entirely replaced with a 1 mm thick

electrolytic copper roofing, 'Astoriana' type, fixed by stainless

steel clips (AISI 304) placed every 60 cm and applied over 40

mm thick black cork agglomerate and a waterproofing plas-

tomer bitumen membrane.



sobrepor imperm. ALLUFOL, Rufos em cobre, aglomerado de contigo posthode o. 15 de lorgo oproximad 15×4 208 2015 15×6

5.38



5.37

Conservation (2018-2021)

The roof's copper cladding was cleaned with a soft brush so as not to damage the patina and overhauled, including the replacement of elements, welding, the strengthening of joints and tops, and the replacement of seam clips.



5.40

- 5.36 Changing rooms' roof, 1968.
- 5.37 Changing rooms' roof detail, 1966.
- 5.38 Changing rooms' roof, 1968.
- 5.39 Changing rooms' roof detail, 1965.
- 5.40 Changing rooms' roof, 2021.

ACTION LINES

ii. Cleaning	Annual manual cleaning of the copper plates u water drainage components. These should al winds, also observing the possible occurrence
iii. Proaction	Every five years, control and record the existent the seam clips and screws of the copper plate
iv. Repair	If necessary, repair or replace damaged or m geometry as the existing ones. Correct any a replacing damaged plates. These works must

of waste or sand.

i. Inspection Annual condition check-up and record to ensure that there is no damage, such as signs of corrosion (especially from pitting and/or interstitial), cracks in the joints between the sheets, deformations (kinks and warping) or other anomalies, observing if the copper plates are mounted correctly; semi-annual condition check--up and record of the water drainage components, to ensure that no blockages occur from the accumulation

> ising a soft brush so as not to damage the patina, including the lways be checked after a prolonged period of rain and strong of infiltration inside.

> ence of early degradation in the joints/overlays (seams) and in s. The use of a video endoscope may be required.

> hissing components with new ones in the same material and nomaly in the overlays and assembly of the copper cladding, include a previous diagnosis.

Roofs

Wooden structures (Rw)

"There is wood, in very protected places, which resists very well by the seaside. There is this idea that wood is something vulnerable and that it rots; it has been there for over fifty years but that wood is at least two hundred years old, it is reclaimed Baltic pine from demolitions at that time." (Siza, 2015)

Original design (1960-1973)

The sloping roofs of the changing rooms, south bathrooms, and bar are made up of 3 cm thick tongue and groove boards, over reclaimed Baltic pine beams. The wooden surfaces were first impregnated with a coat of boiled linseed oil, applied hot, and this protection was replaced with two coats of varnish, 'BONDEX-DYRUP' type, after previous scraping, between 1971 and 1973.

Conservation (2018-2021)

The beams and other wooden components of the roofs were overhauled and cleaned in order to remove all contaminants from the surfaces. To do so, a universal stripper (ref. 8015) and a steel wire brush were applied following the wood grain direction until it was in its natural state. This was followed by cleaning with a water jet and the application, without dilution,





5.41

5.42



5.41 South bathrooms roof's wooden structures, n/d.
5.42 South bathrooms roof's wooden structures, n/d.
5.43 Wooden structures details, 1965.
5.44 Wooden structures during conservation works, 2020.
5.45 Wooden structures during conservation works, 2020.

	ACTION
i. Inspection	Annual integrity check-up and record of the wor nomena, observing the existence of cracks, de or signs of attacks by xylophagous organisms. out by a structural engineer to evaluate the app
ii. Cleaning	Every two years, wooden surfaces must be cle contaminants, such as fungi, algae, dust, and a
iii. Proaction	Every two years, if necessary, wooden surfaces layer of coating, followed by the application of 4385) with a brush following the wood grain di
iv. Repair	If necessary, damaged wooden elements must tics. These works must include a previous diag

5.44

of a coat of 'Bondex Classic Mate' stain (ref. 4385 black) with a brush following the wood grain direction.

The existing mosquito nets and metal crates between the bar's beams were removed, as well as the stainless steel cladding on the kitchen ceiling. The screw holes were filled with bitumen made from polyester resins.



5.45

N LINES

oden structures focused on their stability and degradation pheformations, defects of the structural elements, signs of rotting, Every ten years, a structural integrity check-up must be carried bearance of new anomalies or the aggravation of existing ones.

eaned with water and manual brushing to remove any existing accumulated dirt.

s must be lightly sanded without entirely removing the existing one coat of an alkyd-based solution (Bondex Classic Mate ref. rection.

be repaired or replaced with new pieces of similar characterisgnosis.

Roofs

Concrete slabs (Rc)

"The construction processes and materials used are similar to those adopted in the previous phases, given the strict conditions imposed by the location of the pool. That is, bare concrete is used in partition walls and slabs, Baltic pine is used in frames, and concrete slabs are used for interior floors." (Siza, 1973)

Original design (1960-1973)

The roofs of the water treatment and collection rooms, as well as the north and south storage rooms, are made up of reinforced concrete slabs at a percentage of 52kg/m³ in the north building and 130kg/m³ in the south building. The woo-

den plank formwork is visible on the underside of the slab, which is in exposed concrete (in the security room and the water collection room, the ceiling was painted white). Prefabricated plastic-asphalt membranes, 'Morter-Plas' type, were used, consisting of a polyethylene film covered on both sides with layers of special catalytic asphalt. The membranes were applied directly on the leveling layer with 10 cm welded overlaps. The edges were reinforced with overlapping membranes. For a protective finish, a 3 cm thick cement and sand screed in a 1:3 ratio was applied and finished with a trowel over a plastic film. The north and south storage rooms have landscaped roofs at the level of the avenue.





5.46



Conservation (2018-2021)

The roof slabs of the north and south storage rooms, which showed an advanced state of rebar corrosion, were demolished. They were rebuilt with A400NR galvanized steel rebars, and wooden plank formwork with the same stereotomy as the existing one on all exposed concrete surfaces. Two-component structural epoxy binder was applied to all bonding surfaces between new and existing concrete and water-stop joints were applied to all construction joints. The existing waterproofing membranes over the roof slab of the water treatment room were removed, including cleaning the surfaces with solvent gel suitable for removing bituminous material



5.46 South storage room's roof slab during con-

5.49

	0				
struction, 1972.					
5.47 Roof slab wa	5.47 Roof slab waterproofing, 1972.				
5.48 Water treat	ment room's roof slab details,				
1965.					
5.49 Reinforced	concrete roof slabs and water-				
proofing details, 20	018.				
5.50 South stora	age room after the roof slab				
demolition, 2019.					
	ACTION				
i. Inspection	Annual condition check-up and record of the sla (among the most common: cracking, blistering, integrity check-up must be carried out by a struct or the aggravation of existing ones.				
ii. Cleaning	Annual cleaning of concrete surfaces by manual				
iii. Proaction	Every five years, the waterproofing should be in damaging the membranes; pay special attention evaluating their elasticity.				
iv. Repair	If necessary, any material replacement must res wood formwork finish. New concrete must be caparity with the preexisting surfaces. The compl between 15 to 20 years. These works must include				

and high-pressure sprayed water. The adopted waterproofing system consists of a bitumen emulsion primer, a welded bitumen membrane modified with APP polymers and 3kg/mC of nominal mass, preceded by another bitumen membrane modified with APP polymers and 4kg/mC of nominal mass, overlapping and folding at least 20 cm over the vertical planes, the application of finishing profiles and their respective sealing. Additionally, shrubby species were planted to avoid the use of a fence similar to the one that existed before the intervention.



5.50

N LINES

slabs and waterproofing to detect the existence of anomalies g, and accumulation of dirt). Every ten years, a slab structural uctural engineer to evaluate the appearance of new anomalies

ally removing any residue deposits.

e inspected and cleaned with water and a soft brush, without ion to the edges and overlaps that must be perfectly adhered,

espect the characteristics of the original concrete, namely the carefully studied and tested to prevent color and texture displete replacement of the waterproofing system should occur lude a previous diagnosis.

Walls

Cyclopean concrete retaining walls (Wr)

"The construction of retaining walls, to the north and south of the changing rooms, constitutes the necessary finishing to the buildings and, while simultaneously solving the access circuits and connection between areas, completes the embedding of the buildings in the retaining wall of the avenue and the meeting of two materials applied on large surfaces: granite masonry and bare concrete." (Siza, 1966)

Original design (1960-1973)

The retaining walls were built in cyclopean concrete, following the proportion of 70% of 300kg concrete to 30% of coarse crushed aggregates, and waterproofed on their internal face with 3 coats of non-ionic bituminous emulsion, 'FLINKTOTE'

type. On the back of the walls, a drainage curtain was made in dry stone, arranged by hand, and a 20 cm diameter perforated concrete drain was installed on a 250 kg concrete slab. With the extension of the building to the north and south, between 1971 and 1973, new retaining walls were built in a combination of two sections: an interior in cyclopean concrete, with characteristics identical to those that had already been built; and an exterior in exposed concrete, reinforced at a percentage of 10kg/m³ and with wooden plank formwork. The inner face of these walls was waterproofed with water-repellent plaster composed of cement mortar and sand in a 1:2 ratio, to which 0.568 I of a 'Feb-Proof' plasticizing solution was added for every 50 kg of cement.





5.53

5.51	Construction of the retaining walls, 1971.
5.52	Construction of the retaining walls, 1971.

- 5.53 Cyclopean concrete retaining wall detail,
- 1965.
- 5.54 Cyclopean concrete retaining wall detail,
- 2018.
- 5.55 Construction of the retaining walls, 2019.

Conservation (2018-2021)

All retaining walls along the entire length of the new north platform were demolished up to the foundation level of the new exterior floors. The foundation surfaces were leveled with blinding concrete, with 250kg/m3 of cement. New retaining walls were built in slightly reinforced cyclopean concrete, consisting of 90/180 coarse crushed aggregates (30% of the total volume) and ribbed stainless steel mesh of class 1.4571



5.54

	i. Inspection	Annual condition check-up record of the retain (monitoring the most significant cracks - to be evidence of efflorescence, concrete delamination a retaining walls structural integrity inspection anomalies or aggravation of existing ones.
	ii. Cleaning	Every 5 years, if necessary, clean and treat the damaging the patina.
	iii. Proaction	Every ten years, if necessary, treat oxidized red determine the loss of section. Provide for its c against corrosion.
	iv. Repair	If necessary, any material replacement must the wood formwork finish. New concrete must disparity with the preexisting surfaces. Vertic original project, and whenever there is no re long as the conditions of structural performant a previous diagnosis.

BS (EN 10088-1) measuring 50 × 50 × 3 mm, including wooden plank formwork with the same stereotomy as the existing one on all exposed concrete surfaces. All underground surfaces were waterproofed by applying two crossed coats of bituminous emulsion. On the back of the retaining walls, a dry stone drainage curtain was built, arranged by hand.



5.55

ACTION LINES

ning walls to ensure that there is no damage, such as cracking be defined by the technician responsible for the inspection), ion, oxidized rebar and accumulations of dirt. Every ten years, must be carried out by a structural engineer to check for new

he surfaces by removing any biological colonization without

ebars, through the complete removal of the oxidized layer to correct replacement, with the application of a protective layer

respect the characteristics of the original concrete, namely t be carefully studied and tested to prevent color and texture cal cracks caused by the absence of expansion joints in the bar corrosion, must be kept open after careful cleaning, as nce and integrity are guaranteed. These works must include

Walls

Lightly reinforced concrete walls (Wc)

"Some concrete walls support the Baltic pine and copper roof Original design (1960-1973) and support the access paths to the pool." (Siza, 2009)

The building's walls were built in lightly reinforced concrete with a percentage of 15kg/m³, and an average thickness of 30 cm. They are finished in exposed concrete, with horizontal lines resulting from the use of wooden plank formwork. During concreting, 'MEYCO' rubbers were applied to the joints between walls.

A 4630.3











- 5.56 Bar terrace walls, n/d.
- 5.57 Bar terrace walls, n/d.
- 5.58 Lightly reinforced concrete walls detail,
- 1966.
- 5.59 Structural plan, 1965.

5.60 North bathrooms suspended partition

walls, 2018. 5.61 North extension during construction, 2019.



Conservation (2018-2021)

A mapping of all the cracks and anomalies that the concrete walls presented was carried out. Repair mortars that proved to be incompatible with the original concrete were removed, exposing cracks and detachments. Occasionally, localized repairs of the concrete were carried out using chromatic and texture integration in keeping with the formwork stereotomy. However, whenever the cracks did not represent any structural risk or signs of rebar corrosion, they were left open in a deliberate option on the part of the designer to assume the signs of the passage of time. In these cases, to inhibit rebar corrosion, a protective mineral coating was applied.

The former north building was demolished, giving way to a new construction with concrete walls with A400NR galvanized steel reinforcement and wooden plank formwork in keeping with the existing stereotomy to that existing on all



	ACTIO
i. Inspection	Annual condition check-up and record of the lig ge, such as cracking (monitoring the most sign the inspection), evidence of efflorescence, con Every ten years, a retaining walls structural int to check for new anomalies or aggravation of e
ii. Cleaning	Every 5 years, if necessary, cleaning and treat thout damaging the patina.
iii. Proaction	Every ten years, if necessary, assess the need telastic, vapor-permeable one. This action can and its execution must be duly evaluated.
iv. Repair	If necessary, any material replacement must the wood formwork finish. New concrete must disparity with the preexisting surfaces. Verti original project, and whenever there is no re- long as the conditions of structural performa- a previous diagnosis.

exposed concrete surfaces. A 2-component structural epoxy binder was applied to all bonding surfaces between new and existing concrete and water-stop joints were applied to all construction joints. The façade of the new building is 30 cm thick and the beam that tops the longitudinal span has a section of 17 × 15 cm. Inside, 15 cm thick walls and 10 cm prefabricated partitions were built, also in exposed concrete, suspended from the perimeter walls through stainless steel anchors, nailed with chemical anchors for heavy loads.

The walls of the security and water collection rooms were painted with two coats of extra matte white aqueous paint, after previous brushing, treatment of cracks, and application of a colorless pliolite primer, suitable for dusty surfaces. The stainless steel sheets were removed from the kitchen, restoring it to its original condition.



5.61

N LINES

ightly reinforced concrete walls to ensure that there is no damanificant cracks - to be defined by the technician responsible for ncrete delamination, oxidized rebar and accumulations of dirt. tegrity inspection must be carried out by a structural engineer existing ones.

ment of the surfaces, removing any biological colonization wi-

to apply a colorless non-glossy waterproofing membrane or an be performed at any stage of the Maintenance Plan's execution,

respect the characteristics of the original concrete, namely st be carefully studied and tested to prevent color and texture ical cracks caused by the absence of expansion joints in the ebar corrosion, must be kept open after careful cleaning, as ance and integrity are guaranteed. These works must include

Walls

Wooden partition walls (Wp)

"The intention was to suspend the partitions from the roof structure, avoiding any point of contact with the floor, in order to guarantee easy and efficient washing. Wood, due to its lightness, made it possible to achieve this objective, offering, on the other hand, superior comfort to that obtained with the most commonly used materials (wood, for this very reason, is often preferred in similar cases - for example, in Nordic countries)." (Siza, 1967)

Original design (1960-1973)

The partition walls of the changing rooms and south bathrooms are made of 2.5 cm thick reclaimed Baltic pine boards, suspended from the roof's wooden structure. The wooden surfaces were first impregnated with a coat of boiled linseed oil, applied hot, and this protection was replaced, between 1971 and 1973, by two coats of varnish, 'BONDEX--DYRUP' type, after previous scraping. In the bathrooms and showers, the wood was protected with a film of vinyl resin. Also in this period, a partition wall was built in the collective changing room, made of a reclaimed Baltic pine panel, 2.5 cm thick, fixed to the floor with brass blocks. This partition wall supports a wooden bench resting on cantilevered brass bars.









Conservation (2018-2021)

The wooden partition walls have been overhauled and cleaned to remove all contaminants from the surfaces. To do so, a universal stripper (ref. 8015) and a steel wire brush were applied following the wood grain direction until it was in its natural state. This was followed by cleaning with a water jet and







of wooder deformat
ust be cle lust, and a
n surfaces ication of d grain di
ents must vious diag

- 5.52 Men's changing room, n/d.
- 5.63 Wooden partition walls detailing, 1964.
- 5.64 Wooden partition walls perspectives,
- 1964.
- 5.65 Men's changing room during conservation works, 2020.
- 5.66 Copper plated shower partition, 2021.
- 5.67 Men's changing room plan, 2018.

the application, without dilution, of a coat of 'Bondex Classic Mate' stain (ref. 4385 black) with a brush following the wood grain direction. The partition walls in the toilets and showers were replaced with new ones, made from 1 cm thick marine plywood, coated with 1 mm thick copper plate on all sides.



N LINES

n partition walls in terms of stability and degradation phenomeions, signs of rot, or signs of attacks by xylophagous organisms.

eaned with water and manual brushing to remove any existing accumulated dirt.

s must be lightly sanded without entirely removing the existing one coat of an alkyd-based solution (Bondex Classic Mate ref. rection.

be repaired or replaced with new pieces of similar characterisgnosis.

Pavements White concrete slabs (Ps)

"The floor is made of precast cement slabs." (Siza, 1965)

Original design (1960-1973)

The floor of the access ramp, changing rooms, south bathrooms, bar, and north building is made of 4 cm thick white concrete slabs, reinforced with steel mesh, laid on a water-repellent screed foundation. In the connection with the exposed concrete walls, there are gutters with a semi-circular section.









5.69



5.70

- 5.68 Entrance ramp white cement slabs, n/d.
- 5.69 Changing room's hallway white cement slabs, n/d.
- 5.70 White cement slabs layout plan, 1965.
- 5.71 White cement slabs sandblasting, 2020.
- 5.72 Entrance ramp white cement slabs, 2021.
- 5.73 Changing room's hallway white cement slabs, 2021.
- 5.74 White cement slabs under the south bathroom's porch, 2021.

Conservation (2018-2021)

The bar and kitchen flooring, made up of white concrete slabs, was demolished, including the foundation, and replaced by 7 cm thick micro concrete, C30/37 class, reinforced with 2 1.4571 BS (EN 10088-1) stainless steel meshes measuring 50 x 50 \times 3 mm, on 500 micron plastic. The remaining surfaces



5.71



5.73

	ACTION
i. Inspection	Annual condition check-up and record to ensur dation such as staining or cracking.
ii. Cleaning	Daily cleaning of the surfaces (housekeeping pressor without adding any chemical products
iv. Repair	If necessary, existing pavements may receive refully studied and tested to prevent disparitie include a previous diagnosis.

were sandblasted to provide non-slip properties and repaired when necessary. The deteriorated pieces were replaced with new ones, made of white concrete, lightly reinforced with 1.4571 BS (EN 10088-1) stainless steel mesh measuring 50 x 50×3 mm, with a sanded surface, equal dimensions to the existing ones, and 7 cm of thickness.

5.72



5.74

VLINES

re that there is no damage or signs of moisture-induced degra-

routine). Every ten years, cleaning with sandblasting air com-

localized or integral repairs, provided the new concrete is caes in color and texture with the existing one. These works must

Pavements

Cement plaster pavements (Pp)

"The terrain's natural conditions were taken advantage of as much as possible, especially where rock outcrops limited areas sheltered from the prevailing winds. These areas have at times been enlarged by light rock removal. A system of platforms and concrete stairs comfortably connects the different levels of these areas." (Siza, 1965)

Original design (1960-1973)

The pavements of the north, south, and west platforms and the bar terrace were executed in troweled plaster, composed of cement mortar and sand in a 1:3 ratio, on a foundation of cyclopean concrete, composed of 75% of 250 kg concrete and 25% of coarse crushed aggregates. For the interior pavements, a troweled plaster of cement mortar and sand was applied in a 1:2 ratio, on a water-repellent screed foundation.



The north platform pavement was fully demolished, while on the south platform and the bar terrace only the screed was removed. The new exterior pavements were executed in 15 cm thick micro concrete with a troweled surface, on a 15 cm thick tout-venant base. Recesses to conduct rainwater were created in slightly reinforced cyclopean concrete, consisting of 90/180 coarse crushed aggregates (30% of the total volume) and ribbed stainless steel mesh of class 1.4571 BS (EN 10088-1) of 50 \times 50 \times 3 mm, including wooden plank formwork in keeping with the stereotomy on all exposed concrete





5.75



- 5.75 Ground leveling, 1971.
- 5.76 Cement plaster pavement detail, 1966.
- 5.77 North platform, 1972.
- 5.78 Micro concrete detail, 2018.
- 5.79 North platform during construction, 2020.
- 5.80 Suspended walkway detail, 2018.
- 5.81 Suspended walkway during construction, 2020.





	ACTION
i. Inspection	Annual condition check-up and record to ensur dation such as staining or cracking.
ii. Cleaning	Daily cleaning of the surfaces (housekeeping nebulized water and a brush, without adding a
iv. Repair	If necessary, existing pavements may receive refully studied and tested to prevent disparitie include a previous diagnosis.

surfaces. In the case of the new north platform, it was necessary to build new foundation slabs in reinforced concrete, 35 cm thick, with A400NR galvanized steel rebars and wooden plank formwork in keeping with stereotomy on all exposed concrete surfaces.

The slab of the suspended walkway had to be rebuilt given its advanced state of rebar corrosion. A new 22 cm thick slab was built, with the lower and lateral faces in exposed concrete and the upper in troweled cement plaster, including neoprene supports, concrete drip inducers with BS 1.4362 (EN 10088-1) stainless steel reinforcements, and wooden plank formwork.



5.79



5.81

NLINES

re that there is no damage or signs of moisture-induced degra-

routine). Every ten years, the surfaces must be cleaned with ny chemical products.

localized or integral repairs, provided the new concrete is caes in color and texture with the existing one. These works must

Frames and hardware Wooden frames (Fw)

"Baltic pine is used in frames." (Siza, 1973)

Original design (1960-1973)

All the doors of the building are paneled and were made in reclaimed Baltic pine, 2.5 cm thick. For the frames and finishing of the walls and doorways, 3 cm thick boards of reclaimed Baltic pine were used, fixed with brass screws. The wooden surfaces were first impregnated with a coat of boiled linseed oil, applied hot. This protection was replaced with two coats of varnish, 'BONDEX-DYRUP' type, after previous scraping, between 1971 and 1973. All building doors include galvanized hardware and brass or copper fittings.



- 5.84 Changing room's doors, 2018.
- 5.85 South bathrooms' door, 2021.
- 5.86 Copper and brass hardware and fittings,



Conservation (2018-2021)

The wooden frames were subjected to a functioning review of all its components. They were cleaned to remove all contaminants from the surfaces. To do so, a universal stripper (ref. 8015) and a steel wire brush were applied following the wood grain direction until it was in its natural state. This was followed by cleaning with a water jet and the application, without







dilution, of a coat of 'Bondex Classic Mate' stain (ref. 4385 black) with a brush following the wood grain direction. New doors were installed in the new north building as well as in the bar, replacing the previous sliding door and the counter shutters with new elements in reclaimed Baltic pine that faithfully reproduce the original design.



5.85



tence of warping and excessive gaps between profiles and frames, signs of rotting or signs of attacks by xylophagous organisms and its proper functioning - the opening, closing, and latches must be tested.

Weekly cleaning with a damp cloth and, if necessary, a non-abrasive brush; every two years, wooden surfaces must be cleaned with water and manual brushing to remove any existing contaminants, such as fungi, algae,

Annual lubrication and tuning of hinges, locks, and pivots should be carried out. If superficial oxidization is detected, a rust converter (corrosion passivator) must be applied to remove the crumbling rust layers, or even microcrystalline wax (as a lubricant repairer). Every two years, if necessary, wooden surfaces must be lightly sanded without entirely removing the existing layer of coating, followed by the application of one coat of an alkyd-based solution (Bondex Classic Mate ref. 4385) with a brush following the wood grain direction.

If necessary, damaged wooden elements must be repaired or replaced with new pieces of Baltic pine with

Frames and hardware Metal frames (Fw)

"The metal parts (locks, drainage grates, etc.) are made of Original design (1960-1973) brass or copper." (Siza, 1965)

The access doors to the water collection room and the south storage room were made of pickled and thermal sprayed steel, while the doors to the north bathrooms and storage room were made of stainless steel with a brushed finish. All building doors include galvanized hardware and brass or copper fittings. The water treatment room, the chlorine cabinet, and the women's changing room are equipped with skylights made of brass profiles and 6 mm tempered glass.



New 1 mm thick copper sill plates were applied in the doorways of the new north building and the bar, fixed with brass screws, with recessed heads. The access door to the water collection room was restored by replacing the degraded har-











5.90

 5.87 Women's cl 5.88 Water treat 1964. 5.89 Women's cl 5.90 Roof's copp 	nanging room's skylight, 1995. atment room's skylight detail, nanging room's skylight, 1963. per cladding and skylights, 2021.
	ACTIO
i. Inspection	Annual integrity check-up and record of the me the following factors: joints between frames, e drainage channels), observing the existence of and the existence of cracks or breaks in the pe
ii. Cleaning	Every two years, the metallic surfaces must be (5 <ph<8), in="" mixed="" proportion<="" th="" the="" water="" with=""></ph<8),>
iii. Proaction	Lubrication and annual tuning of hinges, lock detected, a rust converter (corrosion passiva even microcrystalline wax (as a lubricant repa
iv. Repair	If necessary, the metallic elements must be reprint ristics. These works must include a previous d

dware, and completely stripping all surfaces. A rust converter was applied before painting with gray forged enamel, 'Cinofer' type. On the north wall of the adults swimming pool, a new removable railing was installed, consisting of vertical rods, cables, and AISI316 stainless steel mesh.

N LINES

etallic elements in terms of degradation phenomena (control of elasticity of the protective fence, functioning of the condensate of warping, excessive clearances and adhesion to the support, erimeter seal and its proper functioning.

e cleaned with a damp cloth and/or a neutral cleaning product of 5%, using a non-abrasive well-impregnated sponge.

ks, and pivots shoud be carried out. If superficial oxidization is ator) must be applied to remove the crumbling rust layers, or irer).

paired and replaced with others of similar design and charactediagnosis.

Furniture and fittings (Ff)

"All the equipment in the bar, preparation area and pantry will be in stainless steel and removable, so that during the winter it can be moved to the protected storage room. The terrace equipment (tables and chairs) will be made of Baltic pine." (Siza, 1973)

Original design (1960-1973)

The south bathrooms are equipped with 6 toilets, 2 washbasins with round mirrors, 3 urinals, and 6 stainless steel shower tubs with brass drains, copper tube shower heads, and brass taps. The north bathrooms have the same number of toilets,





washbasins, and urinals but only 2 shower tubs. Each of the

changing rooms is equipped with a washbasin and a round

mirror. The men's and women's changing rooms also have 10

foot washes and 29 brass hangers, while the collective chan-

ging room only has a single marble foot wash and 6 brass

hangers. The cloakroom is equipped with a brass hanger sus-

The bar was equipped with a full kitchen fit for the preparation

of hot meals. The terrace was equipped with chairs and folding

tables in varnished beech wood and stainless steel fittings.

pension structure.

5.91



5.93

- 5.91 Cloakroom with the clothes hanging struc-
- ture, n/d.
- 5.92 Clothes hanging structure, 1964.
- 5.93 Terrace furniture, 1973.
- 5.94 Reception counter, 2018.
- 5.95 Terrace furniture, 2021.

Conservation (2018-2021)

With the exception of the foot washes in the changing rooms, all bathroom fixtures, the round mirrors in polished stainless steel and the brass hangers have been replaced with new elements that faithfully reproduce the original design. Toilet brush holders, paper dispensers, litter bins, and wall-mounted liquid soap dispensers in stainless steel with a white epoxy finish were also installed. The foot wash in the collective changing room was repaired with a new piece of Estremoz marble, with the same characteristics as the existing one. Support cabinets were built in the employee's



	ACTION
i. Inspection	Annual integrity check-up and record of furnitiving the existence of warping, non-solid connection
ii. Cleaning	Weekly (housekeeping routine) cleaning with a years, the furniture must undergo a technical c
iii. Proaction	Every five years, furniture must be tuned, name and lubricating hardware and fittings. If superfiverer verter (corrosion passivator) must be applied wax (as a lubricant repairer).
iv. Repair	If necessary, any future repairs or replacement scale, proportion, material, texture, and finish must be properly documented.

changing rooms in solid wood from reclaimed Baltic pine. For the new reception counter marine plywood was used. The existing hanger suspension structure in the cloakroom was repaired, including complete stripping, replacement of degraded elements, and protection with two coats of aliphatic polyurethane enamel. The bar counter and the kitchen equipment were replaced with stainless steel components. The terrace furniture was replaced with new elements in varnished ipe wood and synthetic fabric, designed by Álvaro Siza.



5.95

N LINES

ure components, in terms of degradation phenomena, obserections, and gaps between components or damaged parts.

a damp cloth and, if necessary, a non-abrasive brush. Every two cleaning suitable for the type of dirt observed.

ely varnishing wooden surfaces to restore the protective finish icial oxidization is detected in metallic components, a rust conto remove the crumbling rust layers, or even microcrystalline

ts of furniture and fittings must be in keeping with the shape, of the original components. Any replacement of components

Tanks (T)

idea emerged: instead of making a tank with concrete walls, as the engineer had designed, to use, as much as possible, the rocks as the limit of the pool." (Siza, 2015)

Original design (1960-1973)

The leveling of the bottom and the boundary walls of the swimming pools were carried out in cyclopean concrete consisting of coarse crushed aggregates smaller than 30 cm, agglomerated with 210 kg concrete and 90 kg/m³ of pozzolan. The top of these walls was coated with cement mortar in a 1:4 ratio, with a rough finish to prevent slipping. The adults swimming pool has a general drain around the north, east,

"It was when I was invited to participate in this project that this and south perimeter, cast in the concrete of the walls and with an inner coating made of 1/2 cane of fiber cement. Along the entire length of these walls, there is a footrest ledge consisting of a reinforced concrete leveled console at a depth of 1.3 m with a projection of 0.15 m. The access ladders are removable and made of brass tubes and wooden steps.

> The foot wash is 0.25 m deep and variable in width, with a minimum of 1.3 m. The edge on the side of the pool is straight and parallel to it, and the one on the opposite side has an irregular outline along the rocky edge. It is equipped with 2 copper tube showers with pedal control. There are two more foot washes, one next to the children's pool with a shower, and another by the south bathroom's entrance. They are all equipped with a bottom sewer and 'trop-plein'.

Conservation (2018-2021)

The inner face and top of the north and south walls of the adults swimming pool and the wall of the children's swimming pool were demolished to replace the embedded pipes. They were later rebuilt in cyclopean concrete with 90/280 coarse crushed aggregates (30% of the total volume), the outer face in exposed concrete, the inner face prepared to be painted and the upper face troweled, including the application of a 2-component structural epoxy binder in all new/existing/rock bonding surfaces, edging gutters and steps. A concrete wall was built on the rocky edge of the adults swimming pool to contain the water, as a depression in the rocks prevented the









- 5.96 Adults and children swimming pool, 1968. 5.97 Detail of the adults swimming pool wall, 1965.
- 5.98 Detail of the children swimming pool wall, 1965.
- 5.99 Beginning of the pool's construction, 1961.
- 5.100 Details of the swimming pool walls, 2018. 5.101 Adults swimming pool and foot wash, 2021.



		ACTION
	i. Inspection	Annual condition check-up and record of the a ges and cracking. Every ten years, a structural structural engineer to verify the existence of ne
	ii. Cleaning	Daily vacuuming, for one hour and a half to th and other residues. Daily cleaning and disinfe foot washes during the day and after the build next day. Annual cleaning of painted surfaces waterproofing white plastic paint.
	iii. Proaction	Some of the routines may be somewhat condition of the building to the maritime environment, a corrections to the implementation of maintenation of maintenatio
	iv. Repair	If necessary, repair works must be carried out or rement of the opening of important cracks must tion. These works must include a previous diag

tank from being completely filled, including drilling and fixing stainless steel rods using a high-quality heavy-duty performance bonding chemical and the application of a 2-component epoxy binder to all new/rock bonding surfaces. Two coats of white chlorinated rubber paint were applied to the inner face of the walls and bottoms of the tanks, after previously washing the surfaces with water jet and repairing cracks. In the paint used for foot washes, an additive with non-slip properties was incorporated. The removable ladders of the adults swimming pool were restored, including the replacement of the steps with pieces of solid ipe wood, with a grooved surface, and brass screws.



5.101

VLINES

nti-slip surfaces, observing the presence of stains, color chaninspection of the concrete elements must be carried out by a ew anomalies or the aggravation of existing ones.

ree hours, to remove impurities such as sand, algae, plastics, ection (with bleach) of the swimming pools' surroundings and ding closure, in order to leave the place ready for opening the with a water jet, followed by their repainting (if necessary) with

ioned by weather conditions and cumulatively by the exposure especially during the winter. Therefore, any adjustments and ance actions must be foreseen beforehand.

on the white-painted surfaces. In case of cracking, the measust be carried out by the technician responsible for the inspecanosis.
Installations Plumbing (lp)

"The plumbing will be in copper piping." (Siza, 1973)

Original design (1960-1973)

The water used to fill the pools is collected directly from the sea through a collection gallery connected to a well with a tube. diameter of 3 m and 18 m of depth. It is lined with prefabricated concrete blocks where two porous concrete filtering wells were installed, 1 m in diameter and 12 m deep. From this well, a gallery measuring 1.50 × 1.80 m extends 102.90 m under the sea. Both galleries and wells were filled with 'Caia borgau' and coarse sand. At convenient points in the gallery, deep cracks were opened in the rocks by means of explosions, which allowed water to enter the gallery and the filtering wells. The water is then sent to the treatment room, which is equipped with 3 clarifying filters. Subsequently, the water circulates to the

pools through cast iron and fiber cement pipes. Both pools are equipped with water inlets, foot washes, and showers.

The remaining water supply piping is made of copper when exposed and galvanized iron when embedded. All the faucets are in copper-plated brass while the showers are in copper

Drainage of rainwater and wastewater is carried out using glazed stoneware pipes, patio siphons and manholes, siphoned boxes, and connection boxes with brass grids. The bottom discharge of the adults swimming pool is located at the lowest point of the sill, leading directly to the beach through a 250 mm diameter cast iron pipe fitted with a drain. This tube is embedded in the south wall, closed from the inside by a special sand and salinity-proof valve, controlled remotely from the top of the wall. The valve is located in a niche so that it can be inspected and removed if necessary.

Conservation (2018-2021)

The water supply system was entirely refurbished, with the external network in HDPE pipe installed in a buried trench and the interior network installed in the open, in copper pipe with copper-plated brass clamps. The pipes of the wastewater collection system, which were in poor condition, were replaced with new ones made of PVC embedded in the floors or buried in a trench in the case of the external collectors. Lids with a rim for filling and finishing were applied to the manholes, in accordance with the surrounding floor. The washbasins and urinals were equipped with bottle siphons, in copper-plated brass, connected to this network via exposed stainless steel tubes, duly ventilated. The existing rainwater drainage system was maintained. To drain the roof and pavement of the new north building, collectors buried in a ditch were installed in rigid PVC 6 kg/cm². The grids of the existing drains were 5.103 Water collection well, 1965. replaced with a model similar to the original, in brass. All iron 5.104 Water treatment and pumping system, pipes and accessories in the pools' recirculation system were 1965. replaced with new HDPE or PVC PN10 kg/cm² pipes. In the 5.105 Water supply network in copper tube, adults' swimming pool, the existing water outlets were refor- 2021. mulated and 4 water inlets were inserted on the east wall to improve the disinfection capacity. The treatment circuit for



5.105

	ACTION
i. Inspection	Annual check-up and record of the plumbing s damage to joints. Verification of fire extinguish authorized for this purpose.
ii. Cleaning	Two times a day, pool filters should be cleaned bing system must be conducted, resorting to a
iii. Proaction	Every five years, fire extinguishers must be load for this purpose.
iv. Repair	If necessary, repair or replacement of any co existing ones. In the event of future intervent perficial demolition must be carried out to avo diagnosis.





5.102



214

the children's swimming pool was separated, equipped with a closed-type winding fiberglass reinforced polyester filter, with a single filtering bed in sand 1.20 m high, and a filtration pump in marine bronze with a 12h regeneration cycle. In the water treatment room, the 3 existing physical treatment filters and respective collectors were replaced, as well as the chemical treatment process. For this purpose, 3 membrane dosing pumps were installed to automatically measure and regulate the chlorine, the pH value, and the flocculant for each treatment circuit. The existing fire-fighting means were complemented with sprayed water extinguishers.

5.102 Water treatment room, n/d. 5.106 Updated equipment inside the water treatment room, 2021.

5.106

VLINES

system to prevent water leaks, signs of clogging, corrosion, or er supports and safety seals/pins, carried out by an entity duly

d. Annual cleaning of the water collection galleries and plumspeleology team (if necessary).

ded with new extinguishing agent by an entity duly authorized

mponent must be in keeping with the characteristics of the ions that require access to the pool plumbing system, a subid damaging the slabs. These works must include a previous

Installations Electrical wiring (le)

"The site will be equipped with artificial lighting, with particular attention to the entrance, bar and annexes, since only in

this area is night-time operation foreseen." (Siza, 1973)

Original design (1960-1973)

Initially, only the lighting of technical areas such as storage rooms or the water treatment room was planned, together with the occasional installation, outside, of oval wall-mounted fixtures, with an aluminum grille. Later, spotlights were installed on the west façade. The water collection system is equipped with electric motors and has its own electrical panel, as well as the bar.

Conservation (2018-2021) equipped with circular light fixtures for ceiling or wall installation, 21 cm in diameter, natural aluminum body, frosted glass The electrical wiring was entirely replaced with HDPE-type diffuser with anti-insect surfaces, equipped with LED lamps cables in embedded tubes (on the floors, walls, and ceilings) with low energy consumption. Inside the building, the teleor XG-type cables inside exposed copper tubes, fixed with communications network was made with hidden or embedded copper-plated stainless steel clamps. Outside the building, VD pipe. In the water treatment and collection rooms, a dedithe electrical installation was buried, consisting of cables with cated circuit was added for the children's pool water recircudouble or reinforced outer sheaths threaded into tubes placed lation system. As part of the landscape design, two technical at the bottom of 1 m deep trenches. The pipes used in the emcabinets were built at the waterfront level, in solid granite with bedded network are made of semi-flexible PVC when inside a fine peaked bush-hammered finish and stainless steel doors concrete structures and VD in other cases. In the underground with a brushed finish. network, HDPE pipes were installed. Most of the premises were





5.107

5.108



5.109

- 5.107 Wall mounted exterior light fixture, 1965.
- Wall mounted exterior light fixture, 1965. 5.108
- 5.109 Electrical installation plan, 1965.
- Copper tubes for the electrical network, 5.110 2021.

- 5.111 Exposed electrical network inside copper
- tubes and light fixtures, 2021.
- 5.112 Exterior technical cabinet drawings, 2018.
- 5.113 Exterior technical cabinet, 2021.







	IOITOA
i. Inspection	Semi-annual check-up and record of the elect res, circuits, and equipment.
iii. Proaction	Annual control and record of the electrical ci operation of the equipment.
iv. Repair	If necessary, repair or replacement of any compones. Immediate replacement of defective lam previous diagnosis.



5.111



5.113

NLINES

trical wiring condition, assessing the functioning of light fixtu-

ircuits and lighting through testing the electrical/mechanical

onent must be in keeping with the characteristics of the existing ps or cables must be carried out. These works must include a

5.4.3 Maintenance schedule

Having identified the specifications for the maintenance estimated periodicities (daily, weekly, semi-annual, annual, actions of each Maintenance Source Element and its every two years, every five years, and every ten years), and components, it is important to organize them to allow their those responsible for its implementation. In addition to the planning throughout the expected useful life of the building scheduled maintenance actions, the allocation of intervention in the context of a Maintenance Plan. Therefore, a schedule priorities can also be outlined depending on the severity and was prepared that simultaneously allows the definition of urgency of the occurrence of a given failure or damage. the works that will have to be carried out and contracted, the

Daily (bathing season) Inspection rounds before closure to ensure all electrical and plumbing installa (fines are properly turned off. Maintenance manager/ Technical operator Record of housekeeping routines, filter cleaning, water and light consumption. Maintenance manager/ and number of users in the pool. Maintenance manager/ Cleaning assistant Vacuuming, for one hour and a half to three hours, to remove impurities such as sand, algae, plastics, and other residues. Technical operator Disinfection treatment of the swimming pools' water. Technical operator/ Technical operator/ Cleaning (housekeeping routine) of interior and exterior pavements and disin- fection (with bleach) of the surroundings of the swimming pools, foot washes, and bathrooms. Cleaning assistant Weekly Cleaning of garden spaces, with the removal of waste and weeds, as well as grass and shrub trimming. Gardener Technical operator Semi-annual Condition check-up and record of the water drainage components, to ensure that no blockages occur from the accumulation of waste or sand. Maintenance manager/ Technical operator Condition check-up and record of the electrical wiring, assessing the functio- ing of light fixtures, circuits, and equipment. Technical operator Annual Condition check-up and record of the cooper cladding to ensure that ther re is no damage, such as signs of corrosion (especially from pitting and/or in- terstital), cracks in the joints between the sheets, deformations, (kinks and war- ping) or other anomalies, observing if the cooper plates are m	PERIODICITY	MAINTENANCE ACTION	SPECIALIST
season Record of housekeeping routines, filter cleaning, water and light consumption, and number of users in the pool. Maintenance manager/ Cleaning assistant Vacuuming, for one hour and a half to three hours, to remove impurities such as sand, algae, plastics, and other residues. Technical operator Cleaning of the water treatment filters two to three times a day. Technical operator Disinfection treatment of the swimming pools' water. Technical operator Cleaning (housekeeping routine) of interior and exterior pavements and disin- fection (with bleach) of the surroundings of the swimming pools, foot washes, and bathrooms. Technical operator/ Cleaning assistant Weekly Cleaning (housekeeping routine) of furniture and frames with a damp cloth and, if necessary, a non-abrasive brush. Cleaning assistant Cleaning of garden spaces, with the removal of waste and weeds, as well as grass and shrub trimming. Gardener grass and shrub trimming. Gardener Semi-annual Condition check-up and record of the water drainage components, to ensure that no blockages occur from the accumulation of waste or sand. Electrician Maintenance of the plumbing system, such as pumps and filters. Technical operator Annual Condition check-up and record of the vorfs copper cladding to ensure that the te is no damage, such as grass of corrosion (especially from pitting and/or in- te is no damage, such as grass of corrosion (especially from pitting and/or in- te is no damage, s	Daily (bathing season)	Inspection rounds before closure to ensure all electrical and plumbing installa- tions are properly turned off.	Maintenance manager/ Technical operator
Vacuuming, for one hour and a half to three hours, to remove impurities such as sand, algae, plastics, and other residues. Technical operator Cleaning of the water treatment filters two to three times a day. Technical operator Disinfection treatment of the swimming pools' water. Technical operator Cleaning (housekeeping routine) of interior and exterior pavements and disin- fection (with bleach) of the surroundings of the swimming pools, foot washes, and bathrooms. Technical operator/ Cleaning assistant Weekly Cleaning (housekeeping routine) of furniture and frames with a damp cloth and, if necessary, a non-abrasive brush. Cleaning assistant Cleaning of garden spaces, with the removal of waste and weeds, as well as grass and shrub trimming. Gardener Semi-annual Condition check-up and record of the water drainage components, to ensure that no blockages occur from the accumulation of waste or sand. Electrician Semi-annual Condition check-up and record of the electrical wiring, assessing the functio- ning of light fixtures, circuits, and equipment. Technical operator Annual Condition check-up and record of the voof's copper cladding to ensure that the- re is no damage, such as signs of ortorison (bepcalult from pitting and/or in- terstitial), cracks in the joints between the sheets, deformations (kinks and war- ping) or other anomalies, observing if the copper plates are mounted correctly. Technical operator/ Carpenter Condition check-up and record of the w		Record of housekeeping routines, filter cleaning, water and light consumption, and number of users in the pool.	Maintenance manager/ Cleaning assistant
Cleaning of the water treatment filters two to three times a day.Technical operatorDisinfection treatment of the swimming pools' water.Technical operatorCleaning (housekeeping routine) of interior and exterior pavements and disin- fection (with bleach) of the surroundings of the swimming pools, foot washes, and bathrooms.Technical operator/ Cleaning assistantWeeklyCleaning of garden spaces, with the removal of waste and weeds, as well as grass and shrub trimming.GardenerSemi-annualCondition check-up and record of the water drainage components, to ensure that no blockages occur from the accumulation of waste or sand.Maintenance manager/ Technical operatorAnnualCondition check-up and record of the electrical wiring, assessing the functio- ning of light fixtures, circuits, and equipment.Technical operatorAnnualCondition check-up and record of the roof's copper cladding to ensure that the- re is no damage, such as signs of corrosion (especially from pitting and/or in- terstitial), cracks in the joints between the sheets, deformations (kinks and war- ping) or other anomalies, observing if the copper plates are mounted correctly.Technical operator/ CarpenterCondition check-up and record of the roinforced concrete structures to ensure that there is no damage, such as cracking, evidence of efflorescence, concrete delamination, oxidized rebar, and accumulations of dirt.Technical operator/ CarpenterCondition check-up and record of the roinforced concrete structures to ensure that there is no damage, such as cracking, evidence of efflorescence, concrete delamination, oxidized rebar, and accumulations of dirt.Technical operator/ CarpenterCondition check-up and record		Vacuuming, for one hour and a half to three hours, to remove impurities such as sand, algae, plastics, and other residues.	Technical operator
Disinfection treatment of the swimming pools' water.Technical operatorCleaning (housekeeping routine) of interior and exterior pavements and disin- faction (with bleach) of the surroundings of the swimming pools, foot washes, and bathrooms.Technical operator/ Cleaning assistantWeeklyCleaning (housekeeping routine) of furniture and frames with a damp cloth and, if necessary, a non-abrasive brush.Cleaning of garden spaces, with the removal of waste and weeds, as well as grass and shrub trimming.GardenerSemi-annualCondition check-up and record of the water drainage components, to ensure that no blockages occur from the accumulation of waste or sand.Maintenance manager/ Technical operatorAnnualCondition check-up and record of the electrical wiring, assessing the functio- ning of light fixtures, circuits, and equipment.Technical operatorAnnualCondition check-up and record of the roof's copper cladding to ensure that ther re is no damage, such as signs of corrosion (especially from pitting and/or in- terstitial), cracks in the joints between the sheets, deformations (kinks and war- ping) or other anomalies, observing if the copper plates are mounted correctly.Technical operator/ CarpenterCondition check-up and record of the structural elements, signs of rotting, or signs of attacks by xylophagous organisms.Technical operator/ CarpenterCondition check-up and record of the structural elements, signs of rotting, or signs of attacks by xylophagous organisms.Technical operator/ CarpenterCondition check-up and record of the structural elements, signs of rotting, or signs of attacks by xylophagous organisms.Technical operator/ CarpenterCondition check-up		Cleaning of the water treatment filters two to three times a day.	Technical operator
Cleaning (housekeeping routine) of interior and exterior pavements and disin- fection (with bleach) of the surroundings of the swimming pools, foot washes, and bathrooms.Technical operator/ Cleaning assistantWeeklyCleaning (housekeeping routine) of furniture and frames with a damp cloth and, if necessary, a non-abrasive brush.Cleaning of garden spaces, with the removal of waste and weeds, as well as grass and shrub trimming.GardenerSemi-annualCondition check-up and record of the water drainage components, to ensure that no blockages occur from the accumulation of waste or sand.Maintenance manager/ Technical operatorCondition check-up and record of the electrical wiring, assessing the functio- ning of light fixtures, circuits, and equipment.Technical operatorAnnualCondition check-up and record of the roof's copper cladding to ensure that the ing of other anomales, observing if the copper plates are mounted correctly.Technical operatorAnnualCondition check-up and record of the wooden structures and partition walls, ping) or other anomalies, observing if the copper plates are mounted correctly.Technical operator/ CarpenterCondition check-up and record of the reinforced concrete structures to ensure of cracks, deformations, difects of the structural elements, signs of rotting, or signs of attacks by xylophagous organisms.Technical operator/ CarpenterCondition check-up and record of the reinforced concrete structures to ensure that there is no damage, such as cracking, evidence of efflorescence, concrete delamination, oxidized rebar, and accumulations of dirt.Technical operator/ CarpenterCondition check-up and record of the wooden frames, in terms of degradation phenomena,		Disinfection treatment of the swimming pools' water.	Technical operator
Weekly Cleaning (housekeeping routine) of furniture and frames with a damp cloth and, if necessary, a non-abrasive brush. Cleaning of garden spaces, with the removal of waste and weeds, as well as grass and shrub trimming. Gardener Semi-annual Condition check-up and record of the water drainage components, to ensure that no blockages occur from the accumulation of waste or sand. Maintenance manager/ Technical operator Condition check-up and record of the electrical wiring, assessing the functioning of light fixtures, circuits, and equipment. Electrician Annual Condition check-up and record of the roof's copper cladding to ensure that there is no damage, such as signs of corrosion (especially from pitting and/or interstitial), cracks in the joints between the sheets, deformations (kinks and warping) or other anomalies, observing if the copper plates are mounted correctly. Technical operator/ Condition check-up and record of the structures and partition walls, ping) or other anomalies, observing if the copper plates are mounted correctly. Technical operator/ Condition check-up and record of the structural elements, signs of rotting, or signs of attacks by xylophagous organisms. Technical operator/ Condition check-up and record of the reinforced concrete structures to ensure that there is no damage, such as cracking, evidence of efflorescence, concrete delamination, oxidized rebar, and accumulations of dirt. Technical operator/ Condition check-up and record of the wooden frames, in terms of degradation phenomene, observing the existence of warping and excessive		Cleaning (housekeeping routine) of interior and exterior pavements and disin- fection (with bleach) of the surroundings of the swimming pools, foot washes, and bathrooms.	Technical operator/ Cleaning assistant
Cleaning of garden spaces, with the removal of waste and weeds, as well as grass and shrub trimming.Gardener grass and shrub trimming.Semi-annualCondition check-up and record of the water drainage components, to ensure that no blockages occur from the accumulation of waste or sand.Maintenance manager/ Technical operatorCondition check-up and record of the electrical wiring, assessing the functio- ning of light fixtures, circuits, and equipment.ElectricianMaintenance of the plumbing system, such as pumps and filters.Technical operatorAnnualCondition check-up and record of the roof's copper cladding to ensure that ther re is no damage, such as signs of corrosion (especially from pitting and/or in- terstitial), cracks in the joints between the sheets, deformations (kinks and war- ping) or other anomalies, observing if the copper plates are mounted correctly.Technical operator/ CarpenterCondition check-up and record of the wooden structures and partition walls, focused on their stability and degradation phenomena, observing the existence of cracks, deformations, defects of the structural elements, signs of rotting, or signs of attacks by xylophagous organisms.Technical operator/ 	Weekly	Cleaning (housekeeping routine) of furniture and frames with a damp cloth and, if necessary, a non-abrasive brush.	Cleaning assistant
Semi-annualCondition check-up and record of the water drainage components, to ensure that no blockages occur from the accumulation of waste or sand.Maintenance manager/ Technical operatorCondition check-up and record of the electrical wiring, assessing the functio- ing of light fixtures, circuits, and equipment.ElectricianMaintenance of the plumbing system, such as pumps and filters.Technical operatorAnnualCondition check-up and record of the roof's copper cladding to ensure that the- re is no damage, such as signs of corrosion (especially from pitting and/or in- terstitial), cracks in the joints between the sheets, deformations (kinks and war- ping) or other anomalies, observing if the copper plates are mounted correctly.Technical operatorCondition check-up and record of the reinforced concrete structures and partition walls, focused on their stability and degradation phenomena, observing the existence of cracks, deformations, defects of the structural elements, signs of rotting, or signs of attacks by xylophagous organisms.Technical operator/Condition check-up and record of the reinforced concrete structures to ensure that there is no damage, such as cracking, evidence of efflorescence, concrete delamination, oxidized rebar, and accumulations of dirt.Technical operator/Condition check-up and record of the wooden frames, in terms of degradation phenomena, observing the existence of warping and excessive gaps between profiles and frames, signs of rotting or signs of attacks by xylophagous organisms, and its proper functioning.Technical operator/		Cleaning of garden spaces, with the removal of waste and weeds, as well as grass and shrub trimming.	Gardener
Condition check-up and record of the electrical wiring, assessing the functioning of light fixtures, circuits, and equipment.ElectricianAnnualCondition check-up and record of the roof's copper cladding to ensure that there is no damage, such as signs of corrosion (especially from pitting and/or interstitial), cracks in the joints between the sheets, deformations (kinks and warping) or other anomalies, observing if the copper plates are mounted correctly.Technical operatorCondition check-up and record of the wooden structures and partition walls, focused on their stability and degradation phenomena, observing the existence of cracks, deformations, defects of the structural elements, signs of rotting, or signs of attacks by xylophagous organisms.Technical operatorCondition check-up and record of the wooden frames, in terms of degradation phenomena, observing the existence of cracks, deformation, oxidized rebar, and accumulations of dirt.Technical operatorCondition check-up and record of the wooden frames, in terms of degradation phenomena, observing the existence or profiles and frames, signs of rotting or signs of attacks by xylophagous organisms and its proper functioning.Technical operator	Semi-annual	Condition check-up and record of the water drainage components, to ensure that no blockages occur from the accumulation of waste or sand.	Maintenance manager/ Technical operator
Maintenance of the plumbing system, such as pumps and filters. Technical operator Annual Condition check-up and record of the roof's copper cladding to ensure that there is no damage, such as signs of corrosion (especially from pitting and/or interstitial), cracks in the joints between the sheets, deformations (kinks and warping) or other anomalies, observing if the copper plates are mounted correctly. Technical operator Condition check-up and record of the wooden structures and partition walls, focused on their stability and degradation phenomena, observing the existence of cracks, deformations, defects of the structural elements, signs of rotting, or signs of attacks by xylophagous organisms. Technical operator/ Carpenter Condition check-up and record of the reinforced concrete structures to ensure that there is no damage, such as cracking, evidence of efflorescence, concrete delamination, oxidized rebar, and accumulations of dirt. Technical operator/ Carpenter Condition check-up and record of the wooden frames, in terms of degradation phenomena, observing the existence of warping and excessive gaps between profiles and frames, signs of rotting or signs of attacks by xylophagous organisms, and its proper functioning. Technical operator/ Carpenter		Condition check-up and record of the electrical wiring, assessing the functio- ning of light fixtures, circuits, and equipment.	Electrician
AnnualCondition check-up and record of the roof's copper cladding to ensure that there is no damage, such as signs of corrosion (especially from pitting and/or interstitial), cracks in the joints between the sheets, deformations (kinks and warping) or other anomalies, observing if the copper plates are mounted correctly.Technical operatorCondition check-up and record of the wooden structures and partition walls, focused on their stability and degradation phenomena, observing the existence of cracks, deformations, defects of the structural elements, signs of rotting, or signs of attacks by xylophagous organisms.Technical operator/Condition check-up and record of the reinforced concrete structures to ensure that there is no damage, such as cracking, evidence of efflorescence, concrete delamination, oxidized rebar, and accumulations of dirt.Technical operator/Condition check-up and record of the wooden frames, in terms of degradation phenomena, observing the existence of warping and excessive gaps between profiles and frames, signs of rotting or signs of attacks by xylophagous organisms, and its proper functioning.Technical operator/		Maintenance of the plumbing system, such as pumps and filters.	Technical operator
Condition check-up and record of the wooden structures and partition walls, focused on their stability and degradation phenomena, observing the existence of cracks, deformations, defects of the structural elements, signs of rotting, or signs of attacks by xylophagous organisms.Technical operator/ CarpenterCondition check-up and record of the reinforced concrete structures to ensure that there is no damage, such as cracking, evidence of efflorescence, concrete delamination, oxidized rebar, and accumulations of dirt.Technical operator/ CarpenterCondition check-up and record of the wooden frames, in terms of degradation phenomena, observing the existence of warping and excessive gaps between profiles and frames, signs of rotting or signs of attacks by xylophagous organisms, and its proper functioning.Technical operator/ Carpenter	Annual	Condition check-up and record of the roof's copper cladding to ensure that the- re is no damage, such as signs of corrosion (especially from pitting and/or in- terstitial), cracks in the joints between the sheets, deformations (kinks and war- ping) or other anomalies, observing if the copper plates are mounted correctly.	Technical operator
Condition check-up and record of the reinforced concrete structures to ensure that there is no damage, such as cracking, evidence of efflorescence, concrete delamination, oxidized rebar, and accumulations of dirt.Technical operatorCondition check-up and record of the wooden frames, in terms of degradation phenomena, observing the existence of warping and excessive gaps between profiles and frames, signs of rotting or signs of attacks by xylophagous organisms, and its proper functioning.Technical operator		Condition check-up and record of the wooden structures and partition walls, focused on their stability and degradation phenomena, observing the existence of cracks, deformations, defects of the structural elements, signs of rotting, or signs of attacks by xylophagous organisms.	Technical operator/ Carpenter
Condition check-up and record of the wooden frames, in terms of degradation Technical operator/ phenomena, observing the existence of warping and excessive gaps between Carpenter profiles and frames, signs of rotting or signs of attacks by xylophagous organisms, and its proper functioning.		Condition check-up and record of the reinforced concrete structures to ensure that there is no damage, such as cracking, evidence of efflorescence, concrete delamination, oxidized rebar, and accumulations of dirt.	Technical operator
		Condition check-up and record of the wooden frames, in terms of degradation phenomena, observing the existence of warping and excessive gaps between profiles and frames, signs of rotting or signs of attacks by xylophagous organisms, and its proper functioning.	Technical operator/ Carpenter

	Condition check-up and record of the metallic elements in terms of degradation phenomena (control of the following factors: joints between frames, elasticity of the protective fence, functioning of the condensate drainage channels), ob- serving the existence of warping, excessive clearances and adhesion to the su- pport, and the existence of cracks or breaks in the perimeter seal and its proper functioning.	Technical operator/ Carpenter
	Condition check-up and record of furniture components, in terms of degrada- tion phenomena, observing the existence of warping, non-solid connections, and gaps between components or damaged parts.	Technical operator
	Condition check-up and record of the anti-slip surfaces, observing the presence of stains, color changes, and cracking.	Maintenance manager/ Technical operator
	Condition check-up and record of the plumbing system to prevent water leaks, signs of clogging, corrosion, or damage to joints.	Technical operator/ Plumber
	Verification of the fire extinguisher supports and safety seals/pins.	ANEPC certified company
	Control and record of the electrical circuits and lighting through testing the electrical / mechanical operation of the equipment.	Gestor de manutenção/ Electrician
	Cleaning of the copper cladding using a soft brush so as not to damage the patina including the water drainage components.	Technical operator
	Cleaning of painted surfaces with a water jet, followed by their repainting (if ne- cessary) with waterproofing white plastic paint.	Construction helper/ Painter
	Cleaning of the water collection galleries and all plumbing systems.	Speleology team
	Lubrication and tuning of hinges, locks, and pivots, and, in case superficial oxi- dization is detected, a rust converter (corrosion passivator) must be applied to remove the crumbling rust layers, or even microcrystalline wax (as a lubricant repairer).	Technical operator/ Carpenter
Every 2 years	Cleaning with water jet and manual brushing of all wooden structures, parti- tion walls, and frames. If necessary, wooden surfaces must be lightly sanded without entirely removing the existing layer of coating, followed by the applica- tion of one coat of an alkyd-based solution (Bondex Classic Mate ref. 4385) with a brush following the wood grain direction.	Technical operator/ Carpenter
	Cleaning of metallic surfaces with a damp cloth and/or a neutral cleaning pro- duct (5 <ph<8), 5%,="" a="" in="" mixed="" non-abrasive<br="" of="" proportion="" the="" using="" water="" with="">well-impregnated sponge.</ph<8),>	Carpenter/ Cleaning assistant
	Technical cleaning of furniture suitable for the type of dirt observed.	Technical operator
Every 5 years	Condition check-up and record of the roof's copper cladding, assessing the existence of early degradation in the joints/overlays and in the seam clips and screws of the copper plates.	Technical operator
	Condition check-up and cleaning of the concrete slabs' waterproofing with water and a soft brush, without damaging the membranes. Special attention should be paid to the edges and overlaps that must be perfectly adhered, evaluating their elasticity.	Technical operator
	Clean and treat the surfaces of the cyclopean concrete retaining walls by removing any biological colonization without damaging the patina.	Construction helper
	Load fire extinguishers with new extinguishing agent.	ANEPC certified company
	Tuning of furniture, namely varnishing wooden surfaces to restore the protective finish and lubricating hardware and fittings.	Technical operator/ Carpenter

Every 10 years	Inspection of structural elements' integrity, to evaluate the appearance of new anomalies or the aggravation of existing ones, paying special attention to supports and connections.	Structural engineer
	Cleaning of the white concrete slabs with sandblasting air compressor, without adding any chemical products.	Sweeper
	Cleaning of the cement plaster pavements with nebulized water and a brush, without adding any chemical products.	Sweeper
	Treat (if necessary) oxidized rebars in the walls, through the complete removal of the oxidized layer to determine the loss of section. Provide for its correct replacement, with the application of a protective layer against corrosion.	Structural engineer/ Construction helper

5.114

5.4.4 Operational management and use policies

The Ocean Swimming Pool CMP establishes a set of policies that aim to ensure proper functioning and use, outlining a set of operational management requirements that must include: i) description of suppliers and product guarantees (materials and equipment); ii) description and operation of the hydraulic and mechanical systems (includes regulations, if applicable); iii) description and operation of the security system (includes regulations, security patrols and signaling) and action plan and risk awareness; iv) description and operation of the lifesaving and rescue conditions; v) description and operation of the fire prevention system (includes regulations and signage, if applicable); vi) description and operation of the housekeeping routines.

ii) Maintenance manual;

Operational management and use aim at establishing a set of policies to ensure the correct functioning of the building. Thus, the Portuguese standard (IPQ, 2009) defines guidelines for the implementation of a maintenance management system, namely: i) Statement of maintenance policy and objectives; iii) Documented procedures and records required by the Portuguese standard; iv) Documents, including records, determined by the maintenance managers to be necessary to ensure the effectiveness of

the planning, operation, and control of its processes.

Furthermore, the admission and accessibility conditions must The maintenance management system documentation may be stated in the user manual, which should include: the first acdiffer according to the type and complexity of the building. It tions to be carried out upon entering the building; information is also necessary to consider the role of management responon the suppliers of the various components and elements, in sibility, which must provide evidence of commitment to the deorder to facilitate contact in case of need; rights and responvelopment of the maintenance management system and the sibilities of users; regulations and legislation related to the continuous improvement of its effectiveness, ensuring the prebuilding; prohibitions, warnings and recommendations of use; -established objectives and the availability of resources. health and safety measures.



5.115

5.114 Maintenance calendar.

5.115 Housekeeping routines in the adults swimming pool foot washes, 2021.

C.2	Inspection routines	Promote regular inspection routines that should be more frequent during ba- thing season. Any anomalies identified in the building must be communicated to the site managers.
C.3	Maintenance Plan	C.3.1 <i>Framework</i> - Develop and implement a Maintenance Plan that takes into account the detailed conservation framework and guidelines outlined in this CMP.
		C.3.2 <i>Budget</i> - Consider an estimate of annual maintenance costs (estimated annual average charges, at nominal current value and without updating rate) for each maintenance action, quantifying the expected and accumulated investment over determined time periods.
		C.3.3 <i>Manuals</i> - Develop cyclical maintenance and treatment manuals to establish priorities and short and long-term conservation interventions, thus maintaining a proactive conservation approach.

Accessibility

The building is located on Liberdade Avenue with access to public transport through bus route number 507, connecting it to the city center of Porto. The bus stops by every half an hour by the building's entrance where there is also parking for cars and motorcycles. Access and parking inside the building are prohibited both to bicycles, scooters, and motor vehicles. Even though it is easy to find parking close to the site, there is a lack of traffic signage indicating its precise location. Therefore, many tourists and visitors, who do not know the area, have difficulty reaching the place.

Both community expectations and legal requirements for accessibility have changed considerably since the Ocean Swimming Pool's opening. Public facilities such as this are now expected to be accessible to everyone. Consequently, in the last conservation works, bathrooms for users with impaired mobility were introduced. However, accessibility is no longer just about providing facilities for people with impaired mobility. It includes people with sensory disabilities, older people, and families with young children. Therefore, more needs to be done in what respects ensuring accessibility to everyone as most exterior areas, including the swimming pools, remain largely inaccessible. Mitigation or adaptation measures, however, must not affect Álvaro Siza's vision for the site, ensuring that future interventions are respectful of the design principles identified in section 2.5.2.

Admission

During the bathing season (June to September) the site is open every day from 9h00 to 19h00. Access is subject to an entrance fee and is conditioned to weather conditions. The number of visitors is permanently controlled to ensure the premises' maximum capacity is not surpassed and in this way preserve the asset's integrity. During the rest of the year, access is limited to guided visits, which must be booked in advance.

Housekeeping

Different housekeeping routines are carried out to keep the space functional. For the correct operation of the swimming pools, it is necessary to carry out a daily water maintenance routine. Thus, it is required to perform several procedures consistently throughout the day to ensure that the water remains clean and safe for public use. There is a daily routine related to water quality which includes water disinfection, filter maintenance, pool vacuuming, and sanitary record (cleaning register,

- 5.116 Bus stop at the building's entrance, 2021.
- 5.117 Wristband entrance identification, 2021.
- 5.118 Housekeeping routines in the water treatment room, 2021.
- 5.119 Housekeeping routines in the south bath-
- rooms, 2021.
- 5.120 Pool and building housekeeping routines.



5.116







C.4 Accessibility Plan Develop and implement an Accessibility Plan for users with mobility impairments, ensuring the designated circulation areas and spaces remain free of physical obstacles. C.5 C.5.1 Occupancy - Ensure the building's occupancy is permanently controlled Capacity and entrance control to prevent any damage to the site from exceeding its designated capacity. C.5.2 Visitor information - Display occupancy information (low, high, and "sold out") on the exterior of the building to avoid the formation of long lines and the consequent frustration of visitors who are prevented from entering. The possibility of making this information available online should be considered.

5.118

chlorine control and logistics, pH level, temperatures, water and electricity consumption, and number of users). Weekly preventive maintenance of equipment should be performed to ensure continuity of service. The atmospheric conditions often do not allow to carry out part of the daily routine maintenance tasks, since it exposes technical operators to strong winds and rain, preventing the proper performance of their functions. The most common problem when daily routines in the swimming pools are not performed is clogging of the plumbing system (see detailed policies for the plumbing system in section 5.4.2).

during the day.



A water disinfection plan is carried out constantly during the day on the pools through a pump system preventing any seaweed formation.

Water disinfection

Filters maintenance

The filters of the pool must be cleaned. This process is carried out depending on the number of users of the pool, but it must be done at least twice a day.

BUILDING: during the day it is necessary to repeat a cleaning routine for the building in order to maintain the areas in perfect conditions for visitors and users.



Equipment check and inventorv

Check changing rooms, foot washes and bathrooms (including toilet paper and hand gel).

Sanitary control and record			
daily	record o	of sani	tary
aning	, filters,	water	and
	L		L

cle and electricity consumption, pH level, temperature and number of users on the pool is carried out to inform the cleaning routine.

C.6	Housekeeping routines	Define and imple the best internat to the techniciar fundamental for
-----	-----------------------	---

Α

During bathing season, when the Ocean Swimming Pool is open to the public, there is a daily cleaning routine that consists of an early morning inspection to detect and eventually report any anomaly or missing materials. Then, during the day there is a repeated cleaning and disinfection routine between the pools, foot washes, and bathrooms. The latter suffer from intensive use during summer, being more prone to problems related to misuse such as clogging.

POOL: the pool needs a constant cleaning routine to maintain the optimal conditions for use. Different procedures are followed



The pool must be vacuumed every morning during one and a half to three hours to clean impurities like sand, seaweed and plastics.

Exterior daily cleaning

Daily maintenance cleaning of the beach and pool areas must be done to avoid waste accumulation. Also, the pavement near swimming pools and foot washes must be disinfected (with bleach).

Bathroom cleaning and maintenance

Maintenance cleaning and replenishment of the bathroom must be conducted (toilet paper, soap, etc.).

General cleaning

The general cleaning routine of the building is performed both in interior and exterior areas (pool surroundings, beach and foot washes). The complete routine is performed at night after building's closure in order to leave the site ready for the following day.

ement housekeeping routines that are permanently updated to ational and technical standards. They must be clearly conveyed ns responsible for carrying them out on a daily basis as they are the long-term preservation of the asset's significance.

Security

During the day, in the bathing season, four security guards The Ocean Swimming Pool is equipped with fire extinguishers are in charge of the site surveillance: one is controlling visitor access by the main entrance, two are patrolling the north and south boundaries to prevent trespassing, and the last stands in the proximity of the pools to ensure that the public complies with the regulations of the facility. During the night and off the bathing season, only one security guard patrols the premises to prevent acts of vandalism. Any occurrences or anomalies detected during the patrols must be reported to the site managers. The Ocean Swimming Pool, however, is a complex area to control since it is not an enclosed space, being easily accessed through the beaches.

Lifesaving and rescue

During the bathing season two lifeguards surveil the premises to respond to any aquatic emergency. The lifeguard station is equipped with all the elements necessary for rescue at sea or first aid response. Lifeguards are also responsible for evaluating sea conditions in order to raise the appropriate flag that informs users whether they can or cannot go for a swim.

Fire safety

and has personnel trained on how to use the equipment properly. Nevertheless, until now, not all fire prevention measures have been fully implemented in the building, and there is a lack of proper signage and emergency lights. Even though the implementation of a fire prevention plan is of the utmost importance, any new elements introduced must be integrated in ways that do not hinder the cultural significance of the place.

Risk awareness

The Civil Protection department of the Municipal Council of Matosinhos has learning programs to mitigate risks. One of these projects, named "Casa do Alertinha", is destined for children and implemented in schools, where they are taught to face different types of risks and mitigate them through face-to-face and online activities.

- 5.121 Guard securing the premises, 2021.
- 5.122 Emergency lights, 2021.
- 5.123 Lifeguard station, 2021.
- 5.124 Bathers, 1992 (following page).







C.7	Security system	Imple preve closi
C.8	Lifesaving and rescue	Ensu

Fire Preve

Risk aware

5.123

ystem	Implement a more comprehensive security system that simultaneously prevents misuse during operating hours and acts of vandalism during closing hours.
and rescue	Ensure the permanent availability of lifeguards on the site during the bathing season as immediate emergency responders charged with rescue at sea. Lifeguards' instructions regarding the safety of the bathers must be respected.
ntion Plan	Develop and implement a Fire Prevention Plan. The implementation of safety regulations namely emergency exit signs, fire extinguishing means, staff training, evacuation routes, and protocols on the premises is mandatory.
eness learning plan	Enhance risk awareness activities to raise public awareness about the most significant factors threatening the Ocean Swimming Pool and the possible responses to mitigate them.



C.9

C.10

User regulations

The use of the Ocean Swimming Pool implies compliance with a series of regulations to ensure users' comfort and safety, as well as the preservation of the site. Also, health emergencies such as the COVID-19 pandemic (2020-2021) demonstrated the need for preventive guidelines to ensure user safety on the premises. Thus, it is essential to develop specific measures for aquatic facilities.

Successful management and maintenance are only possible with community involvement and empowerment, namely with the support of user manuals, which clearly convey information and guidelines. Hence, users are a key factor in built heritage maintenance, helping to avoid improper use, preventing risk situations, contributing to the recording of information, and collaborating in daily maintenance activities. From this point of view, civil society has an important role to play in preserving heritage, as well as in contributing to a sustainable and culturally integrated development. The Ocean Swimming Pool illustrated User Manual (fig. 5.128) provides information on prohibitions, warnings, recommendations, and emergency protocols.

User Manual

Prohibitions



mproper disposal

of waste products



Flotation devices

in the pool

Animals (except

X

×

for service animals)

Use of parasols

or windbreaks

Waste or rubbish



Entrance in

technical areas

Showering is



Warnings

Bill posting



Δ



never be left mandatory before entering the pools unaccompanied

Wearing appropriate swimwear is mandatory as is providing adequate diapering for babies

Lifeguards' instructions must be followed

Δ

Recommendations







Use sunscree and avoid direct exposure to the sun when radiation is strongest

Wait at least 3 hours after eating before entering the water







Useful Contacts:



5.125

C.11

C.12

User regulations





5.125 Use restrictions warnings, 2021.

Warning signage, 2021.

COVID-19 pandemic, 2021. 5.128 User Manual.

Visitor temperature control during

5.126

5.127

226

Wear armbands if you can't swim

Ocean Swimming Pool



disposal in toilets and washbasins



Running, jumping or plunging into the water



Ball games



Eating or drinking in proximity of the pools

Δ



Possession or use of sharp objects in the areas destined to barefoot users



Smoking in all indoor spaces and when inside the pools



Walking on the building's roof



Use of sound devices



Report any occurrence of major danger or urgency to the security guard or lifeguard



Diving is limited to the zones with appropriate depth



You should refrain from taking photographs of other customers inside the pool facilities



Keep the access wristband on while using the pool facilities



Use the pool equipment with care



Do not leave your belongings unattended. The pool management is not responsible for lost or stolen items



Bicycles and scooters should be parked in the appropriate places









References

Abrantes, V. (1994) Planeamento das ações de manutenção no parque habitacional. Lisboa: LNEC Edições

Calejo, R. R. (2006) Manuais de manutenção e utilização. Encontro nacional sobre qualidade e inovação na construção. Lisboa: LNEC Edições, pp. 465-476

Resolution of the Council of Ministers No. 107/2019 (2019) Roadmap for Carbon Neutrality 2050 - Long-term Strategy for Carbon Neutrality of the Portuguese Economy by 2050. Avai-CMM (2019) Estratégia Municipal de Adaptação às Altelable at: https://www.portugal.gov.pt/download-ficheiros/firações Climáticas (Municipal Strategy for Climate Change cheiro.aspx?v=%3D%3DBAAAAB%2BLCAAAAAAABACzM-Adaptation), Available at: https://amp2020.amp.pt/ficheiros/ DexBAC4h9DRBAAAAA%3D%3D (Accessed: 10 November PlanosMunicipais/5.%20EMAAC%20%E2%80%93%20MA-2022) TOSINHOS.pdf. (Accessed: 10 November 2022)

CMM (2011) Plano Municipal de Emergência de Protecção Civil de Matosinhos (Matosinhos Municipal Emergency and Civil Protection Plan). Available at: https://www.cm-matosinhos. pt/cmmatosinhos2020/uploads/writer_file/document/5761/ PME_NET.pdf (Accessed: 10 November 2022)

Decree-Law No. 166/2008 (2008) Regime Jurídico da Reserva Ecológica Nacional (Legal Regime of the National Ecological Reserve). Available at: https://dre.pt/dre/legislacao-consolidada/decreto-lei/2008-34501775 (Accessed: 10 November 2022)

Decree-Law No. 308/87 (1987) Estatuto Orgânico da Administração dos Portos do Douro e Leixões (Legal Framework of the Ports of Douro and Leixões Administration). Available at: https://dre.pt/dre/detalhe/decreto-lei/308-1987-417817 (Accessed: 10 November 2022)

Directive 2007/60/EC (2007) Directive of the European Parliament and of the Council on the assessment and management of flood risks. Available at: https://eur-lex.europa.eu/ legal-content/EN/TXT/?uri=CELEX:32007L0060 (Accessed: 10 November 2022)

ICOMOS (2019) The Future of Our Pasts: Engaging Cultural Heritage in Climate Action. Available at: https://openarchive. icomos.org/id/eprint/2459/1/CCHWG_final_print.pdf (Accessed: 10 November 2022)

IPQ (2007) Norma Portuguesa NP EN 13306 2007: maintenance terminology. Caparica: Instituto Português da Qualidade

IPQ (2009) Norma Portuguesa NP 4483 2009: guia para a implementação do sistema de gestão da manutenção. Caparica: Instituto Português da Qualidade

Law No. 107/2001 (2001) Lei de Bases do Património Cultural (Law for Cultural Heritage). Available at: http://www.pgdlisboa.pt/leis/lei_mostra_articulado.php?nid=844&tabela=leis (Accessed: 10 January 2021)

Notice No. 13198/2019 (2019) Plano Director Municipal de Matosinhos (Municipal Master Plan). Available at: https://www. cm-matosinhos.pt/urbanismo/planeamento-urbanistico-e--territorial/plano-diretor-municipal (Accessed: 10 November 2022)

Resolution of the Council of Ministers No. 111/2021 (2021) Programa da Orla Costeira Caminha Espinho (Caminha-Espinho

Building information documentation

During the elaboration of this CMP, a large amount of data was collected, namely from archival research, interviews, and fieldwork. The Municipal Council's Department of Conservation keeps records of interventions, nevertheless, data regarding building management, conservation, and maintenance is dispersed, as there is not an integrated and digitized database. The Municipal Council is working on the implementation of a Building Information Management System with management and maintenance real-time information, allowing for the interoperability through a digital twin between the 3D BIM model, the facility management software (Infraspeak), and on-site sensors (CO₂, water level, among others).

5.129

5.130

5.129 BIM model general view.

5.130 BIM model detailed view of the changing rooms

C.13	Archival database	Gather and organize all information related to conservation interventions, na- mely techniques, methodologies, and materials employed, as well as graphic, photographic, digitized, or other documentation on the adopted procedures.
C.14	Building information management system	Develop and implement a building information management system with faci- lity management tools for inspection and maintenance routines including noti- fications and alerts in real time.

Coastal Zone Program). Available at: https://apambiente.pt/ sites/default/files/_SNIAMB_Agua/DLPC/POC/POC_C-E/ POC%20CE_DIRETIVAS.pdf (Accessed: 10 November 2022)

Siza, A. e Ferrão, B. (1965) Piscina da Praia de Leça da Palmeira - 2ª Fase - Projecto: Memória descritiva e justificativa

Siza, A. and Ferrão, B. (1966) Piscina da Praia de Leça da Palmeira - 3ª Fase - Projecto: Alargamento do recinto, incluindo arrecadações, sanitários, bar, esplanada, plataforma e muros de suporte a norte e a sul: Memória Descritiva

Siza, A. e Ferrão, B. (1967) Piscina da Praia de Leça da Palmeira: Memória Descritiva: Processo completo do projecto, incluindo fases construídas e a construir

Siza, A (1973) Memória Descritiva e Justificativa: Piscina da Praia de Leça da Palmeira: Ante projecto intercalar das 3ª e 4ª fases

UN (2015) Transforming our world: the 2030 Agenda for Sustainable Development. Available at: https://documents-dds--ny.un.org/doc/UNDOC/GEN/N15/291/89/PDF/N1529189.pdf?OpenElement (Accessed: 10 November 2022)

UNDRR (2015) Sendai Framework for Disaster Risk Reduction 2015-2030. Available at: https://www.preventionweb.net/ files/43291_sendaiframeworkfordrren.pdf?_gl=1*5yxa2y*_ ga*MTk0NDA0Mzc3NS4xNjc3NjY0MTAx*_ga_D8G5WX-P6YM*MTY3NzY2NDEwMS4xLjEuMTY3NzY2NDE2MS4wLiAuMA. (Accessed: 10 November 2022)

UNFCC (2015) Paris Agreement. Available at: https://unfccc. int/sites/default/files/english_paris_agreement.pdf (Accessed: 10 November 2022)

WHC (2021) Draft updated Policy Document on the impacts of climate change on World Heritage properties. Available at: https://whc.unesco.org/archive/2021/whc21-44com-7C-en. pdf (Accessed: 10 November 2022)

WHC (2010) Managing Disaster Risks for World Heritage. Available at: https://whc.unesco.org/en/managing-disaster--risks/ (Accessed: 10 November 2022)

WHC (2006a) Policy Document on the Impacts of Climate Change on World Heritage Properties. Available at: https://whc.unesco.org/uploads/activities/documents/activity-397-2.pdf (Accessed: 10 November 2022)

WHC (2006b) Climate Change and World Heritage. Report on predicting and managing the impacts of climate change on World Heritage. Available at: https://unesdoc.unesco.org/ ark:/48223/pf0000160019 (Accessed: 10 November 2022)



6. MONITORING

- 6.1 Introduction
- 6.2 Management system and sources of finance
- 6.3 Monitoring
- 6.4 Priority of actions, implementation and phasing



6.1 Introduction

Chapter 6 presents the monitoring recommendations for the All of these aspects are tightly related to the management sysconservation of the Ocean Swimming Pool. Based on the pretem. The success of monitoring and assessment depends on a viously developed policies, it aims at providing a comprehenrobust management system, capable of handling the articulasive framework for future management decisions, defining tion of different and varied entities, conflicts, and visions (Court priorities and a timeframe for the implementation of conseret al., 2022). As the Burra Charter sustains, while "conservation vation actions, according to funding and the availability of is an integral part of good management of places of cultural significance" (ICOMOS Australia, 2013, article 2.3), monitoring other resources. "should guide managers towards giving emphasis to mainte-The chapter is structured in three sections, starting with the nance and preventive measures, thus relieving the need for curative/restorative interventions" (Boccardi & Stovel, 2004, p. 131).

The chapter is structured in three sections, starting with the description of the management framework and the available resources for conservation (6.2). The following section (6.3) presents a monitoring methodology based on general issues and pressing hazards (identified in chapter 4). Finally, priority actions, implementation, and phasing (6.4) are detailed through the prioritization of policies and the definition of a timeframe for their implementation.

Thus, adequate monitoring inside a well-functioning management system allows the development of a sustainable intervention culture in which the stakeholders act based on preventive measures instead of reactive ones (Ferreira, 2020). This is the ultimate goal of this CMP. In the end, while preserving the property for future generations, it also entails a positive impact through time on improving the quality and efficiency of public services for the visitors and users of the Ocean Swimming Pool, with responsible use of resources (Feilden; Jokkilehto, 1998).

6.2 Management system and sources of finance

6.2.1 Management system

As the Ocean Swimming Pool is a listed building since 2011, the property is subjected to a specific management system created to maintain its heritage values. In the most recent government structure for safeguarding heritage (Decree-Law 78/2023, of September 4) the licensing of any work, intervention or change of use concerning a listed property or in the respective Buffer Zone requires prior consent from the competent Regional Coordination and Development Commission with a binding decision subsequently made by Cultural Heritage, I. P.

Each listed property has a Buffer Zone to reinforce its landscape setting, safeguard the surrounding architectural specificity, and preserve the property's visibility and contemplation conditions (article 43, Law No. 107/2001). The Buffer Zone serves as an administrative control area for the Municipal Council and the other competent authorities (Cultural Heritage, I. P. and Regional Coordination and Development Commission), for construction licenses and any other works that alter the topography, alignments and height and, in general, the distribution of volumes and roofs or the external finishings of buildings.

In addition, on a local level, all Portuguese Municipalities have mandatory Municipal Master Plan that defines the strategic framework for the municipality's spatial planning. All plans include a Heritage Map, and contribute to the safeguarding of cultural heritage while defining policies for conservation and monitoring.

As expressed in Policy A.1 (see chapter 5), this system conveys rights and obligations that must be acknowledged by an Advisory Board in charge and acting in line with Álvaro Siza's design principles (Policy A.2). Formed by a group of managers and experts, this Advisory Board can also be responsible for disseminating information about the property, engaging visitation and adequate communication, while developing evaluation of conservation status through assessments and monitoring reports.

A graphical scheme of this system is shown below:

6.2.2 Sources of finance

The Municipal Council of Matosinhos is the owner and original Other than local use during the bathing season, the sources of commissionaire of the property, from which it obtains relevant finance available for the management of the Ocean Swimming yearly revenue. The Ocean Swimming Pool was visited by a Pool are also associated with the bar concession and guided vitotal of 57 904 visitors in 2018, the last year that the site was sits organized by Casa da Arquitectura. Every year, Matosinhos opened to the public before the start of the recent conserva-Sport promotes a public procurement procedure to select a tion and extension intervention (2019-2021). This resulted in an supplier that will be in charge of the bar's management during income of 207 728 euros, from which 30 381 euros were allothe bathing season. cated to functioning expenses such as security, lifeguards, and cleaning, representing 14,63% of the total revenue. Therefore, there was a profit of 177 347 euros.



6.

6.3 Monitoring

6.3.1 Monitoring and evaluation

Monitoring and evaluating the management framework of a listed property is a necessary part of a management plan, guaranteeing that the management process is functioning as intended, conforming to established rules, and meeting external reporting requirements (Court *et al.*, 2022). Monitoring, then, can be defined as a cyclical planning system whose activities lie on conservation evaluations and impact assessments carried out frequently (Stovel, 2004). As a form of preventive management, monitoring also requires awareness of threats and impacts that take into consideration the vulnerabilities affecting the place and their influence. Therefore, attention to hazards can help the monitoring process and guarantee heritage protection and conservation.

The monitoring of the Ocean Swimming Pool shall be based on qualifying when and how corrective measures are conducted, but also accepting input such as spontaneous reporting, or even suggesting new forms of articulation and organization

(i.e., a memorandum of understanding). This system facilitates multidisciplinary decision-making to achieve this CMP strategic objectives.

Since this goal is also subjected to indicators linked to the place's integrity and authenticity, one level of monitoring must convey general subjects that are related to responsible functioning of the property under the guarantee of preserving its heritage significance. Another level of monitoring, which must be combined – not subjected – with the previous one, is based on considering the most pressing hazards, vulnerabilities, and risk levels (see section 4.4). These hazards are then associated with a priority level, through a scale in which the unacceptable ones must be prioritized in the monitoring process.

The tables that summarize these monitoring levels are presented below:

SUBJECT	ACTION	PERIODICITY	RESPONSIBLE
Authenticity and Integrity	Verify the condition of the elements under ranges of authenticity and integrity.	Annually	Advisory Board
Finance	Review and evaluate the budget available for mainte- nance, repairs, and conservation of the property.	Annually	Matosinhos Sport
Buffer Zone	Identify irregular interventions or changes in land use within the protected area.	Annually	Municipal Council of Matosinhos
Real Estate Development	Identify real estate developments in the surrounding area and analyze impacts on the property.	Annually	Municipal Council of Matosinhos
Management	Evaluate the application of maintenance plans and provide reports.	Annually	Matosinhos Sport
Responsible Visitation	Record the number of daily visits.	Daily	Matosinhos Sport
	Define building capacity according to the effect it has on the property.		
Responsible Use	Identify changes in the behavior of visitors after imple- menting the 'good practices' manual.	As reported	Matosinhos Sport
	Report the number of incidents created by visitors not following the rules.		

6.2

	HAZARD	RISK LEVEL	PRIORITY	MONITORING METHOD	PERIODICITY	RESPONSIBLE
	Sea level rise	Unacceptable	1	Regular monitoring of sea level rise to understand the likelihood of damage to the property and identify measures that can minimize the expected impacts.	Annually	Municipal Council of Matosinhos
Ļ	Increase of atmospheric carbon dioxide	Tolerable	2	Regular monitoring of concrete elements to maximize the likelihood of early-damage detection, and minimize the level of repair that might be needed.	Annually	Municipal Council of Matosinhos
NATUR	Chloride action	Unacceptable	1	Regular monitoring of concrete elements to maximize the likelihood of early-damage detection, and minimize the level of repair that might be needed.	Annually	Municipal Council of Matosinhos
	Storm surge	Unacceptable	1	Regular monitoring of concrete elements and other components that may be dama- ged by storm surges, to maximize the likelihood of early-damage detection, and minimize the level of repair that might be needed.	Annually	Municipal Council of Matosinhos
~	Vandalism	Acceptable	4	Regular monitoring of components prone to vandalism to maximize the likelihood of early-damage detection, and minimize the level of repair that might be needed.	Annually	Municipal Council of Matosinhos
ANTHROPIC	Misuse	Acceptable with monitoring actions	3	Regular monitoring of components prone to misuse, to maximize the likelihood of early- -damage detection, and minimize the level of repair that might be needed.	Annually	Municipal Council of Matosinhos
	Lack of maintenance	Acceptable with monitoring actions	3	Regular monitoring of components prone to weathering over time, to maximize the likelihood of early-damage detection and minimize the level of repair that might be needed.	Annually	Municipal Council of Matosinhos

6.3

These data will be obtained through operational routine reports in the property. Furthermore, information surveyed by different experts is necessary, as well as field observation by researchers or specialists and the assessment of legislation and its possible changes. Therefore, the monitoring process will evaluate the implementation and impact of this CMP, ensuring the protection of heritage values in the future and keeping the development in balance through adequate con-

6.2 General subjects monitoring actions.

6.3 Pressing hazards monitoring actions.

6.3.2 Impact assessment

Impact assessment is an important part of heritage management systems. As such, policies, plans, and interventions in listed properties must demonstrate a *priori* their impact on heritage significance, by identifying, evaluating, avoiding, and mitigating potential environmental and social impacts, in order to guarantee its full protection. If necessary, revisions must be conducted to existing impact assessments and frameworks, especially those pertaining to land use and other use restrictions.

For the conservation management of the Ocean Swimming Pool, the consideration of existing assessment frameworks is of particular importance, as well as the articulation of the different entities and experts involved in assessments, and in turn their articulation with the rights-holders, as they are particularly vulnerable to conflict within management systems, due to their complexity. Through the property's management process, its monitoring cycle, and the research work conducted cyclically within its context, the Advisory Body is supported in building the necessary capacity to engage with these situations and promote a strong involvement of the management framework with these various coordination and articulation needs.

The monitoring process includes an evaluation of the implementation and impact of this CMP for the property, to ensure its protection in the future and keep the development in balance through adequate heritage conservation management. When impact assessments are not required by national and supranational frameworks for all interventions affecting the property, this plan proposes the possibility of employing a Heritage Impact Assessment or "stand-alone" impact assessment (ICOMOS, 2011), thus widening the reach of the management system. This assessment tool was established to specifically manage the challenges related to the loss of heritage values and constitutes an important tool for informing decision-making regarding various factors affecting heritage and providing recommendations for mitigating negative impacts to the Ocean Swimming Pool and enhancing its potentialities



6.4

6.5 Shoed users access.6.4 Priority actions to be implemented immediately.

6.4 Priority actions, implementation and phasing

6.4.1 Priority actions

As presented in chapter 5, policies were established for the safeguarding of the Ocean Swimming Pool. They organize different types of actions that should be taken in this CMP. However, implementation should also respect feasibility, emergency, and available resources and funds, leading to phasing strategies. The following Management guidelines are based on a 5-year timeframe (Feilden; Jokkilehto, 1998). After this period, all recommendations should be reviewed by the Advisory Body (Policy A.1), based on frequent monitoring reports.

POLICY	TITLE	
A.1	Advisory body	Promote the creation of keholders to generate m with the interested partie
A.2.1	Álvaro Siza's design principles - Program	Ensure the site maintair design.
A.2.2	Álvaro Siza's design principles - Interventions	Ensure any intervention i ws Álvaro Siza's design p
A.3	Investigation and knowledge	Ensure any intervention gation, condition survey, ques, methodologies, an nical standards.
A.5	Administrative control	Ensure the building's man ned, and understood by adopted by the Municipa
B.1	Spatial Planning	The Ocean Swimming Poinstruments that regulate at the national, regional, a
B.2	Cultural Heritage Safeguarding	Comply with the Law for ventions, inside or outsid prior consent from the cu
B.3	Buffer Zone preservation	Respect the restrictions ensure the preservation
B.4	Coastal protection regulation	Comply with the Camina constructions, soil sealin in the direct destruction along the Coastal Protect
C.1	Significance and tolerance for change	All elements of the Ocea accordance with their rel tolerance for change for
C.11	User regulations	Enforce the Ocean Swim ensure visitors' safety an
C.12	Health Emergency Plan	Enforce and implement, health emergencies that Swimming Pool.

6.5

- Priority Actions are the most urgent tasks cross-referenced by the conservation detailed policies described in the chapter 5. Priorities are also established having in mind the sustainability of a cyclical system to guarantee conservation interventions, regulations, and adequate use.
- The tasks proposed to be implemented immediately are:

DESCRIPTION

an advisory body, which manages to articulate the different stanechanisms for reaching consensus and enhancing participation es in the implementation and monitoring of the CMP.

ns its current use as established by Álvaro Siza in the original

in the Ocean Swimming Pool, determined by future needs, folloprinciples, defined in section 2.5.2.

in the Ocean Swimming Pool is preceded by a detailed investi-, expert analysis, and the consultation of Álvaro Siza. The technind materials applied must follow the best international and tech-

anagement roles and responsibilities are clearly defined, assigall stakeholders. This CMP recommendations should be formally al Council of Matosinhos.

Pool's management and conservation must comply with the legal te spatial planning, such as the Municipal Master Plan and others , and local levels.

r Cultural Heritage (Law No. 107/ 2001), which forbids any interde listed properties or any change of use likely to affect it, without ultural heritage administration.

posed by the Buffer Zone, defined by Ordinance No. 608/2012, to of views and the integration of the property into the landscape.

ha-Espinho Coastal Zone Program, which determines that new ing actions, changes to the coastline, and activities that result n of relevant marine ecosystems or rock outcrops are forbidden ction Strip in which the property is set.

ean Swimming Pool are to be maintained, used and managed in elative level of significance, defined in chapter 3, and the identified r their component parts.

nming Pool User Regulations, developed by Matosinhos Sport, to nd quality of experience.

, whenever necessary, transitory regulations in case of declared t introduce disruptions in the normal functioning of the Ocean In continuity with these priority principles, it is recommended that the following tasks must be developed up to 12 months:

POLICY	TITLE	DESCRIPTION
A.2.3	Álvaro Siza's design principles - Urban policies	Consider Álvaro Siza's design principles in the definition of landscape and urban policies regarding the site's surroundings.
A.4	Engagement of stakeholders	Engage with ICOMOS, DOCOMOMO, and other heritage related organizations, universities and schools in disseminating and sharing knowledge about the Ocean Swimming Pool.
A.6	Sustainable Development Goals	Comply with the good practices of the Sustainable Development Goals (SDG – UN 2030 Agenda) contributing to the inclusion, education, knowledge sharing, and sustainability of the world.
B.8.1	Landscape Management Plan - Landscape Integration	Develop and implement a Landscape Management Plan that ensures the preservation of the site's surrounding context characteristics, essential for the building's significance. Any intervention in the site or inside its Buffer Zone must be submitted to the Cultural Heritage, I. P. and the Regional Coordination and Development Commission to ensure the close relationship between the property and the surrounding landscape is retained.
B.8.2	Landscape Management Plan - Urban planning	Enforce urban planning restrictions on building height by the seaside avenue, preventing further visual impacts over the site's immediate context.
B.8.3	Landscape Management Plan - Visual relations	Ensure the prohibition of any intervention or structure that obstructs the visual relations between the Ocean Swimming Pool and its surroundings.
C.2	Inspection routines	Promote regular inspection routines that should be more frequent during the bathing sea- son. Any anomalies identified in the building must be communicated to the site managers.
C.3.1	Maintenance Plan - Framework	Develop and implement a Maintenance Plan that takes into account the detailed conservation framework and guidelines outlined in this CMP.
C.3.2	Maintenance Plan - Budget	Consider an estimate of annual maintenance costs (estimated annual average charges, at nominal current value and without updating rate) for each maintenance action, quantifying the expected and accumulated investment over determined time periods.
C.4	Accessibility Plan	Develop and implement an Accessibility Plan for users with mobility impairments, en- suring the designated circulation areas and spaces remain free of physical obstacles.
C.5.1	Capacity and entrance control - Occupancy	Ensure the building's occupancy is permanently controlled to prevent any damage to the site from exceeding its designated capacity.
C.6	Housekeeping routines	Define and implement housekeeping routines that are permanently updated to the best international and technical standards. They must be clearly conveyed to the technicians responsible for carrying them out on a daily basis as they are fundamental for the long-term preservation of the asset's significance.
C.7	Security system	Implement a more comprehensive security system that simultaneously prevents misuse during operating hours and acts of vandalism during closing hours.
C.8	Lifesaving and rescue	Ensure the permanent availability of lifeguards on the site during the bathing season as immediate emergency responders charged with rescue at sea. Lifeguards' instructions regarding the safety of the bathers must be respected.
C.9	Fire Prevention Plan	Develop and implement a Fire Prevention Plan. The implementation of safety regulations namely emergency exit signs, fire extinguishing means, staff training, evacuation routes, and protocols on the premises is mandatory.

6.6

6.4.2 Implementation

Implementation gathers procedures that should be undertaken in a period of 12 to 60 months phased by yearly intervals, depending on the complexity of actions and resources to be administrated by the Advisory Body.

POLICY	TITLE	
A.7	Interpretation Plan	Develop and implement a ding of the significance o communicated through s and its users.
A.8.1	Communication strategy - Online platform	Create a single online plat levant information regard trance fees, use regulation
B.5.1	Risk Management Plan - Risk Management	Develop and implement ments, the development of
B.6.1	Green procurement - environmental analysis	Conduct an environmenta identify energy-saving op
B.7.1	Climate change adaptation - Adaptation measures	Compile a set of measur cases with similar constra- larly, the knowledge obta- sures or guidelines for log
B.8.4	Landscape Management Plan - Landscaping	Implement a landscaping nance cutting and prunin nue.
B.8.5	Landscape Management Plan - Beach cleaning	Implement a cleaning rou of waste on the site.
B.8.6	Landscape Management Plan - Placement of furniture	Limit the presence of furn the use of bathers must design features. The bar of ice cream freezers) on the
B.8.7	Landscape Management Plan - Placement of signage	Control the placement of building, swimming pools the landscape and the sea
C.3.3	Maintenance Plan - Maintenance manuals	Develop cyclical maintena long-term conservation in ch.
C.5.2	Capacity and entrance control - Visitor information	Display occupancy inform avoid the formation of lor vented from entering. The be considered.

6.7

6.6 Priority actions to be implemented in 12 months.

6.7 Actions to be implemented in 24 months.

DESCRIPTION

a comprehensive Interpretation Plan based on a clear understanof the place that establishes how the cultural significance will be specific programs, visits, and activities, engaging the community

tform easily accessible by the general public that gathers all reling the Ocean Swimming Pool, such as opening schedules, enons, or information on the site's history and significance.

a Risk Management Plan which includes regular risk assessof mitigation measures and emergency preparedness measures.

al analysis of the Ocean Swimming Pool's regular functioning to oportunities.

res, or actions (as a study case), for implementation in other aints, to help other listed sites to adapt to climate change. Simiained from this case study should also suggest additional meacal and regional policies.

plan for the gardens on the building's roof, with regular mainteng of the vegetation to avoid obstructing the view from the ave-

utine of the beach and rock outcrops to avoid the accumulation

niture such as chairs and tables to the bar terrace. Parasols for be requested to the bar concessionaire and abide by uniform concessionaire should restrain from placing equipment (such as e exterior.

signage (such as security warnings) and other elements in the s, or rocks to prevent the disturbance of the visual relation with a.

ance and treatment manuals to establish priorities and short and nterventions, thus maintaining a proactive conservation approa-

nation (low, high, and "sold out") on the exterior of the building to ng lines and the consequent frustration of visitors who are prene possibility of making this information available online should It is recommended that the following tasks should be taken up to 36 months:

POLICY	TITLE	DESCRIPTION
A.8.2	Communication strategy - Shared knowledge network	Establish a shared knowledge network with those responsible for the management of other Álvaro Siza's works, creating an integrated dissemination and safeguarding strategy.
A.9.1	Community engagement - Learning programs	Develop learning programs for schools and families, composed of didactic activities for children, related to the Ocean Swimming Pool.
B.5.2	Risk Management Plan - Disaster recovery	Develop and anticipate lines of action for emergency response and disaster recovery.
B.6.2	Green procurement - Strategies	Adopt green procurement (energy, waste, and water) and carbon offsetting strategies, emphasizing green products, services, and business models.
B.7.2	Climate change adaptation - Permanent flooding	Study future lines of action for building conservation in case of permanent damage or flooding that makes the normal use of the built structures and infrastructures impossible (be it relocation, the construction of more permanent protection measures like walls or spurs, etc.).
B.7.3	Climate change adaptation - Staff training	Train staff/stakeholders and inform users on more efficient management strategies, and promote the use of sustainable practices while working, using, or managing the place. It would be beneficial to the implementation of these strategies if there were participatory activities, presentations, or workshops to raise public awareness on appropriate mitigation measures.
C.10	Risk awareness learning plan	Enhance risk awareness activities to raise public awareness about the most significant factors threatening the Ocean Swimming Pool and the possible responses to mitigate them.
6.8		

It is recommended that the following tasks should be taken up to 48 months:

POLICY	TITLE	
A.9.2	Community engagement - Broadening access	Promote specific visits an ditional access needs, suc ness and broadening acce
A.10.1	Archives and collections - Archives	Gather, catalog, and digit is dispersed throughout of available for consultation
B.7.4	Climate change adaptation - Archival information	Organize an archive con (3D and 2D mapping, vis future preservation in cas
C.13	Archival database	Gather and organize all in ques, methodologies, and or other documentation o

6.9

While also a first revision can be conducted to verify the actions that could not be completed accordingly, it is recommended that the following tasks should be taken up to 60 months:

POLICY	TITLE	
A.10.2	Archives and collections - Collections	Create an inventory of all the property with informa vation and exhaustive doe
C.14	Building Information Management System	Develop and implement gement tools for inspect in real time.

6.10

DESCRIPTION

nd knowledge dissemination activities aimed at visitors with adch as deaf and visually impaired audiences, promoting inclusiveress to the site.

tize all documentation related to the Ocean Swimming Pool that different institutions, creating a comprehensive digital database of interested parties from all over the world.

ntaining exhaustive information on the Ocean Swimming Pool sual information, etc.) to assure its proper reconstruction and se of damage or material loss.

nformation related to conservation interventions, namely technid materials employed, as well as graphic, photographic, digitized, on the adopted procedures.

DESCRIPTION

I the furniture and objects specifically designed by Álvaro Siza for ation on their location and condition to assure their future preserocumentation.

a building information management system with facility manation and maintenance routines including notifications and alerts

^{6.8} Actions to be implemented in 36 months.

^{6.9} Actions to be implemented in 48 months.

^{6.10} Actions to be implemented in 60 months.

6.4.3 Phasing

In the following table, all policies are summarized to highlight their importance and correlation in phases of implementation:

POLICY	DESCRIPTION	P	HASIN	IG (up	to - in I	month	s)
TOLICT		0	12	24	36	48	60
A OVE	RARCHING POLICIES						
A.1	Advisory body						
A.2.1	Álvaro Siza's design principles - Program						
A.2.2	Álvaro Siza's design principles - Interventions						
A.2.3	Álvaro Siza's design principles - Urban policies						
A.3	Investigation and knowledge						
A.4	Engagement of stakeholders						
A.5	Administrative control						
A.6	Sustainable Development Goals						
A.7	Interpretation Plan						
A.8.1	Communication strategy - Online platform						
A.8.2	Communication strategy - Shared knowledge network						
A.9.1	Community engagement - Learning programs						
A.9.2	Community engagement - Broadening access						
A.10.1	Archives and collections - Archives						
A.10.2	Archives and collections - Collections						
B SITE	POLICIES						
B.1	Spatial Planning						
B.2	Cultural Heritage Safeguarding						
B.3	Buffer Zone preservation						
B.4	Coastal protection regulation						
B.5.1	Risk Management Plan - Risk Management						
B.5.2	Risk Management Plan - Disaster recovery						
B.6.1	Green procurement - Environmental analysis						
B.6.2	Green procurement - Strategies						
B.7.1	Climate change adaptation - Adaptation measures						
B.7.2	Climate change adaptation - Permanent flooding						
B.7.3	Climate change adaptation - Staff training						
B.7.4	Climate change adaptation - Archival information						
B.8.1	Landscape Management Plan - Landscape integration						
B.8.2	Landscape Management Plan - Urban planning						
B.8.3	Landscape Management Plan - Visual relations						
B.8.4	Landscape Management Plan - Landscaping						

B.8.5	Landscape Management Plan - Beach cleaning			
B.8.6	Landscape Management Plan - Placement of furniture			
B.8.7	Landscape Management Plan - Placement of signage			
CICON	SERVATION AND MANAGEMENT POLICIES			
C.1	Significance and tolerance for change			
C.2	Inspection routines			
C.3.1	Maintenance Plan - Framework			
C.3.2	Maintenance Plan - Budget			
C.3.3	Maintenance Plan - Maintenance manuals			
C.4	Accessibility Plan			
C.5.1	Capacity and entrance control - Occupancy			
C.5.2	Capacity and entrance control - Visitor information			
C.6	Housekeeping routines			
C.7	Security system			
C.8	Lifesaving and rescue			
C.9	Fire prevention plan			
C.10	Risk awareness educational plan			
C.11	Use regulation			
C.12	Health Emergency Plan			
C.13	Archival database			
C.14	Building Information Management System BIM			

6.11

6.11 Policies implementation phasing.

References

Boccardi, G. and Stovel, H. (2004) "Monitoring World Heritage – Conclusions of the International Workshop" in Stovel, H. (org). *Monitoring World Heritage. World Heritage 2002: Shared Legacy, Common Responsibility, Associated Workshops*, 11-12 November 2002, Vicenza – Italy. Paris: ICCROM/ UNES-CO World Heritage Centre, pp. 131-132. Available at: https:// unesdoc.unesco.org/ark:/48223/pf0000136571 (Accessed: 10 January 2023)

Court, S. et al. (2022) Guidance and toolkit for impact assessments in a World Heritage Context. Manual. Paris/ Rome/ Charenton-le-Pont/ Gland: UNESCO/ ICCROM/ ICOMOS/ IUCN. Available at https://whc.unesco.org/en/guidance-toolkit-impact-assessments/ (Accessed: 10 January 2023)

Feilden, B. and Jokkilehto, J. (1998) Management Guidelines for World Cultural Heritage Sites. Rome: ICCROM.

Ferreira, T. C. (2020) "Manutenção do património do Século XX: Contexto, experiências e desafios", *Construção Magazine*, 96, pp. 22-27.

ICOMOS (2011) Guidance on heritage impact assessments for Cultural World Heritage Sites. Charenton-le-Pont: ICO-MOS. Available at: https://www.iccrom.org/sites/default/ files/2018-07/icomos_guidance_on_heritage_impact_ assessments_for_cultural_world_heritage_properties.pdf (Accessed: 10 January 2023)

ICOMOS Australia (2013) The Burra Charter: The Australia ICOMOS Charter for Places of Cultural Significance. Burnwood: ICOMOS Australia. Available at https://australia.icomos.org/wp-content/uploads/The-Burra-Charter-2013-Adopted-31.10.2013.pdf (Accessed: 10 January 2023)



APPENDICES

Design reports of the original design
(1960-1995)
Interviews with the Heads of Municipal
Council Departments
Interviews with the Site Managers and
Staff
Inspection and diagnosis report
Detailed tolerance for change
assessment
Listing information
Admission conditions and user
regulations

248-390



Design reports of the original design (1960-1995)

Leca da Palmeira Ocean Swimming Pool – 1st phase Design report, 1960

General considerations: location

The construction of a saltwater pool in the vicinity of the Leça beach, for the use of its bathers, is an old aspiration that the Matosinhos Municipal Council believes it is time to fulfil.

It chose, for its location, a small rocky cove that develops in an approximate north-south direction, parallel to the wall of the so-called "Meia-larania", of the "Centenários Avenue", which limits it to the east (see "Drawing 1" of this project and the photographs in the "Appendix" to the "Report").

The situation is ideal, not only for the beauty of the site, but also for its short distance to the Leça beach, which can be reached without going up to the avenue, through the picturesque path among the rocks to be regularized in the future, or from the avenue, with which it is indirectly connected by the "Meia-Laranja".

On the other hand, the natural conditions allow for the inscription of the swimming pool with minimum intervention and without disruption of the local arrangement of rocky outcrops and, also, the future creation of solarium areas, cabins and auxiliary constructions, in the natural rock amphitheatre, now covered by the "Meia-laranja" embankment and under the same embankment in the part that was judged to be conserved, on the north side, for natural protection of the swimming pool and solarium, from the summer winds.

In November 1959, the Matosinhos Municipal Council decided to consult the firm "Ribeiro da Silva, Lda", public works contractors, specialized in maritime works, about the viability of the project and its probable cost for a first phase, consisting essentially of the creation of the pool pit, which would fill or empty with the natural movement of the tides, the dismantling of the rock indispensable for its insertion and the execution of the support walls limiting the natural water inlets.

Since the natural conditions allowed for it, it was settled to foresee the swimming pool with the plan dimensions of 20 x 33.33 m., but with the bottom following the existing bedrock, The project here presented takes into account the new proonly regularized in longitudinal section, for economic reasons.

Within this program, the aforementioned firm sent to the Matosinhos Municipal Council, with a letter dated 12/11/1959, a description of the works considered essential and the respective estimate, importing in esc. 200 000\$00 (see "Appendix I" and "Appendix II" to this "Report", the second explains how the estimate in question was prepared).

By letter nº 3927, of 12/30/1959, the Municipal Council communicated the inclusion of that amount in its budget for 1960 and requested the presentation of the definitive project for the swimming pool and an indication of the conditions under which the aforementioned Contractor Firm could undertake the execution of the work, so that it can be used in the 1960 bathing season (see "Appendix III" to this "Report").

During the elaboration of the project, in February this year, the Municipal Council decided, and rightly so, that it was essential to study the local urban arrangement with the conditioning

posed by the swimming pool to be built, and for this purpose indicated the Architect Siza Vieira, who should also collaborate in this project for the 1st phase of the pool construction.

From the joint discussions with the Head of the Municipal Council and its Technical Department, the aforementioned Architect and the signatory, fundamental alterations were made to the initial plan of the construction work, and it was decided that it would be advisable to give the base a regular outline, and to test its coating and the cuts to be made in the peripheral rocks.

For aesthetic reasons, it was decided to use cyclopean concrete for the construction of the support walls that were initially planned to be built in masonry, and it was considered essential to build a cleaning spillway on its periphery and top, and a sidewalk 2 m. wide on the east side, while the definitive arrangement of the solarium area was not settled.

The tops of the north and south support walls, planned to be 1m. wide, with plans to be widened as they were manifestly narrow for the peripheral circulation of bathers, - especially in the south, where the diving boards will be located in the future - were maintained, on the basis of an accepted proposal from the architect, who believes that the enlargement and railing should consist of a removable structure to be placed only in the bathing season, along with the aforementioned boards and the walkways to be studied to connect the pool to the Leca beach.

There was also the need to build a children's swimming pool in the site, in a location to be chosen, for which part of the dismantled rock would be used to raise the sill.

Finally, it was decided that it was not feasible to use the natural tides to fill, empty and refill the pool, so the Municipal Council will consider, in another phase, the installation of the necessary adductor and motor-pump groups.

gram that fundamentally changes the scheme initially laid out, leading to an undoubtedly more perfect solution but costing exactly twice as much.

General description of the pool: dimensioning

As shown in "Drawing 1" of this project, the natural arrangement of the rock facilitates the inclusion of the 20 m, wide pool, without the need for any major rock removal, which allows the possibility of 10 lanes with the usual width of 2 m.

The length that most harmonizes with that provision is the classic measurement of 33.33 m.

The main axis of the pool runs parallel to the wall of the "Meia--laranja", with a 4 m. distance from its east edge, taking advantage of 2 m for the execution of a promenade.

The north and south walls of the pool are made up of support walls and curtains with variable heights depending on the irregular profile of the existing rock (see the transversal profiles P.1 and P.12 of the project).

The east limit is established by cutting the rock along the entire height of the pool (see the longitudinal profile P.B), duly coated, the same happening in the west limit at 20 m, wide, in which the rock does not, however, reach the level of the free surface (longitudinal profile P.F.). Thus, the water of the pool spreads on that side, over the rocks, forming a natural basin with irregular contours and variable depth, limited by the rocks, only foreseeing the need for a support to the west (longitudinal profile PG) filling a gorge to the west, lower than the free surface of the water in the pool.

The regularization of the bottom of the swimming pool, that of the eastern sidewalk (both with 0.30 m. of average thickness), the curtains at the base of the north and south walls (with 0.50 m. of average thickness) and the east and west limits' curtains (with an average thickness of 0.50 m. in the swimming basin and 0.60 m. in the diving basin), are expected to be executed on site with plain concrete, with a dosage of 210 kg. of cement and 90 kg. of pozzolan per m³ of concrete, given its permanent contact with sea water. This dosage is the one the A.P.D.L. has used in similar works.

The top of the walls is located at the level (+2.60) N.P., be 0.23 m. above the level (+2.37) which is that of the M.P.N.A.V. and was taken to that of the free surface of water inside the pool. As for the bottom, the classic solution was adopted, as shown in "Drawing 2", which adapts well to the natural topography, reserving 21.21 m. of the pool length for swimmers and the remaining 13.12 m. for the jumping pit. In that area the minimum depth, to the north, is 1.80 m. and

the maximum, at 21.21 m., of 2.50 m.

The filling of the profile recesses at the bottom of the pool and In the jumping pit, the sill slope is transversal to allow the draiof the north, south and west support walls, given their respecnage through the lowest point, located at the limit of 20.00 tive sections, will be executed with cyclopean concrete made m., with the minimum water height, to the east, of 3.50 m, and of stone no larger than 0.30 m., agglomerated with concrete maximum, to the west, of 4.00 m. of the indicated type.

The swimming and diving basin sills are connected by a slope The stability of the support walls was verified for their maxiat 1.3 m with 3.03 m. wide along the longitudinal axis of the pool. mum height and the most unfavourable conditions (having the pool full at low tide) shown in the graphics that are part of On this axis, the depth of the diving pit is 3.75 m, which allows the "Appendix" to this "Report". The effect of a direct impact jumps with a maximum of 4 m. above the water. of the waves on the support walls was not considered, given Greater depth would only be achieved with costly dismantling the protection they enjoy due to their orientation, natural arat the bottom of the pool, and complementary dismantling to rangement of the rocks and because it is possible to keep the include the bottom discharge in a ditch, at the lower level. pool full in the winter.

The future diving boards should be facing north, on the south In this phase, plastering is only planned for the entire width of the eastern sidewalk and on the top of the north and south wall. as is usual. walls, to be executed with cement mortar with a 1:4 rough mix The entire pool sill is covered in the 20.00 m. wide area, and so it is not slippery.

appropriate devices should be used to mark the western limit, where the irregular natural basin begins.

Safety ledge: cleaning discharger: bottom discharge

In the parameters of the east support wall, in concordance with the jumping pit and of the south support wall, in all the extension, a safety ledge for the swimmers was foreseen, placed at a depth of 1.30 m. (see "Drawing 8").

At the crest and along the highest points of the north and south walls, fibre cement is foreseen for economic reasons, and it is certain that this material is known to have, until now.

proven out in the pipeline of the saltwater pool on the Figueira da Foz beach.

The exit from the bottom of the pool, detailed in the "Drawing 9", is located at the lowest point of the sill, on the south support wall, leading directly to the beach through a 250 mm drain, embedded in that wall, internally closed by a special valve that is resistant to sand and the action of saline water. with remote control, on the top of the support wall. The valve is located in a niche so that it can be inspected and removed if necessary.

Support walls and coatings

Porto, March 15, 1960

Bernardo Ferrão

LECHON INCLARANTELISAS INTEE INCLARANTELISAS INTEE INCLARANTELISAS INTEE INCLARANTELISAS INTEE INCLARANTELISAS INTEE INCLARANTELISAS INTERIOR INCLARANTELIS INCLARANTELISAS INTERIOR INCLARANTE

A.1





A.3



A.4

A.1 Site plan, 1960.

A.2 General dimensioning, plan and sections, 1960.

A.3 Longitudinal sections, 1960.

A.4 Longitudinal sections, 1960.







A.6



 Image: Description

PORMENOR DO DESCAPREGADOR DE LIMPESA

A.8



A.9



A.5 Cross sections, 1960.

A.6 Cross sections, 1960.

A.7 Cross sections, 1960.

A.8 Cleaning discharger detail and sewer layout, 1960.

A.9 Bottom discharge scheme, 1960.

Leca da Palmeira Ocean Swimming Pool Design report, 1962

The Leça da Palmeira seafront enhancement plan is currently under study and is included in the urbanization of the area between the current nucleus and Boa Nova.

The Ocean Swimming Pool, whose preliminary project is now presented, is part of the aforementioned plan, of which the already planned coastal road, between Matosinhos and Póvoa, is the backbone.

The location chosen by the Matosinhos Municipal Council seems to gather excellent conditions, due to its situation in relation to the town, its future expansion, and the set of beaches in which the pool will be a vital element.

The construction of the two pools (one for children and one for adults) takes advantage of the topography of the terrain, not only for economic reasons, but also to avoid a violent section of the landscape, following the spirit that presides over at the exit of the changing rooms and next to the pools. the mentioned plan.

The adjoining facilities (changing rooms, toilets, and water treatment cabin) develop along the retaining wall that currently limits the beach, articulating perpendicularly to the north with a building destined for a restaurant and complementary services.

The development and capacity of the adjoining facilities were established on the basis of commonly adopted principles and taking into account the area of the swimming pool.

In opting for the cabin system for changing clothes, with a central deposit and a separation between shoed and barefoot people, 24 cabins were found to be necessary, assuming that the number of hangers in the deposit should be close to 3/5 of the number of square meters of the pool, that the daily use of each cabin is 40 people, and that each cabin is used twice a day (Prof. Ernest Neufert, "Architects' data").

The buildings will be built with bare concrete walls and a wooden roof, covered with copper sheeting over asphalt fabric.

The floors will be washable, with a careful choice of materials, especially in the changing rooms and toilets, where hygiene care is more pressing.

Outside, areas for the exclusive use of the barefooted are foreseen, with showers and foot washes of mandatory passage,

Matosinhos. October 25, 1962

Álvaro Siza



A.10



A.11



A.10 Site plan, 1962. A.11 Plan, 1962. A.12 Elevations, 1962.

Leça da Palmeira Ocean Swimming Pool – 2nd phase Design report, 1965

1 - General considerations

The currently existing and projected ensemble is, according to drawing no. 2, constituted by:

- Adults' swimming pool
- Children's swimming pool
- Showers and sanitary facilities for women and men
- Changing rooms for men and women and warehouse
- Seawater collection
- Water treatment station
- "Snack-Bar" (to be executed)
- Solarium and accesses.

This complex is located to the north of the Leça beach and develops on the rocks that border the "Centenários Avenue", connecting Leça to the Boa-Nova lighthouse.

In the preliminary design of the swimming pool, dated from March 15, 1960, the successive phases of the initial evolution of the development are described: what had started as a simple pool that took advantage of the irregularities of the local rock and of the tides to serve the bathers of the Leça beach, ended up in the autonomous complex to which the present project refers.

On the preliminary draft in question, the Directorate of Health Services of the G.D. of the Urbanization Services through the Technical Services of Exploitation, in its information no. 201, of April 2, 1960, whose indications were duly considered in this project.

In the natural evolution of the project, a children's pool was added to the existing swimming pool; the common solarium was enlarged through the demolition of the "Meia-Laranja" (half-orange) terrace on the side of "Centenários Avenue"; the sewers leading to the beach were relocated to the south Beach; all the buildings for changing rooms, toilets and a snack bar were planned; the seawater collection was built through underwater galleries and its treatment in a closed circuit; the whole area and its accesses were urbanized and the site was fenced in.

2 - Location

According to "drawing no. 1" the adults' swimming-pool occupies a natural cove in the rocks of the beach, which develops roughly from north to south; the children's swimming-pool is placed taking advantage of a "Talweg" between the rocks to the south-west of the other swimming-pool; the sanitary facilities, treatment cabin and changing rooms lay out parallel to the avenue and the "snack-bar" will be built to the north, at an angle with the changing rooms, protecting the solarium, which develops in a rock amphitheatre limited by the buildings and the swimming pools, from the north winds.

3 – Accesses and car park

The planned accesses and car park are a 1st phase, to be included in the study being carried out on the new waterfront plan.

The access to the pool area is made by a ramp, overcoming the difference in level between the pool and the terrace on the waterfront. The entrance to the pool area for barefoot bathers is through the changing rooms. The area for shoed users has an independent entrance, at the northern end of the facilities. A second ramp is planned, in a north-south direction, allowing a more direct access from the car park.

4 - Changing rooms, showers and sanitary facilities

These facilities run parallel to the waterfront avenue. Their capacity was established on the basis of the swimming pool area, based on calculations transcribed by Prof. Ernest Neufert in "Architects' Data".

4.1 – Changing rooms – The option was made for the system of cabins for changing clothes, in two sections (men and women), with a central coat rack and separation between shoed and barefoot users.

It was found that 24 cabins were necessary, assuming that the number of hangers, in the coat rack, should be close to 3/5 of the number of square meters of the pool, that the daily use of each cabin is 40 people, and assuming that each cabin is used twice a day, (Prof. Ernest Neufert, "Architects' Data").

- Pool approximate area	800 m²
- No. of hangers (3/5 × 800)	480
- Daily use of the hangers	960
- No. of cabins (960 : 40)	24

Each changing room section is equipped with five foot-washes and one washbasin.

4.2 – Sanitary facilities and showers – They are located at the south end of the annexes, near the entrance to the barefoot area, and equipped as follows:

len's section:	2 toilets
	3 showers
	3 urinals
	1 wash basin

3 showers
1 wash basin

4 toilets

The showers distributed by the barefoot area must be added to these numbers.

The entrance to each of the sections is mandatorily made through the same foot wash that separates the facilities of the barefoot area.

4.3 – Construction and materials – The construction system adopted is that of unplastered poorly reinforced concrete walls, supporting a baltic pine wood roof, covered with copper sheeting over asphalt fabric. The height of the timber beams allows for permanent cross ventilation of the entire facility.

The cabin partitions are made of wood, and hung from the The bottom is constituted by three levels: the small bathing roof, so as to allow easy washing of the floor. The floor is made area, sloping in the longitudinal direction with depths betof pre-cast concrete slabs. The connection with the longituween 0.9 and 2.5 m.; an intermediate level, with a slope in the dinal walls is made by gutters with semi-circular section. The same direction and depths between 2.5 to 4.05 m., and the walls are made of washable material (cement) or of wood. bottom of the jumping pit, with a transversal slope towards duly protected. In the sanitary facilities and showers, where the bottom sewer, with depths between 3.8 to 4.0 m. greater care was needed, this protection achieved by a vinyl 8.2 - Children's swimming pool - The children's swimming resin film. The metal parts (locks, drainage grates, etc.) are pool, as shown in "drawing no. 20", has the approximate shape made of brass or copper.

4.4 – Sanitary facilities for shoed users – They will be integrated into the volume of the bar, currently under study. In the meantime, they will operate in a provisional installation, with two sections for men and women, next to the area destined for shoed users (north side).

5 – Bar project

It will be built on the northern side of the site, increasing the area sheltered from prevailing winds, as indicated on the to-pographical plan.

6 - Area for shoed and barefoot users

The terrain's natural conditions were taken advantage of as much as possible, especially where rock outcrops limited areas sheltered from the prevailing winds. These areas have at times been enlarged by light rock removal. A system of platforms and concrete stairs comfortably connects the different levels of these areas. A more systematic use of the terrain is being studied, particularly in the southern part of the site.

Private areas for barefoot users, connected to the pools, are planned, with foot washing basins with mandatory passage near the entrances. These areas will be in sand or paved with cement.

7 – Lighting

The respective project is under study and, as night use of the swimming pools is not foreseen, the current security lighting is made out of light points in the buildings and floodlights outside, which have functioned as a pilot installation on a temporary basis.

8 – Pool dimensioning

8.1 – Adults' swimming pool – The rectangular shaped swimming pool is limited to the north, south and east by support walls or artificial coatings and to the west by the irregular natural rock, of which only a lower part was also covered by retaining walls, as can be seen in "drawing no. 19".

The pool is 33.33 m. long and a variable width that, at its narrowest point allows for 8 swimming lanes, 2.5 m. wide, at full depth of 20.0 m.

8.2 – Children's swimming pool – The children's swimming pool, as shown in "drawing no. 20", has the approximate shape of an "L", in plan, being limited by a curvilinear support wall, by the natural rock on the sides and on the back side by another straight support wall.

The bottom is flat with a slight slope towards the curvilinear wall where the sewer is located. The maximum water depth is 0.5 m.

9 - Collection

The swimming pools are filled with seawater. The initial intention was to capture it between the sinuous local rocks where the bottom sewage outlet is located, but this has proved to be unfeasible given the existence of a large amount of sand in suspension in the captured water.

Therefore, it was necessary to opt for underwater collection, as shown in the two respective "drawings no. 21 and 22", and described below.

A well with a diameter of 3.00 m. and a depth of 18.0 m., duly covered with prefabricated concrete blocks, was dug at about 3 m. from the support wall of the public walkway.

From this well there is a gallery with a section of 1.50×1.80 , which bifurcates at 40.00 m. with a length of 29.00 m. and at 63.90 inflects on the same side in a section of 10.00 m. The total length of the gallery is 102.90 m.

During the construction works for the opening of the gallery, 159.00 m. of horizontal 3" pilot hole soundings were conducted because, as can be seen from the general plan, the galleries are located under the sea.

The galleries were opened in the rock and, therefore, were not covered, with the exception of an initial section with a length of one meter, in the connection with the well.

In the well, two filter wells in porous concrete were placed. with a diameter of 1.00 and a height of 12.00 m.

Both the galleries and the well were filled with Caia borgau and coarse sand.

Holes were drilled at convenient points in the galleries and, by means of explosions, deep cracks were opened in the rock, which allowed water to enter the gallery and, consequently, in the filtering wells.

For the location of the electric pump groups a well was dug under the sidewalk. The walls are in concrete and both the intermediate plate and the cover are in reinforced concrete. Outside access was achieved through a small gallery by the sidewalk retaining wall. An iron door with shutters seals off the entrance. As a ventilation complement, four circular holes with 0.20 m. of diameter were opened in the retaining wall to improve air circulation.

Two groups of "Pargete" centrifugal electric pumps, entirely made of phosphor bronze and stainless steel shafts, and "EFACEC" electric motors, protected flow type, each of 50 I./ sec. were installed there. All the piping, from the filtering wells to the water treatment equipment, is made of cast iron with a - A physical treatment that ensures the clarity of water after diameter of 0.20 m.

The pumping installation was made in order to allow the functioning of only one group or both at the same time.

The electrical installation was carried out in accordance with regulatory standards.

10 - Filling and circulation

The 200 mm. wide adductor of the collection pumps connects to the treatment plant network to allow for the filling of the pools directly or through the respective equipment.

The circulation of water for regeneration in a closed circuit is indicated in drawing no. 23 and proceeds as follows: the water leaves the north wall of the swimming pool through 9 inlets equipped with brass drains, aligned at a depth of 0.5 m. and 2.1 m apart. These entrances, in fibre cement tube with a diameter of 100 mm, are connected by a collector made of the same material with a diameter of 150 mm., in turn discharging into the fibre cement pipe of 300 mm. which, along the aqueduct under the foot wash, on part of the beach, - duly protected by concrete wrapping, - and along the aqueduct under the children's pool and its solarium, opens into the well of

the treatment centre in plunging the circulation pump group sucker. The return circuit described takes place entirely by gravity, with the water leaving the children's pool through a 75 mm copper pipe (equipped with a bronze wedge valve) located halfway between the water inlet and the centre of the support wall on the sea side.

The water inlet circuit is made up of a galvanized iron pipe at the output of the central pumping unit and in the respective 200 mm fibre cement sink pit, following the same route as the return pipe to the south side of the swimming pool.

There it splits into two levelled fibre cement branches measuring 150 mm., to which 9 outputs with 80 mm of diameter connect. equipped with a diffuser and rare brass cone, 4 of which are aligned at a depth of 1.0 m. and 5 at 2.5 m., spaced 4.0 m apart in each row and placed in guincunx.

In the children's pool, the entrance occurs in the same way as the exit, located on the support wall that limits it on the opposite side of the beach.

11 – Circulation, filtering, treatment

11.1 - General considerations - The adopted treatment principle was making the regeneration in a closed circuit, assuming a regeneration cycle of 12 hours, which means, for the total volume of the pools of about 2,250 m³, with an hourly flow of the purifying installation of 190 m³.

Proper regeneration requires:

use:

- A bacteriological treatment aimed at destroying living organisms (microbes, algae, etc.) in the water that cannot be retained through filtration, as well as providing it with some antiseptic properties.

Thus, treated water must comply with the following characteristics:

Physical

 Clarity: it must be crystalline and clear so that the turbidity is less than 10 drops of 1% alcoholic mastic solution verified with the Dienert apparatus.

- Colour: should be clear and bluish, without any yellowish tinge.

Chemical

It will remain constantly alkaline to methyl orange and free from caustic alkalinity; it will contain between 0.3 to 0.5 mg. of free chlorine per litre.

Bacteriological

The water will not contain a number of bacteria greater than 200 per cm³ in more than 10% of the samples examined. Nor will it contain coli bacilli in 50 cm³, of water,

11.2 - Circulation - Circulation is forced through the described circuits by two groups of electric pumps of 12.5 H.P. of power, with an hourly flow rate of 95 m³. each and for 17 m. head height (See attached drawing no. 24).

11.3 – Solid bodies filter – As soon as it enters the treatment The adults' swimming pool has 2 drains: one centred with the cabin, the water goes through a solid bodies filter - retaining north wall, just below the bottom, equipped with a sandbox suspended substances that are harmful to filtration and pumcovered with a perforated slab, and consisting of a "Saunders" ping -, made of mild steel sheet with a hinged lid and a copper type valve with rubber diaphragm and 6-inch cast iron tubing mesh retention sleeve. It has a height of 717 mm. and a diamecoming out into an outer depression of the rock into which the sea enters at high tide; another in the deepest part of the pool. ter of 300 mm. on the south side, also with a sandbox, "Saunders" valve and 10" cast iron piping.

11.4 – Filtering – This filtration is intended to reduce the supply This piping extends along the beach, embedded in the rocks, flow and retain suspended substances and is carried out in a and wrapped in concrete, to open in a massif executed betbattery of 3 quick-type vertical axis filters, under a working ween two rocks within sea reach. pressure of 1 kg/cm² and simple backwash of water, without the need for compressed air. All valve parts are made of bronze or stainless steel as are

The filters, made of mild steel sheet, are cylindrical, with a diameter of 2m and 2.2m high, and contain filtering units made up of lavers of sand and cobble of homogeneous and calibrated granulometry.

They are connected by 6-inch pipes, equipped with external valves to control the various operations, a set of 2 pressure gauges interspersed in the control tree and, inside, and at the bottom, has a branch of pipes that ensure the uniform distribution of water through the filter layers.

The water for washing the filters is received in a tank connected to the rainwater collector of "Centenários Avenue" by a fibre cement tube with a diameter of 200 mm. (see drawing no. 14).

11.5 – Chemical clarification – As accelerating reagents for the formation of the colloidal filtering film, aluminium sulphate is used for chemical bonding and sodium carbonate (for alkalizing the water so that it has a final pH between 7 and 8).

This preparation is made in 3 stoneware tanks of 200 I each and the dosage in a "Duplex M.68/70" electric dosing pump, which injects those reagents in intermittent periods, through plastic tubing of polyvinyl chloride to the circulation tubing, before the filters.

11.6 – Disinfection – Water disinfection is based on gaseous chlorine, whose bottle is located in a special compartment integrated in a storage room, insulated and conveniently ventilated.

Chlorine is applied after filtering and is dosed automatically through a "Degrément ACFI" chlorometer, model CVPA 150, where the chlorine and dilution water are mixed to form the sterilizing liquor that is then released through the antacid pipeline.

12 - Swimming pools sewage

Indicated on drawing no. 25.

their control rods up to the top of the support walls.

The children's pool has a single 6-inch bottom outlet located on the curved support wall, equipped with a wedge valve placed in a sandbox covered with a perforated slab and opening to the beach through cast iron tubing embedded in the wall.

13 – General drainage

The adults' swimming pool has a general drain around the perimeter of its three support walls, to the north, east and south, as does the children's pool along almost of the entire length of the curved support wall near the beach (see drawing no. 25).

The drainage is cast in the concrete of the support walls, in the case of the adults' swimming pool, with a lower lining of 1/2 fibre cement. In this pool, the drains are made of the same material, having a diameter of 60 mm and set 4.5 m apart, connecting to longitudinal collectors of 100 mm of diameter, also made of fibre cement.

Equipped with appropriate slopes, these collectors have two outlets, on the north and south support walls, vertically from the bottom sewers and at levels compatible with those of the adjacent beaches.

In the children's pool, there are only two outlet drains, opening directly onto the beach.

14 – Foot washes: showers

In the adults' swimming pool, due to its special conformation, there is only one longitudinal foot wash along the whole length of the east limit, intercepting the entrance of practically all swimmers, since the access from the south side is impossible, and the access from the north and west sides is not very comfortable due to the characteristics of the rocks.

The foot wash has a depth of 0.25 m. and variable width, with a minimum of 1.3 m. The edge on the pool side is straight and parallel to it and the edge on the solarium side is irregular, following the rocky contour.

It is equipped with two brass showers controlled by foot.

To the east of the children's pool there is another small foot wash with a shower at one end.

Finally, there is another foot washing basin at the entrance to the toilets, along the entire width of the passage and developed in the way indicated by drawing no. 14.

All the foot washing basins are provided with bottom and trop-plein drainage and are supplied, as are the showers, by fresh water from the public network.

15 - Ladders, footrest ledges: diving boards

In the adults' swimming pool there are removable ladders made of brass tubing and wooden steps until the edge of the footrest ledge, as indicated in drawing no. .

This edge has a 0.15 m. projection and consists of a reinforced concrete levelled console at the depth of 1.3 m., extended along the entire support walls.

Porto, February 16, 1965

Álvaro Siza Vieira Bernardo Ferrão



A.13







A.15

A.13 Site plan, 1965.A.14 Plan, 1965.A.15 Structural plan, 1965.



A.16



A.17



A.18

- A.16 Cross section A, 1965.
- A.17 Cross section B, 1965.
- A.18 Cross section C, 1965.

- A.19 Cross section D, 1965.A.20 Detailed plan, 1965.A.21 Detailed longitudinal section, 1965.



A.19







A.21

120 K limite lana, ala

0



A.22



A.23

- A.22 Water treatment room's roof slab, 1965.
- A.23 Children's swimming pool plan and sec-
- tions, 1965.
- A.24 South bathrooms plan, 1965.

- A.25 South bathrooms sections, 1965.
- A.26 Water collection infrastructure, 1965.
- A.27 Water treatment and pumping infrastruc-
- ture, 1965.



. 81 .

A.26

A.24



A.27





A.25



Leça da Palmeira Ocean Swimming Pool - 4th phase - Preliminary draft Restaurant design report, 1965

The operating experience of the Ocean Swimming Pool demonstrated the need to enlarge the enclosure. Therefore, the study now presented was prepared, based on the following principles:

a) - Revitalization of the southern area through the creation of a comfortable access from the changing rooms.

b) - Annexation of the beach to the north of the enclosure and revitalizing it, creating comfortable connections and setting the (already planned) restaurant at the north end.

Considering the advantage of operating the restaurant throughout the year, an access close to the car park was studied, without prejudice to easy control, during the bathing season (at the north and south ends of the premises), provipport the pool enclosure or independently of it.

The proposed solution is that, during the bathing season, the access to the restaurant is conditioned to the payment of the

entrance fee to the premises, recoverable or not in the payment of consumption, according to the movement verified.

The restaurant building is set in a northeast/southwest direction, forming a 45º angle with the supporting wall of the avenue in order to shelter the wide area of the enclosure from the prevailing winds.

This location accentuates the boundary of the enclosure, already defined by the rock mass on which the building is set.

The lowering of the current support wall, and the construction of an almost parallel second wall to form a connecting platform to the changing rooms, allows the restaurant to be embedded in the avenue at the top level, framing the set of pool facilities, and solving the connection with the masonry wall ding for the possibility of functioning either exclusively to su- that limits the beach area to the east, from the port's north pier to Boa Nova.

Porto, September 15, 1965

Álvaro Siza Vieira







A.29

A.28 Restaurant site plan, 1965.

A.29 Restaurant 1st and 2nd floor plans, 1965.

Leça da Palmeira Ocean Swimming Pool - 3rd phase Design report, 1966

Enlargement of the enclosure, including storage rooms, toilets, bar, terrace, platform and retaining walls to the north and south – project.

The attached project concerns the elements for building the first phase of the work that is necessary for the site enlargement of the Leça da Palmeira Swimming Pool.

This first phase does not include the construction of the restaurant planned for the northern end of the premises.

In these complementary works, the principles initially adopted regarding the integration of the building into the landscape are maintained; integral conservation of the conditions of the site, where possible; and superimposition of built areas, where necessary.

The construction of retaining walls, to the north and south of the changing rooms, constitutes the necessary finishing to the buildings and, while simultaneously solving the access circuits and connection between areas, completes the embedding of the buildings in the retaining wall of the avenue and the meeting of two materials applied on large surfaces: granite masonry and bare concrete.

The criteria adopted so far concerning materials (bare concrete, riga wood and copper) and type of finish are still maintained. Having demonstrated the correctness of the bar setting, built on a provisional basis, its definitive construction is now planned, with an added area of influence conveniently paved (screed) and protected from the prevailing winds.

This contract includes sanitary facilities for shoed users and enough storage for the premises (to the north and to the south).

In addition to the definitive integration into the landscape, access solution and its control, the enclosure conditions and possibilities of use will be particularly benefited – decentralization, differentiation of areas and adaptation to local climate conditions.

Porto, February 21, 1966

Álvaro Siza Vieira Bernardo Ferrão



A.30



A.31



A.30 Plan and elevation, 1966.

A.31 Retaining walls and reinforced concrete details, 1966.

A.32 Bar plan, elevation, sections and details, 1966.

A.33 North bathrooms plan, elevation, sections and details, 1966.



A.33

Leca da Palmeira Ocean Swimming Pool - Intercalary draft of the 3rd and 4th phases Design report, 1973

1 – The attached preliminary draft, prepared in accordance with the instructions of the Matosinhos Municipality, defines the points of view presented have in the meantime been tathe works to be carried out for the conclusion of the 3rd phaken into account: se, in order to satisfy the opinions formulated in the meana) The edge of the tank profile was altered, in order to present time, and also to introduce improvements advised by the a 2% slant to the outside (drawing 5). experience of the enclosure operation.

2 - Works resulting from the opinions formulated

a) Connection of sewers to the general network

A diagram (drawing 4) of the referred connection is presented, which is made from a septic tank, since the municipal pipeline is mixed.

b) Separation of shoed and barefoot areas

A foot wash will be built which, together with the existing one on the south side, ensures the separation of the two enclosures (drawing 1).

c) Expansion of sanitary facilities

The number of 500 people was fixed as the maximum attendance of the enclosure. For the expansion of barefoot users' toilets, the numbers referred to in the "General Instructions" on Swimming Pool Constructions", prepared by the Sanitary Engineer of the General Directorate of Health, were considered, assuming that there are 500 visitors, 50% of each gender.

With regard to shoed users, the same "Instructions" were respected, assuming the hypothesis of a maximum frequency of 20% of total entries, and equally 50% of each gender. The shoed users' restrooms will be built in a more sheltered location, adapting the existing ones for staff use (changing rooms and restrooms for men and women).

d) Protection on the sea side of the pool.

A drawing (sheet 5) of the removable railing to be placed on the pool sidewalks is attached. This railing prevents access to the rocks, on the west side, making it inevitable to go through the foot wash, slightly extended on the north and south ends. A removable railing was chosen considering the violence of the sea to which the pool is subject, which would make a permanent solution extremely expensive.

e) Bar

Drawing 6 defines the constitution of the bar and the servi-The site will be equipped with artificial lighting, with particular ce area corresponding to the preparation area and pantry, as attention to the entrance, bar and annexes, since only in this well as refrigeration and other equipment. The staff facilities area is night-time operation foreseen. and storage area and container deposit, shown at 1/50 scale on page 2, are located under the retaining wall and to the east g) Sound installation of the bar. The much needed audio speaker device will be installed.

3 - It is clarified that, with regard to other objections made,

b) The shallowest area of the tank currently has a depth of 0.90 m, with 3.80 m being the minimum height of the jumps area. The edge for the footrest, with a 0.15m protrusion, consists of a reinforced concrete console at a depth of 1.30m and covers the entire length of the pool walls beyond that depth. The plan and 1/250 scale sections of the swimming pool is attached (sheet 5).

c) The situation of the access stairs to the swimming pool, and the respective details are also presented on sheet 5.

4 - Works for the completion of the 3rd phase and improvements to the construction already carried out.

a) Completion of the north platform. This platform, accessible only to shoed users, will be extended to the place where the restaurant is planned to be built, which will constitute the definitive limit to the north (4th phase). At the northern end of the platform there is a ramp connecting to the avenue level.

b) Raising the flowerbeds to the level of the avenue, in the extension surrounding the site, in order to avoid trespassing and to facilitate entrance control. This control will be established at two points, respectively at the north and south ends of the access platform that is now intended to be completed.

c) Construction of a storage room at the northern end of the access platform, taking advantage of the height difference between this construction and the raised flower beds.

d) Completion of the south side ramp along the avenue retaining wall. This ramp, which will be covered with vegetation, will complete the alignment of the reinforced concrete wall, where it meets the plastered supporting wall, and will end against the rocks indicated in drawing 1.

e) Access to the north beach adjacent to the swimming pool area. An access ramp to the beach will be built to the north, interrupted by a foot wash that limits the bar's terrace.

f) Site illumination

h) Improvements to the existing changing rooms

A slight modification is foreseen in order to improve the natural lighting of the changing rooms (top lighting) and the remodelling of the chlorine cabin in order to clear division 3.

treatment.

5 - Construction

The construction processes and materials used are similar to those adopted in the previous phases, given the strict conditions imposed by the location of the pool. That is, bare con- The terrace equipment (tables and chairs) will be made of crete is used in partition walls and slabs, Baltic pine wood is used in frames, and concrete slabs are used for interior floors. According to the opinions formulated, the partitions between sanitary facilities of different genders will not be interrupted at Porto, April 2, 1973 the top, as was done in the past to facilitate ventilation and the passage of pipes, but entirely closed. The interior spaces to be built, whose location within reach of the sea during spring Álvaro Siza Vieira

All wooden frames will be scraped and receive appropriate tides does not allow, without the damage already verified, to provide for openings, unless the ones strictly indispensable and equipped with iron doors, will be mechanically ventilated. All the equipment in the bar, preparation area and pantry will be in stainless steel and removable, so that during the winter it can be moved to the protected storage room. The plumbing will be in copper piping.

Baltic pine wood.



A.34

- A.34 Plan and elevation, 1973.
- A.35 Site cross sections, 1973.
- A.36 South platform ending plan and elevation,
- 1973.
- A.37 Bar plan and equipment layout, 1973.
- A.38 Adults swimming pool access ladder, 1973.
- A.39 Terrace furniture, 1973.
- A.40 Restaurant cross and longitudinal sec-
- tions, 1995.





A.36



A.37



A.38



A.39

Ocean Swimming Pool Restaurant - Leca da Palmeira Restaurant design report, 1995

second rocky outcrop, distancing itself from the avenue wall The Restaurant project is part of the overall study for the Ocean Swimming Pool, started in 1961. at an angle of 45°. As in the changing rooms, already built, the roof height exceeds very slightly that of the avenue. The The site includes two pools, partially limited by the rocky outresulting construction height allows for the use of two floors.

crops that characterize this area of the Atlantic coast.

The lower floor communicates with a terrace, accessible from The changing rooms, accessed by a ramp, stand parallel to the beach, and is occupied by storage rooms and the panthe retaining wall of the seaside avenue, at beach level, so as try, which connects to the kitchen by a freight elevator. The not to become a visual obstacle. restaurant and services of public access are located on the The solarium is divided by the existing rocky formations, whiupper floor.

ch define communicating spaces of varying dimensions, sui-The materials used are, as in the first phase, almost exclusitable for different forms of occupation. These natural platforvely exposed concrete (floors, walls, and ceilings) and wood. ms, supported by small interventions (stairs, ramps, sections of wall) adjust to the slope of the terrain, establishing a natural The roof, also in exposed concrete, is protected by a permarelationship with the beaches to the north and south of the nent reflecting pool. rock outcrop.

A wall, set at a 45^o angle to the seafront, limits the site and a terrace served by a small bar to the north.

This first phase of construction was completed in 1966. The restaurant, whose project has now been prepared, is set on a



The volume of the restaurant shelters the beach to the north of the central enclosure from the prevailing wind.

December of 1995

Álvaro Siza

APPENDIX B

Interviews with the Heads of Municipal Council Departments

Head of the Culture Department

NAME	POSITION	DESCRIPTION
Clarisse Castro	Head of the Culture Department	Serves in this position since 2019. Has been working for the Municipal Council since 2001 in the area of culture
Isabel Flores	Coordinator of the Architectural and Historic Heritage Commission	Serves in this position since 2015. Has been working for the Municipal Council since 1985 in the area of urban planning
João Quintão	Head of the Planning Department	Serves in this position since 2019. Has been working for the Municipal Council since 1999 in the area of urban planning
Pedro Rocha	Head of the Environment Department	Serves in this position since 2019. Has been working for the Municipal Council since 1991
Susana Gonçalves	Head of the Civil Protection Department	Serves in this position since 2020. Has been working for the Municipal Council since 2006 in the area of civil protection (was lifeguard at the Ocean Swimming Pool)
Pedro Machado	Head of the Municipal Buildings Division	Serves in this position since 2016. Has been working for the Municipal Council since 2005 in the area of supervision



Name: Clarisse Castro Address: Vila Nova de Gaia Position: Head of the Culture Department

What do you LIKE most about the Ocean Swimming Pool?

"I like the insertion into the landscape, the surprise that awaits us behind every wall and the materials. It is wonderful."

What would you like to CHANGE in the **Ocean Swimming Pool?**

"I would like people did not see the pool as a mere sports facility but as the national monument it is."

How do you IMAGINE the Ocean Swimming Pool in the future?

"I imagine it shall remain a referential building in the context of world architecture, cherished and protected by all those who live in Matosinhos."

What does your job and work routine consist of?

The management of the cultural services under the responsability of the Municipal Council such as the archive, libraries, museums, galleries, theatre, entertainment and educational activities. All this dynamic and the relationship between services, combined with all the other activities of the Municipal Council, determines a very demanding routine.

What are the main difficulties you encounter in your job?

Having to work on multiple fronts and to deal with the general lack of awareness regarding heritage conservation. Achieve the sometines conflictual and difficult balance between preservation and the significant pressure coming from new developments.

What are the main problems you identify in the (cultural/ patrimonial) management of the Ocean Swimming Pool?

The Department of Culture and the Architectural and Historic Heritage Commission were not consulted during the conservation works. In this case in particular no negative consequences arose from this fact as the process was led by the architect responsible for the original design but it would be more enriching for all if there had been an exchange of knowledge between all the actors, such as a non-binding opinion or information issued by the Architectural and Historic Heritage Commission.

Education: Degree in History / Post-graduation in Museology

Serves in this position since 2019. Has been working for the Municipal Council since 2001 in the area of culture

Does it seem to you that there is a good understanding of the work and its value by the population?

Yes, I do. The building opened for visits after the conservation works but I think that there is no such thing as too much promotion as it adds value to our collective heritage.

Could the cultural dynamism of/at the Ocean Swimming Pool be further enhanced?

The building already hosted different events off bathing season such as concerts by the Matosinhos Jazz Orchestra, film screening, fashion shows and book launches. Nevertheless, being nearby a residential area, the population is not very receptive to night events. On the other hand, the climate constraints and maritime exposure do not allow for advanced scheduling, as weather conditions are very uncertain in this location.

Would it make sense to have a reception for visitors all year round?

There is a tourism office nearby and the possibility of it ensuring visits to the building has been considered. This something that has to do with management, as the Ocean Swimming Pool is managed by Matosinhos Sport (a municipally owned corporation).

Is there any plan of visits or cultural and school promotion in the scope of the Municipal Council regarding the Ocean Swimming Pool or Álvaro Siza's architecture?

In educational services we work essentially with municipal cultural facilities which do not include the Ocean Swimming Pool, managed together with other sports facilities. In the context of workshops and vacation camps we organize contemporary architecture visits that include the Ocean Swimming Pool.

Does the fact that the Ocean Swimming Pool is a pilgrimage destination for architects from all over the world have any reflection on local cultural policies?

The impact and recognition are always positive. There are tourism offices in Matosinhos and Leça and we are aware that the most popular points of interest, besides the Way of St James, are the works of Siza. This shows us that the building is a point of pilgrimage for many people and we have reports of people getting emotional when they manage to visit the Ocean Swimming Pool.

World Heritage listing (and what impact would it have on the territory)?

I think it would very beneficial, raising international awareness about Matosinhos and promoting our heritage.

How do you see the integration of the work in a UNESCO What suggestions and recommendations would you make in the context of the Ocean Swimming Pool Conservation Management Plan?

Conservation actions should be more regular and assertive so that the building does not reach the state of decay it was in before the works. The management plan has to take into account that it is a National Monument and raise awareness among the public and its users that it is not a swimming pool like any other.

Coordinator of the Architectural and Historic Heritage Commission



Name: Isabel Flores

Address: Porto Education: Architect

Position: Advisor on Heritage and Urban Regeneration (Office of the President); Coordinator of the Architectural and Historic Heritage Commission

Serves in this position since 2015. Has been working for the Municipal Council since 1985 in the area of urban planning

What do you LIKE most about the **Ocean Swimming Pool?**

"What I like most, is basically everything. I have never been a user of the pool. I first visited it during these conservation works and I really felt my heart full of joy. When Álvaro Siza designed this pool he made sure that you could see the sea, the Port of Leixões, the Titan, and that from Leça you could not see the pool. So, many people who pass by the Leça waterfront don't realise there is a work of art there."

What would you like to CHANGE in the **Ocean Swimming Pool?**

"Nothing."

How do you IMAGINE the Ocean Swimming Pool in the future?

"The same."

What does your job and work routine consist of?

It is a privilege to work with great contemporary architects. In Matosinhos we have a great architectural tradition since the presidency of Fernando Pinto de Oliveira. There are great works of architecture and great architects working in the area. I think there is a lack of a modern/contemporary architecture guide in Matosinhos.

What are the main problems you identify in the (cultural/heritage) management of the Ocean Swimming Pool?

The Municipal Council has many competencies and in the area of heritage we are actually ahead in terms of architecture and urbanism, but it has not had much support from the State.

Are there any other type of instruments for safeguarding and managing the Ocean Swimming Pool (Inventory, Municipal Master Plan, Heritage Safeguarding Map)?

Heritage listing is mostly limited to structures built until 1974 (including palaces, rural heritage, ensembles, etc.) and it is necessary to list what has been built since then to prevent the its destruction. The Architectural and Historic Heritage Commission, however, has a severe shortage of human resources to pursue this objective, having only 3 architects and one archaeologist. It is a small team. On the other hand, there has been significant investments in urban rehabilitation, as is the case of Casa da Arquitectura.

Does the regulation for the intervention in real estate of municipal interest apply to the Ocean Swimming Pool?

Our regulation applies to the Ocean Swimming Pool and other monuments that are on our Heritage Safeguarding Map. Our Municipal Master Plan has a Heritage Safeguarding Map and a Restrictions Map. The Special Protection Zone of the Ocean Swimming Pool and the Boa Nova Tea House is an administrative easement and the rules are clearly defined (Article 43 of 107/2001 - National Law of Cultural Heritage). There are some inconsistencies between national and municipal level regulations that require adaptations. There are still no mechanisms for the protection of views. The Ocean Swimming Pool is a

work of great landscape integration. However, today this idea has been compromised by urban development and the construction of residential buildings.

Head of the Planning Department



Name: João Ouintão

Address: Matosinhos

Education: Architect

Position: Head of the Planning Department

What do you LIKE most about the **Ocean Swimming Pool?**

What does your job and work routine consist of?

Beach bars. The problem is that despite they pollute the coast, their activity makes a lot of money. It is one of the central the-"The way it is present and absent at the same time. The mes of the coastal zone revision, as they are given more imway it merges into the landscape. It is a chameleon and portance than land use planning. Beach bars and restaurants simultaneously has affirmative gestures, establishing are now licensed by the port authority. The Municipal Council harmony between the artificial and natural. I think it is issues a non-binding opinion, so it cannot have an effective one of Siza's manifesto works without being neutral." control of the issue. The POC (Coastal Zone Program) establishes that the Portuguese Environmental Agency has juris-What would you like to CHANGE in the diction along the rest of the coastline that extends to several **Ocean Swimming Pool?** municipalities. This agency intends to relocate buildings further inland and that raises a lot of questions. This was the Mu-"No, nothing." nicipal Council's responsibility but it has neither the resources nor the land available for this to take place. Any issue invol-How do you IMAGINE the Ocean Swimming Pool ving the loss of heritage should always include hypotheses in the future? on what to do. Restore? Keep photographic records or create virtual reality models to have tactile experiences and leave "Like it is, but covered with water, because the prosthe work under water? We should put solutions into perspecpects are not very good." tive according to the level of technology available in the future and question whether we want them to disappear or not. If in fact the sea level rises, many things will disappear and there is no plan that will succeed. There are many issues to be Coordination of the Municipal Master Plan, its elaboration, reverified here, starting with the predictions that are not even visions and implementation. Integrated and interdisciplinary consensual. These are things that go beyond any plan, incluwork of articulation with the various departments. Definition ding the Municipal Master Plan. The Ocean Swimming Pool is of planning strategies and spatial planning in the Municipality a work of great landscape integration. However, this idea was of Matosinhos. compromised by urban development and the construction of residential buildings on the other side of the avenue.

What suggestions and recommendations would you make in the context of the Ocean Swimming Pool Conservation Management Plan?

I think there should be a year-round visit programme to the pool. The existence of other works by Álvaro Siza and multiple other significant contemporary architecture works in Matosinhos should allow for the creation of a route to visit modern and contemporary architecture. Matosinhos is a fertile territory for architects and we are very proud of that.

Serves in this position since 2019. Has been working for the Municipal Council since 1999 in the area of urban planning

What are the main problems you identify in the (territorial and urban) management of the Ocean Swimming Pool?
the Ocean Swimming Pool?

The pool is set on a national ecological reserve and natural area. In front of it there are central areas of public domain where the Municipal Council will certainly not build. The Land Use Map defines the construction and impermeability indexes and areas, the spacing between constructions... In the Zoning Map we have actions that we foresee for the site. Particularly for your case, you will be interested in the Environmental Safeguard Map, but the old POOC (Coastal Zone Management Plan) is still being presented and must be replaced by the new POC (Coastal Zone Programme). It is through the Municipal Master Plan that these special inter-municipal plans will bind the private individual. The Coastal Zone and Forest Management plan will be the one of least interest to you as it was the old PROF (Regional Forest Management Plan). The Heritage Safeguarding Map is the one that indicates the pool and its protection areas. Finally, in the Restriction Map there are several issues such as REN (national ecological reserve), water lines...

Where can we find the main risks and constraints affecting Does the Municipal Master Plan have a strategy for the protection of views?

No. The dynamics of the economy are brutal and there has to be some flexibility. The Heritage Safeguarding Map is very confusing and somewhat contradictory because we have listed heritage in central areas where high constructions are allowed. Either we keep the city as it is, with the rules we have, which is a risk from the economic, demographic, social and cultural point of view, or we preserve individual buildings.

What suggestions and recommendations would you make in the context of the Ocean Swimming Pool Conservation Management Plan?

Study the Municipal Master Plan maps and the POC (Coastal Zone Program). Finding out what to do with the buildings that are going to be submerged is something to be studied; it is a subject that invites serious reflection.

Head of the Environment Department

Name: Pedro Rocha

Address: Matosinhos

Education: Environmental Engineering

Position: Head of the Environment Department

Serves in this position since 2019. Has been working for the Municipal Council since 1991

What do you LIKE most about the **Ocean Swimming Pool?**

"Landscape integration."

What would you like to CHANGE in the **Ocean Swimming Pool?**

"No, nothing."

How do you IMAGINE the Ocean Swimming Pool in the future?

"I am concerned because of the inherent risk of climate change and the scarce knowledge that we have about it. The Ocean Swimming Pool is in an area susceptible to high risk. I would like to see it as it is for 30 or 40 years, but that is not likely to be the case."

What does your job and work routine consist of?

I coordinate two areas: one more operational, which is the management of contracts, interventions, water, beaches and cemeteries; the other has to do with environmental monitoring and education, interventions in schools, monitoring various indicators such as noise, air quality, and other elements.

What are the main difficulties you encounter in your job?

Unfortunately, the Environment is not yet seen as an integrative tool with a priority overview. There is frequently no time for the important issues, only for the urgent ones.

What are the main problems and risks you identify in the (environmental) management of the Ocean Swimming Pool?

Climate change, floods, rainwater, groundwater, surface water and their effects on the coastline. Matosinhos has a coastline of about 8 km and, therefore, its repercussions will go beyond the maritime component. It is necessary to invest in infrastructures and network knowledge as we do not have precise notions on the future behaviour and impacts of these elements. A project is being developed to address these issues and to sustain the Municipal Council's management and investment policies regarding infrastructure and monitoring.

These are elements on which we have to set a track record in cleanliness, sand management and concessions. The Matosinhos Municipal Council is in a transition phase because the order to have a sustained evaluation. At the Ocean Swimming Pool site, which is a high-risk site, the biggest problem is that management was previously from APA (Portuguese Environwe do not have accurate information about what the actual mental Agency) and in the case of Leça (from the lighthousea level rise will be. The risk is real, but at the moment we se to the southern limit of the municipality) from APDL (Port do not have that capacity. We are still in the very early stages Administration of Douro and Leixões), so all this brings a set of trying to materialise and begin to experiment, and then reof needs and adjustments to contracts that were managed flect it in the model. by both entities, things that were framed in the old POOC and that are framed in the new POC.

What advice can you give us regarding a mitigation strategy for climate change? Can we find some information in the Coastal Zone Program?

I see the POC (Coastal Zone Program) more as a coastal management instrument in terms of delimitation of uses than as We can give notes on solid waste, beach cleaning, urban cleaa support in that perspective. The Environment Department ning but the most important thing would be to have a frameassumed the jurisdiction of beach management (something work or policy on climate change. The area of monitoring also that was previoulsy in the sphere of the Portuguese Environhas partnerships on issues that may be relevant. mental Agency) that has to do with the maintenance of the

Head of the Civil Protection Department



Name: Susana Gonçalves

Address: Matosinhos

Education: Environmental Health

Position: Head of the Civil Protection Department

Serves in this position since 2020. Has been working for the Municipal Council since 2006 in the area of civil protection (was lifeguard at the Ocean Swimming Pool)

What do you LIKE most about the **Ocean Swimming Pool?**

"The Ocean Swimming Pool has a special charm for me because it was where i had my first job. I was a lifeguard. It's a space that is engraved in my memory."

What would you like to CHANGE in the **Ocean Swimming Pool?**

"No and it has been able to modernise its services while keeping its identity."

How do you IMAGINE the Ocean Swimming Pool in the future?

"The Ocean Swimming Pool will always be one of the landmarks of Matosinhos."

What suggestions and recommendations would you make in the context of the Ocean Swimming Pool Conservation Management Plan?

What does your job and work routine consist of?

Management of the Civil Protection Department which consists of several areas: planning, risk analysis, risk management (mitigation and risk identification strategies), emergency service working 24 hours a day, emergency communications centre, articulated management with the Matosinhos fire brigade, technical forestry office, outreach to the population and rescue.

What are the main difficulties you encounter in your job?

Work that presents daily challenges. Try to find the best strategies to solve the problems that come along.

What are the main problems and risks you identify in the Ocean Swimming Pool?

The Ocean Swimming Pool is in a place of great exposure where we can identify different types of risks: on the one hand, risks of natural origin: maritime exposure, extreme weather phenomena (coastal overflow, storm surges); on the other hand, technological risks: proximity of the port of Leixões (navigation routes, maritime accidents), the oil terminal (hazardous materials) and othe oil refinery (there is a pipeline under the coastal avenue that connects the refinery with the oil terminal). The impact of risk factors on the coastline is do-

Head of the Municipal Buildings Division

cumented and recorded, fulfilling a preventative function in support of risk prevention through a historical, photographic survey and geo-referencing process (ArcGIS) for damage assessment and reporting.

The Metropolitan Plan of Adaptation to Climate Change is a work coordinated by the Department of Environment and Environmental Monitoring. The Department of Civil Protection contributes by providing information and reporting.

How are those risks mitigated?

Technological risks have an impact analysis and evaluation. We work with companies that are active in the municipality in order to work together in the area of prevention and thus assess and establish mitigating regulations. We work with fire brigades and in awareness programmes for children to raise their consciousness of the risk. The awareness work in schools includes educational movies (safe beaches, dangerous materials, fire safety), a project that has been implemented for 7 vears. Drills for children are in place through the pilot project "The house of the little Alert boy" where the main character must confront situations of risk to then create strategies to mitigate them. On the other hand, one of the most frequent phenomena on the coast is the accumulation of sand. We carrv out a survey of the phenomenon that allows us to evaluate with the Environment Department to avoid coastal landslides.

How is the security control made?

The engineer Miguel Sousa is a specialist in fire safety, we have already visited the pool after the conservation works, in order to prepare whatever is necessary to implement in the building.

Engineer Miguel Sousa: Our job is to perform a safety and legal compliance diagnosis. We make a first visit and observe the potential vulnerabilities and from that document we outline an action plan of the measures that are missing. Then, in a second phase, we start to implement self-protection measures, which is part of a more wide-ranging strategy in which we

develop a simulation plan so that people get to know the plan, prepare the teams and implement self-protection measures.

In swimming pools, the biggest problem is emergency lighting, evacuation routes and signage.

We have the example of working at the Boa Nova Tea House. When it underwent its last conservation intervention we worked very directly with the architectural team and managed to find solutions and strategies to be comply with the requlations. Although there were occasional difficulties in combining the two languages of security and the artistic dimension of architecture, we managed to overcome these difficulties by working together and achieving a joint result.

What are the adopted measures in an emergency situation?

The intervention is divided into two phases: internal interventions are seen case by case, with specific interventions for each building and the external interventions depend on the type of accident that we are talking about (in case of fire there is a specific type of approach, etc...).

What suggestions and recommendations would you make in the context of the Ocean Swimming Pool Conservation Management Plan?

Integrate the aspects of risk, especially those associated with climate change. We find it difficult to control them. A building with this kind of value is installed in a municipality with high technological risks that should not be ignored in the plan. Do the maintenance of the security equipment, detection centre, inspect the equipment when implemented, train the security teams to detect anomalies and instruct them to make the necessary interventions. Make a record of anomalous situations and report them to be integrated into the protection plan, georeferencing for later integration, and make a record of interventions made by lifeguards in the pool.



Name: Pedro Machado

Address: Matosinhos

Management.

Position: Head of municipal buildings division.

Serves in this position since 2016. Has been working for the Municipal Council since 2005 in the area of supervision

What do you LIKE most about the **Ocean Swimming Pool?**

"The fluidity that the building has with the sea. The connection that makes the pool perfectly integrated into the landscape."

What would you like to CHANGE in the **Ocean Swimming Pool?**

"From a technical perspective, the water collection system. From a user perspective, the construction of the restaurant would be an asset."

How do you IMAGINE the Ocean Swimming Pool in the future?

"The same."

What does your job and work routine consist of?

The Department is divided into three divisions: mine deals with buildings, then the others deal with public roads and equipment. We have several operational work teams and the technical staff who follow up on contracts and other maintenance actions such as external maintenance contracts. My function is to coordinate the management and maintenance of buildings in order to work with preventive maintenance logistics. Previously this information was all on paper, dispersed, and now we are building a data-base alongside the field response.

What are the main difficulties you encounter in your job?

In the operational part the biggest difficulty is to have qualified labour. At this moment we have almost no gualified employees and we have difficulty in attracting workers for a salary that is equivalent to the minimum wage. We are trying to find ways to attract people at the end of their career and even the beginning of their career. On the technical side it is difficult to find the necessary information to move forward (registration phase). On the other hand, we also have difficulty in generating information that allows us to draft a maintenance contract that solves these problems that we have day by day, because the legislation is very restrictive and we have to specify much more

Education: Civil Engineering, Master in Construction Project

of what has to be done. It is difficult to draft contracts that can solve the problems of repair maintenance without basic information, in addition to the legislation restrictions.

How is building maintenance carried out in Matosinhos Municipal Council?

We have a set of preventive maintenance contracts defined by law (fire extinguishers, HVAC), repair maintenance contracts, hardware and glass repair maintenance and then we have internal teams that solve the problems that do not fit into these contracts. The communications of these preventive needs are loaded into Infraespeak and there is a routine that schedules these preventive and repair needs.

What about the Ocean Swimming Pool in particular, how is the management and maintenance of this building carried out?

The Ocean Swimming Pool has always been a shared building between the Matosinhos Municipal Council and Matosinhos Sport, they do the operation during the bathing season and then the Municipal Council has the responsibility for the rest of the year. Normally we would do an intensive repair at the beginning of the year as in the winter it is difficult because of the rough seas. There is a team of specialised operators who do preventive maintenance of equipment (pump operation) to monitor and guarantee continuity of service (weekly work). They fill the pool and deliver the equipment in operating condition to Matosinhos Sport. In terms of routine, the following works are performed from January to May: the cleaning of the tank, revision of painting, painting wooden structure, repairs, revision of hydraulic installations.

What are the main problems you identify in the management and maintenance of this building?

It is unpredictable, during the visit in January we never know how the building like and the necessary works. It is very exposed to vandalism, since there are no boundaries, and also to the action of high tides. We never wanted to change the building, we don't want to take decisions like integrating video surveillance systems because they change the original design. For example, when the building was taken over by SUMA (a company in the environmental field of action) they altered the wood by applying burnt oil. The water collection system was not changed. There was a remodelling intervention in 1990 but it was not completed so it works in a rather critical way. It affects the functioning because when the bathing season starts it takes 3 to 4 days to fill the main tank, so there ends up being

some difficulty in controlling that part of the process. Today it is already possible to provide an alternative solution that does not interfere with the architecture and that allows the filling in to occur in a more controlled way. Regarding anomalies: tank cleaning, submerged pipes, vandalism (theft of fixtures), in recent years the hydraulic system has had several valve issues, 3 filters last season were no longer working. Funding difficulty: we have to make a study to see which costs we should allocate to the maintenance of buildings. We don't have the necessary funding. No one has an idea of the cost that this maintenance implies. The goal is to have a notion of the operating cost of the building, which is important to understand the constructive solutions that will best satisfy the client.

Is there a maintenance plan for the Ocean Swimming Pool?

There is a plan, but not yet a physical plan, there is a periodicity of tasks that, based on previous experience, are being implemented.

If it is done, what are the perspectives, methodologies and tools for its elaboration and implementation?

Our goal is to make a database with digital information, work the information in order to standardize and load it in the Infraspeak platform (Management and Maintenance software) with all the buildings typified according to the COBIE standard (typifies all the typologies of use that is poured in the BIM system,) survey point cloud plan.

What suggestions and recommendations would you make in the context of the Ocean Swimming Pool Conservation Management Plan?

Be aware of the costs. The cost of no maintenance is 3 to 5 times higher than the cost of preventive maintenance.

APPENDIX C

Interviews with the Site Managers and Staff

POSITION

Head of Division (Matosinhos Sport)

a

Name: João Regufe Birth date: 1981 Address: Matosinhos Education: Physical Education Teacher Position: Head of Division

Serves in this position since 2016, being responsible for the management of the 9 swimming pools of Matosinhos. Has been working for Matosinhos Sport since 2004.

What do you LIKE most about the **Ocean Swimming Pool?**

"I like the architecture of the space."

What would you like to CHANGE in the **Ocean Swimming Pool?**

"Although I understand that the original design should be respected, I think some changes could be made. For example, the situation of people with mobility impairments. The access signage could also be improved, as this is an important monument, very sought after by national and international visitors that may find it hard to find the building."

How do you IMAGINE the Ocean Swimming Pool in the future?

"Seen as a monument. A monument that is simultaneously a swimming pool, used by locals and marketed internationally, with a differentiated price for people that comes from abroad. This building allows us to make Matosinhos known to the world."

What does your job and work routine consist of?

Technically coordinate everything related to municipal swim-Improve signage on the access roads to the property and imming pools (that are nine, seven of which are indoor and two prove the conditions for users with mobility impairments to outdoor), from teachers to security, water treatment, cleafully enjoy the building. ning, reception, maintenance and operators. Besides that, I attend Matosinhos Sport administration meetings. Matosinhos Sport has 165 employees besides service providers.

What are the main difficulties you encounter in your job?

The main problems are in dealing with and managing people as they are all different, with different functions. Managing the budget. We always want to do more but we have to achieve our goals with the few financial resources we have. Also the logistics of the space such as restocking as there are several procedures that must be followed.

João Regufe	Head of Division	Serves in this position since 2016, being responsible for the management of the 9 swimming pools of Matosinhos. Has been working for Matosinhos Sport since 2004
João Galvão	Technical Coordinator of municipal swimming pools	Serves in this position since 2010. Has been working in the Ocean Swimming Pool since 2015
Catarina Teixeira	Technical Director	Serves in this position since 2018. Has been working for Mato- sinhos Sport since 2006
Eduardo Silva	Bar concessionaire	Has been the concessionaire of the bar since 2012
Nuno Silva	Maintenance foreman	Serves in this position since 2008. Had previously worked at the Ocean Swimming Pool as a pool operator
Paula Santos	Receptionist	Serves in this position since 2016. Has been working for Matosinhos Sport since 2007
Tiago Macedo	Lifeguard	Serves in this position since 2021. Has worked at the marina for seven years and works as a lifeguard for ISN since 2017
Manuel Jesus	Security guard	Serves in this position since 2019. Had already worked at the Ocean Swimming Pool before and has been a security guard since 1993
Maria da Conceição	Cleaning assistant	Serves in this position since 2021

DESCRIPTION

NAME

What are the main problems you identify in this building?

Most of the problems have to do with maintenance. It is a building in contact with the sea and we have to pay close attention to it. There are always problems with the equipment (a sink that breaks or a dispenser) which is normal because the facility has a very intensive use during summer months (more than 50,000 people).

What would you propose as prohibitions, alerts and recommendations for users?

There are two types of users in swimming pools, the bathers and the architects. The architects come and want to know about the behaviour of the concrete, the resistance of the materials, take measurements of the building... All users are different and it is up to us to understand what the user expects from the space and provide the best experience. On the other hand, we have groups of people who come for birthdays, bachelor parties, and it is normal that we have difficulties enforcing rules with these groups.

What behaviours are adopted in emergency situations?

The emergency must be reported to the technical director who contacts the head of division. In the meantime, if there is a high degree of emergency it is necessary to contact directly the emergency services.

What recommendations would you make/suggest? to improve the use of the Ocean Swimming Pool's spaces?

Technical Coordinator of Municipal Swimming Pools (Matosinhos Sport)



Name: João Galvão Birth date: 1981 Address: Matosinhos Education: Sports Management/Political Sciences Position: Technical Coordinator of municipal swimming pools Serves in this position since 2010. Has been working in the Ocean Swimming Pool since 2015.

What do you LIKE most about the **Ocean Swimming Pool?**

"Working in sports related with a monument that is integrated into nature. The fact that we work with a variety of publics, there is a lot of cultural richness."

What would you like to CHANGE in the **Ocean Swimming Pool?**

"Not in the building itself, I think it's very important to maintain it. It would be important to complement the security aspect that was not contemplated in the original design."

How do you IMAGINE the Ocean Swimming Pool in the future?

"I honestly hope that with more users and if possible to return to the capacity we had before the covid-19 pandemic."

What does your job and work routine consist of?

Coordinating the company's human resources, articulating the pool's operation with the technical aspects of maintenance, defining the regulations, creating the price list, coordinating group visits, articulating and managing reservations. Occasionally I also perform the functions of technical coordinator and identify the needs of the site.

What are the main difficulties you encounter in your job?

The articulation between stakeholders: we have two security teams, we have the concessionaire, our team from Matosinhos Sport and the Matosinhos Municipal Council.

The relationship with the public when there are longer waiting times to enter the premises or the capacity is sold out. This creates a lot of anxiety at the entrance and we have to know how to manage that.

What are the main problems you identify in this building?

Plumbing problems in the toilets, clogging, damaged washbasins, providing restocking when there is heavy use. On

the other hand, to reduce the risk of vandalism, security has been reinforced. When these problems are detected by the employees, they are reported to the technical directors that are in charge of presenting solutions to the identified issues.

What recommendations would you make to improve the use of the Ocean Swimming Pool's spaces?

A clear transmission the site's regulation. We have the mandatory signs, like the dangerous area signs, but we also have to look very closely at where to put them so as not to much visual noise.

Technical Director of Municipal Swimming Pools (Matosinhos Sport)



Name: Catarina Teixeira Birth date: 1982 Address: Matosinhos Education: Degree in Physical Education Position: Technical Director

Matosinhos Sport since 2006.

What do you LIKE most about the **Ocean Swimming Pool?**

"The space itself. It's a different pool, it has salt water."

What would you like to CHANGE in the **Ocean Swimming Pool?**

" I wish the changing rooms had more light, but I understand what the architect's intention was."

How do you IMAGINE the Ocean Swimming Pool in the future?

"I think it will remain as it is."

What does your job and work routine consist of?

The technical directors of the municipal swimming pools in I would recommend to check the equipment. From year to Matosinhos work as technical directors at the Ocean Swimyear we try to improve the measures. ming Pool and at Quinta da Conceição during summer months. There are eight in total and there are two per day in each one, one during the morning and another during the afternoon. Our job is to coordinate all the staff: receptionist, security guards, lifeguards and cleaning staff. We also have two security guards from the Municipal Council who help to control the beach limits to prevent trespssing. We have the task of checking and communicating all anomalies to be repaired. We are responsible for communicating any complaints or relevant information.

What are the main difficulties you encounter in your job?

The most difficult thing today is dealing with people at the reception on days with very good the weather conditions. There is a lot of affluence and the maximum occupation is quickly reached. The public does not understand when the capacity is sold out. Inside the venue, the most difficult is managing the correct distance between people. It is also hard to establish communication with external companies working in the pool such as the security company, for example.

What are the main problems you identify in this building?

The most common are clogged toilets.

Serves in this position since 2018. Has been working for

What recommendations would you make to improve the use of the Ocean Swimming Pool's spaces?

One of the most important actions is cleaning the space. I would recommend to inform users to keep the spaces clean and dispose of rubbish where it is supposed to be. Use the space as if they were at home.

For users, what would you define as prohibitions, alerts and recommendations?

The prohibitions of use are already defined, the prohibitions relating to pandemics are also set out.

Is there a procedure to report problems detected in the building?

Any member of the team can report a problem to us (technical directors) and we report it to Matosinhos Sport as soon as possible to try to solve the problem immediately.

When it comes to the building maintenance, what actions would you recommend to be done on a daily, weekly, monthly, yearly routine, among others?

Maintenance foreman



Bar concessionaire

Name: Eduardo Silva Birth date: 1971 Address: Matosinhos Education: Degree in Civil Protection Engineering Position: Bar concessionaire Has been the concessionaire of the bar since 2012.

What do you LIKE most about the **Ocean Swimming Pool?**

"I live this pool intensely. I used it when I was a child and I am very grateful for the opportunity I have been given to work here. I feel like a caretaker of this space. Even when it was closed I have been here everyday. Because of all my childhood memories, the relationship I have with the sea and the space is above all of gratitude."

What would you like to CHANGE in the **Ocean Swimming Pool?**

"As I see things there is no reason for it to be open for just three months every year."

How do you IMAGINE the Ocean Swimming Pool in the future?

"I fight for it to be open off the bathing season."

What does your job and work routine consist of?

I manage the bar during the bathing season.

What are the main difficulties you encounter in your job?

In 2014 storm Hercules affected the entire north coast with flooding. The sea destroyed everything but there was no one to come here, it was one of the most dramatic moments of my life. I felt the space was being abandoned, only remembered during the summer period. I do not forget that this is in fact a pool with a bar and not a bar with a pool, but I have always seen the existence of a bar as an attractive point. There was a great lack of articulation. I already tried to tell the Municipal Council how many people come here during the winter without passing by the tourism office or the Casa da Arquitectura.

What are the main problems you identify in this building?

When talking about the conservation works, I asked the architect if he had already studied the possibility of equipping it with sunshades. I find it concerning that the pool is working in this type of conditions. It is not at all abiding hygiene and food safety standards. We are talking about functionality problems, food safety and space. The lighting is not up to stan-

dard. There are many visits that happen without appointment. I consider this as a monument and I think it has to be welcoming to tourists. The space has to be open for visits or at least have staff that can guide a visit. These are opportunities that are lost due to poor promotion of the space. One problem is the lack of security in winter. During bathing season there is a security company that is here for 24 hours. There are two more elements in the north and south, hired by the Municipal Council for the security of the space. Then it comes September and there is no one here.

For users, what would you define as prohibitions, alerts and recommendations?

It is a permeable space, a dangerous space. There is a concern for people's physical safety. Sometimes people pass by the beach and climb down the rocks.

What recommendations would you make to improve the use of the the Ocean Swimming Pool spaces?

In the past there was no preventive maintenance plan, only a corrective one. Maintenance work was always done thinking about the summer, but I think that the whole year has to be revised and the space has to be taken care of. If it functioned as a thermal space, with a warm water pool, the use of the space would be much broader. I hope that this abandonment does not happen in the future.



Name: Nuno Silva Birth date: 1981 Address: Matosinhos Education: Secondary school Position: Maintenance foreman

What do you LIKE most about the **Ocean Swimming Pool?**

"Working in a national heritage site is a source of pride. I like the context where it is inserted, a natural pool on a beach."

What would you like to CHANGE in the **Ocean Swimming Pool?**

"Nothing, you have to preserve heritage."

How do you IMAGINE the Ocean Swimming Pool in the future?

"I hope it continues to have the receptivity it has. I hope that I and all the people of Matosinhos will continue to enjoy the pool."

What does your job and work routine consist of?

Management of maintenance operations (water treatment. tank cleaning and disinfection, filter washing, tank vacuuming, stock reposition) and coordination of the team of operators consisting of two daily service attendants and one vacuum cleaner.

What are the main difficulties you encounter in your job?

Sometimes the weather conditions do not allow us to carry out our operations.

What are the main problems you identify in this building?

Mainly problems with pipes and clogging.

What behaviours are adopted when emergency situations arise?

In the event of an emergency we have two options: either own team is able to solve it or we resort to an external specialized company (Omninstal company that has a maintenance contract with Matosinhos Sport).

How is the maintenance of the building's machinery carried out?

First of all the filters are washed by means of a pressure filtering process that purifies the water, where impurities are retained on the surface. This process is done at least twice

Serves in this position since 2008. Had previously worked at the Ocean Swimming Pool as a pool operator.

> a day depending on the usage. The water is then disinfected, which is a constant process throughout the day, using a dosing pump with sodium hypochlorite (the quantity must be between 1 and 2 ppm). A coagulant is added for greater absorption of particles, improving the filtration process, and a product is administered to prevent the formation of algae. The tanks are sucked up by a pump every morning from 7 am for a period of between one and three hours. Through aspiration all impurities are removed from the water (sand, algae, pieces of wood, plastics, etc.). These processes are carried out in each separate tank with different treatments by the technical operators, all trained to carry out the maintenance operations. Besides the daily maintenance at the beginning and end of the bathing season, a general maintenance of the equipment is done by Matosinhos Municipal Council, which is in charge of the management of the swimming pools off the bathing season.

Is there a timetable for these actions?

The daily routine, which is the washing of filters, disinfection of water, vacuuming of tanks and the sanitary log (sanitary wash log, control and logistics of chlorine, pH level, temperatures, control of water, light and number of users).

What recommendations would you make to improve the use of the the Ocean Swimming Pool spaces?

Improve the conditions of the reception, it is a very windy area. The engine room is also very noisy.

Receptionist



Name: Paula Santos

Birth date: 1977

Address: Matosinhos

Education: Secondary school (project design. Had photography classes with Teresa Siza).

Position: Receptionist

Serves in this position since 2016. Has been working for Matosinhos Sport since 2007.

What do you LIKE most about the Ocean Swimming Pool?

"The features, the integration of the natural with the urban."

What would you like to CHANGE in the Ocean Swimming Pool?

"Some details could be updated. The accessibility of the pool for people with mobility impairments (this community is becoming more active and nowadays they have to enter the pool with the help of the staff). More safety for children (stairs without handrails). More protection in the reception area (exposed to north wind)".

How do you IMAGINE the Ocean Swimming Pool in the future?

"I can't imagine it any differently."

What does your job and work routine consist of?

Logistics of setting up and dismantling the counter with the computers, cash register and ATM. Customer service: providing information on prices, water temperature, information on capacity and handing out wristbands, differentiated by colour for full day or half day.

What are the main difficulties you encounter in your job?

The reception area has little protection. It is exposed to the weather conditions.

What are the main problems you identify in this building?

Mainly the maintenance of the toilets.

Is there any control on the number of people frequenting the spaces?

A counting system is carried out by a controller. Currently, with the pandemic, the maximum capacity is 618 people. According to the number of people, we place signs in public view indicating the occupation level (low, medium and high/ full capacity).

What behaviours are adopted when emergency situations arise?

In an emergency situation we call 112. If it is a covid emergency there is an isolation room with a testing kit.

What recommendations would you make to improve the use of the the Ocean Swimming Pool spaces?

I would recommend users to respect the signs in the toilets, such as putting waste in the appropriate bin and have more civility.

Lifequard



Name: Tiago Macedo Birth date: 1992 Address: Porto Education: Degree in Sport Position: Lifeguard Serves in this position since for seven years and works as

What do you LIKE most about the Ocean Swimming Pool?

"The view. It's like the pool merges with the sea."

What would you like to CHANGE in the Ocean Swimming Pool?

"Improve the sand quality in the main part, with less dust."

How do you IMAGINE the Ocean Swimming Pool in the future?

"I don't think it will change much, I think it will remain as it is."

What does your job and work routine consist of?

Raising the flags on the north and south beach before the opening and setting up the lifeguard station (with the life-saving instruments, surfboard, life stick, torpedo buoy, belt, and first aid kit). In our work, prevention is very important, warning children not to run, jump, or dive.

What are the main difficulties you encounter in your job?

Being exposed to the sun for extended periods (about 10 hours), despite the sunshade, is very tiresome. Dealing with people that do not comply with safety recomendations.

What are the main problems you identify in this building?

Sometimes people do not respect the rules and it is normal for children to get hurt.

For users, what would you define as prohibitions, alerts and recommendations?

No climbing on rocks, no diving, no apnea without the supervision of a lifeguard, no buoys inside the pool, no balls, no animals.

What behaviours are adopted when emergency situations arise?

In an emergency situation you should call 112. If the emergency is at sea, we call the ISN that is responsible for the search and rescue vessels and part of the national maritime authority.

Serves in this position since 2021. Has worked at the marina for seven years and works as a lifeguard for ISN since 2017.

Security guard



Name: Manuel Jesus Birth date: 1959

Address: Porto

Education: 9th grade

Position: Security guard

Serves in this position since 2019. Had already worked at the Ocean Swimming Pool before and has been a security guard since 1993.

Has the support of two security guards from a different private company and 4 Municipal Council employees that control the site boundaries.

What do you LIKE most about the Ocean Swimming Pool?

"I like its structure."

What would you like to CHANGE in the Ocean Swimming Pool?

"Nothing."

How do you IMAGINE the Ocean Swimming Pool in the future?

"I can't imagine it any other way."

What does your job and work routine consist of?

During the day we control the entrances and exits, support the reception and measure the temperature of users upon entrance. During the night we patrol the entire premises, from one end to the other. The walking patrols take place at an hourly basis and take about 20 minutes to complete. During patrols we must detect intruders and check for water leaks or other malfunctions. If there are any occurrences during the rounds we need to fill in a report.

What are the main difficulties you encounter in your job?

The arrival of groups (mainly foreigners), off the bathing season, who want to visit the building. We are not authorized to give access because these visits are coordinated by the Municipal Council, and we can only open the facilities in specific situations with authorization from the Municipal Council. are the only ones that have access from outside a licence to enter the area. Handle the equipment with care. For example, there is a shower that so damaged, but otherwise I think it is working well.

What are the main problems you identify in this building?

The reception is not sheltered from the weather conditions. In terms of operation there are no problems. In the winter an inspection is made so that in the summer the equipment is in good condition.

What behaviours are adopted when emergency situations arise?

If we detect a water leak or an electrical failure during the night we have to call the security company, report it to the central office and they take measures. Although we have several fire extinguishers and we are qualified to use them if there is an emergency situation, we always have to report to the company, even if it is an emergency that we can solve ourselves.

For users, what would you define as prohibitions, alerts and recommendations?

It is forbidden to bring parasols, animals, taking photographs. We have a sign with the forbidden activities.

When the building is closed, do other problems usually arise, such as theft, vandalism or unauthorised entry?

It can happen. For example, graffiti is easy because it's a very quick process, and, therefore, difficult to prevent. It would be interesting to have video surveillance. I do not know if it would be possible because of the aesthetic component, but I would be able to control a larger area. We also don't have an alarm system. Since I've been here, they've never removed the copper plates, but it can happen.

What recommendations would you make to improve the use of the the Ocean Swimming Pool spaces?

That the users don't go beyond the site boundaries. The tapes are placed so people know it is a limited space, although many people do not respect this and go underneath. Sport fishermen are the only ones that have access from outside as they have a licence to enter the area. Handle the equipment and facilities with care. For example, there is a shower that some user has damaged, but otherwise I think it is working well.



APPENDICES

Cleaning assistant

Name: Maria da Conceição Birth date: 1974 Address: Matosinhos Education: 6th grade Position: Cleaning assistant Serves in this position sinc other cleaning assistants of

What do you LIKE most about the Ocean Swimming Pool?

"Everything."

What would you like to CHANGE in the Ocean Swimming Pool?

"Nothing."

How do you IMAGINE the Ocean Swimming Pool in the future?

"I think it looks well as it is."

What does your job and work routine consist of?

Cleaning the pool area and the bathrooms, replenishing toilet paper, washing the foot washes and the floor around the pool. All the process is carried out with bleach supplied by the company Euromex.

What are the main difficulties you encounter in your job?

None. People are very approachable and always willing to help.

What problems do you identify regarding the users of this building?

None.

Is there a procedure to report problems detected in the building?

Report to Matosinhos Sport.

Is there a schedule of cleaning routines for the building?

In the morning check the bathrooms and report any missing materials. Then during the day repeatedly do the cleaning and disinfection routine between pools, foot washes and toilets.

What recommendations would you make to improve the use of the the Ocean Swimming Pool spaces?

Dispose of the waste in the rubbish bins and respect the space.

Serves in this position since 2021. Has the support of two other cleaning assistants after the building's closure.

APPENDIX D

Inspection and diagnosis report

1.1 Damage survey

The building remains in a reasonable state of conservation, without any interventions that have substantially altered its original physiognomy. However, the building is at risk because of its maritime location and the nearby oil refinery, which together have aggravated the decay of the concrete to moderate extent, by triggering cracking, corrosion and spalling of its steel reinforcement. While the carbon dioxide from the refinery accelerates the carbonation process, the chlorides of the salt water and salt fog penetrate into the concrete and cause localized corrosion and spalling. Furthermore, interventions conducted by the Matosinhos Municipal Council since the 1980s have led to problems such as delamination, pattern cracking and staining.

The building and pools are mainly constructed in good quality concrete, with a small amount of reinforced steel, according to the structural project of the Engineer Bernardo Ferrão (dated c. 1960). The building walls have a thickness of 30 cm and have a steel mesh of 5mm, with a grid of 15×15 cm. In contrast, the beams and slabs have thicker reinforced steel bars, and it is here that the main problems of reinforced steel corrosion and spalling have been detected (Fig. 34). Spalling also occasionally occurs at the top of the walls or in the swimming pool tanks, which exhibit some alterations, namely at the points where the tanks connect with the rocks.

The most evident signs of alterations and degradation in the concrete walls come in the form of cracks, creating visible discontinuities in the surface of the material. Most of these cracks are not apparently related with steel corrosion and the vertical cracks in the longitudinal walls seem to be caused by the absence of movements joints, which corresponds to an evolutionary damage process possibly due to shrinkage and / or thermal movements. These were aggravated by interventions performed by the Municipal Council, filling the cracks with incompatible mortar. However, in some cases (Fig. 35), steel corrosion is starting to appear and this will require conservation actions and future maintenance. Moreover, some concrete surfaces have small red/brown stains created by the oxidation of rusted metal inside the concrete, which have deposited on the surface. In some cases, namely in the beams, there are signs of a loss of material (spalling) (Fig. 34), caused by the corrosion of reinforced steel. There are situations (Fig. 36) where the corrosion of the reinforced steel spread across a large portion of a concrete slab which, in result, affected the structure stability, even though there was an attempt to fix one of these locations by applying repair mortar to cover the unprotected reinforced steel.

There is also damage associated to distributed cracking (taking the form of a polygonal net, similar to a spider's web) caused by the addition, in the 1980s, of a 4 cm concrete layer (with light mesh) over some walls, because of incompatibility with the preexisting concrete walls or shrinkage. (Fig. 37).

Some of the walls show signs of efflorescence in the form of a textured white stain (Fig. 38), which is caused by the infiltration of water in the concrete. The building also suffers from localized spots displaying a chromatic change that has a "dragged" appearance (Fig. 39). This is the result of the rainwater running off the surface and leaving a deposit. There are also the effects of biological colonization (Fig. 40) growing on the concrete surface, which, again, changes its texture and color.

Moreover, the copper surface of the building's roofs has a green color due to oxidation (Fig. 41) and leakage has been identified in the assembly of the copper elements, resulting from the exposure and lack of maintenance. In addition, the timber structure of the roof and of the changing rooms' partition walls presents localized detachment of the coating, and an oily texture (Fig. 41) that results from the excessive amounts of linseed oil used in its maintenance. The screws used for the timber structure show signs of oxidation, with brown textured spots on their surface. Finally, the adults' tank presents spots and biological colonization.

Despite the reported condition, the problem that has most seriously affected the building's integrity and authenticity is the series of interventions performed by the Municipal Council over the years, such as the introduction of incompatible repair mortars, as well as unauthorized electrical installations (Fig. 43), which have a distinctive light grey color and smooth texture, in comparison with the preexisting concrete. Also, the bar concession holder has performed unauthorized alterations to the interior of the building and the original design was not preserved. Thus, the Conservation Management Plan will also be an important tool for providing guidelines as to the correct use of the building in the future.

The most notable deficiency in the building's use is related to the hydraulic infrastructure, as many of the pipes of the water system have either been destroyed by the corrosion or are clogged with sand (Fig. 44), which means that they were compromising the pools' functionality (the pools were closed to the public in 2018 and have reopened in 2021). Finally, Fig. 45 presents the damage mapping of the building.



Fig. 34 – Examples of spalling caused by reinforced steel corrosion in beams.



Fig. 35 - Details of vertical cracks.



Fig. 36 – Concrete slabs severely affected by the corrosion of the reinforced steel.





Fig. 37 – Distributed crack pattern.





Fig. 38 – Crack in the concrete wall and efflorescence on the north wall of the reception area.



Fig. 39 – Stains created by rainwater run-off.



Fig. 40 – Biological colonization.



Fig. 41 – Oxidized copper roofs, corroded screws and an oily texture of the wood.



Fig. 42 – Spots and biological colonization in the adults' tank .









Fig. 43 – Incorrect interventions.



Fig. 44 – Corroded pipes of the water system.









phases and damage mapping).

1.2 **Evaluation of the Out-the-plane Deformations**

The diagnosis of the building included a laser scanner survey, which was used to evaluate the out-of-plane deformation of the concrete walls. In this first analysis, the out-of-plane deformations of the retaining wall and the main façade's North

were evaluated (Fig. 46). It is noted that the deformations were evaluated with respect to a theoretical vertical plane passing through the base of the wall, using colormaps and 2D cross-sections (Fig. 47-50).



Fig. 47 - Colormap of the out-of-plane deformation of the retaining wall (Section AA).

The results of this first analysis allow to verify that the maximum out-of-plane deformation of the retaining wall is equal to 28 mm and occurs at the cross-section W1-4 in the east direction (inwards) (Fig. 47 and 48). The maximum out-of--plane deformation in the west direction (outwards) is equal to 12 mm (cross-section W1_18). In the main facade's North, the maximum out-of-plane deformation is equal to 34 mm

Fig. 48 - Cross-sections of the retaining wall (Section AA) with the highest out-of-plane deformation.

and occurs at the cross-section W3 18 in the west direction (Fig. 49 and 50). In the opposite direction, the maximum deformation of this wall is equal to 27 mm (cross-section W3_6). Although these deformations are low, the out-of-plane deformation of the other walls may be also evaluated in the future for further documentation.



façade's North (Section BB).

Fig. 50 - Cross-sections of the main façade's North (Section BB) with the highest out-of-plane deformation.

1.3 Non-destructive and Minor-destructive Testing 1.3.1 **Concrete Carbonation Testing**

Carbonation is a chemical process that causes a reduction in In the diagnosis, three zones of the building were selected to carry out in-situ concrete carbonation tests: (1) adults' tank the alkalinity of the concrete and, consequently, corrosion in the steel rebars and damage in the concrete. This chemical (Phase 1 - exterior); (2) children's tank (Phase 2.1 - exterior); (c) process occurs when atmospheric carbon dioxide reacts with water collection area (Phase 2.1 - interior) (Fig. 33). The tests calcium hydroxide of the cement paste, producing calcium involved the extraction of three concrete cores and the applicarbonate and reducing the pH. Typically, the cement paste cation of a phenolphthalein solution on the core's surface, aino longer provides a passive environment, which protects the ming at determining the carbonation depth into the concrete. steel rebars, when the pH of the concrete reduces to about 9. The carbonation depth is determined based on the reaction In general, for very dry or saturated concrete, the carbonation of the phenolphthalein solution with the concrete (color of the process is slow. It is noted that young concrete is a high alkasurface), i.e. pink means non-carbonated concrete and grev line material with pH values around 12-13, protecting the steel means carbonated concrete. The concrete cores were extracrebars against corrosion. ted using a drilling machine with 110 mm of diameter (Fig. 51). The phenolphthalein solution was prepared according to the EN 12390-12:2020 (CEN, 2020).



Fig. 51 - Concrete cores extraction: (a) adults' tank; (b) children's tank: (c) water collection area.

Fig. 52 presents the concrete cores sprayed with the phenolrelative humidity and the carbonation testing with the phenolphthalein solution, and it is possible to observe that the entire phthalein solution (simplified method) includes uncertainties. surface of all the concrete cores is pink, meaning the concrete Thus, cement paste samples were collected and tested at the in these zones of the building is not carbonated. However, the laboratory to conclude on the carbonation of the concrete. concrete elements are located in an environment with high (Section 3.3.10.1).



Fig. 52 - Carbonation concrete tests: (a) application of the phenolphthalein solution; (b) detailed view of a concrete core of the adults' tank; (c) general view of the concrete cores of the adults' tank; (d) general view of the concrete of the children's tank; (e) general view of the concrete of the water collection area.

(c)

1.3.2 Laboratory Tests to Determine the Concrete and Steel Mechanical Properties

The concrete cores extracted for the carbonation tests were used in the laboratory tests to determine the mechanical properties of the concrete. Ten cylindrical concrete specimens were prepared based on the EN 12390-1:2012 (CEN, 2012) (Fig. 53a), namely three specimens of the adults' tank (T1.1; T1.2; T1.3), four specimens of the children's tank (T2.1; T2.2; I/d ratio (length/diameter) lower than 2 was corrected based T2.3; T2.4) and three specimens of the water collection area on the correction factors presented in the ASMT C 42/C 42M (I1; I2, I3). The area and density of the concrete specimens are presented in the Table 2. Two types of tests were carried out: (1) tests to determine the Young's modulus based on the LNEC E397:1993 (LNEC, 1993)(Fig. 53b); (2) tests to determine the compressive strength based on the EN 12390-3:2019 (CEN, 2019) (Fig. 53c). In the test planning, one concrete specimen of each zone was firstly tested in compression (destructive test) to estimate the compressive strength needed to perform the tests to determine the Young's modulus. Then, these tests were performed for the remaining specimens, with exception of the specimen T2.3_1, due to its low length. Finally, the specimens were tested in compression.

Table 2 presents the results of the laboratory tests carried out in the concrete specimens. The mean compressive strength is equal to 36 MPa, 24 MPa and 23 MPa for the concrete of the adults' tank, children's tank and water collection area, respectively. The compressive strength of the specimens with (ASMT, 2013). The mean Young's modulus is equal to 39 GPa, 27 GPa and 38 MPa for the concrete of the adults' tank, children's tank and water collection area, respectively. It is noted that high values for the mechanical properties of the concrete specimens are expected since the concrete of these parts of the building corresponds to cyclopean concrete, with large stone aggregates. The external concrete walls present another type of concrete. However, no concrete cores could be extracted in the external walls, in order to affect the original materials in visible areas.



Fig. 53 – Laboratory tests to determine the mechanical properties of the concrete: (a) general view of the specimens; (b) test to determine the Young's modulus; (c) test to determine the compressive strength.

Location	Specimen	Area [cm²]	Density [kg/m³]	Average density [kg/m³]	F _{max} [kN]	f _C [MPa]	fm [MPa]	E [GPa]	E _m [GPa]
	T1.1	86.39	2345		325.90	37.72		-	
Adults tank	T1.2	86.61	2361	2365	326.30	37.67	36.09	39.80	39.36
	T1.3	86.41	2390		284.10	32.88		38.92	
	T2.1	104.88	2298	2209	268.70	25.62		27.18	26.69
Children	T2.2	104.92	2127		331.10	27.25	23.83	-	
tank	T2.3_1	104.93	2131		273.30	22.22		-	
	T2.3_2	104.99	2281	-	212.50	20.24		26.19	
Water	11	104.81	2271		250.30	23.20		34.18	
collection	12	105.03	2292	2298	250.20	23.29	23.03	42.33	38.28
room	13	104.86	2331		257.20	22.60		-	

(Fmax: maximum force; fc: compressive strength; fm: mean compressive strength; E: Young's modulus; Em: mean Young's modulus)

Table 2 - Résumé of the properties of the concrete specimens.

Samples of steel rebars were also collected, namely at the 54b and Table 3). The steel specimens of the adults' tank have top of the retaining wall, the adults' tank and in the slab of a mean diameter equal to 6.30 mm (smooth rebars without the South's storage room. In the laboratory, one steel specisignificant corrosion) and ultimate strength equal to 397 MPa. men of the rebar of the retaining wall (P1.1), three steel spe-The mean yield strength (fy,0.6fu) of these steel specimens is cimens of the rebars of the adults' tank (T1.1: T1.2: T1.3) and equal to 238 MPa (Table 3), which allows to conclude that this two steel specimens of the slab of the South's storage room steel corresponds to the class A235 (Portuguese steel class (A1; A2) were prepared and tested, aiming at determining the for smooth rebars of normal ductility and yield strength equal tensile strength of the steel (Fig. 54a). The tensile tests were or higher than 200 MPa). Finally, two rebars of the slab of the carried out based on the EN 10002-1:2001 (CEN, 2001). The South's storage room present corrosion and have a mean dia-P1.1 specimen presents corrosion (minimum diameter equal meter of 9.44 mm. The mean vield strength (fv.0.6fu) of these to 5.72 mm) and a tensile strength significantly lower (ultimatwo steel specimens is equal to 294 MPa. te strength equal to 253 MPa) than the other specimens (Fig.



erties of the steel rebars: (a) tests to determine the tensile strength; (b) results of the tests.

Specimen	Diameter	Area	Fmax	fu	^f y,0.6fu	fy,0.2%
	[mm]	[cm ²]	[kN]	[MPa]	[MPa]	[MPa]
P1.1	5.72	0.26	6.49	252.56	151.54	143.52
T1.1	6.40	0.32	13.59	422.77	253.66	301.69
T1.2	6.16	0.30	11.16	375.00	225.00	294.75
T1.3	6.34	0.32	12.47	394.65	236.79	276.90
Average	6.30	0.31	12.41	397.48	238.49	291.11
A1	9.16	0.66	32.60	493.94	296.36	465.31
A2	9.71	0.74	36.09	487.70	292.62	487.47
Average	9.44	0.70	34.35	490.82	294.49	476.39

(Fmax: maximum force; fu: ultimate tensile strength; fv.0.6fu: yield tensile strength assuming the proof stress equal to 0.6 of the ultimate strength; f_{v.0.2%}: yield tensile strength assuming the proof stress associated to the strain equal to 0.2%)

Table 3 - Résumé of the properties of the steel rebar specimens.

Chloride Content Testing 1.3.3

Under normal conditions, concrete provides protection that prevents the corrosion of the steel, mainly associated with the high pH of concrete and low electrical conductivity. However, during the lifetime of the reinforced concrete structure, external actions, such as the penetration of chlorides, can promote the electromechanical corrosion of the rebars, causing reduction of the effective cross-section of the steel rebars and damage in the concrete. The penetration of chlorides is associated with environmental factors, such as the exposure of the building.

Since the building is located very close to the sea (sea water, salt fog, winds and high relative humidity), samples of the concrete paste were collected and the chloride content was estimated based on chemical tests performed at the laboratory. The samples were collected at the adults' tank (T1.10: T1.20: T1.30), the children's tank (T2.10; T2.20; T2.10.B; T2.20.B), the water collection area (C10; C20; C30) and the bar (B10; B20; B30) (Fig. 55 and Table 4). The cement paste samples were collected using a drilling machine at different depths (from 10 cm to 30 cm. from the external surface), without contamination of the samples (Fig. 55). In general, three samples of each zone were collected, with exception of the children's tank where four samples were extracted (two at the external mortar laver, namely T2.10 and T2.20, and two at the original concrete, namely T2.10.B and T2.20.B). The collection of samples causes minor damage and, consequently, no concrete paste samples were collected at other parts of the building, such as at the external walls. It is noted that, during the collection of samples, the wall of the bar (external wall) was cut, due to the intervention that was being carried out, and the cement paste

samples were collected orthogonally to the cross-section of the wall without causing damage in the external surface, but not according to the typical procedure (from the external surface to the interior of the wall).

Table 4 presents the results of the chemical tests with the estimation of chloride content in the cement paste. In general, the results present a significant chloride content (higher than 1% - upper limit definied by the EN 206-1 (CEN, 2000)), which decreases in depth. In contrast, the samples of the adults' tank present an increase of the chloride content in depth. It is noted that it corresponds to a cyclopean concrete with large stones aggregates and, consequently, the samples can also include stone, influencing the percentage of chlorides in the sample. The samples of the bar also present an unexpected evolution of the chloride content in depth. However, and it was previously referred, the collection of these samples did not follow the typical procedure. It is also noted that the concrete of the water collection area (interior wall) presents a significant reduction of the chloride content in the cement paste at the 30 cm depth (0.18%).



Fig. 55 – Collection of concrete samples for the chemical tests to estimate the chloride content in the cement paste: (a) procedure; (b) samples.

Location	Sample	Depth	Chloride content in the cement paste
	Campio	[mm]	[%]
	T1.10	10	1.32
Adults tank	T1.20	20	1.68
	T1.30	30	1.86
Children tank	T2.10	10	2.96
(external mortar layer)	T2.20	20	2.00
Children tank	T2.10_B	10	1.84
(concrete)	T2.20_B	20	1.36
	C10	10	0.78
Water collection room	C20	20	0.40
	C30	30	0.18
	B10	10*	2.16
Bar ¹	B20	20*	2.11
	B30	30*	3.35

Table 4 - Results of the chemical tests to estimate the chloride content in the cement paste.

Water Penetration Testing 1.3.4

Table 5 presents the results of the water penetration tests, in which it is observed that the surfaces of the tested walls present significant different performances. The highest water absorption (permeability of the concrete) occurs at the wall of the water treatment area (1.6 ml and 1.1 ml at the interior and external surface, respectively, after 20 min), which corresponds to a water absorption coefficient of 1.00 kg/m². min0.5 after 20 min (for example, the expected range for traditional cement-based renders is 0.2-1.5 kg/m².min0.5). The tested surface of the wall of the South's corridor showed low permeability and no water absorption was observed at the tested wall of the changing rooms, during 20 min of the test. The results are according to the expected, since the external surfaces of the concrete walls present a significantly different appearance.

The in-situ water penetration tests with a Karsten's tube aim to estimate the amount of water that penetrates into the concrete over time, which is also an indirect measure of the superficial porosity or permeability. In this test, the Karsten's tube (glass tube with a graduated scale) is glued to the concrete surface, without causing damage, and filled with water. The water exerts a pressure on the surface, simulating wind--driven rain speeds up to 98 mph (pressure equal to 1140 Pa). In the diagnosis of the building, four water penetration tests were carried, namely at the interior surface of the wall of the water treatment area (Q1), external surface of the wall of the water treatment area (O2). external surface of the wall the South's corridor (CA) and external surface of the wall of the changing rooms (PV) (Fig. 33 and Fig. 56). The penetration of the water into the concrete was measured every 5 min for 20 min.



(a)

Fig. 56 – Examples of water penetration tests at the: (a) external surface of the wall of the water treatment area (Q2); (b) external surface of the wall of the changing rooms (PV).

Time		Decrease of the water le	vel in the Karsten's tube	
[min]		[m	1]	
	Q1	Q2	CA	PV
5	0.3	0.3	0.1	0
10	0.7	0.6	0.2	0
15	1.1	0.8	0.3	0
20	1.6	1.1	0.3	0

Table 5 - Results of the water penetration tests.



(b)

1.3.4 Concrete Testing with Schmidt Hammer

Non-destructive tests were also carried out at the external concrete walls (where it was not possible to extract concrete cores) and the tanks, such as tests with Schmidt hammer. This type of non-destructive test is based on the surface hardness, in which the rebound number provided by the Schmidt hammer is correlated with the compressive strength. Thus, this type of test is only representative of a layer of about

5 cm depth and the results can be affected by steel rebars, large aggregates, carbonation and moisture.

The concrete tests with Schmidt hammer were performed according to the EN 12504-2 (CEN, 2013), in several areas of the building (Fig. 33), with ten test repetitions in each location, aiming at evaluation the dispersion of the results (Fig. 57).



Fig. 57 – Examples of concrete testing with Schmidt hammer: (a) wall of the South's corridor; (b) main façade's North.

Table 6 presents the resume of results, namely the mean compressive strength (fcm) and the coefficient of variation (CoV). The original concrete of the adults' tank presents an average compressive strength equal to 42 MPa (15% higher the value obtained from the laboratory tests). On the other hand, the original external mortar of the children's tank presents an average compressive strength equal to 54 MPa. The average compressive strength of the new concrete applied in the tanks during the intervention is equal to 25 MPa. The

compressive strength estimated by the tests with Schmidt hammer of the original concrete of the external walls ranges from 38 MPa to 77 MPa, in which the high values can be related with the hardening of the concrete over time, and the presence of aggregates and rebars at the testing points. Finally, the tests showed that the compressive strength of the concrete of the retaining wall ranges from 30 MPa (new concrete) to 54 MPa (Phase 3). Again, the high values can be affected by the presence of steel rebars close to the testing points.

Location	Point	fcm	CoV
		[MPa]	[%]
	T1_P1	48	18
Adults tank	T1_P2	37	25
	T1_P31	30	18
Children tank	T2.P1 ²	54	11
	T2.P2 ¹	25	12
Changing rooms	PV.P1	79	7
	PV.P2	70	8
Main facade south	PS.P1	68	15
3	PS.P2	68	17
Main facade north	PN.P1	68	11
	PN.P2	38	26
South corridor	CA.P1	77	10
Bar	B.P1	57	31
Retaining wall	P.P1	54	13
	P.P2 ¹	30	14

1.3.6 Sonic Testing

Sonic testing is a non-destructive technique that allows to determine the velocity of the wave propagation (V) from a transmitting transducer to a receiving transducer:

$$V = \frac{s}{\Delta t}$$

where s is the distance between the transmitting and the receiving transducers, and Δt is the time that the wave takes from the transmitting transducer to the receiving transducer. The velocity of the wave is associated with the elastic material properties and can be used to evaluate the material homogeneity in the structure.

In this experimental campaign, direct tests were carried based on the ASTM C597-02 (ASTM, 2002), using a piezoelectric accelerometer with a sensitivity of 10 V/g (receiving transducer), an instrumented hammer (transmitting transducer), an acquisition board with 24 bits resolution, coaxial cables, and software developed by the University of Minho (Fig. 58). The sonic tests were performed in five concrete walls: (1) three



(a)

Fig. 58 - Sonic testing: (a) equipment; (b) test.

points of the wall of the South's corridor (CA); (2) three points of the wall of the South's bathrooms (CS); (3) four points of the main's façade South (PS, two points above and below the horizontal crack, Fig. 58b); (4) three points of the wall of the changing rooms (PV); (5) three points of the wall of the water treatment area (Q) (Fig. 59). The distance between the transducers is equal to the thickness of the walls (0.298-0.300 m) and the Δt was determined from the P waves of the direct sonic tests. At each point, six repetitions of the direct test were performed.

The results of the direct sonic tests (Table 7) show that the average velocity of the waves ranges from 2326 m/s (main's façade South) to 2898 m/s (changing rooms), in which the coefficient of variation is equal to 8%. The tested walls of the South's corridor, South's bathrooms and Water treatment area present similar results (velocity about 2580 ms/s; coefficient of variation of 1%), leading to the conclusion that the concrete of these walls does not present significant differences in the elastic properties.

(b)



(a)



(b)





(e)

(d)

Fig. 59 - Location of the sonic tests: (a) South's corridor (CA);
(b) South's bathrooms (CS); (c) main's façade South (PS); (d) changing rooms (PV); (e) water treatment area (Q).

Location	Point	Mean velocity	Average velocity
		[m/s]	[m/s]
	P1	2195	
South corridor (CA)	P2	2737	2598
	P3	2862	
South bathrooms (CS)	P1	2231	
	P2	2728	2560
	P3	2720	
Main facade south (PS)	P1	2524	
	P2	2317	2326
	P3	2078	
	P4	2387	
	P1	2760	
Changing rooms (PV)	P2	3052	2898
	P3	2881	
	P1	2474	
Water treatment room (Q)	P2	2797	2582
	P3	2474	

Table 7 - Resume of the results of the direct sonic tests.

1.3.7 Color Analysis Based on Spectrophotometry

The color analysis of the concrete was performed using a The tests with spectrophotometer were carried out at ten lospectrophotometer Konica Minolta CM-2600d (Fig. 60a). The cations of the building, including original concrete and new concrete applied in the intervention (Fig. 33 and Fig. 60). Mospectrophotometer provides the parameters L (lightness), a (redness-greyness of the color) and b (yellow-blueness of the reover, ten test repetitions were considered in each location. color) (CIELAB color space) for a testing point, which allow to The results were evaluated in terms of ΔE (see Appendix C) evaluate the color difference between testing points, based and represented using the Adobe RGB 1998 and sRGB color on the ΔE distance (Eq. 2). In general, it is considered that the spaces (Fig. 61). As expected, the results present a high discolor difference is perceivable by the human eye when ΔE is persion, with the color ranging from beige to dark gray. The lighter colors were detected in the children's tank (T2_e1, orihigher than 2.0. ΔE higher than 5.0 and 6.0 mean significant color difference and different colors, respectively. ginal concrete) and the main façade South's (PN_e1). The new concrete (T1_e3; T2_e2; P_e2) presents also different color with respect to original concrete (T1_e1, T1_e2; T2_e1; P_e1).



(a)



(c)

Fig. 60 – Color analysis testing: (a) spectrophotometer; (b) test at the adults' tank (original concrete); (c) test at the wall of the changing rooms (east surface); (d) test at the wall of the bar (west surface).





(d)



Ground Penetrating Radar (GPR) tests were carried out in several locations of the building. The main objective of the GPR tests was to determine the type of connection existing between the cantilever beams located over the changing rooms. GPR tests were also carried out at other reinforced concrete walls, aiming to verify the spacing of the vertical and horizontal reinforcement.

walls, aiming to verify the spacing of the vertical and horizontion can be measured, which allows the determination of tal reinforcement. the location and depth of the anomaly observed. The trans-The tests were carried out using the RAMAC/GPR system mission and reception antennas are within the same devifrom MALA (Guideline Geo). Given the objective of the works ce, which is also a cart (Fig. 62). Thus, the antennas can be and the estimated thickness of the structural elements under moved along the surface of the element under investigation, analysis (around 30 cm), the tests were carried out using a producing radargrams. Radargrams are charts that show 1600 MHz antenna. The GPR method is based on the emisthe position of the antenna against the travel time of the sion of high-frequency electromagnetic waves (radar waves) wave. If the velocity of propagation of the radar waves within into a building element using a dipole antenna. The waves are the media is known, the location and depth of the different generated by a transmission antenna placed on the surface of obstacles (interfaces, rebars, the backside of elements, etc.) the analyzed object. The wave propagates through the matecan be estimated. For reference, it is noted that the average rial and part of it is reflected back to the testing surface (wheradar-wave velocity in concrete is 10 cm/ns, according to the re the reception antenna is also located) when discontinuities literature (Daniels, 2014). are observed. Discontinuities correspond to a change in the



(a)

Fig. 62 – GPR testing: (a) equipment used in the GPR tests; (b) test carried out at the cantilever beam over the changing rooms.



Fig. 61 – Results of the color analysis.

(b)

Assessing the Connection Between the Cantilever Beams at the Changing Rooms

A series of GPR profiles were carried out in the three beams that compose the entrance of the changing rooms. The main objective was to understand the connection between the beam with no evident supports (beam B in Fig. 63) and the two perpendicular cantilever beams (beams A and C in Fig. 63). Assuming the likely presence of dowels connecting the

beams, vertical GPR profiles were carried out each 10 cm (close to the connection) and each 20 cm (around the center of beam B). The test aimed to determine two specific construction details: (1) the number of dowels connecting the beams; (2) the length of the dowels. Fig. 63 shows schematically the number and location of the profiles carried out.



Fig. 63 - Location of the GPR profiles carried out on the tree cantilever beams over the changing rooms.

The thickness of the beam is known (30 cm). Thus, the velocity of the waves in the concrete could be defined for this specific case. A velocity of 11 cm/ns was found, which is within the common range recommended in the literature (ASTM, 2002). Once the velocity was calibrated, the depth of the steel reinforcement bars and ties can be determined from the radargrams.

Fig. 64-68 show five representative radargrams corresponding to locations 1-5 (as indicated in Fig. 63). The first radargram (Fig. 64) was obtained at the head of beam A. The radargram shows parabolas that indicate the presence of steel reinforcement elements, separated approximately 20 cm. These reinforcement elements can be more clearly detected in the second radargram (Fig. 65), carried out on beam B, 30 cm from the joint between beams A and B. Therefore, there

seem to be five longitudinal reinforcement elements bars in beam B. Among these five rebars, some of them should go through the joint and penetrate the perpendicular cantilever beam (beam A) to make the connection between the two beams. These five bars are spaced 20 cm in height and are located at a depth of approximately 4-5 cm within the beams. Fig. 65 clearly shows the opposite face of the beam (at 30 cm), indicated as a yellow discontinuous line. Note that this known thickness was used to calibrate the velocity of the radar waves throughout the concrete. Note also that only the bars located close to the inspected surface are clearly observed. The bars from the opposite surface are hidden by the initial reflections. Nevertheless, a symmetric configuration is observed by tests carried out at both surfaces, showing five longitudinal reinforcement elements in both faces.





Fig. 65 – Radargram 2 on beam B, 30 cm from the joint between beams A and B.

Radargram 3 (Fig. 66) was carried out 50 cm away from the forcement of beam B, located at the top, bottom, and middle joint between beams A and B, confirming the presence of of the height given the beam large size. the five reinforcement bars) and indicating that their length Radargram 5 (Fig. 68) was carried out 180 cm away from the within beam B is greater than 50 cm. The tests performed at joint between beams A and B and 30 cm away from the joint a location further than 50 cm from the joint no longer show between beams B and C. The radargram shows again five the presence of the five bars. As an example, Fig. 67 shows reinforcements, indicating the presence of dowels in the interadargram 4, carried out 110 cm away from the joint between rior of beam B at this end of the beam to connect with beam beams A and B. Only three steel reinforcement elements can C. The reinforcement details thus seems to be similar at both be detected. In conclusion, the dowels that connect beams A ends of the beam. The tests carried out led to determining and B seem to have a length of 50 cm within beam B and there that two dowels were used to connect the beams. These doare two of them (the two longitudinal reinforcement elements wels are separated 40 cm, located approximately 40 cm from that are no longer visible in Fig. 67). The three reinforcement the top and 40 cm from the bottom of the beam. They have a elements located in Fig. 67 seem to be the longitudinal reinlength of approximately 50-60 cm within beam B (beam with no vertical supports).



Fig. 66 – Radargram 3 on beam B, 50 cm from the joint between beams A and B.



Fig. 67 – Radargram 4 on beam B, 110 cm from the joint between beams A and B.



Fig. 68 – Radargram 5 on beam B, 180 cm from the joint between beams A and B.

Several radargrams were carried out on the interior face of the beam, leading to similar conclusions. The results indicate that the same reinforcement detail was used at both faces of the beams. For example, Fig. 69 shows a radargram carried out on the interior face of the beam, 30 cm away from the joint between beams B and C. The radargram shows the longitu-





Fig. 69 – Radargram carried out on beam B (interior face), 30 cm from the joint between beams B and C.

Another test was carried out on beam B in the longitudinal horizontal direction, aiming to determine the spacing between the stirrups. Fig. 70 shows that the stirrups have a regular spacing of 25 cm throughout the beam length. However, the spacing is reduced close to the beam ends. The radargram indicates that the spacing of the stirrups at the beam ends



Fig. 70 - Longitudinal radargram carried out on beam B.



Fig. 71 - Vertical radargram carried out on beam C.

In conclusion, Fig. 72 shows a hypothesis of the connection between the cantilever beams over the changing rooms. The hypothesis that is shown in Fig. 72 indicates the probable presence of two dowels connecting the perpendicular beams in each face (in dark red), making it four it total. It also shows an approximate distribution of the stirrups (in light blue) and the longitudinal reinforcement bars (in orange) of beam B, again in each face. The probable location of the three longitudinal reinforcement bars in beams A and C (in dark blue), and in each face, is also shown. The arrangement is assumed to be symmetric from the vertical axis of the beams.



Fig. 72 - Likely reinforcement details of the connection between the cantilever beams over the changing rooms, and beams main reinforcement.

Verification of the Reinforcement Scheme in Reinforced **Concrete Walls**

GPR readings were carried out in two reinforced concrete areas, probably corresponding to two different phases of conwalls to verify the reinforcement scheme (vertical and horicrete pouring. At the area closer to the entrance of the chanzontal spacing). The two walls were located at: (1) the exterior ging room (first part of the radargram), the spacing between wall of the changing rooms; (2) the exterior wall of the south's vertical bars is 20 cm. In the second area, the spacing is 30 corridor. To locate the horizontal and vertical reinforcement cm. The bars are located at a depth of approximately 4 cm. Fig. 74 shows a vertical GPR profile at same wall. In this case, elements, tests were carried out in both orthogonal directions on the walls. the spacing between horizontal bars is constant (30 cm). The bars are located at a depth of approximately 3 cm. The radar-Fig. 73 shows the result of one test carried out following a hogram also shows clearly the horizontal interface between two different phases of concrete pouring.

rizontal alignment at the exterior wall of the changing rooms. Variable spacing between vertical reinforcement bars could be estimated. There is a vertical separation between two

0.20 m



Fig. 73 - Horizontal radargram carried out on the exterior wall of the changing rooms.

0.30 m

Fig. 74 - Vertical radargram carried out on the exterior wall of the changing rooms.

In the exterior wall of the south's corridor, the tests were carreinforcement bars can be clearly observed. Similarly, Fig. 80 ried out in a grid following the orthogonal directions on the shows a representative vertical radargram carried out on the walls. A total of 8 parallel scans were carried out in the horiwall of the south's corridor. In this case, a spacing of 10 cm zontal and vertical direction (Fig. 75). The separation between between horizontal reinforcement bars can be also clearly scans was 20 cm, covering a total area of 1.4 m x 1.4 m. Fig. observed. 76 shows a representative horizontal radargram carried out on the south's corridor. A spacing of 30 cm between vertical



2-3 cm. The vertical reinforcement bars seem to be more crete materials. deeply located, approximately at 4 cm within the concrete. Note that the velocity of propagation of the radar waves was calibrated based on the known thickness of the wall (30 cm),

The horizontal bars are placed at a depth of approximately resulting in a velocity of 12 cm/ns, which is common for con-



Fig. 75 – Horizontal and vertical scans carried out on the south's corridor.



Fig. 76 - Representative example of horizontal radargram carried out on the wall of the south's corridor.



Fig. 77 - Representative example of vertical radargram carried out on the wall of the south's corridor.

The collection of many two-dimensional profiles (radareach amplitude slice should show information of a thicker grams) in a grid allows to derive amplitude maps that illusarea and not only at the precise depth. Nevertheless, higher trate in three dimensions the location of the reflections. The amplitudes are clearly produced by the reinforcements, shoamplitude slice maps show reflected wave amplitudes diffewing their probable location and configuration. The reinforrences spatially at different depths, which allows for a more cements form a grid with 30 cm horizontal spacing and 10 cm direct visualization of the result. Moreover, the process allovertical spacing for vertical and horizontal reinforcements, ws the analysis of the spatial distribution of the amplitudes respectively, confirming the results previously obtained in the generated by all radargrams simultaneously, instead of the individual profiles. analysis of each scan individually. The maps will show areas This method of amplitude analysis can also produce threewith greater amplitudes, corresponding to interfaces bet--dimensional images of the reflected waves, which also help ween materials with a greater difference in their physical and in the interpretation of the results. Fig. 79a shows a 3D pseuchemical properties. Areas with low amplitude reflections do-representation of the interior of the reinforced concrete typically indicate a uniform material. In this case, areas with wall, by means of iso-amplitude surfaces representing the greater amplitudes should indicate the location of the rebars, threshold enveloped. Fig. 79b shows only the amplitudes exwhich have clearly different physical properties than the surceeding a certain threshold. Both images show well the prerounding concrete. viously discussed configuration of the reinforcement of the exterior wall of the storage corridor.

Fig. 78 shows amplitude slice maps obtained at different depths (d) within the concrete: at 4.5 cm and 8 cm deep. Note that





(a) d = 0.045 m

Fig. 78 – Amplitude slice maps at different depths (d) within the concrete.



Fig. 79 – 3D visualization of the interior of the reinforced concrete wall by means of: (a) iso-amplitude surfaces; and (b) am-

plitudes exceeding a certain amplitude threshold.



Verification of the Construction Detail of the Wall at the Changing Room

Finally, the last GPR test was carried at the wall of the wash foot's room, aiming to understand the construction detail of the connection between the concrete wall and the timber elements. Fig. 80 shows that the vertical timber element is superficial with a thickness of approximately 1 cm. Thus, the timber element is not a continuation of the timber element



Fig. 80 – Horizontal radargram carried out on the wall of the wash foot's room.

1.3.9 Laboratory Tests on a Timber Specimen

A timber specimen $(2 \times 12 \times 3 \text{ cm}^3)$ was taken from the structure in order to be inspected and tested in laboratory conditions. From an initial visual inspection (Fig. 81), the plank did not present any superficial defects, e.g knots or splits and cracks. There was no slope of grain and the growth rings are regular. From the colour and the dimension of the rings, it is believed that the species of the specimen is riga (pinus sylvestris).

The density of the specimen was obtained according to standard ISO 13061-2 (2014), in which 10 specimens were cut with dimensions of $20 \times 20 \times 25$ mm³. The specimens were measured and weighed. A wood density of 635.41 kg/m³ (CoV of 9.8%) was obtained.

Resistograph tests were performed on the timber specimen to determine the quality of the timber, the presence of possible cavities or decayed parts in the timber specimen not detected by a simple visual inspection. The resistograph is an equipment that drills with a 1.5 mm drill into the wood at

a speed of 8000 rpm (Fig. 82). The plan was to perform 4 holes in the timber specimen. However, due to the high quality of the specimen and its high density, as well as its low moisture content, only one hole was made, breaking the needle while performing the second hole, due to the high values of resistance. The resistographic measurement (RM), valid for sound and defect-free timber, is given by the ratio between the area underneath the curve and the drilling depth (in this case, 12 cm). A resistographic measurement of 93.27% was found. From the graph (Fig. 83), it is clear that throughout the section, the timber has a good quality, maintaining a uniform resistance. The second hole, which broke the needle, showed even higher values of momentary drill resistance.

There is a direct relationship between RM and the compressive strength of sound timber, i.e. timber without defects (Henrique et al., 2011), showing that the higher the RM the higher the compressive strength of wood.

Fig. 81

Fig. 82





1.3.10 Laboratory Tests on Cement Paste Samples

Paste cement samples were collect from the structure, including the concrete cores, namely at: (1) adult's tank (T1.1); (2) children ´s tank (T2.1); (3) water collection area (I1); (4) water treatment area (Q); (5) changing rooms (PV); (6) bar (B1); (7) South's storage room (A). The samples were used to perform

Thermal Gravimetric Analysis

The thermal gravimetric analysis (TGA) is a thermal analysis for material characterization, in which the mass loss of the sample is measured over time as function of the temperature increase. The analyses were performed in an SDT Q600 thermal analyzer of the TA Instruments for a temperature range between 0 °C and 1200 °C. Seven cement paste samples were analyzed. The initial mass of the samples ranges from 19.70 mg and 27.65 mg (Fig. 84).



Fig. 84 – TGA thermal curves.

Fig. 81 - Cross-section of the timber specimen.

Fig. 82 – Performing a test with the resistograph.

Fig. 83 – Resistograph result.

the following tests and analyses in the laboratory: (1) thermal gravimetric analysis (TGA); (2) nanoindentation; (3) energy dispersive X-ray analysis (EDS); (4) X-ray diffraction (DRX); (5) scanning electron microscopy (SEM); (6) mercury intrusion porosimetry tests.

The TGA thermal curves (Fig. 84) shows water release from 0-200 °C. Between 400-450 °C, the samples Q and I1 present calcium hydroxide (portlandite). There is a significant mass drop around 700 °C for all almost samples, which is associated with the presence of calcium carbonate. The TGA results show that these paste cement samples are carbonated, mainly the B1 (exterior wall of the bar), PV (exterior wall of the changing rooms), I1 (interior wall of the water collection area) and A (slab with corroded rebars) samples. It is noted the Q sample, collected from the water treatment area (interior surface of a closed area), presents low carbonation.

Nanoindentation

The nanoindentation tests were performed with a nanoindenter tester, provided with a vibrating isolating system and constant temperature and humidity. For each sample, 10 tests were carried, using a 2×5 grid (spacing of the horizontal and vertical alignments equal to 75 μ m and 250 μ m, respectively). All the tests were performed using the same protocol: loading with a constant rate 5 mN/min up to a maximum force, dwell time td=5 [s] at maximum load and unloading with a constant rate 5 mN/min.

The results of the nanoindentation tests are presented in Tables 8 to 14 and Fig. 85, namely the hardness and the reduced (effective) elastic modulus obtained from the unloading stiffness (Er). The sample T1.1 (phase 1) presents a high dispersion on the results, with elastic modulus ranging from 2.98 to 97.16 GPa (mean value equal to 39.95 GPA and CoV of 82%).

the adult's tank (T1) present a mean Young's modulus equal to 39.36 GPa (Table 2). The T2.1 and I1 cement paste samples of phase 2.1 present a similar mean elastic modulus, namely 45.28 GPa and 49.86 GPa, respectively, with exception of the sample Q (interior surface of a closed area), which presents a higher value (74.56 GPa). The sample PV (phase 2.4) presents a mean elastic modulus of 92.75 GPa and the highest value of all tests (177.87 GPa), which can be associated with the many aggregates presented in this sample. The B1 and A samples of the phase present very similar mean elastic modulus, namely 37.14 GPa and 37.53 GPa, respectively. However, tests carried out in sample A presents a high dispersion (CoV equal 145%), with very low and high values, which can be associated with low properties of the gel and the high properties of the aggregates, respectively. It is noted that sample A was collected Although this is a cement paste sample, the concrete core of from a slab with carbonated concrete and corroded rebars.

Indentation	Cycle	Max. Depth (nm)	Plastic Depth (nm)	Max. Load (mN)	Hardness (GPa)	Er (GPa)
1	1	519.42	463.67	5.05	0.64	20.75
2	1	4548.35	4501.07	5.05	0.01	2.98
3	1	143.74	103.01	5.05	6.12	87.75
4	1	118.34	72.09	5.05	9.68	97.16
5	1	459.77	356.78	5.05	0.99	13.94
6	1	450.68	375.12	5.05	0.91	18.24
7	1	329.80	276.94	5.05	1.48	33.21
8	1	259.17	213.23	5.05	2.20	46.67
9	1	273.90	243.70	5.05	1.80	64.19
10	1	494.72	406.13	5.05	0.80	14.58
				Minimum	0.01	2.98
				Maximum	9.68	97.16
				Mean	2.46	39.95
				CoV [%]	123.76	82.45

	Indentation	Cycle	Max. Depth (nm)	Plastic Depth (nm)	Max. Load (mN)	Hardness (GPa)	Er (GPa)
_	1	1	143.54	99.84	5.05	6.38	83.48
	2	1	99.58	60.26	5.05	12.07	127.62
	3	1	381.38	302.97	5.05	1.28	20.87
	4	1	163.58	114.17	5.05	5.34	67.53
	5	1	434.19	308.60	5.05	1.25	12.84
	6	1	122.53	88.69	5.05	7.44	116.44
	7	1	294.42	229.67	5.05	1.97	31.31
	8	1	787.30	674.30	5.05	0.34	7.42
	9	1	273.79	198.57	5.05	2.45	30.05
	10	1	6362.81	6264.91	5.05	0.00	1.04
_					Minimum	0.00	1.04
					Maximum	12.07	127.62
					Mean	3.85	49.86
					CoV [%]	100.58	92.28

Table 10 - Results of the nanoindentation tests for the I1 sample.

Indentation	Cycle	Max. Depth (nm)	Plastic Depth (nm)	Max. Load (mN)	Hardness (GPa)	Er (GPa)
1	1	787.05	647.66	5.05	0.36	6.23
2	1	160.08	122.40	5.05	4.86	84.49
3	1	137.99	107.60	5.05	5.78	114.26
4	1	155.92	124.92	5.05	4.73	101.28
5	1	121.47	76.51	5.05	8.98	96.29
6	1	631.77	529.38	5.05	0.51	10.10
7	1	152.08	106.87	5.05	5.83	77.15
8	1	137.53	89.62	5.05	7.34	81.69
9	1	112.38	60.53	5.05	12.00	96.52
10	1	136.79	84.35	5.05	7.94	77.60
				Minimum	0.36	6.23
				Maximum	12.00	114.26
				Mean	5.83	74.56
				CoV [%]	61.31	49.45

Table 8 - Results of the nanoindentation tests for the T1.1 sample.

Indentation	Cycle	Max. Depth (nm)	Plastic Depth (nm)	Max. Load (mN)	Hardness (GPa)	Er (GPa)
1	1	205.94	138.94	5.05	4.08	43.56
2	1	388.16	317.49	5.05	1.19	22.31
3	1	319.51	285.98	5.05	1.41	51.07
4	1	186.36	145.11	5.05	3.84	68.65
5	1	160.35	115.09	5.05	5.28	73.35
6	1	351.20	292.79	5.05	1.35	28.78
7	1	430.50	392.89	5.05	0.84	35.29
8	1	150.89	98.12	5.05	6.53	69.93
9	1	368.34	325.49	5.05	1.14	36.08
10	1	383.12	316.75	5.05	1.20	23.80
				Minimum	0.84	22.31
				Maximum	6.53	73.35
				Mean	2.69	45.28
				CoV [%]	76.88	43.07

Table 9 - Results of the nanoindentation tests for the T2.1 sample.

Indentation	Cycle	Max. Depth (nm)	Plastic Depth (nm)	Max. Load (mN)	Hardness (GPa)	Er (GPa)
1	1	16107.43	15268.51	4.43	0.00	0.04
2	1	18704.86	15095.85	4.41	0.00	0.01
3	1	19914.06	14801.08	3.47	0.00	0.01
4	1	88.54	50.19	5.05	15.03	146.04
5	1	141.43	89.97	5.05	7.30	75.87
6	1	17909.84	13865.70	4.67	0.00	0.01
7	1	19798.12	16280.41	3.70	0.00	0.01
8	1	19904.55	18056.86	3.44	0.00	0.01
9	1	103.92	58.72	5.05	12.46	112.78
10	1	395.36	360.25	5.05	0.97	40.57
				Minimum	0.00	0.01
				Maximum	15.03	146.04
				Mean	3.58	37.53
				CoV [%]	163.41	146.89

-	Indentation	Cycle	Max. Depth (nm)	Plastic Depth (nm)	Max. Load (mN)	Hardness (GPa)	Er (GPa)
	1	1	114.12	70.59	5.05	9.93	104.59
	2	1	296.80	263.95	5.05	1.59	55.49
	3	1	231.65	193.36	5.05	2.55	60.19
	4	1	206.44	160.47	5.05	3.33	57.38
	5	1	205.48	163.91	5.05	3.23	62.49
	6	1	226.02	181.85	5.05	2.78	54.58
	7	1	83.21	52.57	5.05	14.23	177.87
	8	1	92.86	53.63	5.05	13.89	137.26
	9	1	80.81	42.18	5.05	18.44	160.58
	10	1	205.79	159.39	5.05	3.37	57.11
_					Minimum	1.59	54.58
					Maximum	18.44	177.87
					Mean	7.33	92.75
					CoV [%]	84.50	52.46

Table 12 - Results of the nanoindentation tests for the PV sample.

Indentation	Cycle	Max. Depth (nm)	Plastic Depth (nm)	Max. Load (mN)	Hardness (GPa)	Er (GPa)
1	1	591.93	484.39	5.05	0.60	10.36
2	1	162.60	111.76	5.05	5.49	66.59
3	1	270.48	219.46	5.05	2.11	41.12
4	1	247.46	194.56	5.05	2.52	43.37
5	1	170.62	126.73	5.05	4.63	70.86
6	1	439.13	350.06	5.05	1.02	16.37
7	1	358.70	277.40	5.05	1.47	21.57
8	1	199.55	162.18	5.05	3.28	70.05
9	1	355.25	286.46	5.05	1.40	24.86
10	1	892.33	774.59	5.05	0.26	6.30
				Minimum	0.26	6.30
				Maximum	5.49	70.86
				Mean	2.28	37.14
				CoV [%]	75.81	67.36

Table 13 - Results of the nanoindentation tests for the B1 sample.

Table 14 - Results of the nanoindentation tests for the A sample.



Fig. 85 – Results of the nanoindentation tests for all samples.

Energy Dispersive X-ray Analysis

The energy dispersive X-ray analysis (EDS) is a technique that allows to perform the elemental analysis or chemical characterization of surfaces of samples. Several zones of the surfaces of the samples were evaluated. The general results of the EDS (for all the zones of each sample), namely the spectra, shell (k), weight (Wt) and atomic (At) percentages, and K-ratios are presented in Fig. 86 to Fig. 92. The EDS results for







2.00 4.00 6.00 Fig. 88 – Results of the EDS tests for sample I1



Element	Wt [%]	At [%]	K-Ratio	Z	А	F
CK	12.07	20.43	0.0222	1.0433	0.1760	1.0005
ОК	38.06	48.35	0.0675	1.0258	0.1728	1.0003
NaK	0.84	0.75	0.0028	0.9600	0.3466	1.0030
AIK	3.14	2.36	0.0194	0.9551	0.6412	1.0105
SiK	23.20	16.79	0.1678	0.9830	0.7337	1.0028
CaK	21.36	10.83	0.1940	0.9546	0.9508	1.0006
FeK	1.33	0.49	0.0113	0.8674	0.9811	1.0000

C:	Carbon
0:	Oxygen
Na:	Sodium
AI:	Aluminum
Si:	Silicon
Ca:	Calcium
Fe:	Iron

10.00		10.00		13	2.00	1	4.00 keV
Wt [%]	At [%]	K-Ratio	Z	A	F		
9.19	16.01	0.0126	1.0457	0.1315	1.0004		
34.60	45.24	0.0707	1.0281	0.1987	1.0004		
0.38	0.35	0.0014	0.9622	0.3889	1.0048		
0.34	0.29	0.0018	0.9863	0.5433	1.0098		
3.27	2.54	0.0220	0.9573	0.6894	1.0173		
38.17	28.43	0.2902	0.9852	0.7703	1.0016		
3.15	1.68	0.0261	0.9347	0.8754	1.0130		
9.18	4.79	0.0793	0.9568	0.9011	1.0011		
0.53	0.23	0.0043	0.8738	0.9255	1.0011		
1.17	0.44	0.0101	0.8693	0.9860	1.0000		
				C: Ca O: Ox Na: So Mg: Ma Al: Ali Si: Sili K: Po	rbon ygen dium agnesiun uminum icon tassium		
	10 Wt [%] 9.19 34.60 0.38 0.34 3.27 38.17 3.15 9.18 0.53 1.17	10.00 Wt [%] At [%] 9.19 16.01 34.60 45.24 0.38 0.35 0.34 0.29 3.27 2.54 38.17 28.43 3.15 1.68 9.18 4.79 0.53 0.23 1.17 0.44	10.00 12 Wt [%] At [%] K-Ratio 9.19 16.01 0.0126 34.60 45.24 0.0707 0.38 0.35 0.0014 0.34 0.29 0.0018 3.27 2.54 0.0220 38.17 28.43 0.2902 3.15 1.68 0.0261 9.18 4.79 0.0793 0.53 0.23 0.0043 1.17 0.44 0.0101	10.00 12.00 Wt [%] At [%] K-Ratio Z 9.19 16.01 0.0126 1.0457 34.60 45.24 0.0707 1.0281 0.38 0.35 0.0014 0.9622 0.34 0.29 0.0018 0.9863 3.27 2.54 0.0220 0.9573 38.17 28.43 0.2902 0.9852 3.15 1.68 0.0261 0.9347 9.18 4.79 0.0793 0.9568 0.53 0.23 0.0043 0.8738 1.17 0.44 0.0101 0.8693	10.00 12.00 1 Wt [%] At [%] K-Ratio Z A 9.19 16.01 0.0126 1.0457 0.1315 34.60 45.24 0.0707 1.0281 0.1987 0.38 0.35 0.0014 0.9622 0.3889 0.34 0.29 0.0018 0.9863 0.5433 3.27 2.54 0.0220 0.9573 0.6894 38.17 28.43 0.2902 0.9852 0.7703 3.15 1.68 0.0261 0.9347 0.8754 9.18 4.79 0.0793 0.9568 0.9011 0.53 0.23 0.0043 0.8738 0.9255 1.17 0.44 0.0101 0.8693 0.9860 C: Ca 0: Ox Na: So Mg: Ma Al: Ali Si: Sili K: Po K: Po K: Po		







Fig. 92 - Results of the EDS tests for sample A

X-Ray Diffraction

The X-ray diffraction (DRX) was performed aiming at identifrom the results of the EDS, it was still possible to determine, fying the crystalline structure of the samples, using a D8 DISwith less certainty, the presence of the phases of monoclinic COVER X-ray analyzer of the Bruker, with Cu-K α (λ =1,54060Å) rankinite, hexagonal vaterite, monoclinic dickite-2M1, triclinic radiation. The analyses were carried out in the $\theta/2\theta$ configuanorthite, aluminium silicate, tetragonal calcium, oxide of iron ration, at ambient temperature, using a sweep between 5° and and orthorhombic potassium. 80°, with steps of 0.02°, and integration time of 1 second per The sample I1 presents (Fig. 95), with a high degree of cerstep. The crystal structure analysis was done using the EVA tainty, the following phases: hexagonal silicon oxide (quartz) software. The identification of the phases was carried out by and hexagonal portlandite and hexagonal vaterite. From the comparison with the respective experimental pattern from results of the chemical analysis, it was still possible to deterthe ICDD (International Center for Diffraction Data) databamine, with less certainty, the presence of the phases of monose, using a search matching algorithm. Furthermore, and as clinic beidellite, rhombohedral calcite/hexagonal, monoclinic previously referred, the DRX results were evaluated together sodium silicate and calcium and aluminium oxide carbonate with the EDS results. hydrate.

The analysis of the sample T1.1 (Fig. 93) allows to determine, The DRX diffractogram of the sample Q shows (Fig. 96), with with a high degree of certainty, the following phases: hexaa high degree of certainty, the following phases: hexagonal sigonal silicon oxide (quartz), monoclinic muscovite-2M1 and licon oxide (quartz) and hexagonal portlandite. Furthermore, triclinic albite. Furthermore, from the results of the chemical from the results of the chemical analysis, it was still possible analysis, it was still possible to determine, with less certainty, to determine, with less certainty, the presence of the phases the presence of the phases of monoclinic gismondine, hexaof triclinic pectolite, monoclinic phlogopite, cubic leucite, mogonal vaterite, triclinic anorthoclase, albite, and triclinic calnoclinic glauconite, triclinic albite, potassium and titanium cian. oxide hydrate and calcium and aluminium silicate.

Fig. 94 presents the diffractogram of the sample T2.1, in which it is observed, with a high degree of certainty, the presence of the following phases: hexagonal silicon oxide (quartz), muscovite-2M1 monoclinic and microcline triclinic. Furthermore, from the results of the chemical analysis, it was

Element	Wt [%]	At [%]	K-Ratio	Z	Α	F
СК	13.01	21.35	0.0221	1.0408	0.1629	1.0005
OK	39.39	48.52	0.0781	1.0233	0.1937	1.0003
NaK	1.60	1.37	0.0055	0.9577	0.3591	1.0033
MgK	0.30	0.24	0.0015	0.9818	0.4975	1.0067
AIK	2.26	1.65	0.0141	0.9530	0.6459	1.0119
SiK	27.01	18.95	0.1983	0.9808	0.7472	1.0020
КК	1.08	0.54	0.0093	0.9301	0.9084	1.0229
CaK	14.01	6.89	0.1250	0.9521	0.9371	1.0006
FeK	1.34	0.47	0.0114	0.8649	0.9882	1.0000
					Na: Soo Mg: Ma Al: Alu Si: Sili K: Po Ca: Ca Fe: Iro	dium Ignesium Iminum con tassium Icium n
1 8.00 9		.00 1	+	+ 2.00 13		i 1.00 keV

of monoclinic potassium and iron silicate, hexagonal chlorite, triclinic calcium and aluminium silicate and orthorhombic anthophyllite.

The results of sample B1 (Fig. 98) shows, with a high degree of certainty, the following phases: hexagonal silicon oxide (quartz) and monoclinic sanidine. Furthermore, from the results of the chemical analysis, it was still possible to determine, with less certainty, the presence of the phases of monoclinic clintonite-1M, hexagonal nepheline, monoclinic calcium silicate, tetragonal calcium hydride chloride and rhombohedral calcite/ hexagonal.

still possible to determine, with less certainty, the presence The DRX diffractogram of sample A (Fig. 99) presents, with a high degree of certainty, the following phases: hexagonal silicon oxide (quartz) and monoclinic illite-2M2. Furthermore, from the results of the chemical analysis, it was still possible to determine, with less certainty, the presence of the phases of triclinic orthoclase, hexagonal calcium carbonate (vaterite), triclinic albite, monoclinic calcium silicate and rhombohedral calcium carbonate /hexagonal.

> Finally, it is noted that the DRX results of the samples T1.1, T2.1, I1 and A present vaterite, which is a polymorph of calcium carbonate (CaCO3).



Fig. 93 – DRX diffractogram of the sample T1.1.





Fig. 95 - DRX diffractogram of the sample I1.



Fig. 96 – DRX diffractogram of the sample Q.



Fig. 97 – DRX diffractogram of the sample PV.





Fig. 99 – DRX diffractogram of the sample A.

Scanning Electron Microscopy

images of samples by scanning their surfaces with a low-energy beam of electrons, achieving high resolutions (in the low nanometer range). The high-resolution images provide information on the surface morphology and composition of (Section 3.3.3). The samples present several impurities in the the samples. In the first analysis, images with magnification aggregates, which can be an indicator of lack of quality conof 200x and 500x were created for all samples (Fig. 100 to trol in the aggregates (e.g. absence or deficient washing and/ Fig. 102). Additionally, images with a magnification of 1000x, or uncontrolled origin of the aggregates). Finally, the results 5000x, 10000x and 25000x were also obtained for the T1.1, of this analysis do not allow to conclude on the presence of T2.1, I1 samples (Fig. 103). All images are presented in the Annex (SEM and EDS).

The SEM analysis allowed to identify different zones of the samples, namely zones associated with aggregates, matrix

The scanning electron microscopy (SEM) allows to create and interfacial transition zones. The results show the presence of chloride (Cl and Na) in the samples T2.1 (Fig. 100b, Z2) and B1 (Fig. 101c, Z1), which is in agreement with the results of the EDS (Section 3.3.10.5) and the chloride content tests pozzolans in the composition of the concretes, which has been a common practice for many years to improve the durability of the concrete.







Fig. 100 - Examples of images obtained from SEM analysis (magnification: 200x and 500x): (a) T1.1 sample; (b) T2.1 sample; (c) I1 sample.





(b)



(c)









(b)

(c)

Fig. 101 - Examples of images obtained from SEM analysis (magnification: 200x and 500x): (a) Q sample; (b) PV sample; (c) B1 sample.



Fig. 102 – Examples of images obtained from SEM analysis (magnification: 200x and 500x) of the A sample.





Fig. 103 – Examples of images obtained from SEM analysis (magnification: 25000x): (a) T1.1 sample; (b) T2.1 sample; (c) I1 sample.







(c)

Mercury Intrusion Porosimetry Tests

The mercury intrusion porosimetry (MIP) tests were performed to evaluate the pore size distribution of the cement paste samples. Several parameters on the pore structure were obtained (see Annex). The critical pore diameter (dc) is one of the most relevant parameters obtained from the MIP tests, which corresponds to the steepest slope of the cumulative porosity curve and can be determined from the highest point of the logarithmic differential intrusion curve.

The logarithmic differential intrusion curve (Fig. 104) shows that the lowest dc is equal to $0.026\,\mu$ m and is associated with the sample T1.1 (adult's tank, phase 1). The dc of the samples

of phase 2.2 ranges from $0.032 \,\mu$ m (T2.1) to $0.077 \,\mu$ m (Q). It is noted that the sample I1 (phase 2.1) presents also three relevant peaks for the 10.5114 μ m, 6.5834 μ m and 5.714 μ m pore size diameter. The sample PV (phase 2.4) presents a dc of 0.2840 μ m associated with the lowest porosity (6.73%), which is in agreement with the results of the water penetration tests (Section 3.3.4). Sample B1 (phase 3) presents two relevant ranges of pore size diameter, namely 0.0263-0.0055 μ m and 1.3312-0.4341 μ m. Finally, sample A (phase 3) presents the highest dc, namely 3.8968 μ m (sample collected from a slab with carbonated concrete and corroded rebars).



1.4 Conclusions

The inspection and diagnosis of the building involved the following works: (1) damage survey; (2) evaluation of the outt-of-plane deformations of walls; (3) concrete carbonation testing; (4) laboratory tests to determine the mechanical properties of the concrete and steel rebars; (5) chloride content testing; (6) water penetration testing; (7) concrete testing with Schmidt hammer; (8) sonic testing; (9) color analysis based on spectrophotometry; (10) Ground Penetrating Radar (GPR) testing; (11) laboratory tests on a timber specimen; (12) laboratory tests on cement past samples.

These works allowed to conclude that the building presents The results obtained from the laboratory tests on cement moderate damage, namely several discrete cracks at the concrete walls, distributed cracking in some walls and corpaste samples allowed to obtain detailed data of the cement rosion of the steel rebars with detachment of the concrete. pastes, such as their chemical characterization, phases and The most severe steel corrosion was located at the bottom pore size. The highest critical pore, estimated from the mersurface o the slab of the South's storage room. The tanks cury intrusion porosimetry tests, was obtained in the sample (Phases 1 and 2.1) are made of cyclopean concrete with larcollected at the slab (bottom surface) of the South's storage ge stone aggregates (see Table 2). The walls (Phases 2.2-2.4) room, which presents steel corrosion. These tests allowed to present differences in terms of deterioration of the surfaces. conclude, as opposed to the results obtained from the concolor and permeability. The external surface of the tested wall crete carbonation tests with phenolphthalein on-site, that the of the changing rooms presented the lower water absorption concrete of all samples are carbonated. The sample collected (see Table 5), the highest compressive strength (estimated by from a surface previously covered with a switchboard of the the Schmidt hammer, see Table 6) and velocity of the P waves water treatment area (closed area) presents low carbonation. (obtained from direct sonic tests, see Table 7). The highest Moreover, they allowed to validate the results obtained from water absorption coefficient (1.00 kg/m².min0.5) occurs at the first tests, namely the presence of high chloride content the wall of the water treatment area (see Table 5). However, in the cement paste of the children's tank and bar, which is and for example, it is within the expected range for traditional also expected for all external surfaces of walls. It is also concement-based renders (0.2-1.5 kg/m².min0.5). A significant cluded that the physical, chemical and mechanical properties chloride content was detected in the concrete of the tanks of the concrete of the building present high dispersion, whiand the walls of the water collection area and bar (see Table ch is expected since corresponds to concretes made on-site 4), including higher the upper limit defined by the EN 206-1 and made in different phases, with different exposures (tanks, (1%). The two evaluated walls (content retaining wall and the wall without cover, closed areas) and different damage sevemain façade's North) do not present significant out-of-plane rity. However, it should be noted that the low percentage of deformations. The GPR tests allowed to estimate the connecsteel rebars is a crucial aspect so that the damage association between the upper beam and two orthogonal cantilever ted with the corrosion (carbonated concrete and presence of beams of the changing rooms (probable presence of four dochlorides) is not most severe. Finally, the presence of dilation wels, namely two dowels at each face, connecting the upper joints at the connection between walls and slabs prevented beam to the two orthogonal cantilever beams), and to concluthe occurrence of damage, at these connections, associated de that the walls present a low percentage of steel rebars. The with deformations caused by thermal actions. test for determining the tensile strength of the steel allowed

to conclude that the mean yield strength (fy,0.6fu) of steel specimens of the adults' tank (Phase 1) is equal to 238 MPa (Table 3), which corresponds to the steel of class A235 (Portuguese steel class for smooth rebars of normal ductility and yield strength equal or higher than 200 MPa). The two tested rebars of the slab of the South's storage room (Phase 3) present corrosion and mean yield strength (fy,0.6fu) of 294 MPa. The tests carried out in the timber specimen at the laboratory allowed to conclude that the species of the timber seems to be riga (pinus sylvestris) and presents high quality, resistance and density, and low moisture content.

Fig. 104 – MIP results: Logarithmic differential intrusion vs. pore size diameter.

APPENDIX E

Detailed tolerance for change assessment

	<image/>
Space	Entrance ramp and changing rooms hallway (1) (3)
Level of significance	Exceptional significance
Tolerance for change	Low tolerance
Description	Built between 1962 and 1965, both spaces are essential parts of the oriented spatial experience in which all users take part. The entrance ramp is the main access to the building, leading visitors inside through the accelerated perspective effect caused by its convergent walls. After leaving the dark atmosphere of the building's interior, it is in the changing rooms hallway that visitors experience their first contact with the exterior. The access path to the beach level goes around a high wall that prevents them from immediately seeing the ocean.
	During the last conservation works the precast white concrete slabs were washed and the chan- nel drainage gratings replaced. Two localized concrete repair interventions were undertaken in the changing rooms hallway west wall. All the cracks in the concrete that did not present struc- tural risks to the building were intentionally left open by Álvaro Siza as signs of the passage of time.
Considerations and opportunities for change	Any intervention in these spaces must be of conservation as their configuration and material are most important. The i) exposed concrete walls with horizontal formwork finish and the vi) precast white concrete slabs must be retained unaltered. The placement of foreign objects such as temporary signage totems should be avoided so as to keep the perception of the spaces unhindered.



Space	Changing rooms (2)
Level of significance	Exceptional significance
Tolerance for change	Low tolerance
Description	Built between 1962 and 1965, the an essential part of the oriented level and the interior of the bathi
	During the last conservation wor tionally, the electrical wiring was architectural design and in accord
Considerations and opportunities for change	Any intervention in this space r most important. The i) Baltic pin exposed concrete walls with ho doors and joinery with dark stat slabs must be retained unaltered
	There is some tolerance for char washes to respond to future need nt the overall coherence and opt
	There is some tolerance for chan networks to respond to future ne sibility of new elements should b

e changing rooms, with their dark and involving atmosphere, are I spatial experience, mediating the transition between the street hing complex.

orks all the wooden elements were cleaned and varnished. Addis placed inside exposed copper pipes, carefully integrated in the ordance to Álvaro Siza's design principles.

must be of conservation as its configuration and material are ne roof structure with dark stain and its copper cladding, ii) the orizontal formwork finish, iii) the Baltic pine partition walls, iv) ain, v) original brass fittings and vi) the precast white concrete ed.

ange in form or location of the vii) ceramic wash basins and foot eds. The replacement of any component should take into accout for similar models.

nge in form or location of viii) the exposed water and ix) electrical eeds. Nevertheless, only copper tubes are to be used and the vibe minimized, in compliance with Álvaro Siza's design principles.

Space	Collective changing room (21)
Level of significance	Moderate significance
Tolerance for change	Low tolerance
Description	Built between 1962 and 1965, the collective changing room's space was used as a storage room that was accessed by the chlorine cabinet when the Ocean Swimming Pool first opened to the public. It was only after 1972 that it took the configuration that we see today, with the addition of the wooden partition wall and benches and the marble foot wash.
	During the last conservation works all the wooden elements were cleaned and varnished. Addi- tionally, the electrical wiring was placed inside exposed copper pipes, carefully integrated in the architectural design and in accordance to Álvaro Siza's design principles.
Considerations and opportunities for change	Any intervention in this space must be of conservation as its configuration and material are most important. The i) Baltic pine roof structure with dark stain and its copper cladding, ii) the exposed concrete walls with horizontal formwork finish, iii) the Baltic pine partition walls, iv) doors and joinery with dark stain, v) original brass fittings, vi) the precast white concrete slabs must be retained unaltered and vii) the original marble foot wash must be retained unaltered.
	There is some tolerance for change in form or location of the viii) ceramic wash basins and foot washes to respond to future needs. The replacement of any component should take into account the overall coherence and opt for similar models.
	There is some tolerance for change in form or location of ix) the exposed water and x) electrical networks to respond to future needs. Nevertheless, only copper tubes are to be used and the vi-

sibility of new elements should be minimized, in compliance with Álvaro Siza's design principles.



Space	Cloakroom (15)
evel of significance	High significance
Folerance for change	Low tolerance
Description	Built between 1962 and 1965, the towards the entrance ramp and t reception of visitors, it still featu
	During the last conservation wo tionally, the opening towards the designed to support the recepti
Considerations and opportunities for change	Any intervention in this space is most important. The i) Baltic pir Baltic pine partition walls, iii) do the precast white concrete slabs
	There is some tolerance for char respond to future needs. Nevert elements should be minimized,

e cloakroom is located between the changing rooms and opens the changing rooms hallway. Even if today it mostly supports the ures a metallic structure to support hangers.

orks all the wooden elements were cleaned and varnished. Addie entrance ramp was enlarged and a new movable counter was ion of visitors.

must be of conservation as its configuration and material are ne roof structure with dark stain and its copper cladding, ii) the bors and joinery with dark stain, iv) original brass fittings and v) s must be retained unaltered.

inge in form or location of vi) the exposed electrical networks to heless, only copper tubes are to be used and the visibility of new in compliance with Álvaro Siza's design principles.


Space	Water treatment room and chlorine cabinet (18) (20)
Level of significance	Moderate significance
Tolerance for change	Moderate tolerance
Description	Built between 1962 and 1965, the water treatment room features the site's only concrete slab under copper cladding and is characterized by the strong presence of hydraulic equipment. The chlorine cabinet is located between the water treatment area and the changing rooms, fea- turing the chlorine tanks.
	During the last conservation works the plumbing system and equipment were replaced and updated.
Considerations and opportunities for change	The i) exposed concrete walls and roof slab with horizontal formwork finish, ii) the Baltic pine doors and joinery with dark stain, iii) original brass fittings and vi) the precast white concrete slabs must be retained unaltered as their configuration and material are most important.
	There is high tolerance for change of the iv) plumbing system which must be permanently up- dated to respond to the pool functioning needs.



Space	South bathrooms (13)
_evel of significance	High significance
Folerance for change	Low tolerance
Description	Built between 1962 and 1965, the destined to barefoot users. The horizontal volumes, extending the bathrooms' entrance.
	During the last conservation wo partition walls between the show ce under such direct exposure to posed copper pipes, carefully int Siza's design principles.
Considerations and opportunities for change	Any intervention in this space r most important. The i) Baltic pir exposed concrete walls with ho doors and joinery with dark sta slabs must be retained unaltered
	There is some tolerance for char vases to respond to future needs the overall coherence and opt for
	There is some tolerance for chan networks to respond to future ne

the south bathrooms are preceded by a foot wash as they are eir high wooden roof structure stands out from the otherwise to a porch over the changing rooms hallway that shelters the

orks all the wooden elements were cleaned and varnished. The wers were replaced by copper ones to improve their performanto water. Additionally, the electrical wiring was placed inside extegrated in the architectural design and in accordance to Álvaro

must be of conservation as its configuration and material are ne roof structure with dark stain and its copper cladding, ii) the orizontal formwork finish, iii) the Baltic pine partition walls, iv) ain, v) original brass fittings and vi) the precast white concrete ad.

nge in form or location of the vii) ceramic wash basins and toilet ls. The replacement of any component should take into account or similar models.

There is some tolerance for change in form or location of viii) the exposed water and ix) electrical networks to respond to future needs. Nevertheless, only copper tubes are to be used and the visibility of new elements should be minimized, in compliance with Álvaro Siza's design principles.



Space	Security room (22)
Level of significance	Moderate significance
Tolerance for change	High tolerance
Description	Built between 1970 and 1972, the security room is located under the roof garden and forms part of the building's extension towards south. It features white painted walls and an exposed concrete roof slab.
	During the last conservation works its roof slab and the exterior surface of its north wall were rebuilt. Additionally, the electrical wiring was placed inside exposed copper pipes, carefully integrated in the architectural design and in accordance to Álvaro Siza's design principles.
Considerations and opportunities for change	There is high tolerance for change in fabric or function as this is a technical area which should retain its role in supporting elements and functions of higher significance.



	Space	Water collection room (19)	
	Level of significance	Some significance	
Tolerance for change High tolerand		High tolerance	
	Description	Built between 1962 and 1965, the water collection room is located beneath the coastal avenue and is accessed through the south storage room.	
		During the last conservation works all the hydraulic and electrical infrastructures were replaced and updated, as were the metal doors.	
	Considerations and opportunities for change	There is high tolerance for change in form or fabric as this is a technical area which should retain its role in supporting elements and functions of higher significance.	



Space	South storage rooms (24) (25)
Level of significance	Moderate significance
Tolerance for change	Moderate tolerance
Description	Built between 1970 and 1972, th form part of the building's extensional slab.
	During the last conservation we was placed inside exposed copp accordance to Álvaro Siza's desi
Considerations and opportunities for change	The i) exposed concrete walls a unaltered.
	There is some tolerance for cha ments and functions of higher si
	There is some tolerance for char respond to future needs. Nevertl elements should be minimized,



Space	South platform (10)
Level of significance	High significance
Tolerance for change	Low tolerance
Description	Built between 1970 and 1972, this its ends, an amphitheatre was bu
	During the last conservation wor
Considerations and opportunities for change	Any intervention in this space r most important. Its continuous of and fabric are maintained.



he south storage rooms are located under the roof garden and nsion towards south. It features exposed concrete walls and roof

orks its roof slab was rebuilt. Additionally, the electrical wiring per pipes, carefully integrated in the architectural design and in ign principles.

and roof slab with horizontal formwork finish must be retained

ange in function as long as it retains its role in supporting eleignificance.

inge in form or location of ii) the exposed electrical networks to heless, only copper tubes are to be used and the visibility of new in compliance with Álvaro Siza's design principles.

is platform follows the building's extension to the south. In one of built in 1973 to clearly define the south limit of the site.

orks its continuous concrete pavement was replaced.

must be of conservation as its configuration and material are concrete pavement can be replaced if needed as long as form

Space	Beach and access paths (8) (4)	
Level of significance	Exceptional significance	
Tolerance for change	Low tolerance	
Description	Built between 1962 and 1965, the access paths to the swimming pools are composed of small exposed concrete platforms, staircases and walkways. Together with the beach and its rock outcrops configuration, they are an essential part of the oriented spatial experience, mediating the transition between the interior of the building and the swimming pools.	
	During the last conservation works the suspended walkway was rebuilt.	
Considerations and opportunities for change	Any intervention in this space must be of conservation as its configuration and material are most important. The i) beach and rock outcrops configuration, ii) the exposed concrete suspended walkway and iii) the exposed concrete platforms and staircases must be retained unaltered.	



Space	Swimming pools and foot washes (6) (7) (5)	
Level of significance	Exceptional significance	
Tolerance for change	Low tolerance	
Description	Designed in 1960, the adults swimming pool was the first part of the bathing complex to be built. It is nestled amongst the coastal rock outcrops, featuring cyclopean concrete walls only when necessary to contain the water. The children swimming pool, featuring a characteristic curve wall, and the foot washes were built between 1962 and 1965 and also seek to merge with their surrounding context following an organic design.	
	During the last conservation works the inner side of the adults swimming pool north and south walls was rebuilt, as was the children swimming pool wall, following the replacement of the buil- t-in plumbing. Additionally, a new technical gallery was built underneath the foot washes to ac- commodate the new plumbing.	
Considerations and opportunities for change	Any intervention in this space must be of conservation as its configuration and material are most important. The i) swimming pool configuration amongst the surrounding rocks, ii) the cyclopean concrete walls, iii) the foot washes configuration amongst the surrounding rocks and iv) the copper showers and removable access ladders must be retained unaltered.	



Space	West platform (11)
Level of significance	High significance
Tolerance for change	Low tolerance
Description	Built between 1962 and 1965, th south beach, linked by a ramp.
	During the last conservation wo
Considerations and opportunities for change	Any intervention in this space is most important. Its continuous and fabric are maintained.

ne west platform stands between both swimming pools and the

orks its continuous concrete pavement was replaced.

must be of conservation as its configuration and material are concrete pavement can be replaced if needed as long as form



Space	Bar and terrace (16) (9)
Level of significance	High significance
Tolerance for change	Low tolerance
Description	Built between 1970 and 1973, the bar features a curve counter that follows the outline of the wooden roof overhang, supported by a single pillar and a cantilever beam. Its triangular shaped terrace is sheltered from the predominant winds by a wall set in a 45° angle that interrupts the sequence of parallel walls to the coastal avenue retaining wall.
	During the last conservation works the wooden doors and shutters were replaced, with the lat- ter being changed from a folding mechanism to a sliding one. A new wooden partition wall was added before the wood pillar separating the curve section from the remaining counter space. Additionally, the electrical wiring was placed inside exposed copper pipes, carefully integrated in the architectural design and in accordance to Álvaro Siza's design principles. The terrace pa- vement was replaced, featuring built-in anchoring points for the sunshades.
Considerations and opportunities for change	Any intervention in this space must be of conservation as its configuration and material are most important. The i) Baltic pine roof structure with dark stain and its copper cladding, ii) the exposed concrete walls and curve counter with horizontal formwork finish, iii) Baltic pine doors and joinery with dark stain, iv) original brass fittings, v) the precast white concrete slabs and vi) the terrace furniture designed by Álvaro Siza must be retained unaltered.
	There is some tolerance for change in form or location of vii) the exposed water and viii) elec- trical networks to respond to future needs. Nevertheless, only copper tubes are to be used and the visibility of new elements should be minimized, in compliance with Álvaro Siza's design prin- ciples. Its continuous concrete pavement can be replaced if needed as long as form and fabric are maintained.



Space	Bar kitchen (17)
Level of significance	Moderate significance
Tolerance for change	High tolerance
Description	Built between 1970 and 1972, th the bar and the changing rooms
	During the last conservation we had been placed by the concess ced and updated. all the wood el wiring was placed inside expose and in accordance to Álvaro Siza
Considerations and opportunities for change	The i) Baltic pine roof structure v walls with horizontal formwork f tings and v) the precast white co
	There is high tolerance for chan appliances.
	There is some tolerance for cha trical networks to respond to fut the visibility of new elements sho ciples.



he bar kitchen is a narrow and enclosed space located between s hallway.

orks it was entirely remodeled and saw the stainless steel that sionaire removed. All infrastructures and equipment were replalements were cleaned and varnished. Additionally, the electrical ed copper pipes, carefully integrated in the architectural design a's design principles.

with dark stain and its copper cladding, ii) the exposed concrete finish, iii) doors and joinery with dark stain, iv) original brass fitoncrete slabs must be retained unaltered.

nge in form, fabric or location of the vi) kitchen equipment and

ange in form or location of vii) the exposed water and viii) electure needs. Nevertheless, only copper tubes are to be used and ould be minimized, in compliance with Álvaro Siza's design prin-

Space	North platform (12)
Level of significance	High significance
Tolerance for change	Low tolerance
Description	Built between 2018 and 2021, the north platform extends towards the north limit of the site whi- ch ends in a triangular configuration. Even though it formed part of the original designs since 1965 it had never been built. Its purpose was to connect the existing buildings with a restaurant that was to be built further north to limit the enclosure, while also protecting it from the prevai- ling winds.
Considerations and opportunities for change	Any intervention in this space must be of conservation as its configuration and material are most important. Its continuous concrete pavement can be replaced if needed as long as form and fabric are maintained.

|--|--|

Space	North bathrooms (14)
Level of significance	Moderate significance
Tolerance for change	Moderate tolerance
Description	Built between 1970 and 1972, the north bathrooms are located under the roof garden and form part of the building's extension towards north. They are destined to the exclusive use of shoed visitors.
	During the last conservation works the north volume was demolished and rebuilt in the same lo- cation. Nevertheless, the north bathrooms were placed further south and its internal layout was entirely redesigned to accommodate facilities for users with impaired mobility. Even though this space was entirely rebuilt, it was designed by Álvaro Siza himself in accordance to the design principles of the original construction.
Considerations and opportunities for change	The i) exposed concrete walls and roof slab with horizontal formwork finish, ii) the Baltic pine doors and joinery with dark stain, iii) brass fittings and iv) the continuous concrete pavement must be retained unaltered.



Space	Employee's changing rooms and
Level of significance	Some significance
Tolerance for change	High tolerance
Description	Built between 2018 and 2021, th der the roof garden and form pa entrance with the north storage servation works, it was designed of the original construction.
Considerations and opportunities for change	The i) exposed concrete walls a doors and joinery with dark stai must be retained unaltered.
	There is some tolerance for char vases to respond to future needs the overall coherence and opt for
	There is some tolerance for char networks to respond to future ne sibility of new elements should b

d bathrooms (23)

he employee's changing rooms and bathrooms are located unart of the building's rebuilt extension towards north. It shares its room. Even though this space was only built during the last cond by Álvaro Siza himself in accordance to the design principles

and roof slab with horizontal formwork finish, ii) the Baltic pine in, iii) brass fittings and iv) the continuous concrete pavement

inge in form or location of the v) ceramic wash basins and toilet ls. The replacement of any component should take into account or similar models.

nge in form or location of vi) the exposed water and vii) electrical eeds. Nevertheless, only copper tubes are to be used and the vibe minimized, in compliance with Álvaro Siza's design principles.

Area/function	North storage room and waste management room (26) (27)
Level of significance	Some significance
Tolerance for change	High tolerance
Description	Built between 1970 and 1972, the north storage room is located under the roof garden and forms part of the building's extension towards north.
	During the last conservation works the north volume was demolished and rebuilt in the same location. It retained a space destined to storage, to which a waste management room was added to fulfill with the current environmental standards. Even though this space was entirely rebuilt, it was designed by Álvaro Siza himself in accordance to the design principles of the original construction.
Considerations and opportunities for change	The i) exposed concrete walls and roof slab with horizontal formwork finish, ii) the Baltic pine doors and joinery with dark stain, iii) brass fittings and iv) the continuous concrete pavement must be retained unaltered.
	There is some tolerance for change in function as long as it retains its role in supporting ele- ments and functions of higher significance.
	There is some tolerance for change in form or location of v) the exposed electrical networks to respond to future needs. Nevertheless, only copper tubes are to be used and the visibility of new elements should be minimized, in compliance with Álvaro Siza's design principles.



Listing information

2936

retroactividade idêntica à da convenção. No entanto, as compensações das despesas de deslocação não são objecto de retroactividade, uma vez que se destinam a compensar despesas já feitas para assegurar a prestação de trabalho.

Atendendo a que a convenção regula diversas condições de trabalho, procede-se à ressalva genérica de cláusulas contrárias a normas legais imperativas.

A extensão da convenção tem, no plano social, o efeito de uniformizar as condições mínimas de trabalho dos trabalhadores e, no plano económico, o de aproximar as condições de concorrência entre empresas do mesmo sector.

Embora a convenção tenha área nacional, a extensão das convenções colectivas nas regiões autónomas compete aos respectivos Governos Regionais, pelo que a presente extensão apenas é aplicável no território do continente.

Foi publicado o aviso relativo à presente extensão no *Boletim do Trabalho e Emprego*, 1.ª série, n.º 13, de 8 de Abril de 2011, ao qual não foi deduzida oposição por parte dos interessados.

Assim:

Manda o Governo, pela Ministra do Trabalho e da Solidariedade Social, ao abrigo do artigo 514.º e do n.º 1 do artigo 516.º do Código do Trabalho, o seguinte:

Artigo 1.º

1 — As condições de trabalho constantes do contrato colectivo entre a GROQUIFAR — Associação de Grossistas de Produtos Químicos e Farmacêuticos e a FIEQUIMETAL — Federação Intersindical das Indústrias Metalúrgica, Química, Farmacêutica, Eléctrica, Energia e Minas, publicado no *Boletim do Trabalho e Emprego*, 1.ª série, n.º 8, de 28 de Fevereiro de 2011, são estendidas:

a) Às relações de trabalho entre empregadores não filiados na associação de empregadores outorgante que nos distritos de Beja, Castelo Branco, Évora, Faro, Leiria, Lisboa, Portalegre, Santarém e Setúbal exerçam a actividade de comércio por grosso de produtos farmacêuticos e ou veterinários e trabalhadores ao seu serviço das profissões e categorias profissionais nele previstas;

b) Às relações de trabalho entre empregadores filiados na associação de empregadores outorgante que no território do continente exerçam a actividade económica referida na alínea anterior e trabalhadores ao seu serviço das profissões e categorias profissionais previstas na convenção não representados pela associação sindical outorgante.

2 — A presente extensão não se aplica às relações de trabalho em que sejam parte empregadores filiados na NORQUIFAR — Associação Nacional dos Importadores/Armazenistas e Retalhistas de Produtos Químicos e Farmacêuticos.

3 — As retribuições previstas no anexo IV, inferiores à retribuição mínima mensal garantida, apenas são objecto de extensão nas situações em que sejam superiores à retribuição mínima mensal garantida resultante de redução relacionada com o trabalhador, de acordo com o artigo 275.º do Código do Trabalho.

4 — Não são objecto de extensão as disposições contrárias a normas legais imperativas.

Artigo 2.º

1 — A presente portaria entra em vigor no 5.º dia após a sua publicação no *Diário da República*.

Diário da República, 1.ª série—N.º 101—25 de Maio de 2011

2 — A tabela salarial e os valores das cláusulas de conteúdo pecuniário, à excepção do n.º 5 da cláusula 29.ª e do n.º 1 da cláusula 30.ª, produzem efeitos a partir de 1 de Janeiro de 2010.

3 — Os encargos resultantes da retroactividade poderão ser satisfeitos em prestações mensais de igual valor, com início no mês seguinte ao da entrada em vigor da presente portaria, correspondendo cada prestação a dois meses de retroactividade ou fracção e até ao limite de seis.

A Ministra do Trabalho e da Solidariedade Social, *Maria Helena dos Santos André*, em 18 de Maio de 2011.

MINISTÉRIO DA CULTURA

Decreto n.º 16/2011

de 25 de Maio

O presente decreto procede à classificação como monumentos nacionais da Casa do Passal, dos Concheiros de Muge, da Igreja do Carmo, do Terreiro da Batalha do Ameixial, do antigo Convento dos Eremitas de São Paulo da Serra de Ossa ou de Jesus Cristo, incluindo a cerca, do sistema de abastecimento de águas à cidade de Braga no século xvIII, designado por «Sete Fontes», da Casa de Chá da Boa Nova e das Piscinas de Marés de Leça da Palmeira.

De acordo com os critérios e os pressupostos de classificação previstos na Lei n.º 107/2001, de 8 de Setembro, que estabelece as bases da política e do regime de protecção e valorização cultural, os bens imóveis que o Governo classifica como monumentos nacionais revestem-se de excepcional interesse nacional, pelo que se torna imperativo que se lhes proporcione especial protecção e valorização, nos termos que a lei prevê.

O valor científico, patrimonial e cultural de cada um dos bens ora classificados articula-se segundo critérios como autenticidade, originalidade, raridade, singularidade e exemplaridade, que se revelam expressivamente no modo como foram apropriados pelos cidadãos e na relevância simbólica que adquiriram como lugares das artes e da memória histórica e política.

A Casa do Passal, também denominada «Vila de São Cristóvão», foi a residência de Aristides de Sousa Mendes e encontra-se localizada na Quinta de São Cristóvão, na freguesia de Cabanas de Viriato, concelho de Carregal do Sal.

Trata-se de um palacete cuja arquitectura, de inspiração francesa, se insere no gosto das *beaux-arts* do segundo império, estilo característico dos finais do século XIX e que se destaca não só pelo eclectismo da arquitectura e pela imponência da fachada principal, mas principalmente pela memória do cônsul que a habitou e sacrificou os interesses pessoais em prol dos refugiados do holocausto.

Aristides de Sousa Mendes ocupava o lugar de cônsul de Portugal em Bordéus quando, no decorrer da Segunda Guerra Mundial, passou vistos a milhares de refugiados, permitindo-lhes fugir e sobreviver às perseguições de que eram objecto, tendo, inclusivamente, alguns desses refugiados sido albergados na Casa do Passal.

A atitude de Aristides de Sousa Mendes, que salvou várias vidas, ditou-lhe também o fim da carreira diplomática, facto que teve um custo pessoal muito elevado, e que o deixou, em conjunto com a sua numerosa família, em péssima situação económica.

A relevância deste imóvel a nível nacional, não só em termos arquitectónicos mas também histórico-sociais, faz dele um lugar de memória, justificando-se, assim, a sua integral salvaguarda.

Os Concheiros de Muge, no concelho de Salvaterra de Magos, englobam os concheiros da Moita do Sebastião, do Cabeço da Amoreira e do Cabeço da Arruda e constituem uma das mais importantes estações arqueológicas da pré-história portuguesa, com grande projecção a nível nacional e internacional.

Devido ao seu incalculável valor científico, os Concheiros de Muge são citados em todos os manuais de préhistória da Europa e são inúmeros os trabalhos científicos realizados por académicos ou investigadores para o estudo e compreensão de muitos aspectos da vida quotidiana, dos rituais funerários e do comportamento dos nossos antepassados.

A Igreja da Nossa Senhora do Carmo, situada na Rua da Sofia, em Coimbra, é considerada um dos corolários das pesquisas arquitectónicas citadinas na linha evolutiva das primeiras edificações portuguesas de estrutura renascentista. Construída por iniciativa do bispo de Portalegre, D. Frei Amador Arrais, e concluída em 1597, a Igreja, tal como o seu claustro, encontra-se integrada no antigo Colégio do Carmo Calçado, fundado em 1542 pelo bispo do Porto, D. Frei Baltazar Limpo, e onde se encontra agora sediada a Ordem Terceira de São Francisco, e que merece destaque especial na categoria dos colégios universitários situados na Rua da Sofia.

A Igreja de Nossa Senhora do Carmo integra-se na tipologia das igrejas caixa, como uma original e consistente variação das mesmas. Apresenta uma fachada de grande simplicidade, constituída por altas pilastras dóricas sobre pedestais que a dividem em três secções, em que o pórtico ocupa toda a largura.

No interior, de nave única e cobertura em abóbada de berço aquartelada, destaca-se a capela-mor, onde se salienta o retábulo maneirista de talha dourada dos ensambladores e escultores Gaspar e Domingos Coelho e as pinturas maneiristas de Simão Rodrigues e Domingos Vieira Serrão, bem como as capelas laterais, com belos retábulos setecentistas das épocas joaninas e rococó e os retábulos em talha dourada e policromada das capelas dos flancos da nave, do século XVIII.

São ainda de realçar os azulejos da abside, seiscentistas e de fabrico lisboeta, as muitas esculturas de madeira, e o cadeiral, do coro-alto, de dois andares com 42 cadeiras dispostas em U, onde se podem ver, em oito espaldares, pinturas setecentistas da autoria de Pasquale Parente.

A batalha do Ameixial, de 1633, representa um momento fundamental para a manutenção de Portugal como país independente, inserindo-se numa forte ofensiva de Espanha sobre Portugal na reconquista do país perdido.

Ocorrida nos campos elevados do Ameixial, a cerca de 5 km a ocidente de Estremoz, esta batalha foi uma das mais violentas e esforçadas nas Guerras da Restauração, com importantes consequências tanto para Portugal como para Espanha. Para Portugal, a batalha do Ameixial foi a mais importante vitória militar da Restauração, resolvendo uma das situações mais perigosas que Portugal enfrentou durante o período de 1640 a 1668, enquanto que para Espanha a batalha contribuiu para reforçar a convicção, nomeadamente na Corte e na nobreza espanhola, de que seria praticamente impossível a submissão de Portugal pelas armas e que seria inútil o prosseguimento da luta.

Deste modo, com a batalha do Ameixial e a vitória das forças portuguesas comandadas pelo conde de Vila Flor, terminou uma das maiores ameaças à restauração da independência portuguesa.

Atento o grande valor arquitectónico e a importância artística do seu espólio, a Igreja de Santa Catarina, em Lisboa, foi classificada como monumento nacional pelo Decreto n.º 5046, publicado no *Diário do Governo*, n.º 268, de 11 de Dezembro de 1918, não se tendo, no entanto, incluído nesta medida de salvaguarda o restante conjunto edificado incluído no denominado «Convento dos Eremitas de São Paulo da Serra de Ossa» (Paulistas).

O Convento dos Eremitas da Serra de Ossa, da invocação do Santíssimo Sacramento, foi construído por esta Ordem em 1647. Os eremitas, inspirados pela figura de São Paulo, eram igualmente conhecidos por Eremitas de São Paulo ou de Jesus Cristo, razão pela qual o edifício conventual é conhecido por múltiplas designações.

Trata-se de uma construção austera, maneirista, junto à qual se ergue a Igreja de Santa Catarina. As fachadas são ritmadas por janelas idênticas, de verga recta, dispostas a espaços regulares, com janela de sacada em pedra encimada por frontão curvo no corpo principal. Conserva-se parte do claustro quadrangular com arcada de arcos redondos, um monumental corredor de acesso à zona das celas, o átrio de acesso à igreja de Santa Catarina, o espaço da antiga portaria, com azulejos do 1.º quartel do século xvIII, uma escadaria de mármore, a magnífica sacristia poligonal com estuques atribuíveis a João Grossi e dois belos lavabos, e ainda a biblioteca do exército, ocupando a antiga livraria conventual, ao modo da biblioteca do Convento de Mafra.

A importância histórica e arqueológica do que resta da antiga cerca conventual, como campo arqueológico de pesquisa do eventual segundo claustro, na ala norte e do prolongamento da ala poente do Convento, no aprofundamento do conhecimento histórico e arquitectónico do conjunto conventual e da marca da sua imponente massa arquitectónica na estrutura urbana à ilharga do Bairro Alto, justifica a integração da cerca na presente classificação.

O sistema de abastecimento de águas à cidade de Braga, designado por «Sete Fontes», foi construído em meados do século xvIII, sob a égide do arcebispo D. José de Bragança, destinado a dotar e a melhorar o abastecimento de água potável à cidade de Braga.

O sistema de abastecimento é composto pelo conjunto de condutas, galerias subterrâneas, mães de água e fontes, ainda existente, com cerca de 3500 m de extensão: cerca de 2250 m correspondem a galerias e os restantes correspondem às condutas de ligação, em manilha de pedra ou em tubo de ferro.

Subsistem 11 galerias de minas subterrâneas, algumas com braços de ramificação. As fontes mais a jusante registam na padieira da porta a data de 1744 e a fonte mais a montante a data de 1752.

Este conjunto é o testemunho de uma época (século XVIII, sob a égide do marquês de Pombal) em que se construíram, em Portugal, estruturas destinadas à melhoria de qualidade de vida dos cidadãos, representativas de um impulso ao urbanismo e à arquitectura barroca.

A concepção técnica desta obra representa, de forma material, a evolução de conceitos que se aplicaram na

engenharia hidráulica e que muito contribuíram para a qualificação de infra-estruturas urbanas.

Este sistema conserva quer o papel memorial original, quer as funções para as quais foi construído. Pese embora, por volta de 1930-1940, tenham sido introduzidas, em alguns dos seus troços, tubagens de ferro para evitar perdas aquíferas e facilitar a manutenção das condutas, não foram, porém, destruídas as estruturas existentes, permitindo que o sistema permaneça em actividade nos dias de hoje.

O sistema de abastecimento de águas à cidade de Braga é, pois, especialmente valorizado pelo seu significado cultural e por manter a sua autenticidade e integridade, representando um valor cultural inestimável de interesse nacional.

A Casa de Chá da Boa Nova, na freguesia de Leça da Palmeira, foi projectada e construída na sequência de um concurso levado a cabo pela Câmara Municipal de Matosinhos, em 1956. O arquitecto Fernando Távora, vencedor desse concurso, entregou o projecto a um dos seus colaboradores, Álvaro Siza Vieira, então ainda numa fase inicial da sua carreira. Esta obra, que decorre entre 1960 e 1963, marca uma nova etapa da produção arquitectónica modernista em Portugal e é hoje objecto de amplo reconhecimento internacional.

O edifício estabelece uma notável relação formal com a paisagem e com a topografia, através de uma implantação minuciosa, que utiliza as rochas e a impressiva paisagem marítima como parte integrante do projecto e do efeito cénico. O edifício, apesar disso, assume plenamente a sua condição artificial, com paredes brancas opacas e telhados de grande expressão plástica que se dissolvem no terreno. O percurso para a Casa de Chá é pensado de modo a acentuar o acto de entrada num espaço intimista, que amplia o efeito surpresa do visitante perante a espectacularidade da paisagem, que surge subitamente a partir do interior.

A classificação da Casa de Chá da Boa Nova fundamenta--se, assim, no valor arquitectónico e paisagístico do imóvel, obra exemplar e pioneira do arquitecto Siza Vieira, reconhecida internacionalmente como um marco na arquitectura modernista.

Também as Piscinas de Marés de Leça da Palmeira são um projecto da autoria do arquitecto Siza Vieira.

Projectadas em 1961, embora apenas concluídas em 1966, as Piscinas de Marés de Leça da Palmeira constituem uma realização notável pela capacidade de integração no sítio mas sem recurso a concessões miméticas, antes assumindo frontalmente o seu carácter artificial, que o rigor das formas e o betão à vista salientam.

Os edifícios estruturam-se ao longo do muro da praia de forma linear, sem criarem rupturas volumétricas, mas convidando, pelo desenho dos percursos e pela geometria dos muros, à contemplação da paisagem marítima. A capacidade de diálogo harmonioso com a envolvente, sem deixar de se afirmar a artificialidade da obra, é uma das características principais do trabalho inicial protagonizado por Siza Vieira, que encontra nas Piscinas de Marés de Leça da Palmeira um dos melhores exemplos em Portugal.

A classificação justifica-se pelo valor arquitectónico, urbanístico e paisagístico, mas também pelo valor histórico de uma obra que é já uma referência incontornável da arquitectura modernista e que permanece em plena utilização.

As zonas especiais de protecção dos bens imóveis agora classificados serão fixadas por portaria, nos termos do disposto no artigo 43.º da Lei n.º 107/2001, de 8 de Setembro.

Diário da República, 1.ª série-N.º 101-25 de Maio de 2011

Assim:

Ao abrigo do disposto no n.º 1 do artigo 28.º da Lei n.º 107/2001, de 8 de Setembro, e nos termos da alínea g) do artigo 199.º da Constituição, o Governo decreta o seguinte:

Artigo único

Classificação

São classificados como monumento nacional os bens imóveis a seguir identificados:

a) A Casa do Passal, também denominada «Vila de São Cristóvão», sita na Quinta de São Cristóvão, na freguesia de Cabanas de Viriato, concelho de Carregal do Sal e distrito de Viseu, conforme planta constante do anexo 1 do presente decreto, do qual faz parte integrante;

b) Os Concheiros de Muge — Moita do Sebastião, Cabeço da Amoreira e Cabeço da Arruda, na freguesia de Muge, concelho de Salvaterra de Magos e distrito de Santarém, conforme planta constante do anexo II do presente decreto, do qual faz parte integrante;

c) A Igreja do Carmo, sita na Rua da Sofia, freguesia de Santa Cruz, concelho e distrito de Coimbra, conforme planta constante do anexo III do presente decreto, do qual faz parte integrante;

d) O Terreiro da Batalha do Ameixial, nas freguesias de Santo Estêvão, Santa Vitória e São Bento do Ameixial, concelho de Estremoz e distrito de Évora, conforme planta constante do anexo IV do presente decreto, do qual faz parte integrante;

e) O antigo Convento dos Eremitas de São Paulo da Serra de Ossa ou de Jesus Cristo (Paulistas), incluindo a cerca, sito na Calçada do Combro, freguesia de Santa Catarina, concelho e distrito de Lisboa, conforme planta constante do anexo v do presente decreto, do qual faz parte integrante;

f) O sistema de abastecimento de águas à cidade de Braga no século XVIII, designado por «Sete Fontes de São Victor», freguesia de São Victor, concelho e distrito de Braga, conforme planta constante do anexo vi do presente decreto, do qual faz parte integrante;

g) A Casa de Chá da Boa Nova, na freguesia de Leça da Palmeira, concelho de Matosinhos e distrito do Porto, conforme planta constante do anexo vii do presente decreto, do qual faz parte integrante;

h) As Piscinas de Marés de Leça da Palmeira, na freguesia de Leça da Palmeira, concelho de Matosinhos e distrito do Porto, conforme planta constante do anexo VIII do presente decreto, do qual faz parte integrante.

Visto e aprovado em Conselho de Ministros de 3 de Março de 2011. — José Sócrates Carvalho Pinto de Sousa. — Maria Gabriela da Silveira Ferreira Canavilhas.

Assinado em 14 de Abril de 2011.

Publique-se.

O Presidente da República, ANÍBAL CAVACO SILVA.

Referendado em 18 de Abril de 2011.

O Primeiro-Ministro, José Sócrates Carvalho Pinto de Sousa.

Diário da República, 1.ª série—N.º 101—25 de Maio de 2011

ANEXO I

[alínea a) do artigo único]



ANEXO II

[alínea b) do artigo único]



2939

ANEXO III

[alínea c) do artigo único]



ANEXO IV

[alínea d) do artigo único]



Concelho de Lisboa Freguesia de Santa Catarina Lugar de Lisboa

Limite do conjunto classificado

Diário da República, 1.ª série—N.º 101—25 de Maio de 2011

ANEXO VII

MC

APPENDICES

ANEXO V [alínea e) do artigo único]

ANEXO VI [alínea f) do artigo único]

Sistema de captação do abastecimento de água do século XVIII à cidade de Braga - «Sete Fontes de S. Vitor»

Concelho de Braga Freguesia de Braga (São Vitor)



ANEXO VIII

[alínea h) do artigo único]



M



APPENDIX G

Admission conditions and user regulations

OCEAN SWIMMING POOL ADMISSION CONDITIONS

(adopted by Matosinhos Sport on April 29, 2021)

Free and guided tours

Free visits during the bathing season, without the right to use the swimming pool, have a cost of $2 \in$. Guided tours for groups (min. 5 - max. 25 participants) organized by Casa da Arquitectura are carried out in Portuguese or English with a duration of 45 to 60 minutes. The visit has a cost of $5 \in$ and must be booked in advance through the email visitas@casadaarquitectura.pt.

Capacity and entrance control

The entry of customers into the facility and participation in activities may be suspended when the capacity Is full. In case of full capacity, Matosinhos Sport cannot allow entry to any other customer, even those who benefit from priority service.

Matosinhos Sport responsibility

The organization and operation of the Ocean Swimming Pool and the establishment of schedules and prices are responsibility of Matosinhos Sport.

Access rights

The access to the installation, services and activities of the Ocean Swimming Pool is subjected to the terms provided in the regulation.

Access admission

The right of admission to the Ocean Swimming Pool is subjected to the payment of the usage fees defined in the respective fee list (posted in a visible place).

Children access

Children under the age of 13 must be accompanied by an adult. It is mandatory to present a citizen's card or identity card to confirm their age.

Access entrance ticket

The half-day rate applies to entries from 9:00 until 14:00, or access from 14:00, until closing time.

Availability

Benefits, promotions and discounts are subject to confirmation of availability and legitimacy in order to be applied.

Cancellation

Matosinhos Sport reserves the right to cancel and/or change at any time the benefits, promotions and discounts due to its commercial policy, which the customer acknowledges and accepts.

Wristband identification

A wristband identification will be given at the entrance by the reception service. The use of the wristband, with color that shows the type of ticket purchased (half-day or full-day), is mandatory, and it must be always visible for access control and surveillance. The wristband is of personal and non-transferable nature. Breaking this rule implies the expulsion from the building and the payment of a daily entry.

Wristband use period

The customer must keep the ticket and wristband until the site is closed.

10 days access card

Card promotion with access for ten days are available. The prices for adults and children are differentiated according to their use (full day or half day).

Commercial activities access

Any commercial activity like photography, filming, events, among others, might occur upon previous request and appointment with Matosinhos Sport through the email piscinamares@ matosinhosport.com.

Groups reservations

Reservations of space or groups appointments upon previous request with Matosinhos sport, through the email piscinamares@matosinhosport.com

Building closure due weather conditions

Matosinhos Sport is not responsible for the full or partial closure of the installation when there are adverse weather conditions, not granting the customer any deduction or refund on the usage fee.

OCEAN SWIMMING POOL USER REGULATIONS

(adopted by Matosinhos Sport on April 29, 2021)

Regulation purpose

to the Ocean Swimming Pool and the respective use of the installation and equipment.

Reception information

The reception must provide customer service with information on prices, usage rules, and capacity. Also, it will always display the temperature, pH and chlorine information of each pool.

Pool clothing

It is not allowed to remain inside the pool tanks with shoes or clothing not suitable for the aquatic environment.

Babies clothing

It is not allowed the entry of babies without the use of nappies appropriate to the aquatic environment.

Technical areas' permanence

The permanence of the general public in technical areas reserved for staff is prohibited.

Use of equipment

Swimming pool support elements (showers, foot washes, sanitary ware, etc.) must be handled with care.

Damages

Any damage will be charged to its author(s), under the expenses fixed by Matosinhos Sport.

Loss of objects and personal accidents

Matosinhos Sport is not responsible for damages resulting from loss or theft of objects inside the enclosure of the Ocean Swimming Pool unless found and delivered to the lost and found services of the installation.

Photograph

Users must respect privacy and image rights, refraining from photographing or filming other customers (unless authorized).

Animals

The entry of animals is prohibited (except for service animals).

Food

The purpose of this regulation is to define the customer access It is not allowed to eat, consume alcoholic beverages and smoke in all water activities zones.

Bar concession damage

Any damage, issue or conflict arising from the concession of the bar is the complete responsibility of its management. The bar must have appropriate documentation and licenses and the corresponding complaints book.

Regulation changes

This regulation may be amended by Matosinhos Sport whenever it deems convenient.

Regulation appliance

This regulation enters into force the day after its approval.

Limit control

It is forbidden to exceed the limits of the building capacity. Any person who breaches the limits will be expelled from the site with an obligation to pay an entrance fee. The use of part or all the facilities may be limited to carry out specific activities (such as construction works, maintenance, cultural or sporting events, among others). Matosinhos Sport commits to notify all customers of this limitation with due advance notice, through a message posted in a visible place, without granting any kind of deduction in the entrance fees to the customer.

Service Changes

Due to the permanent updating of sports and leisure activities, or due to changes in its commercial policy, Matosinhos Sport reserves the right at any time to add or change the services provided, as well as the equipment and activities available at the facility to safeguard the best interests of customers. These measures must be acknowledged and accepted by the customer.

Showers

It is mandatory to shower and go through the foot washes before entering the tanks.

Prohibited activities in the swimming pool Jumping into the water is not allowed. Games or activities likely to cause danger or harm the physical integrity of people and goods, namely with balls or rackets, are not allowed. **Prohibited objects** The entry and/or use of sharp objects (bottles, knives, among others) are not allowed in the entire pool area, except at the bar. Prohibited beach elements It is not allowed the entry of parasols, windscreens, awnings, or other similar objects, nor beach chairs, except for mini tents for babies. **Beach elements support** The support elements for the beach, such as parasols or chairs, can be rented at the bar concessionaire. **Dock footwear** It is not allowed to use, in the dock area (the area surrounding the pool tanks), any footwear other than slippers/sandals, except in situations of emergency or professional need. Dock behavior In the dock area, it is not allowed to run, jump, push or have any other type of behavior that puts the physical integrity of other customers at risk. Sound devices The use of sound emission equipment is not allowed. From time to time. Matosinhos Sport is allowed to conduct classes or activities that uses sound and music. **Failure regulation** Failure to comply with this regulation and the practice of harmful acts may result in verbal warnings or expulsion from the premises, depending on the gravity of the case. Exceptional cases Exceptional cases will be judged in the first instance by the most responsible person present in the installation (the Head of Division of the Building) and then by the Board of Directors of Matosinhos Sport.

IMAGE CREDITS

Image Credits

Cover | Inês d'Orey (2021)

1. Introduction

Chapter opener | Inês d'Orey (2021)

2. Understanding the Place

Chapter opener | Inês d'Orev (2021)

Figure 2.1 | Municipal Archive of Matosinhos

Figure 2.2 | Municipal Archive of Porto

Figure 2.3 | Municipal Archive of Matosinhos

Figure 2.4 | A. Vieira (1950) Municipal Archive of Matosinhos

Figure 2.5 | Sindicato Nacional do Arquitectos (1961) Arquitectura Popular em Portugal. Lisboa: Sindicato Nacional dos Arauitectos

Figure 2.6 | Luiz Trigueiros (1993) Fernando Távora. Lisboa Editorial Blau

Figure 2.7 | Mário Novais, 1966, Calouste Gulbenkian Foundation

Figure 2.8-2.9 | Roberto Collovà

Figure 2.10 | Foto Beleza (1947) Espólio Fotográfico Português

Figure 2.11 | Foto Beleza (1947) Municipal Archive of Matosinhos

Figure 2.12 | Álvaro Siza, Álvaro Siza fonds, Canadian Centre for Architecture

Figure 2.13 | Álvaro Siza fonds, Canadian Centre for Architecture

Figure 2.14-2.15 | (1960) Municipal Archive of Matosinhos

Figure 2.16 | A. Vieira (1961) Municipal Archive of Matosinhos

Figure 2.17 | Álvaro Siza (1961) Álvaro Siza fonds, Canadian Centre for Architecture

Figure 2.18 | Bernardo Ferrão (1960) Municipal Archive of Matosinhos

for Architecture

Figure 2.20 | Álvaro Siza (1962) Álvaro Siza fonds. Canadian Centre for Architecture

Figure 2.21 | Álvaro Siza fonds, Canadian Centre for Architecture

Figure 2.22 | A. Vieira (1968) Municipal Archive of Matosinhos

Figure 2.23 | Álvaro Siza fonds, Canadian Centre for Architecture

Figure 2.24-2.25 | Álvaro Siza (1965) Álvaro Siza fonds, Canadian Centre for Architecture

Figure 2.26 | Álvaro Siza, Álvaro Siza fonds, Canadian Centre for Architecture

Figure 2.27 | Álvaro Siza (1965) Álvaro Siza fonds. Canadian Centre for Architecture

Figure 2.28 | Álvaro Siza, Brigitte Fleck

Figure 2.29-2.30 | Álvaro Siza fonds, Canadian Centre for Architecture

Figure 2.31 | Álvaro Siza (1973) Municipal Archive of Matosinhos

Figure 2.32-2.34 | (1995) Álvaro Siza fonds. Canadian Centre for Architecture

Figure 2.35 | Álvaro Siza (1995) Álvaro Siza fonds, Canadian Centre for Architecture

Figure 2.36 | Pixel (2021)

Figure 2.37 | Ocean Swimming Pool CMP (2023) Adapted from Álvaro Siza's drawings (2018)

Figure 2.38-2.39 | Ocean Swimming Pool CMP (2023)

Figure 2.40 | Álvaro Siza (1973) Álvaro Siza fonds, Canadian Centre for Architecture

Figure 2.41 | Bernardo Ferrão (1966) Municipal Archive of Matosinhos

Figure 2.42-2.43 | Rui Mota (1971) Documentation Centre for Urbanism and Architecture of the Faculty of Architecture of the University of Porto

Figure 2.44 | Bernardo Ferrão (1965) Municipal Archive of Matosinhos

Figure 2.45 | Rui Mota (1971) Documentation Centre for Urbanism and Architecture of the Faculty of Architecture of the University of Porto

Figure 2.46 | Almeida, P. V. (1967) "Un análisis de la obra de Siza Vieira", Hogar y Arquitectura, 68.

Figure 2.47 | Almeida, P. V. (1967) "Uma análise da obra de Siza Vieira" and "Três obras de Álvaro Siza Vieira: Cooperativa de Lordelo. Casa unifamiliar em Maia. Piscina de Leça", Arguitectura: Revista de Arte e Construção, 96

Figure 2.19 | Álvaro Siza, Álvaro Siza fonds, Canadian Centre Figure 2.48 | Bohigas, O. (1976) "Álvaro Siza Vieira", Bis, 12

Figure 2.49 | Gregotti, V. and Bohigas, O. (1976) "La passion d'Alvaro Siza", L'Architecture d'Aujourd'hui: Portugal, 185

Figure 2.50 | Gregotti, V. (ed.) (1979) Padiglione d'Arte Contemporanea di Milano: ALVARO SIZA Architetto 1954-1979. Milano: Idea Books

Figure 2.51 | Salgado, J. (1985) Álvaro Siza em Matosinhos. Matosinhos: CMM

Figure 2.52 | Siza, A. (1986) Álvaro Siza: Poetic Profession. Milano/New York: Electa/Rizzoli

Figure 2.53 | Moura, E. S. (1986) "La Piscina de Leça, 25 años después", Arquitectura: Revista del COAM, 261

Figure 3.32 | Teresa Cunha Ferreira (2021) Figure 3.33 | Frederico Barbosa (2021) Figure 2.54 | Ganshirt, C. (2004) 1959-73 Swimming Pool on Figure 3.34 | (2022) Faculty of Architecture of the University of Porto Figure 2.55 | Toussaint, M. and Melo, M. (coord.) (2016) Pisci-Figure 3.35 | David Ordóñez Castañón (2022) Figure 3.36 | (2022) Faculty of Architecture of the University Figure 2.56 | Frampton, K. (2016) Álvaro Siza Vieira in conof Porto versation with Kenneth Frampton: a pool in the sea. Chicago: IITAC Figure 3.37 | David Ordóñez Castañón (2022) Figure 2.57 | João Morgado (2014) Figure 3.38 | (2022) Faculty of Architecture of the University of Porto Figure 2.58 | Ocean Swimming Pool CMP (2023) Adapted from Álvaro Siza's drawings (2018) Figure 3.39 | David Ordóñez Castañón (2022) Figure 2.59 | Ocean Swimming Pool CMP (2023) Figure 3.40 | Ana Resende (2022) Figure 3.41 | Ocean Swimming Pool CMP (2023) 3. Assessment of Significance Figure 3.42 | Inês d'Orey (2021) Chapter opener | Inês d'Orey (2021) Figure 3.43 | Ocean Swimming Pool CMP (2023) Adapted from Álvaro Siza's drawings (2018) Figure 3.1 | (2011) Decree No. 16/2011 Figure 3.44 | Ocean Swimming Pool CMP (2023) Figure 3.2 | (2012) Ordinance No. 608/2012 Figure 3.45 | Inês d'Orey (2021) Figure 3.3 | Inês d'Orey (2021)

the Beach at Leca da Palmeira: Álvaro Siza, Lisboa: Blau na na praia de Leça: a pool on the beach. Lisboa: A+A Books

Figure 3.4 | Álvaro Siza fonds, Canadian Centre for Architecture

Figure 3.5 | Roberto Collovà

Figure 3.6 | Ocean Swimming Pool CMP (2023) Adapted from UNESCO database

Figure 3.7 | Álvaro Siza fonds, Serralves Foundation

Figure 3.8 | (1936) Archives Municipales de Saint-Malo

Figure 3.9 | Sam Hood (1935) Library of New South Wales

Figure 3.10 | The Box Plymouth

Figure 3.11 | Ocean Swimming Pool CMP (2023)

Figure 3.12 | Ocean Swimming Pool CMP (2023) Adapted from Figure 4.50-4.53 | Ocean Swimming Pool CMP (2023) Adapthe 'Imagine Ballarat' methodology (City of Ballarat, 2013) ted from Álvaro Siza's drawings (2018)

Figure 3.13 | Ocean Swimming Pool CMP (2023) Adapted from Tarrafa Silva and Pereira Roders taxonomy of cultural values (Tarrafa Silva and Pereira Roders, 2012)

Figure 3.14-3.20 | Ocean Swimming Pool CMP (2023)

Figure 3.21-3.22 | Ocean Swimming Pool CMP (2023) Poll Everywhere app

Figure 3.23-27 | Ocean Swimming Pool CMP (2023)

Figure 3.28-3.29 | Rui Murka (2022)

Figure 3.30 | (2022) Faculty of Architecture of the University of Porto

Figure 3.31 | Rui Murka (2022)

4. Condition Assessment, Conservation and Risks

Chapter opener | Inês d'Orey (2021)

Figure 4.1 | Inês d'Orey (2021)

Figure 4.2 | Teresa Cunha Ferreira (2020)

Figure 4.3 | Teresa Cunha Ferreira (2020)

Figure 4.4-4.13 | Frederico Barbosa (2019-2020)

Figure 4.14 | Ocean Swimming Pool CMP (2023) Adapted from Álvaro Siza's drawings (2018)

Figure 4.15-4.49 | Nuno Mendes (2020)

Figure 4.54-4.63 | Frederico Barbosa (2019)

Figure 4.64 | Ocean Swimming Pool CMP (2023) Adapted from Álvaro Siza's drawings (2018)

Figure 4.65-4.74 | Frederico Barbosa (2019-2020)

Figure 4.75 | Ocean Swimming Pool CMP (2023) Adapted from Álvaro Siza's drawings (2018)

Figure 4.76-4.85 | Inês d'Orev (2021)

Figure 4.86 | Ocean Swimming Pool CMP (2023) Adapted from Álvaro Siza's drawings (2018)

Figure 4.87 | Frederico Barbosa (2019-2021)

Figure 4.88-4.89 | Inês d'Orey (2021)

Figure 4.90-4.91 | Frederico Barbosa (2019-2021)

Figure 4.92 | Ocean Swimming Pool CMP (2023) Adapted from Álvaro Siza's drawings (2018)

Figure 4.93-4.116 | Frederico Barbosa (2021)

Figure 4.117 | Inês d'Orey (2021)

Figure 4.118-4.129 | Frederico Barbosa (2021)

Figure 4.130 | Inês d'Orey (2021)

Figure 4.131 | Adapted from Campos et al. (2019)

Figure 4.132-135 | Adapted from Antunes et al. (2017)

Figure 4.136-4.137 | Ocean Swimming Pool CMP (2023)

Figure 4.138-4.141 | (2017-2019) Civil Protection Department of the Municipal Council of Matosinhos

Figure 4.142 | Ocean Swimming Pool CMP (2023) Adapted from maps of the Civil Protection Department of the Municipal Council of Matosinhos

Figure 4.143 | (2018) Civil Protection Department of the Municipal Council of Matosinhos

Figure 4.144 | Ocean Swimming Pool CMP (2023)

5. Management and Conservation Policies

Chapter opener | Inês d'Orey (2021)

Figure 5.1 | Ocean Swimming Pool CMP (2023)

Figure 5.2 | Ana Resende (2022)

Figure 5.3-5.4 | Ocean Swimming Pool CMP (2023)

Figure 5.5 | Ocean Swimming Pool CMP (2023) Adapted from UN 2030 Agenda

Figure 5.6 | Frederico Barbosa (2021)

Figure 5.7 | (2023) Matosinhos Sport

Figure 5.8 | Ocean Swimming Pool CMP (2023)

Figure 5.9-5.10 | Frederico Barbosa (2021)

Figure 5.11 | Álvaro Siza (1973) Álvaro Siza fonds, Canadiar Centre for Architecture

Figure 5.12 | Ocean Swimming Pool CMP (2023)

Figure 5.13 | Municipal Master Plan of Matosinhos, Heritage Map (2019)

Figure 5.14 | Caminha Espinho Coastal Zone Program (2021)

Figure 5.15 | Ocean Swimming Pool CMP (2023) Adapted from drawings of the Municipal Master Plan of Matosinhos

Figure 5.16 | (2018) Civil Protection Department of the Municipal Council of Matosinhos

Figure 5.17-5.18 | Ocean Swimming Pool CMP (2023) Adapted from Álvaro Siza's drawings (2018)

Figure 5.19-5.20 | Pixel (2021)

Figure 5.21 | (2021) Municipal Council of Matosinhos

Figure 5.22 | Inês d'Orey (2021)

Figure 5.23 | Frederico Barbosa (2021)

Figure 5.24-5.25 | Inês d'Orey (2021)

Figure 5.26 | Pixel (2021)

Figure 5.27-5.28 | Inês d'Orey (2021)

Figure 5.29 | Frederico Barbosa (2021)

Figure 5.30-5.33 | Ocean Swimming Pool CMP (2023) With photographs by Inês d'Orey

Figure 5.34-5.35 | Ocean Swimming Pool CMP (2023) Adapted from SizaATLAS

Figure 5.36 | A. Vieira (1968) Municipal Archive of Matosinhos

Figure 5.37 | Álvaro Siza (1966) Álvaro Siza fonds, Canadian Centre for Architecture

Figure 5.38 | Álvaro Siza fonds, Canadian Centre for Architecture

Figure 5.39 | Álvaro Siza (1965) Álvaro Siza fonds, Canadian Centre for Architecture

Figure 5.40 | Frederico Barbosa (2021)

Figure 5.41-5.42 | Álvaro Siza fonds, Canadian Centre for Architecture

Figure 5.43 | Álvaro Siza (1965) Álvaro Siza fonds, Canadian Centre for Architecture

Figure 5.44-5.45 | Frederico Barbosa (2020)

Figure 5.46-5.47 | Rui Mota (1971) Documentation Centre for Urbanism and Architecture of the Faculty of Architecture of the University of Porto

Figure 5.48 | Bernardo Ferrão (1965) Municipal Archive of Matosinhos

Figure 5.49 | GOP (2018)

Figure 5.50 | Frederico Barbosa (2019)

Figure 5.51-5.52 | Rui Mota (1971) Documentation Centre for Urbanism and Architecture of the Faculty of Architecture of the University of Porto

Figure 5.53 | Bernardo Ferrão (1965) Municipal Archive of Matosinhos

Figure 5.54 | GOP (2018)

Figure 5.55 | Frederico Barbosa (2019)

Figure 5.56-5.57 | Álvaro Siza fonds, Canadian Centre for Architecture

Figure 5.58 | Bernardo Ferrão (1966) Municipal Archive of Matosinhos Figure 5.59 | Bernardo Ferrão (1965) Municipal Archive of Matosinhos Figure 5.91 | Álvaro Siza fonds, Canadian Centre for Architecture

Figure 5.60 | GOP (2018)

Figure 5.61 | Frederico Barbosa (2019)

Figure 5.62 | Álvaro Siza fonds, Canadian Centre for Architecture

Figure 5.63-5.64 | Álvaro Siza (1964) Álvaro Siza fonds, Canadian Centre for Architecture

Figure 5.65 | Frederico Barbosa (2020)

Figure 5.66 | Inês d'Orey (2021)

Figure 5.67 | Álvaro Siza (2018)

Figure 5.68 | A. Vieira (1968) Municipal Archive of Matosinhos

Figure 5.69 | Álvaro Siza fonds, Canadian Centre for Architecture

Figure 5.70 | Álvaro Siza (1965) Álvaro Siza fonds, Canadian Centre for Architecture

Figure 5.71 | Frederico Barbosa (2020)

Figure 5.72-5.74 | Inês d'Orey (2021)

Figure 5.75 | Rui Mota (1971) Documentation Centre for Urbanism and Architecture of the Faculty of Architecture of the University of Porto

Figure 5.76 | Bernardo Ferrão (1966) Municipal Archive of Matosinhos

Figure 5.77 | Rui Mota (1971) Documentation Centre for Urbanism and Architecture of the Faculty of Architecture of the University of Porto

Figure 5.78 | GOP (2018)

Figure 5.79 | Frederico Barbosa (2020)

Figure 5.80 | GOP (2018)

Figure 5.81 | Frederico Barbosa (2020)

Figure 5.82 | Álvaro Siza fonds, Canadian Centre for Architecture

Figure 5.83 | Álvaro Siza (1964) Álvaro Siza fonds, Canadian Centre for Architecture

Figure 5.84 | Álvaro Siza (2018)

Figure 5.85-5.86 | Inês d'Orey (2021)

Figure 5.87 | (1995) Álvaro Siza fonds, Canadian Centre for Architecture

Figure 5.88 | Álvaro Siza (1963) Álvaro Siza fonds, Canadian Centre for Architecture

Figure 5.89 | Álvaro Siza (1964) Álvaro Siza fonds, Canadian Centre for Architecture

Figure 5.90 | Pixel (2021)

Figure 5.92 | Álvaro Siza (1964) Álvaro Siza fonds, Canadian Centre for Architecture

Figure 5.93 | Álvaro Siza (1973) Álvaro Siza fonds, Canadian Centre for Architecture

Figure 5.94 | Álvaro Siza (2018)

Figure 5.95 | Inês d'Orey (2021)

Figure 5.96 | A. Vieira (1968) Municipal Archive of Matosinhos

Figure 5.97-5.98 | Álvaro Siza (1965) Álvaro Siza fonds, Canadian Centre for Architecture

Figure 5.99 | A. Vieira (1961) Municipal Archive of Matosinhos

Figure 5.100 | GOP (2018)

Figure 5.101 | Inês d'Orey (2021)

Figure 5.102 | Álvaro Siza fonds, Canadian Centre for Architecture

Figure 5.103-5.104 | Bernardo Ferrão (1965) Municipal Archive of Matosinhos

Figure 5.105-5.106 | Frederico Barbosa (2021)

Figure 5.107-5.108 | Álvaro Siza fonds, Canadian Centre for Architecture

Figure 5.109 | (1965) Municipal Archive of Matosinhos

Figure 5.110-5.111 | Inês d'Orey (2021)

Figure 5.112 | GOP (2018)

Figure 5.113 | Frederico Barbosa (2021)

Figure 5.114 | Ocean Swimming Pool CMP (2023)

Figure 5.115 | Inês d'Orey (2021)

Figure 5.116-5.119 | Frederico Barbosa (2021)

Figure 5.120 | Ocean Swimming Pool CMP (2023)

Figure 5.121-5.123 | Frederico Barbosa (2021)

Figure 5.124 | Luís Ferreira Alves (1992)

Figure 5.125-5.127 | Frederico Barbosa (2021)

Figure 5.128-5.130 | Ocean Swimming Pool CMP (2023)

6. Monitoring Chapter opener | Inês d'Orey (2021) Figure 6.1-6.3 | Ocean Swimming Pool CMP (2023) Figure 6.4 | Inês d'Orey (2021)

Figure 6.5-6.11 | Ocean Swimming Pool CMP (2023)

Managing change with a living architect OCEAN SWIMMING POOL BY ÁLVARO SIZA CONSERVATION MANAGEMENT PLAN

Project leader

Teresa Cunha Ferreira (FAUP, University of Porto)

Senior consultants

Rui Fernandes Póvoas (FAUP, University of Porto) Paulo B. Lourenço (EEUM, University of Minho) Ana Tostões (Técnico, University of Lisbon)

Junior consultants

Hugo Mendonça (FAUP, University of Porto) Frederico Barbosa (FAUP, University of Porto) Raquel Matos (FAUP, University of Porto) Constanza Frigolett (FAUP, University of Porto) Juan Piedrahita (FAUP, University of Porto) Carmen Fernández-Muñoz (FAUP, University of Porto) Jonas Barbosa (FAUP, University of Porto)

Graphic Design

Ana Resende Luís Sousa Teixeira

Photography

Inês d'Orey

Editing Hugo Mendonça (FAUP, University of Porto)

Funding

Getty Foundation, Los Angeles, California

Project hosted by

Centre for Studies in Architecture and Urbanism (CEAU) Faculty of Architecture of the University of Porto (FAUP)

Institutional Partnership

Câmara Municipal de Matosinhos

Institutional Support

Canadian Centre for Architecture (CCA) ICOMOS Portugal

Collaborations

Luís Urbano (FAUP, University of Porto) José Miguel Rodrigues (FAUP, University of Porto) Joaquim Teixeira (FAUP, University of Porto) Pedro Murilo Freitas (FAUP, University of Porto) José Pedro Sousa (FAUP, University of Porto) Filipa Guerreiro (FAUP, University of Porto) Clara Vale (FAUP, University of Porto) Hugo Pires (FAUP, University of Porto) Patrícia Rocha (FEUP, University of Porto) Ana Tarrafa Silva (TU Delft/CEAU) Xavier Romão (FEUP, University of Porto) Teresa Portela Marques (FCUP, University of Porto) Eduardo Fernandes (EAAD, University of Minho) Nuno Mendes (EEUM, University of Minho) Judite Miranda (Técnico, University of Lisbon) Jonatas Valença (Técnico, University of Lisbon) Hugo Costa (ISEC, Polytechnic of Coimbra) Eduardo Júlio (Técnico, University of Lisbon) Pedro Antunes (Cinábrio Restauro)

'Sharing Memories'

João Pedro Xavier, Nuno Sampaio, Susan Macdonald, Alexandre Alves Costa, Dominique Machabert, Michel Toussaint, Nuno Grande, Brigitte Fleck, Pierluigi Nicolin, Christian Ganshirt, Roberto Cremascoli, Wilfried Wang, Peter Testa, Carlos Machado, Juan Domingo Santo, Jonathan Sergison, Luis Martinez Santa-Maria, Nuno Brandão Costa, Teresa Novais, Ana Alves Costa, José Cabral Dias, Giovanni Chiaramonte, Pedro Leão Neto, Joaquim Moreno

Álvaro Siza / GOP

Álvaro Siza, Anabela Monteiro, Chiara Porcu, Rita Amaral, Jorge Nunes da Silva, Raquel Dias

Câmara Municipal de Matosinhos / Matosinhos Sport

Fernando Rocha, Manuela Álvares, Maria José Mesquita, Pedro Machado, Manuela Batista, Clarisse Castro, Isabel Flores, João Quintão, Pedro Rocha, Susana Gonçalves, João Regufe, João Galvão, Catarina Teixeira

ISBN

978-989-8527-66-0

